

Frances Yee Acting Director, Regulatory Compliance and Support Gas Operations 375 N. Wiget Lane, Suite 200 Walnut Creek, CA 94598

925-974-4316 Fax: 925-974-4232 Internet: FSC2@pge.com

March 6, 2013

General Jack Hagan, Director Safety and Enforcement Division California Public Utilities Commission 505 Van Ness Avenue, Room 2205 San Francisco, CA 94102-3298

Re: CPUC Resolution ALJ-274 Self-Identified Non-Compliance Notification Missed Atmospheric Corrosion Inspections on High Pressure Regulators

Dear General Hagan:

Pursuant to Resolution ALJ-274, PG&E is providing notification of a self-identified noncompliance issue regarding missed atmospheric corrosion inspections for 11 high pressure regulators (HPRs).

49 CFR §192.481(a) requires that onshore pipelines be inspected for atmospheric corrosion "at least once every 3 calendar years, but with intervals not exceeding 39 months."

A customer primary regulator, or "farm tap," is an HPR used to serve one or two customers directly from a transmission line or distribution feeder main rather than from a distribution system. Historically, farm taps received maintenance only when issues were reported. However, in 2009, PG&E recognized a gap in atmospheric corrosion inspection monitoring for farm taps and implemented Risk Management Instruction-12 (RMI-12) to establish an inventory of farm taps throughout the PG&E service territory. The results were used as the first step to conducting the required atmospheric corrosion inspections.

After completing the RMI-12 inventory effort, to date PG&E has found eleven previously unidentified farm taps (see Table 1). These were identified through various reviews and projects, including PG&E's HPR Replacement Program and the MAOP Validation Project. Five of the farm taps (#4 - 8) were identified in previous non-compliance notifications, dated May 18, 2012 and July 18, 2012, but those notifications did not address the atmospheric corrosion inspections.

General Jack Hagan March 6, 2013 Page 2

Farm Tap	Division	Plat	City or County	Corrective AC Inspection Date
1	Central Coast	Redacted	Monterey County	2/25/2013
2	North Coast		Santa Rosa	2/19/2013
3	San Francisco		San Francisco	Removed
4	San Jose	Π	Santa Clara County	6/20/2012
5	San Jose		Santa Clara County	6/20/2012
6	San Jose	Π	Santa Clara County	6/20/2012
7	San Jose		Santa Clara County	6/20/2012
8	San Jose		Santa Clara County	6/20/2012
9	Yosemite	T T	Madera County	2/20/2013
10	Yosemite		Stanislaus County	Removed
11	Yosemite		Stanislaus County	Removed

Table 1:	Farm	Taps	Identified	Subseq	uent to	RMI-12

Following identification, each farm tap was inspected for atmospheric corrosion, except for three that were removed. Furthermore, PG&E is adding the remaining eight farm taps to its asset registry and will place each on appropriate maintenance schedules, in accordance with 49 CFR §192.481(a). PG&E will continue to identify any remaining farm taps throughout its system through the MAOP Validation Project, which is expected to be completed in April 2013.

PG&E is conducting a causal evaluation of this issue and based on the results of the evaluation, will develop the appropriate corrective actions to address this issue on a longer term or system-wide basis, if warranted.

PG&E will notify the local authorities for the appropriate cities and counties of this issue and will provide confirmation of notification as a supplement to this letter.

Please contact Redacted at Redacted or Redacted for any additional questions you may have regarding this notification.

Sincerely,

Frances Yee Acting Director, Regulatory Compliance and Support

cc: Dennis Lee, CPUC Liza Malashenko, CPUC Mike Robertson, CPUC Sunil Shori, CPUC

Redacted	PG	
Redacted		PG&E
Shilpa Ran	naiya	a, PG&E