From:	Doll, Laura
Sent:	1/23/2014 5:55:39 AM
To:	pac@cpuc.ca.gov (pac@cpuc.ca.gov); eim@cpuc.ca.gov (eim@cpuc.ca.gov); terrie.prosper@cpuc.ca.gov (terrie.prosper@cpuc.ca.gov)
Cc:	
Bcc:	
Subject:	Fw: CPUC reportable gas incident - San Francisco
Fyi	
From: Redacted Sent: Wednesday, January 22, 2014 11:20 PM To: UO EP Gas Incident Notify Cc: Redacted Subject: CPUC reportable gas incident - San Francisco	
striking to stop the friser continued to make puther incide building.	in San Francisco causing a release of gas. The driver fled the scene after he meter. PG&E's gas service rep arrived on scene at 2012 hours and attempted to flow of gas by closing the service valve but gas was still hissing from the valve and nection. PG&E crews arrived on site at 2045 hours and tighten the valve at the connection to further stop the flow of gas at 2100 hours. Crews are currently working permanent repairs to the service line. The affected building was vacant at the time of ent. Out of an abundance of caution, the fire department evacuated the neighboring. There were no injuries, no fatalities and no ignition as a result of this incident. This rt to the CPUC because Channel 4 news was observed on scene.

Redacted

Regulatory Compliance

Gas Operations | Pacific Gas and Electric

6111 Bollinger Canyon Road, San Ramon, Ca 94583

Redacted