From:	Doll, Laura
Sent:	3/6/2014 1:31:01 PM
To:	pac@cpuc.ca.gov (pac@cpuc.ca.gov); eim@cpuc.ca.gov (eim@cpuc.ca.gov); terrie.prosper@cpuc.ca.gov (terrie.prosper@cpuc.ca.gov)
Cc:	
Bcc:	
Subject:	Fw: CPUC Reportable Incident: San Jose
Fyi	
From: Redacted Sent: Thursday, March 06, 2014 01:28 PM To: UO EP Gas Incident Notify Cc: Redacted Subject: CPUC Reportable Incident: San Jose	
Redacted performin through a repair cre departme approxim incident. 0 restored a ½-inch dia pm. The t Redac The USA ticke	that caused an unintentional release of gas. The third-party was g pavement cutting work in preparation for installing a new water main when they cut ½-inch diameter copper service. PG&E's GSR was on-site at 10:58 am, and PG&E's ws were on site at 11:30 am. Traffic was re-routed and the area blocked off. The fire nt issued a shelter in place order. Media presence was reported on site at ately 11:44 am. There were no fires/explosions/injuries/fatalities as a result of this Gas services to two neighboring houses were shut off as a precaution, but are being as of the time of reporting. The flow of gas was stopped at 12:05 am by squeezing the ameter copper service. Repairs are estimated to be complete at approximately 4:30 hird-party involved was Lewis & Tibbitt - point of contact is Redacted at Redacted agas services in the area were located and marked, and the third-party had a valid at (#055013), but the third-party failed to expose and verify prior to excavation.
Redacted	
Pacific Ga	as & Electric Co.
Regulator	ry Compliance Analyst
Gas Oper	rations Support
Redacted	