**Bulletin Number: 325** Publication Date: 6/16/2010



	Gas Information Bulleting Gas Information Bulleting
Title:	Changes to Gas Transmission Station Maintenance and Addition of Leak Survey Form
RECOMMEN	·
• •	of this bulletin is to notify users of Utility Procedure TD-4430P-02, "Gas n Stations Inspection, Testing, and Maintenance Procedures" of the anges.
Change #1:	Change the third paragraph in Step 4.8.1 to read:
	For Becker pilots only, perform a Class A inspection annually (see Becker training manual). Perform a Class B inspection for cause
	and
	Change the title for Step 4.21 to read: "Pilots (excludes Becker pilots)"
Change #2:	Change the title for Step 4.13 to read: "Fire Protection Systems and Equipment"
	Also, Attachment 6, "Station Fire Protection Systems/Equipment Routine" is changed to conduct an annual review of the facility's Fire Pre-Plans (if one exists), and an annual inspection for designated fire walls and penetration seals (as designated in the facility's Fire Pre-Plans).
Change #3:	A new Attachment 13 (Form TD-4430P-02-F08), "Gas Transmission Station Leak Survey Report" has been added to this procedure to document the results of the annual leak surveys at gas transmission stations.
	Also, the following paragraph is added to Section 3 of the procedure.
	7. Use form TD-4430P-02-F08 to document the results of the annual leal

surveys at gas transmission stations.

The above changes are effective immediately, and must be implemented no later than 30 days upon publication of this bulletin. These changes will be incorporated into the next revision of this procedure. Page 1

GTR0118343 Material Redacted

## Approved by:

**Date**: (06/16/2010)

If you have any questions about this bulletin, please call the employee(s) listed below:

Contact(s): LAN ID(s):

Author:

Phone(s):

Page 2

Material Redacted GTR0118344