



KOP-South-8 was established from the passenger's seat of a vehicle on Colima Road, just west of the intersection of Hacienda Boulevard. This KOP was selected to represent views for local residents traveling west-southwest on Colima Road into the residential areas north of the transmission corridor. This is a typical streetscape view of a divided four-lane collector street in Hacienda Heights with convenience commercial development at the intersection.

**Overall Visual Sensitivity: moderate-to-high.** For people driving on Hacienda Road or Colima Road in general and KOP-South-8 specifically, the ratings of moderate-to-high viewer exposure, moderate-to-high viewer concern, and moderate visual quality lead to a moderate-to-high overall visual sensitivity of the visual setting and viewing characteristics.

**Figure 3.14-43a**  
**Existing Conditions**  
**for KOP-South-8**  
**Colima Road,**  
**Hacienda Heights**  
**(Alternative 2, Segment 8)**

Source: SCE, 2007.