



KOP-South-3 is located within a residential neighborhood in the southern portion of Landscape Unit 10, in close proximity to the transmission corridor.

Overall Visual Sensitivity: moderate-to-high. For residents of South El Monte in general and KOP-South-3 specifically, the ratings of high viewer exposure, high viewer concern, and low-to-moderate visual quality lead to a moderate-to-high overall visual sensitivity of the visual setting and viewing characteristics.

Figure A-38a
Existing Conditions
for KOP-South-3
Linard Street/Kayann Place
Intersection, South El Monte
(Alternative 2, Segment 7)
Source: SCE, 2007.