

**Sierra Pacific Power Company
Annual GO 165 Report**

Total California

	Year 2002						Year 2003		
	Units Scheduled for Inspection	Total Units Inspected	# of Units for Repair	% Total Units for Repair	# Units Repaired	% of Units Repaired	Units Scheduled for Repair	# of Units Repaired	% of Units Repaired
All inspected Circuits									
Transformers									
Overhead	971	937	0	0.0%	0	100%	0	0	
Underground	3	3	0		0		0	0	
Padmounted	276	239	0	0.0%	0	100%	0	0	
Switching/Protective Devices									
Overhead	765	765	0	0.0%	0	0%	0	0	
Underground	5	5	0		0		0	0	
Padmounted	61	61	0	0.0%	0	0%	0	0	
Regs/Capacitors									
Overhead	6	6	0	0.0%	0	0%	0	0	
Underground	0	0	0		0		0	0	
Padmounted	0	0	0		0		0	0	
Distribution Conductors & Cable Miles	227.7	180	1	0.6%	1	0%	0	0	
Pole Line Hardware, Infractions, Etc.	3577	4509	313	6.9%	59		194	0	0.0%
Vaults, Boxes & Manholes	145	145	3	2.1%	3	0%	0	0	
Junction Enclosers	55	55	0	0.0%	0	0%	0	0	
Wood Poles									
Wood Poles Inspected	3577	4509	8	0.2%	8	0%	0	0	
Wood Poles Intrusively Inspected	4138	4138	218	5.3%	218	100%	0	0	100%

Carson

All inspected Circuits	Year 2002						Year 2003		
	Units Scheduled for Inspection	Total Units Inspected	# of Units for Repair	% Total Units for Repair	# Units Repaired	% of Units Repaired	Units Scheduled for Repair	# of Units Repaired	% of Units Repaired
Transformers									
Overhead	161	127	0				0	0	
Underground								0	
Padmounted	40	3	0				0	0	
Switching/Protective Devices									
Overhead	3	3	0				0	0	
Underground							0	0	
Padmounted	2	2	0				0	0	
Regs/Capacitors									
Overhead	3	3	0				0	0	
Underground							0	0	
Padmounted							0	0	
Distribution Conductors & Cable Miles	47.7		1	2	1	100	0	0	
Pole Line Hardware, Infractions, Etc.		932	66	8	8	12	0	0	
Vaults, Boxes & Manholes							0	0	
Junction Enclosers	2	2	0				0	0	
Wood Poles	1009								
Wood Poles Inspected		932	8	0.01	8	100	0	0	
Wood Poles Intrusively Inspected							0	0	

Notes:

8 poles for repair were replaced.

**Annual GO 65 Report
Sierra Pacific Power Company**

Tahoe

	Year 2002						Year 2003		
	Units Scheduled for Inspection	Total Units Inspected	# of Units for Repair	% Total Units for Repair	# Units Repaired	% of Units Repaired	Units Scheduled for Repair	# of Units Repaired	% of Units Repaired
All inspected Circuits									
Transformers									
Overhead	810	810	0	0.00%	0	0.00%	0	0	0.00%
Underground	3	3	0	0.00%	0	0.00%	0	0	0.00%
Padmounted	236	236	0	0.00%	0	0.00%	0	0	0.00%
Switching/Protective Devices									
Overhead	762	762	0	0.00%	0	0.00%	0	0	0.00%
Underground	5	5	0	0.00%	0	0.00%	0	0	0.00%
Padmounted	59	59	0	0.00%	0	0.00%	0	0	0.00%
Regs/Capacitors									
Overhead	3	3	0	0.00%	0	0.00%	0	0	0.00%
Underground	0	0	0	0.00%	0	0.00%	0	0	0.00%
Padmounted	0	0	0	0.00%	0	0.00%	0	0	0.00%
Distribution Conductors & Cable Miles	180	180	0	0.00%	0	0.00%	0	0	0.00%
Pole Line Hardware, Infractions, Etc.	3577	3577	247	6.90%	51	1.40%	194	0	0.00%
Vaults, Boxes & Manholes	145	145	3	2.00%	3	100.00%	0	0	0.00%
Junction Enclosures	53	53	0	0.00%	0	0.00%	0	0	0.00%
Wood Poles									
Wood Poles Inspected	3577	3577	0	0.00%	0	0.00%	0		0.00%
Wood Poles Intrusively Inspected	4138	4138	218	5.00%	218	100.00%	0	0	0.00%