

July 1, 2014

#### VIA OVERNIGHT DELIVERY

Benjamin Brinkman
California Public Utilities Commission
Safety Enforcement Division
505 Van Ness Avenue
San Francisco, CA 94102-3298
benjamin.brinkman@cpuc.ca.gov
usrb@cpuc.ca.gov

Re: PacifiCorp's (U 901-E) 2013 Annual report of Inspection Activities Filed Pursuant to General Order No. 165

Pursuant to General Order No. 165, PacifiCorp provides an original and one (1) copy of the attached 2013 annual report of inspection activities for electric distribution facilities.

It is respectfully requested that all formal correspondence and Staff requests regarding this matter be addressed to:

By E-mail (preferred):

datarequest@pacificorp.com

By regular mail:

Data Request Response Center

PacifiCorp

825 NE Multnomah, Suite 2000

Portland, OR 97232

Informal inquiries may be directed to Heide Caswell, Director, Transmission & Distribution Asset Performance, at (503) 813-6216 or Cathie Allen, Regulatory Manager, at (503) 813-5934.

Sincerely,

R. Bryce Dalley /ca

Vice President, Regulation

cc: Paul Clanon, Energy Division

# ANNUAL REPORT OF INSPECTION ACTIVITIES FILED PURSUANT TO GENERAL ORDER 165 FOR THE CALENDAR YEAR 2013

## **2013 GENERAL ORDER 165 ANNUAL REPORT**

# Reporting Period: 01/01/13 - 12/31/13 PacifiCorp

### Distribution

District	Overhead Patrol		Overhead Detail		Underground Patrol		Undergound Detail		Intrusive	
	Due	Outstanding	Due	Outstanding	Due	Outstanding	Due	Outstanding	Due	Outstanding
Tulelake	6,266	0	1,250	0	38	0	26	0	1,253	0
Alturas	1,679	0	235	0	33	1	21	0	376	0
Crescent City	4,441	0	821	0	625	0	648	1	685	1
Yreka	17,018	0	3,153	1	2,978	1	1,412	0	3,229	2
Total	29,404	0	5,459	1	3,674	2	2,107	1	5,543	3

	Transmission									
District	Over	nead Safety	Ove	head Detail	Intrusive					
	Due	Outstanding	Due	Outstanding	Due	Outstanding				
Tulelake	2,644	0	0	0	0	0				
Alturas	0	0	0	0	0	0				
Crescent City	831	0	0	0	0	0				
Yreka	2,993	0	2,073	0	0	0				
Total	6,468	0	2,073	0	0	0				

The units listed in the table are defined as "facility points" within PacifiCorp's inspection system. For overhead facilities, a facility point is a pole including all equipment installed on the pole. The span of wire between poles or service drops spanning from poles to customer's facilities are associated to the nearest facility point for inspection purposes. For underground facilities a facility point is the location associated with ground mounted equipment, including all equipment at that individual location such as a padmount transformer or switch cabinet.

One underground patrol, one underground detail and one wood pole intrusive test are outstanding due to inability to access the physical location of the facility. One underground patrol shown as outstanding was completed on May 24, 2014. Two wood pole instrusive inspections and one overhead detail inspection shown as outstanding are believed to have been removed from service and will be verified by field staff.

### **VERIFICATION**

I am Vice President of Operations for the Transmission and Distribution Business
Unit of Pacific Power, and am authorized to make this verification on its behalf. I am
informed and believe that the matters stated in the foregoing document are true.

I declare under penalty of perjury that the foregoing is true and correct.

Executed this 1<sup>st</sup> day of July, 2014 at Portland, Oregon.

Douglas R. Butler

Vice President, Operations