

Liberty Utilities (CalPeco Electric) LLC (U 933-E)

ANNUAL GO 165 REPORT

Year - 2014

	G	H	I	J	K	L
<i>All Inspected Circuits</i>	<i>Units Scheduled for Inspection</i>	<i>Total # of Units Inspected</i>	<i># of Units Scheduled for Repair</i>	<i>% of Total Units Scheduled for Repair (Column I/H)</i>	<i>Total # of Units Repaired</i>	<i>% of Units Repaired (Column K/I)</i>
<i>Transformers</i>						
OVERHEAD (OH)	495	495	119	24.0%	0	0.0%
UNDERGROUND (UG)	1	1	0	0.0%	0	0.0%
PADMOUNT (PM)	400	400	194	48.5%	240	123.7%
<i>Switching / Protective Devices</i>						
OVERHEAD (OH)	123	123	24	19.5%	0	0.0%
UNDERGROUND (UG)	0	0	0	0.0%	0	0.0%
PADMOUNT (PM)	28	28	19	67.9%	19	100.0%
<i>Regulators / Capacitors / Reclosures</i>						
OVERHEAD (OH)	5	5	2	40.0%	0	0.0%
UNDERGROUND (UG)	0	0	0	0.0%	0	0.0%
PADMOUNT (PM)	0	0	0	0.0%	0	0.0%
<i>Junction Enclosures</i>						
	39	39	14	35.9%	4	28.6%
<i>Pole Line Hardware, Infractions, etc.</i>						
	1,817	1,817	392	21.6%	1709	436.0%
<i>Distribution Conductors & Cable Miles</i>						
	59.14	59.14	~	~	~	~
<i>Wood Poles</i>						
WOOD POLES INSPECTED	1,817	1,817	~	~	~	~
WOOD POLES INTRUSIVELY INSPECTED	2,408	2,408	~	~	~	~

Note: The "Total # of Units Repaired" (K) and the "% of Units Repaired" (L) also include repairs in arrears, but completed in 2014.