

June 8, 2016

***VIA ELECTRONIC FILING AND
OVERNIGHT DELIVERY***

Benjamin Brinkman
California Public Utilities Commission
Safety Enforcement Division
505 Van Ness Avenue
San Francisco, CA 94102-3298
benjamin.brinkman@cpuc.ca.gov
usrb@cpuc.ca.gov

Re: PacifiCorp's (U 901-E) 2015 Annual Report of Inspection Activities Filed Pursuant to General Order No. 165

Pursuant to General Order No. 165, PacifiCorp provides an original and one (1) copy of the attached 2015 annual report of inspection activities for electric distribution facilities.

It is respectfully requested that all formal correspondence and Staff requests regarding this matter be addressed to:

By E-mail (preferred): datarequest@pacificorp.com

By regular mail: Data Request Response Center
PacifiCorp
825 NE Multnomah, Suite 2000
Portland, OR 97232

Informal inquiries may be directed to Heide Caswell, Director, Transmission & Distribution Asset Performance, at (503) 813-6216 or Cathie Allen, Regulatory Manager, at (503) 813-5934.

Sincerely,



R. Bryce Dalley
Vice President, Regulation


**ANNUAL REPORT OF INSPECTION ACTIVITIES FILED PURSUANT
TO GENERAL ORDER 165
FOR THE CALENDAR YEAR 2015**

VERIFICATION

I am Vice President of Transmission and Distribution Operations, and am authorized to make this verification on its behalf. I am informed and believe that the matters stated in the foregoing document are true.

I declare under penalty of perjury that the foregoing is true and correct.

Executed 6/1, 2016 at Portland, Oregon.



Curtis Mansfield
Vice President, Transmission and Distribution Operations

2015 GENERAL ORDER 165 ANNUAL REPORT
Reporting Period: 01/01/15 - 12/31/15
PacifiCorp

| Distribution | | | | | | | | | | |
|---------------|-----------------|-------------|-----------------|-------------|--------------------|-------------|--------------------|-------------|--------------|-------------|
| District | Overhead Patrol | | Overhead Detail | | Underground Patrol | | Underground Detail | | Intrusive | |
| | Due | Outstanding | Due | Outstanding | Due | Outstanding | Due | Outstanding | Due | Outstanding |
| Alturas | 1,925 | 0 | 291 | 0 | 61 | 0 | 26 | 0 | 486 | 0 |
| Crescent City | 4,487 | 0 | 783 | 0 | 1,282 | 535 | 626 | 0 | 1,243 | 1 |
| Tulelake | 7,594 | 0 | 1,219 | 0 | 67 | 0 | 41 | 0 | 2,015 | 0 |
| Yreka | 17,117 | 0 | 4,227 | 0 | 4,402 | 0 | 2,983 | 3 | 3,043 | 0 |
| Total | 31,123 | 0 | 6,520 | 0 | 5,812 | 535 | 3,676 | 3 | 6,787 | 1 |

| Transmission | | | | | | |
|---------------|-----------------|-------------|-----------------|-------------|--------------|-------------|
| District | Overhead Patrol | | Overhead Detail | | Intrusive | |
| | Due | Outstanding | Due | Outstanding | Due | Outstanding |
| Alturas | 0 | 0 | 640 | 0 | 0 | 0 |
| Crescent City | 698 | 0 | 0 | 0 | 533 | 0 |
| Tulelake | 0 | 0 | 0 | 0 | 0 | 0 |
| Yreka | 4,864 | 0 | 522 | 0 | 652 | 0 |
| Total | 5,562 | 0 | 1,162 | 0 | 1,185 | 0 |

The units listed in the table are defined as "facility points" within PacifiCorp's inspection system. For overhead facilities, a facility point is a pole including all equipment installed on the pole. The span of wire between poles or service drops spanning from poles to customer's facilities are associated to the nearest facility point for inspection purposes. For underground facilities a facility point is the location associated with ground mounted equipment, including all equipment at that individual location such as a padmount transformer or switch cabinet.

Status of Outstanding Inspections

Crescent City:

Distribution UG Patrol - **To be completed in 2016**

Distribution PTT - **Field verifying if pole exists.**

Yreka:

Distribution UG Detail - inspections completed Jan 21, 2016