



**Liberty Utilities**<sup>SM</sup>

Liberty Utilities (CalPeco Electric) LLC  
933 Eloise Avenue  
South Lake Tahoe, CA 96150  
Telephone: 1-800-782-2506  
Fax: 530-544-4811

July 1, 2016

Mr. David Lee  
Utility Engineer  
California Public Utilities Commission  
505 Van Ness Avenue  
San Francisco, CA 94102

Re: **Liberty Utilities (CalPeco Electric) LLC (U 933-E) Filing for 2015**

**General Order Number 165**

**Public Utilities Commission of the State of California**

**Rules for Inspection cycles for electric distribution facilities**

Dear Mr. Lee:

Enclosed please find the annual General Order ("GO") 165 Report of Liberty Utilities (CalPeco Electric) LLC (U 933-E) for calendar year 2015. This report is submitted in compliance with Section III.D of GO 165.

If additional information is required, please do not hesitate to call me at (530) 721-0357.

Regards,

Kendrick (Ken) Wittman  
Senior Manager of Finance, Accounting and Regulatory

# Liberty Utilities (CalPeco Electric) LLC (U 933-E)

## ANNUAL GO 165 REPORT

Year - 2015

	G	H	I	J	K	L
<i>All Inspected Circuits</i>	Units Scheduled for Inspection	Total # of Units Inspected	# of Units Scheduled for Repair	% of Total Units Scheduled for Repair (Column I/H)	Total # of Units Repaired	% of Units Repaired (Column K/I)
<i>Transformers</i>						
OVERHEAD (OH)	134	134	5	3.7%	4	80.0%
UNDERGROUND (UG)	133	133	8	6.0%	4	50.0%
PADMOUNT (PM)	78	78	46	59.0%	45	97.8%
<i>Switching / Protective Devices</i>						
OVERHEAD (OH)	84	84	1	1.2%	1	100.0%
UNDERGROUND (UG)	0	0	0	0.0%	0	0.0%
PADMOUNT (PM)	0	0	0	0.0%	0	0.0%
<i>Regulators / Capacitors / Reclosures</i>						
OVERHEAD (OH)	2	2	0	0.0%	0	0.0%
UNDERGROUND (UG)	0	0	0	0.0%	0	0.0%
PADMOUNT (PM)	0	0	0	0.0%	0	0.0%
<i>Junction Enclosures</i>						
	4	4	4	100.0%	4	100.0%
<i>Pole Line Hardware, Infractions, etc.</i>						
	743	743	119	16.0%	343	288.2%
<i>Distribution Conductors &amp; Cable Miles</i>						
	29.21	29.21	~	~	~	~
<i>Wood Poles</i>						
WOOD POLES INSPECTED	743	743	~	~	~	~
WOOD POLES INTRUSIVELY INSPECTED	2,419	2,419	~	~	~	~

Note: The "Total # of Units Repaired" (K) and the "% of Units Repaired" (L) also include repairs in arrears, but completed in 2015.