








 Source: Aspen 2015 and SCE 2014 	 Existing Substation  Impact Corridor  Survey Area	Plant Observations Points  Paniculate tarplant  Smooth tarplant	Plant Observations Polygons  Paniculate tarplant  Smooth Tarplant  Small-flowered microseris
	Figure C.5-4b Map B Special-status Plant Species Occurrences		