



This report provides a summary of environmental monitoring and compliance activities conducted by Burns and McDonnell (BMcD) staff and BMcD subconsultants for the San Diego Gas & Electric (SDG&E) Sunrise Powerlink Project during the above weekly time period.

Training

- SWEAP and PBS training was held for new Project personnel on Tuesday. Additional trainings were provided as requested.
- Flat-tailed horned lizard (FTHL) trainings were provided to any new crew members or monitors prior to construction per mitigation measure B-7b and in accordance with the FTHL Rangewide Management Strategy. During morning tailboard meetings, guidelines were provided about recognizing, protecting, and notification requirements for FTHL. FTHL information cards were made available to any crew members or monitors as needed.

Pre/Post Construction

- Avian biologists surveyed for nesting birds prior to work commencing in inactive areas. For sites off of USFS lands, the results of those surveys were submitted to the CPUC/BLM biologist for review and concurrence. For USFS lands, the results of those surveys were submitted to the USFS for review and concurrence. For any active nests found, a buffer was established and no construction activities were permitted within the buffer area without consultation with the CPUC/BLM/USFS biologist. Active nests were mapped and monitored for success or failure and updated on the nest monitoring log.
- Post construction impact surveys occurred from EP205 to EP218, EP220 to EP226, EP227, EP228 to EP234, EP249, EP235 to EP238, EP239, EP240 to EP248, EP250 to EP255, and EP313 to EP323.
- Water bar surveys at EP131 and EP140.
- TEWS surveys at EP32-1 and EP119-2.
- Additional signs and stakes were repaired as needed. Due to traffic and narrow access roads, broken stakes and run over signs were replaced. Maintenance (e.g., writing over faded signs, reinforcing signs/stakes in the ground, replacing zip ties, and adding additional signs) was performed as needed. The ESA Team conducted the following activities during this reporting period:
 - § Repaired, refreshed, replaced, and maintained the previously installed project signs and ESAs at CP30 to CP42, access road to EP244, EP243 pole site, access road to EP205, access road to Bartlett Hauser Yard, access road to EP90, and access road to Kreutzkamp Yard.

Construction

- Monitors were present during construction activities to ensure compliance with mitigation measures as identified in the Final EIR/EIS Mitigation Monitoring, Compliance, and Reporting Program. Archaeologists, Paleontologists, and Native American Monitors were present at sites where required as identified prior to construction activity and as approved in the NTPs. On average, the following number of monitors were on the Project throughout the week:
 - § 92 Biological monitors.
 - § 1 Archaeological monitor.



Sunrise Powerlink Project
Weekly Report 90 – June 03, 2012 through June 09, 2012



- § 1 Native American monitor.
- § 8 SWPPP monitors.

- Project staff carpooled to site reviews, kick-off tailgates, and off-site meetings. Construction and traffic control crews were observed carpooling from yards to work areas.
- Deterrents were utilized to discourage bird nest building activities throughout the Project. Deterrents are determined depending upon the location and type of possible nesting areas and may include metallic flagging, compact discs, plastic owls, and the presence of biological monitors.
- The table below demonstrates the construction progress to date:

OVERHEAD			
Agency	Foundations Completed	Towers Erected	Wire Installed
Non-Federal	169 of 169	169 of 169	166 of 169 EP30-2 to EP32-1, EP62A-1, EP64 to EP67, EP77, EP78
Bureau of Land Management	179 of 179	179 of 179	166 of 179 EP39-1 to EP41, EP56-4, EP 63, EP68 to EP76-2
Miramar	14 of 14	14 of 14	14 of 14
U.S. Forest Service	76 of 76	76 of 76	50 of 76 EP33-1 to EP37-2, EP125 to EP130-1, EP57-2, EP58-2
UNDERGROUND			
Agency	Vaults Installed	Trenches Excavated & Backfilled	
Non-Federal	40 of 40	42 of 42	
SUBSTATION UPGRADES			
4 of 7 Completed			
SUNCREST SUBSTATION			
100 Percent Complete			



Overhead Construction

- Link 1
 - § Final grading at EP170 pull site, EP220-1-N, EP226-1 pull site, EP240, EP242, EP244, EP245-1, EP247, and EP248-1.
 - § Fence grounding at EP215 and EP238-1.
 - § Miscellaneous tower work at EP146, EP170, EP174, EP176 to EP179, EP187-2, EP189-3, EP190-2, EP197-3 to EP199-3, EP239-1, EP240, EP242, EP247, EP248-1, EP252-1, and EP304-2.
 - § QA/QC from EP204-3 to EP209-1.
 - § Work continued at EP215 regen site.
 - § Insulator cleaning from EP182 to EP220-1, EP239-1, EP242 to EP252-1, EP255, EP313 to EP350, and EP354 to Imperial Valley Substation.
 - § BMP maintenance at EP144 to EP152, EP170 to EP177 (including pull site), EP186-1, EP187-2 to EP191, EP192-2-N, EP192/EP193 pull site, EP193-2-N, EP194-3 to EP196-2, EP208 to EP211, EP211-E to EP219-1-E, EP213 to EP215, EP219-1, EP221-2, EP221A, EP223-1 to EP224-1, EP226-1 to EP230-1, EP231A to EP237-1, EP239-1, EP240, EP242 to EP245-1 (including pull site), EP247, EP248-1, EP252-1 to EP255, GS-NF-31, GS-NF-32, and GS-NF-36.
 - § Hydromulching at EP187-2, EP189-3, EP192-2, EP198-3, EP228, EP243, and EP243/EP244 pull site.
- Link 2
 - § During this reporting period, the PAL levels were as follows: Sunday-Ev, Monday-Ev, Tuesday-C, Wednesday-C, Thursday-C, Friday-C, and Saturday-C. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

- § Vegetation maintenance at EP112-3 to EP112A-1 including associated access roads.
- § Final grading at EP23-2 pull site.
- § Fence grounding at EP108-2, EP112-3-N, EP116-1-E, EP141, and EP142-1.
- § Grounding at EP121-3 and EP121A-1.
- § Tower assembly at EP33-1, EP112-3 to EP118-2, EP120-4 to EP126, EP129, EP131, and EP137 to EP141.
- § Miscellaneous tower work at EP2-3 to EP8-2, EP11-3, EP13-3 to EP24-1, EP29-2, EP33-1 to EP37-2, EP57-2, EP58-2, EP112-3, EP115-1 to EP118-2, EP120-4 to EP122-1, EP124, EP126-1, EP127, EP130-1, EP142-1, and EP143-1.
- § QA/QC at EP6-1, EP7-1, EP33-1, EP35-1, EP36-1, EP111-4, EP112-3, EP112A, EP116-1, EP117-2, EP120A, and EP121A-1.
- § Ground resistance testing at EP114-2, EP115-1, EP121-3, EP121A-1, EP123-1, and EP128.
- § OPGW flown from EP54-1 to EP67 and EP113-5 to EP126-1.
- § OPGW clipping in from EP126-2 to EP128.
- § OPGW sagged at EP57-2 and EP58-2.
- § Sock line, hardline, and conductor pulled from EP54 to EP67 pull site.
- § Sock line and hardline flown from EP113-5 to EP124.
- § Conductor pulled from EP12-3 to EP22-1 and EP113-5 to EP124.
- § Sagging, clipping in, dead-end, and spacing work at EP125 to EP131.
- § Dead-end work at EP57-2 and EP58-2.
- § Clipping in and dead-end work from EP30-2 to EP42.
- § Traveler work at EP113-5 to EP124.



Sunrise Powerlink Project
Weekly Report 90 – June 03, 2012 through June 09, 2012



- § Insulator work at EP12-3 to EP22-1 and EP113-5 to EP124.
- § Insulator washing at EP112-3 and EP112A-1.
- § Jumper work at EP30-2 to EP42 and EP54-1 to EP67.
- § Spacers installed at EP24-1 and EP29-2.
- § Marker ball installation at EP5-2, EP7-1, and EP9-1.
- § Splicing at EP9-1, EP34-1, and EP130-1.
- § Punchlist wire work at EP137, EP139-1, EP141, and EP143-2.
- § Cleanup at EP2-3 to EP8-2, EP10-2, EP14-1 to EP24-1, and EP30-2 to EP42.
- § BMP maintenance at EP7-1, EP8-2, EP33-1, EP35-1, EP36-1, EP37-2, EP109-1, EP110-2, EP111-4, EP112-3, EP114-2, EP116-1, EP117-2, EP120-4, EP121A-1, EP123-1, EP124, EP125, EP125-E-A to EP141-E-B, EP134, EP141, and EP141 pull site.
- § Hydromulching at EP4-3, EP34-1, EP37-2, EP108-2, EP111-4, EP120-4 to EP124, EP128, EP129, EP139-1, and EP142-1.

BLM Land

- § Grading from EP94-N to EP99-2-N-A.
- § Tower assembly at EP48.
- § Miscellaneous tower work at EP42, EP48, EP50, EP53-3, EP75-2, EP76-2, EP96, and EP102A-1.
- § Grounding at EP74-1.
- § QA/QC at EP99-2 and EP103A.
- § OPGW flown from EP54-1 to EP67.
- § Sock line, hardline, and conductor pulled from EP54 to EP67 pull site.
- § Dead-end work at EP30-2 to EP42 and EP69.
- § Jumper work at EP30-2 to EP42, EP54-1 to EP67, EP69, EP75-2, EP76-2.
- § Clipping in at EP30-2 to EP42, EP47-2, and EP63.
- § Insulator washing at EP73-1, EP75-2, EP94 to EP99-2, and EP103A.
- § Jumper work at EP30-2 to EP42, EP54-1 to EP67, EP69, EP75-2, and EP76-2.
- § Spacers installed at EP39-1 and EP69 to EP76-2.
- § Splicing at EP42.
- § Wire punchlist work at EP70, EP74-1, and EP76-2.
- § Cleanup at EP30-2 to EP42.
- § BMP installation/maintenance at EP40-1, EP41, EP47-2 to EP51-1, EP53-1, EP56-4, EP70 to EP73-1, EP75-2, EP76-2, EP94 to EP99-2, EP101-2 pull site, and EP103A.
- § BMPs removed from EP99-2-N-B and EP101-2-PS-N.
- § Restoration at EP99-2 and EP101-2 pull site.

Non-Federal Land

- § Grading at EP92-N and EP93-N.
- § Grounding at EP80 to EP82-1, EP87-1, EP107-3, EP108-2, and GS-NF-29.
- § Tower assembly at EP54-1, EP77 to EP79, EP84 to EP88-2, EP91, EP92, and EP119-2.
- § Miscellaneous tower work at EP26-1, EP27-1, EP30-2, EP32-1, EP54-1, EP77, EP79, EP80, EP84, EP85-2, EP93, EP106-3, EP107-3, and EP119-2.
- § QA/QC at EP104-2 and EP105-2.
- § Regen work continued near EP54-1.
- § Guard structure installation at EP32-1.
- § OPGW flown from EP54 to EP67 pull site and EP113-5 to EP126-1.
- § Sock line, hardline, and conductor pulled from EP54 to EP67 pull site.
- § Conductor pulled from EP113-5 to EP124.
- § Insulator work at EP119-2.



Sunrise Powerlink Project
Weekly Report 90 – June 03, 2012 through June 09, 2012



- § Insulator washing at EP77, EP78A, EP85-2, EP89-1, EP92, EP93, EP104-2, and EP105-2.
- § Traveler work at EP67 and EP119-2.
- § Sagging and clipping in at EP30-2 to EP42.
- § Jumper work at EP30-2 to EP42, EP54-1 to EP67, and EP79.
- § Dead-end work from EP30-2 to EP42, EP62A-1, and EP64 to EP67.
- § Clipping in at EP30-2 to EP42, EP62A-1, and EP64 to EP66.
- § Marker ball installation at EP1-3.
- § Spacer work at EP25-2 to EP29-2, EP32-1, EP67, EP77, and EP78.
- § Cleanup at EP25-2 and EP30-2 to EP42.
- § Splicing at EP30-2 and EP78A.
- § Wire punchlist work at EP77 and EP78.
- § Guard structure demobilization at GS-NF-17.
- § BMP installation/maintenance at EP25-2, EP26-1, EP30-2, EP31-1, EP32-1, EP52-1, EP54-1, EP77, EP80, EP81, EP83 to EP89-1, EP91 to EP93, EP104-2, EP105-2, EP107-3, EP119-2, GS-NF-14, GS-NF-17, GS-NF-22, GS-NF-23, and GS-NF-24.
- § Hydromulching at EP25-2 and EP87-1.

· Link 5

- § During this reporting period, the PAL levels were as follows: Sunday-Ev, Monday-Ev, Tuesday-C, Wednesday-C, Thursday-C, Friday-C, and Saturday-C. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

- § Miscellaneous tower work at CP69-2, CP103-2, CP104-1, and CP105-1.
- § Gate work at CP69-2.
- § Ground resistance testing at CP103-2 and CP104-1.
- § QA/QC at CP98-1, CP100-1, and CP105-1.
- § BMP maintenance at CP69-2, CP99-2, CP100-1, CP101-1, CP103-2, and CP105-1.
- § BMP removal at CP98-N, CP99-2, CP100-1, and CP100-1-N.

BLM Land

- § Miscellaneous tower work at CP65-1.
- § BMP installation and maintenance at CP59.
- § Hydromulching at CP59.

Non-Federal Land

- § Rock stabilization at CP47A-1.
- § Final grading at CP98-N-A.
- § Miscellaneous tower work at CP37-2, CP63-3, and CP72-2.
- § QA/QC at CP95-1 and CP96-1.
- § BMP installation and maintenance at CP17-1, CP19-1, CP37-2, CP43-1, CP44-1, CP49-1, CP55 pull site, CP57, CP70-3, CP72-1, CP73-2, CP75-1, CP85-1, CP87-1, CP88-1, CP95-1, CP96-1, CP98-1, CP109-1, GS-NF-6, GS-NF-7, GS-NF-8, GS-NF-9, and GS-NF-25.
- § BMP removal at CP39 to CP42-1, CP43-1 pull sites, and CP98-N-A.
- § Restoration at CP49-1-PS-N and CP49-1 pull site.
- § Hydromulching at CP18-1, CP19-1, CP28-1, CP29-1, CP41-2, CP42-1, and CP72-2.

Miramar

- § Final grade and restoration at CP6-1, CP7, and CP9-1 to CP11-1.
- § Miscellaneous tower work at CP8-2, CP12-1, and CP15-1.
- § Spacer work at CP11-1 and CP15-1.
- § BMP installation and maintenance at CP2, CP3, CP6-1 to CP12-1, CP14, CP15-1, and GS-DOD-1.

Underground Construction (Link 4)

- Revitalization at Alpine Blvd.
- Splicing inside V20R.
- Pulling cable between V19 and V20.
- Hydroseeding at the bore site.
- Cleanup activities at the bore site.
- Prysmian working on CP88.
- Work inside V1.
- Kinnectrics cleaning up testing materials and removing a testing trailer at Loritz property.
- Testing setup at Loritz and Slay properties.
- Mass crew working on CP87.
- Work inside V20.
- BMP removal at the Bauer property.

Suncrest Substation Construction (Link 3)

- Work inside the control shelter.
- Anderson drilling excavating foundation hole near the water tank.
- Pinnick crew hauling off equipment from the site.
- Beta crew flushing storm drain line.
- Beta crew removing materials from the site.
- SDG&E working in the 230kV yard.
- Pinnick crew decompacting soil at the former office location.
- Pinnick crew removing rock from the parking area for the office trailers.

Substation Upgrades

San Luis Rey:

- Bird sweeps/surveys ongoing to identify and deter nest building.

Encina:

- SDG&E relay and wiring crews performing wiring near the control house.
- SDG&E crew pulling new section of cable in the northern portion of the substation.

Scripps:

- No Sunrise-related work.

Pomerado:

- No Sunrise-related work.

Sycamore:

- On-going bird sweeps/surveys ahead of planned work for the following week.
- SDG&E crew installing jumpers and working in the control house.

Construction Yards

- Sycamore Yard – Crew staging.
- Helix Yard – Occasional helicopter operations and crew staging.
- El Monte Yard – No activity.
- Alpine Yard – Hub for equipment/materials staging, vegetation maintenance, and crew staging.
- Wilson Yard – Intermittent helicopter operations and crew staging.
- SWAT Yard – Frequent helicopter operations and crew staging.
- Barrett Canyon Yard – No activity.
- Kreuzkamp Yard – Intermittent helicopter operations and crew staging.
- Bartlett Hauser Yard – Frequent helicopter operations and crew staging.
- Thing Valley Yard – Helicopter operations and staging for assembly and wire crews.
- McCain Valley Yard – Crew staging.
- Rough Acres Yard – Crew staging.
- Jacumba Valley Ranch (JVR) Yard – Crew staging.

NOTE: In addition, all active yards typically have miscellaneous activities throughout the day such as materials delivery and staging, equipment mobilization/demobilization, water supply and dust control, and porta-potty maintenance.

Wildlife Reporting

The following listed or Species of Special Concern were found dead in Project construction limits during this reporting period:

- Coastal Rosy Boa (*Charina trivirgata roseofusca*) – Two (2) coastal rosy boas were found dead; one (1) on the main access road to Kreuzkamp Yard and one (1) at EP39.
- Northern Three-lined Boa (*Lichanura orcutti*) – One (1) northern three-lined boa was found dead at Kreuzkamp Yard

The following listed or Species of Special Concern were relocated during construction activities this reporting period:

- Coastal Rosy Boa (*Charina trivirgata roseofusca*) – Two (2) coastal rosy boas were relocated; one (1) from EP39 and one (1) from EP121-3.
- Coast Horned Lizard (*Phrynosoma coronatum blainvillii*) – Two (2) coast horned lizards were relocated (1) one from EP116-1, and (1) one from EP120A.
- Coast Patch-nosed Snake – (*Salvadora hexalepis virgultea*) – One (1) coast patch-nose snake was relocated from Thing Valley Yard.
- California Legless Lizard (*Anniella pulchra*) – Two (2) California legless lizards were relocated from EP99-2.
- Coronado Skink (*Plestiodon skiltonianus interparietalis*) – One (1) Coronado skink was relocated from EP12.
- Two-striped Garter Snake (*Thammonphis hammondi*) – One (1) two-striped garter snake was relocated from Kreuzkamp Yard.

Spills/Hazardous Waste

- No spills were reported during this reporting period.



Customer Complaints

- No customer complaints were received during this reporting period.

Non-Compliances

- No non-compliances were received during this reporting period.

Variations and TEWS

- No new variations and TEWS were approved during this reporting period.

Weather

- No rain events occurred during this reporting period.
- BMPs were installed or maintained as needed throughout Project areas. In accordance with the Construction General Permit (CGP), daily site BMP inspections, and photos, appropriate BMPs for stormwater and non-stormwater were implemented. Any sites requiring repairs began within 72 hours of identification.

Appendices

Flat-Tailed Horned Lizard Monitoring Report

Raven Control Monitoring Report

Flat Tailed Horned Lizard Counts - Week Ending 06/09/2012

Date	Location	Observed		Injured		Relocated		Dead	
		Day	Night	Day	Night	Day	Night	Day	Night
	Post RCLMP*								
5/7/2012	AR btwn EP321 and EP320							1	
4/18/2012	AR btwn EP354-N and EP354	1							
2/23/2012	West side of AR to EP324	1							
11/1/2011	Dunaway CY					1			
10/13/2011	AR to EP354							1	
9/20/2011	AR btwn EP357 and EP358							1	
9/19/2011	AR btwn EP352 and EP353	1							
9/12/2011	EP325					1			
9/9/2011	AR to EP363	1							
9/6/2011	AR to EP360/361					1			
9/6/2011	EP360					2			
9/6/2011	EP359					1			
9/3/2011	SWPL AR to EP324					1			
9/3/2011	SWPL AR to EP342					1			
9/3/2011	SWPL AR to EP345							1	
9/3/2011	SWPL AR to EP344 and EP345					1			
8/31/2011	EP324					1			
8/31/2011	SWPL AR to EP325-2					1			
8/30/2011	SWPL AR to EP346 and EP347					1			
8/29/2011	SWPL AR to EP353 and EP354							1	
8/29/2011	SWPL AR to EP324							1	
8/27/2011	EP349					1			
8/25/2011	EP360							1	
8/25/2011	Btwn EP320/321					1			
8/24/2011	SWPL AR near EP346					1			
8/23/2011	EP349					1			
8/21/2011	SWPL AR btwn EP344/345					1			
8/21/2011	SWPL AR to EP345							1	
8/19/2011	SWPL AR to EP339					1			
8/20/2011	SWPL AR to IV Sub							1	
8/20/2011	SWPL AR btwn EP346/347					1			
8/19/2011	EP338/339 Pullsite					1			
8/19/2011	EP355/356 Pullsite					1			
8/18/2011	EP347					1			
8/18/2011	SWPL AR to EP353							1	
8/11/2011	SWPL AR by EP348					1			
8/11/2011	EP348/EP349 Pullsite					1			
8/10/2011	EP347					1			
8/8/2011	SWPL AR to EP351					2			
8/6/2011	BLM AR near EP327							1	
8/1/2011	IV Substation Yard	1							
8/1/2011	EP325					1			
8/1/2011	AR to EP345					1			

Flat Tailed Horned Lizard Counts - Week Ending 06/09/2012

Date	Location	Observed		Injured		Relocated		Dead	
7/30/2011	EP322					1			
7/28/2011	EP355/EP356 Pullsite					1			
7/27/2011	Near EP316-2	1							
7/26/2011	SWPL AR to EP344	1							
Post RCLMP*		Day	Night	Day	Night	Day	Night	Day	Night
7/26/2011	EP347					1			
7/26/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/22/2011	AR to IV Sub					1			
7/21/2011	EP360					1			
7/21/2011	AR to EP326					1			
7/19/2011	SWPL AR to IV Sub	1							
7/19/2011	EP353					1			
7/19/2011	AR to Dunaway CY					1			
7/18/2011	EP318					1			
7/17/2011	EP355					1			
7/15/2011	EP359	1							
7/15/2011	EP352	1							
7/15/2011	EP350	1							
7/14/2011	Spur Rd to EP355							1	
7/14/2011	EP322	1							
7/13/2011	EP357	1							
7/12/2011	EP344	1							
7/12/2011	SWPL AR btwn EP348/345							1	
TOTAL POST RCLMP		14	0	0	0	43	0	13	
Prior to RCLMP		Day		Day		Day		Day	
7/11/2011	AR to EP352					2			
7/11/2011	AR to EP345					2			
7/10/2011	EP358					1			
7/10/2011	SWPL AR to EP354					2			
7/9/2011	AR to EP330	1							
7/8/2011	Spur Rd. to EP352	1							
7/7/2011	EP324					1			
7/7/2011	EP355					1			
7/6/2011	SWPL AR btwn EP362/363							1	
7/5/2011	EP354					1			
7/1/2011	AR to EP353	1							
6/30/2011	AR between EP310/311							1	
6/30/2011	EP358	1							
6/30/2011	EP360	1							
6/30/2011	AR to EP312							1	

Flat Tailed Horned Lizard Counts - Week Ending 06/09/2012

Date	Location	Observed	Injured	Relocated	Dead
6/30/2011	EP360				1
6/27/2011	EP350			1	
6/27/2011	SWPL AR to IV Substation	2			
6/26/2011	IV Substation			1	
6/25/2011	SWPL AR to EP361	1			
6/24/2011	EP359			1	
6/23/2011	SWPL AR to EP360			2	
6/22/2011	SWPL AR to EP355			1	
6/20/2011	EP356	2			
6/20/2011	SWPL AR to EP359	1			
6/20/2011	Near EP356	2			
6/20/2011	AR between EP358/357				1
6/18/2011	AR to Dunaway CY				1
6/17/2011	Near EP322	1			
6/7/2011	Near EP355	1			
6/7/2011	EP361			1	
6/7/2011	AR btwn EP343/EP344				1
6/7/2011	AR between EP324/325				1
6/6/2011	SWPL AR btwn EP344/EP345			1	
6/3/2011	EP359			1	
6/3/2011	SWPL AR EP362			1	
6/2/2011	AR to EP358			1	
6/2/2011	SWPL AR to EP316-2				1
6/2/2011	AR east of EP325				1
6/1/2011	SWPL AR btwn EP319/EP320			1	
6/1/2011	SWPL AR to EP318			1	
5/31/2011	SWPL AR btwn EP359/EP360			1	
5/31/2011	SWPL AR to EP320			1	
5/31/2011	EP360				1
5/27/2011	EP357			1	
5/26/2011	SWPL AR to EP359			1	
5/25/2011	Spur Rd to EP321			1	
5/23/2011	EP323			1	
5/21/2011	EP324			1	
5/20/2011	IV CY			1	
5/20/2011	AR to EP362			1	
5/20/2011	AR btwn EP324/EP325			1	
5/20/2011	SWPL AR btwn EP326/EP327			1	
5/20/2011	IV Substation			3	
5/19/2011	IV Substation			5	
5/19/2011	EP324			1	
5/18/2011	IV Substation Yard			1	
5/18/2011	IV Substation Yard				1

Flat Tailed Horned Lizard Counts - Week Ending 06/09/2012					
Date	Location	Observed	Injured	Relocated	Dead
5/17/2011	AR to IV Substation				1
5/16/2011	IV Substation Yard			1	
5/13/2011	SWPL AR Near EP362-1	1			
5/12/2011	AR to EP355			1	
5/11/2011	EP360	1			
5/11/2011	Dunaway CY	3			
5/11/2011	Dunaway Yard			4	
5/10/2011	EP322	1			
5/10/2011	AR to Dunaway CY	1			
5/9/2011	Dunaway Yard			4	
5/7/2011	EP322	1			
5/7/2011	Spur Road to EP344	1			
5/7/2011	Dunaway Yard			1	
5/6/2011	AR to EP321-1	1			
5/5/2011	AR to EP321-1	1			
5/5/2011	AR to Dunaway CY	2			
5/5/2011	Dunaway Yard			2	
5/4/2011	AR btwn EP343/EP344			1	
5/3/2011	SWPL AR btwn EP320/EP321	1			
4/27/2011	AR to EP322	2			
4/26/2011	EP322	1			
4/25/2011	Plaster City CY	1			
4/20/2011	Plaster City			1	
4/18/2011	Plaster City			1	
4/14/2011	AR to IV Substation	1			
4/2/2011	Dunaway CY	1			
TOTAL PRIOR TO RCLMP		35	0	60	13
YTD		49	0	103	26

*RCLMP refers to the Revised Construction Lighting Mitigation Plan

Raven Control Monitoring Report - Week Ending 06/09/2012

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
6/9/2012			No ravens observed					
6/8/2012			No ravens observed					
6/7/2012			No ravens observed					
6/6/2012			No ravens observed					
6/5/2012			No ravens observed					
6/4/2012			No ravens observed					
6/3/2012			No ravens observed					
6/2/2012			No ravens observed					
6/1/2012			No ravens observed					
5/31/2012			No ravens observed					
5/30/2012			No ravens observed					
5/29/2012			No ravens observed					
5/28/2012			No ravens observed					
5/27/2012			No ravens observed					
5/26/2012			No ravens observed					
5/25/2012			No ravens observed					
5/24/2012			No ravens observed					
5/23/2012			No ravens observed					
5/22/2012			No ravens observed					
5/21/2012			No ravens observed					
5/20/2012			No ravens observed					
5/19/2012			No ravens observed					
5/18/2012			No ravens observed					
5/17/2012			No ravens observed					
5/16/2012			No ravens observed					
5/15/2012			No ravens observed					
5/14/2012			No ravens observed					
5/13/2012			No ravens observed					
5/12/2012	EP355/356 SWPL line and EP348	3		1	2			no
5/11/2012			No ravens observed					
5/10/2012			No ravens observed					
5/9/2012			No ravens observed					
5/8/2012			No ravens observed					
5/7/2012			No ravens observed					
5/6/2012			No ravens observed					
5/5/2012			No ravens observed					
5/4/2012			No ravens observed					
5/3/2012			No ravens observed					
5/2/2012			No ravens observed					
5/1/2012			No ravens observed					
4/30/2012			No ravens observed					
4/29/2012			No ravens observed					
4/28/2012			No ravens observed					
4/27/2012	EP314 Pullsite	1		1				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
4/26/2012			No ravens observed					
4/25/2012			No ravens observed					
4/24/2012			No ravens observed					
4/23/2012	EP348/EP349 Pullsite	1		1				no
4/22/2012			No ravens observed					
4/21/2012			No ravens observed					
4/20/2012	EP348/EP349 Pullsite	1			1			no
4/19/2012			No ravens observed					
4/18/2012			No ravens observed					
4/17/2012			No ravens observed					
4/16/2012			No ravens observed					
4/15/2012			No ravens observed					
4/14/2012			No ravens observed					
4/13/2012			No ravens observed					
4/12/2012			No ravens observed					
4/11/2012			No ravens observed					
4/10/2012			No ravens observed					
4/9/2012			No ravens observed					
4/8/2012			No ravens observed					
4/7/2012			No ravens observed					
4/6/2012			No ravens observed					
4/5/2012			No ravens observed					
4/4/2012			No ravens observed					
4/3/2012			No ravens observed					
4/2/2012	S2 Yard	1		1				no
4/1/2012			No ravens observed					
3/31/2012			No ravens observed					
3/30/2012			No ravens observed					
3/29/2012			No ravens observed					
3/28/2012			No ravens observed					
3/27/2012			No ravens observed					
3/26/2012			No ravens observed					
3/25/2012			No ravens observed					
3/24/2012			No ravens observed					
3/23/2012			No ravens observed					
3/22/2012			No ravens observed					
3/21/2012	Plaster City Yard	2			2			no
3/20/2012			No ravens observed					
3/19/2012			No ravens observed					
3/18/2012			No ravens observed					
3/17/2012			No ravens observed					
3/16/2012	EP363	1			1			no
3/15/2012			No ravens observed					
3/14/2012			No ravens observed					
3/13/2012	Plaster City Yard	6		4			2	no
3/12/2012	Plaster City Yard	5		2			3	no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
3/11/2012			No ravens observed					
3/10/2012			No ravens observed					
3/9/2012			No ravens observed					
3/8/2012	Plaster City Yard	3		2			1	no
3/8/2012	EP326	2		2				no
3/7/2012	Plaster City Yard	1			1			no
3/6/2012	EP350	1			1			no
3/5/2012			No ravens observed					
3/4/2012			No ravens observed					
3/3/2012			No ravens observed					
3/2/2012	EP352	2			2			no
3/2/2012	Plaster City Yard	1					1	no
3/2/2012	EP357	2		2				no
3/1/2012			No ravens observed					
2/29/2012	EP359-EP362	5		5				no
2/28/2012	EP357 and EP359	3			3			no
2/28/2012	EP349	2	2					no
2/27/2012			No ravens observed					
2/26/2012	EP351	1			1			no
2/25/2012			No ravens observed					
2/24/2012	EP355	3		3				no
2/23/2012	EP355	1		1				no
2/22/2012	EP347	2		2				no
2/22/2012	EP343/EP344 Pullsite	2					2	no
2/21/2012			No ravens observed					
2/20/2012	EP313-EP354	2		2				no
2/19/2012	EP360-EP362	2		2				no
2/18/2012			No ravens observed					
2/17/2012			No ravens observed					
2/16/2012	S2 Yard	3		3				no
2/15/2012	S2 Yard	5		5				no
2/14/2012	S2 Yard	2		2				no
2/13/2012			No ravens observed					
2/12/2012			No ravens observed					
2/11/2012			No ravens observed					
2/10/2012			No ravens observed					
2/9/2012	S2 Yard	2		2				no
2/8/2012	S2 Yard	3		2			1	no
2/7/2012	S2 Yard	3		2			1	no
2/6/2012	S2 Yard	3		2			1	no
2/5/2012			No ravens observed					
2/4/2012	S2 Yard	2			2			no
2/3/2012			No ravens observed					
2/2/2012	Pull site EP338/EP339	2			2			no
2/2/2012	S2 Yard	1		1				no
2/1/2012	Pull site EP338/EP339	3		3				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
1/31/2012	EP330	2		2				no
1/30/2012	No ravens observed							
1/29/2012	No ravens observed							
1/28/2012	No ravens observed							
1/27/2012	Plaster City Yard	2					2	no
1/26/2012	S2 Yard	2		2				no
1/26/2012	EP341	2			2			no
1/26/2012	EP316	2		2				no
1/25/2012	EP324	1		1				no
1/24/2012	No ravens observed							
1/23/2012	No ravens observed							
1/22/2012	No ravens observed							
1/21/2012	No ravens observed							
1/20/2012	No ravens observed							
1/19/2012	EP326-EP328	2		2				no
1/18/2012	EP334	1		1				no
1/17/2012	EP329-1	2			2			no
1/16/2012	No ravens observed							
1/15/2012	No ravens observed							
1/14/2012	No ravens observed							
1/13/2012	No ravens observed							
1/12/2012	No ravens observed							
1/11/2012	No ravens observed							
1/10/2012	No ravens observed							
1/9/2012	No ravens observed							
1/8/2012	No ravens observed							
1/7/2012	No ravens observed							
1/6/2012	No ravens observed							
1/5/2012	No ravens observed							
1/4/2012	No ravens observed							
1/3/2012	No ravens observed							
1/2/2012	No ravens observed							
1/1/2012	No ravens observed							
12/31/2011	No ravens observed							
12/30/2011	No ravens observed							
12/29/2011	EP313-EP304 & EP295-EP292	2			2			no
12/28/2011	EP294	20			20			no
12/27/2011	EP292	2			2			
12/26/2011	EP292	2					2	no
12/25/2011	No ravens observed							
12/24/2011	EP281, EP281GS & EP290	5		5				no
12/23/2011	No ravens observed							
12/22/2011	EP300-1, EP301 & EP304	3		3				no
12/21/2011	No ravens observed							
12/20/2011	EP290-EP291/EP292 Pullsite	2			2			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
12/19/2011	No ravens observed							
12/18/2011	No ravens observed							
12/17/2011	EP325	1		1				no
12/17/2011	S2 Yard	3					3	no
12/16/2011	No ravens observed							
12/15/2011	IV Substation	1			1			no
12/15/2011	EP293	2		2				no
12/15/2011	S2 Yard	3					3	no
12/14/2011	S2 Yard	3					3	no
12/13/2011	S2 Yard	2					2	no
12/12/2011	S2 Yard	2					2	no
12/11/2011	S2 Yard	2					2	no
12/10/2011	EP306 & EP306/EP307 Pullsite	3		3				no
12/9/2011	IV Substation	1		1				no
12/9/2011	EP308 & EP306/EP307 Pullsite	2		2				no
12/9/2011	EP291 & EP291/EP292 Pullsite	2		2				no
12/8/2011	S2 Yard	3					3	no
12/8/2011	IV Substation	1		1				no
12/8/2011	EP301	2		2				no
12/8/2011	EP300-EP309	2		2				no
12/8/2011	EP291/EP292 Pullsite	2	2					no
12/8/2011	EP281	2		2				no
12/7/2011	IV Substation	1		1				no
12/7/2011	EP301	1			1			no
12/7/2011	EP291/EP292 Pullsite	1			1			no
12/7/2011	EP281	7		4	2	1		no
12/7/2011	S2 Yard	2			2			no
12/6/2011	S2 Yard	3				3		no
12/6/2011	EP301	2			2			no
12/6/2011	EP281	5		4		1		no
12/5/2011	S2 Yard	2					2	no
12/5/2011	IV Substation	2		2				no
12/5/2011	EP363	2		2				no
12/5/2011	EP281	6		6				no
12/4/2011	S2 Yard	3				3		no
12/4/2011	IV Substation	2		2				no
12/4/2011	Fromm CY	2				1	1	no
12/4/2011	EP294	1		1				no
12/3/2011	EP281	1		1				no
12/2/2011	IV Substation	1		1				no
12/1/2011	S2 Yard	2					2	no
11/30/2011	S2 Yard	2			2			no
11/29/2011	S2 Yard	2			2			no
11/28/2011	S2 Yard	4			4			no
11/28/2011	EP290-EP301	5		2	3			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
11/27/2011	S2 Yard	1		1				no
11/26/2011	No ravens observed							
11/25/2011	NO WORK: DAY AFTER THANKSGIVING							
11/24/2011	NO WORK: THANKSGIVING							
11/23/2011	Plaster City Yard	3					3	no
11/22/2011	S2 Yard	4			4			no
11/22/2011	IV Substation	1			1			no
11/21/2011	S2 Yard	4					4	no
11/21/2011	IV Substation	1		1				no
11/21/2011	EP281	2			2			no
11/20/2011	EP360	2			2			no
11/20/2011	IV Substation	2		2				no
11/19/2011	No ravens observed							
11/18/2011	EP358 and IV Substation	2		2				no
11/17/2011	No ravens observed							
11/16/2011	S2 Yard	5			5			no
11/15/2011	EP330-1	2					2	no
11/15/2011	EP304; EP330	1			1			no
11/14/2011	S2 Yard	6			6			no
11/13/2011	No ravens observed							
11/12/2011	Dunaway CY	1			1			no
11/11/2011	Dunaway CY	4					4	no
11/11/2011	S2 Yard	5					5	no
11/10/2011	Fromm CY	2					2	no
11/10/2011	EP355	1		1				no
11/9/2011	Dunaway CY	1			1			no
11/8/2011	S2 Yard	5			5			no
11/8/2011	Dunaway CY	2			2			no
11/7/2011	S2 Yard	3					3	no
11/7/2011	EP308-EP310	1					1	no
11/7/2011	EP301 Pullsite	7		6	1			no
11/6/2011	No ravens observed							
11/5/2011	S2 Yard	7			7			no
11/5/2011	IV Substation	1			1			no
11/4/2011	S2 Yard	5			5			no
11/3/2011	S2 Yard	5			3		2	no
11/3/2011	IV Substation	1			1			no
11/3/2011	Fromm CY	1				1		no
11/3/2011	EP303 and EP302	2			2			no
11/3/2011	EP281	2			2			no
11/2/2011	S2 Yard	4			4			no
11/2/2011	IV Substation	1		1				no
11/2/2011	EP305, EP310, EP311	1		1				no
11/1/2011	S2 Yard	2			2			no
11/1/2011	IV Substation	1		1				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
11/1/2011	EP305 and EP312	1			1			no
10/31/2011	S2 Yard	5			5			no
10/31/2011	AER and Fromm CY	1				1		no
10/30/2011	No ravens observed							
10/29/2011	IV Substation	3		3				no
10/28/2011	IV Substation	1		1				no
10/28/2011	EP256, EP357 & EP358	5		5				no
10/27/2011	EP356, EP358 & EP362	2		2				no
10/27/2011	EP305, EP307, EP310-EP312	1		1				no
10/26/2011	EP306, EP307 & EP310	2		2				no
10/25/2011	IV Substation	1		1				no
10/25/2011	EP310	1		1				no
10/24/2011	S2 Yard	3					3	no
10/24/2011	EP305	1			1			no
10/23/2011	S2 Yard	3			3			no
10/22/2011	No ravens observed							
10/21/2011	Dunaway CY	1			1			no
10/20/2011	S2 Yard	2					2	no
10/20/2011	Dunaway CY	5					5	no
10/19/2011	EP314	1		1				no
10/19/2011	EP290	5		5				no
10/18/2011	No ravens observed							
10/17/2011	EP301	3		3				no
10/16/2011	No ravens observed							
10/15/2011	S2 Yard	2					2	no
10/15/2011	Dunaway CY	1				1		no
10/15/2011	EP315	2					2	no
10/15/2011	EP301	3			3			no
10/14/2011	Fromm CY	3				3		no
10/14/2011	EP305	2		2				no
10/14/2011	EP301	3			3			no
10/13/2011	S2 Yard	2					2	no
10/13/2011	Dunaway CY	5					5	no
10/13/2011	Fromm CY	1					1	no
10/13/2011	EP354-EP363	2			2			no
10/13/2011	EP301	4		4				no
10/12/2011	EP300-EP301	2		2				no
10/11/2011	Plaster City Yard	2			2			no
10/11/2011	IV Substation	2					2	no
10/10/2011	Fromm CY	2				2		no
10/10/2011	EP359-EP360	2		2				no
10/10/2011	EP355-EP363	2		2				no
10/10/2011	EP301	3		3				no
10/9/2011	S2 Yard	3					3	no
10/9/2011	EP300	6		6				no
10/8/2011	EP357	2			2			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed	
			Nesting	Flying	Perching	Roosting	Scavaging		
10/8/2011	EP306	3					3	no	
10/7/2011	Dunaway CY	1		1				no	
10/7/2011	EP291-EP301	3		3				no	
10/6/2011	Fromm CY	2					2	no	
10/5/2011	Dunaway CY	2		2				no	
10/5/2011	EP303-2	2		2				no	
10/4/2011	EP310 & EP311	2		2				no	
10/4/2011	EP301	3					3	no	
10/4/2011	EP293	2		2				no	
10/3/2011	S2 Yard	2					2	no	
10/3/2011	Dunaway CY	2			2			no	
10/2/2011	EP356-EP363	2		1	1			no	
10/1/2011	Plaster City Yard	2					2	no	
10/1/2011	EP360	2			2			no	
9/30/2011	S2 Yard	2					2	no	
9/30/2011	EP355	1		1				no	
9/30/2011	EP314	2		2				no	
9/30/2011	EP301	2		1	1			no	
9/29/2011	EP291/EP292 Pullsite	1			1			no	
9/28/2011	EP361	1			1			no	
9/27/2011	EP315	2		1	1			no	
9/27/2011	EP309	1		1				no	
9/27/2011	EP301 & EP304	4		3	1			no	
9/27/2011	EP290	1			1			no	
9/26/2011	EP362	2			2			no	
9/26/2011	Fromm CY	1				1		no	
9/25/2011	No ravens observed								
9/24/2011	Plaster City Yard	2					2	no	
9/24/2011	EP317	1		1				no	
9/24/2011	EP309	1		1				no	
9/23/2011	EP362	4			4			no	
9/23/2011	EP303	2		2				no	
9/22/2011	Fromm CY	1				1		no	
9/22/2011	EP303	2		2				no	
9/22/2011	EP301	2		2				no	
9/22/2011	EP295-EP322	3		3				no	
9/21/2011	S2 Yard	3			3			no	
9/21/2011	Fromm CY	1					1	no	
9/21/2011	EP303	1		1				no	
9/20/2011	S2 Yard	2			2			no	
9/20/2011	Fromm CY	1				1		no	
9/19/2011	S2 Yard	3			3			no	
9/19/2011	EP304, EP307, EP309	1		1				no	
9/18/2011	S2 Yard	3				3		no	
9/18/2011	EP281	1		1				no	

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed	
			Nesting	Flying	Perching	Roosting	Scavaging		
9/17/2011	S2 Yard	3					3	no	
9/17/2011	EP362	1			1			no	
9/17/2011	Fromm CY	3				3		no	
9/16/2011	EP363	2			2			no	
9/16/2011	Fromm CY	1					1	no	
9/16/2011	EP304	2		2				no	
9/16/2011	EP290	1		1				no	
9/15/2011	S2 Yard	4			4			no	
9/15/2011	Fromm CY	3					3	no	
9/15/2011	EP296	1		1				no	
9/15/2011	EP306	2					2	no	
9/15/2011	EP304	1		1				no	
9/15/2011	EP301	2		2				no	
9/14/2011	Plaster City Yard	1			1			no	
9/14/2011	EP361	2			2			no	
9/14/2011	Fromm CY	1				1		no	
9/14/2011	EP308	1					1	no	
9/14/2011	EP301	5		4	1			no	
9/14/2011	EP292	3		3				no	
9/13/2011	S2 Yard	10			10			no	
9/13/2011	EP348	3		3				no	
9/13/2011	EP345	2		2				no	
9/13/2011	EP326	1					1	no	
9/13/2011	EP325	2		2				no	
9/13/2011	EP326	1		1				no	
9/13/2011	EP304	7		7				no	
9/13/2011	EP291	7		7				no	
9/12/2011	S2 Yard	3			3			no	
9/12/2011	EP350	1		1				no	
9/12/2011	EP304	1		1				no	
9/12/2011	EP301	1		1				no	
9/11/2011	S2 Yard	2				2		no	
9/10/2011	S2 Yard	2					2	no	
9/9/2011	EP304	1			1			no	
9/8/2011	S2 Yard	3					3	no	
9/7/2011	S2 Yard	3					3	no	
9/6/2011	No ravens observed								
9/5/2011	No ravens observed								
9/4/2011	No ravens observed								
9/3/2011	No ravens observed								
9/2/2011	EP348	1		1				no	
9/2/2011	S2 Yard	1		1				no	
9/2/2011	EP303	1		1				no	
9/2/2011	EP363	2		2				1 at IV Sub	
9/1/2011	EP303	2					2	no	
9/1/2011	EP293	1					1	no	

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
9/1/2011	EP304	2					2	no
8/31/2011	S2 Yard	1		1				no
8/31/2011	EP308	1		1				no
8/31/2011	EP305-3	2					2	no
8/31/2011	EP303	2		2				no
8/30/2011	EP303	1		1				no
8/29/2011	S2 Yard	1		1				no
8/29/2011	EP303	1		1				no
8/28/2011	No ravens observed							
8/27/2011	EP305	3			3			no
8/26/2011	EP301	2		2				no
8/25/2011	S2 Yard	2					2	no
8/25/2011	EP301	2		2				no
8/24/2011	S2 Yard	3				3		no
8/23/2011	EP292-1	3		3				no
8/22/2011	No ravens observed							
8/21/2011	No ravens observed							
8/20/2011	S2 Yard	2				2		no
8/20/2011	EP312	2		2				no
8/20/2011	S2 Yard	2					2	no
8/20/2011	EP312	2		2				no
8/19/2011	EP307	2			2			no
8/19/2011	EP296	1		1				no
8/18/2011	S2 Yard	2				1	1	no
8/18/2011	EP301	Flock		x				no
8/17/2011	S2 Yard	2				1	1	no
8/17/2011	EP301	3			3			no
8/16/2011	S2 Yard	1					1	no
8/16/2011	EP301	1		1				no
8/15/2011	No ravens observed							
8/14/2011	No ravens observed							
8/13/2011	S2 Yard	2					2	no
8/12/2011	IV Substation	2				2		no
8/12/2011	S2 Yard	3				3	3	no
8/11/2011	EP294	4			4			no
8/11/2011	S2 Yard	3				3	3	no
8/10/2011	S2 Yard	3				2	1	no
8/9/2011	S2 Yard	not specified						no
8/8/2011	EP294	2			2			no
8/8/2011	S2 Yard	1						no
8/7/2011	No ravens observed							
8/6/2011	S2 Yard	1						no
8/5/2011	EP301	3		3				no
8/4/2011	S2 Yard	not specified						no
8/3/2011	S2 Yard	2		2				no
8/3/2011	S2 Yard	1						no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
8/2/2011	S2 Yard	3					3	no
8/1/2011	EP314	not specified		x				no
7/31/2011	No ravens observed							
7/30/2011	EP314	3		2			1	no
7/30/2011	S2 Yard	1					1	no
7/29/2011	S2 Yard	1						no
7/28/2011	EP319	4	1	2	1			no
7/28/2011	S2 Yard	not specified						no
7/27/2011	S2 Yard	not specified						no
7/26/2011	No ravens observed							
7/25/2011	EP290	1			1			no
7/24/2011	No ravens observed							
7/23/2011	No ravens observed							
7/22/2011	EP290	2		1	1			no
7/21/2011	S2 Yard	1		1				no
7/20/2011	Ocotillo, CA	5						no
7/19/2011	Ocotillo, CA	1						no
7/17/2011	No ravens observed							
7/15/2011	No ravens observed							
7/14/2011	EP357	not specified						no
7/14/2011	EP358	not specified						no
7/14/2011	EP359	not specified						no
7/14/2011	Plaster City Yard	2		2				no
7/13/2011	EP313-EP314 PS	not specified						no
7/13/2011	S2 Yard	3					3	no
7/11/2011	EP304-EP314	not specified						no
7/10/2011	No ravens observed							
7/9/2011	EP351	not specified						no
7/9/2011	EP353	not specified						no
7/9/2011	EP354	not specified						no
7/9/2011	EP355	not specified						no
7/9/2011	not specified	not specified						no
7/9/2011	S2 Yard	3					3	no
7/8/2011	EP303	2			1		1	no
7/8/2011	EP303	1		1				no
7/8/2011	S2 Yard	3					3	no
7/1/11-7/7/11	No ravens observed							
6/30/2011	EP300	3		3				no
6/21/11-6/29/11	No ravens observed							
6/20/2011	S2 Yard	2					2	no
6/1/11-6/19/11	No ravens observed							
5/1/11-5/31/11	No ravens observed							
4/22/11-4/30/11	No ravens observed							
4/21/2011	EP341	1	1					no
4/1/11-4/20/11	No ravens observed							

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
3/1/11-3/31/11	No ravens observed							
2/1/11-2/28/11	No ravens observed							
1/21/11-1/31/11	No ravens observed							
1/21/2011	Rough Acres Yard	not specified					no	