

This report provides a summary of environmental monitoring and compliance activities conducted by Burns and McDonnell (BMcD) staff and BMcD subconsultants for the San Diego Gas & Electric (SDG&E) Sunrise Powerlink Project during the above weekly time period.

Training

- SWEAP and PBS training continued for new Project personnel every Tuesday and Thursday. Additional trainings were provided as requested.
- Flat-tailed horned lizard (FTHL) trainings were provided to any new crew members or monitors prior to construction per mitigation measure B-7b and in accordance with the FTHL Rangewide Management Strategy. During morning tailboard meetings, guidelines were provided about recognizing, protecting, and notification requirements for FTHL. FTHL information cards were made available to any crew members or monitors as needed.
- Barefoot banded gecko (BBG) trainings were provided to crews prior to pre-construction activities pursuant to the California Department of Fish and Game (CDFG) 2081 Incidental Take Permit requirements.

Pre/Post Construction

- Staked, flagged, and refreshed work areas near SPL-69-9, SPL-69-10, CP13-2, CP14, EP16-1, EP290, EP291-1, EP292-1, EP293, EP294, EP295, EP296, EP297, EP298, EP299, EP300-1, EP301, EP302-1, EP303-2, EP304-2, EP305-3, EP306-1, EP307-1, EP308, EP309, EP310, EP311-1, and EP312.
- The ESA Team conducted the following activities during this reporting period:
 - Repaired, refreshed, and maintained the previously installed project signs and ESAs at Shell Canyon Road, EP67 pull site, access road from Dunaway Yard to EP348-E-A, EP349, EP349-E, EP349-N to EP350-N, EP350, between EP350-N and EP351-N, and EP351.

Construction

- Monitors were present during construction activities to ensure compliance with mitigation measures as identified in the Final EIR/EIS Mitigation Monitoring, Compliance, and Reporting Program. Archaeologists, Paleontologists, and Native American Monitors were present at sites where required as identified prior to construction activity and as approved in the NTPs. On average, the following number of monitors were on the Project throughout the week:
 - 8 Archaeological Monitors.
 - 130 Biological Monitors.
 - 8 Native American Monitors.
 - 1 Paleontological Monitor.
 - 8 SWPPP Monitors.
- Project staff carpooled to site reviews, kick-off tailgates, and off-site meetings. Construction and traffic control crews were observed carpooling from yards to work areas.
- Deterrents were utilized to discourage bird nest building activities throughout the Project. Deterrents are determined depending upon the location and type of possible nesting areas and may include metallic flagging, compact discs, plastic owls, and the presence of biological monitors.

The table below demonstrates the construction progress to date:

OVERHEAD			
Agency	Foundations Completed	Towers Erected	Wire Installed
Non-Federal	93 of 169	53 of 169	23 of 169 CP 70-3 to CP 72-2 CP74-2, CP75 CP106-1 to CP 109
Bureau of Land Management	127 of 179	93 of 179	67 of 179 CP 65-1 to CP 68-1 EP 42 to EP 47-2
Miramar	4 of 14	3 of 14	0 of 14
US Forest Service	20 of 76	16 of 76	17 of 76 CP 69-2,CP73-2 CP 100-1 to CP 105-1 EP 131 to EP 141
UNDERGROUND			
Agency	Vaults Installed	Trenches Excavated & Backfilled	
Non-Federal	40 of 40	40 of 42	
SUBSTATION UPGRADES			
2 of 7 Completed			
SUNCREST SUBSTATION			
76 Percent Complete			

Overhead Construction

- Link 1
 - Boulder removal at EP194-3, EP195-2, EP196-2, and EP254-3.
 - Gate installation at EP172, EP191-2, EP192-2, EP206-1, EP207, and EP208.
 - Fencing installed at EP172 and EP178.
 - Grading at EP185-1.
 - Site prep for micropile drilling at EP144, EP145, EP150, EP151, EP152-2, EP189-3, EP194-3, EP195-2, EP228, EP233-1, EP236-1, and EP254-3.
 - Micropile drilling at EP228, EP234-1, EP236-1, EP237-1, EP249-1, and EP254-3.

- Micropile cap work at EP221-2, EP221A, EP223-1, EP224-1, EP225-1, EP226-1, EP227, EP229-1, EP230-1, EP231-1, EP231A, EP232-1, EP233-1, EP235-1, EP238-1, EP253-2, EP254-3, EP272-3, EP273-1, EP274-1, EP275-1, EP278-1, and EP279-1.
 - Air track drilling at EP177, EP184-1, and EP185-1.
 - Conventional drilling at EP170, EP184-1, EP185-1, EP191-2, EP192-2, and EP193-2.
 - Rebar installation at EP191-2.
 - Concrete pouring at EP184-1, EP191-2, and EP192-2.
 - Form removal and cleanup at EP191-2 and EP192-2.
 - Tower assembly at EP190-2, EP198-3, EP199-3, EP200-3, EP201-3, EP202-3, EP204-3, EP205-2, EP206-1, EP207, EP266-2, EP271-2, EP272-3, EP273-1, EP275-1, EP276-1, EP278-1, EP279-1, EP280-2, and EP281.
 - QA/QC at EP207, EP247, EP250, EP251, EP270-2, EP271-2, EP272-3, EP273-1, EP276-1, and EP277-1.
 - Concrete anchors installed at EP265-2, EP266-2, EP269-1, EP271-2, EP272-3, EP273-1, and EP281.
 - Concrete anchors cut at EP259-3, EP259B, EP261-2, EP264-4, EP265-2, EP266-2, EP267-2, EP269-1, and EP270-2.
 - Ground resistance testing at EP255-2, EP274-1, EP275-1, EP276-1, EP277-1, EP278-1, EP279-1, EP280-2, and EP281.
 - Ground rod installation at EP175, EP176, EP178, EP179, EP180, EP181, EP182, EP186-1, EP190-2, EP202-3, EP248-1, EP250, EP270-2, EP274-1, EP276-1, and EP277-1.
 - BMPs installed at/from:
 - EP177-N to EP187-2-N, EP183, and EP267-NF-38 guard structure.
 - BMPs maintained from:
 - EP170-N to McCain Valley Yard, EP170 to EP185-1, EP225/EP226 pull site, EP244, EP248-1, EP280-2, and EP281.
 - Trained FTHL monitors, BBG monitors, BHS monitors, and Visible Emission Evaluators (VEEs) were onsite as required.
- Link 2
 - During this reporting period, the PAL Levels were as follows: Monday-D, Tuesday-Ev, Wednesday-D, Thursday-D (no work on USFS due to letter from the USFS requiring shut down for potential high winds), Friday-E, and Saturday-C. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

- Access road construction at:
 - EP11-3-N, EP78-E to CY-Bartlett-E (excluding ARTO sections), and EP125-E-A to EP141-N.
- Vegetation clearing at EP14-1 TSAP, EP17 TSAP, EP21-1 TSAP, EP23-2 TSAP, and EP28-3 TSAP.
- Grading at EP9-1.
- Topsoil salvage at EP9-1.
- Micropile drilling at EP3-3, EP5-2, and EP7-1.
- Micropile demobilization from EP6-1.
- All conductor and OPGW installed from EP130 to EP141.
- Hardline haulback, insulator work, traveler work, and sock line installation from EP130 to EP141.
- Tower assembly at EP139-1, EP140, and EP141.
- Hydromulching from EP131 to EP141.
- BMP installation at:
 - EP9-1, EP9-1-N, EP9-1-PS-N, and EP11-3-N.

BLM Land

- Vegetation clearing at EP103-2 pull site.
- Access road construction at:
 - EP47-2-PS-N and EP94-N to EP99-2-N-B.
- Fence and gate repairs along EP103-2-N.
- Micropile site preparation at EP56-4.
- Soil boring at EP99-2 and EP104-2.
- Conventional drilling at EP39-1, EP94, and EP95.
- QA/QC at EP47-2.
- All conductor and OPGW installed from EP42 to EP47-2.
- Insulator installation, traveler work, dead end work, marker ball installation, and sagging from EP42 to EP47-2.
- Spacing from EP42 to EP45.
- BMP installation at:
 - EP42-N and EP94-N to EP99-2-N-B.

Non-Federal Land

- Vegetation clearing at EP26-1, EP27-1, EP30-2, and EP30-2 pull site.
- Access road construction at:
 - EP78-E to CY-Bartlett-E (excluding ARTO sections), and EP94-N to EP99-2-N-B.
- Tree trimming occurred near EP77-1 and EP78-1.
- Driveway construction at EP90-1-N.
- Micropile cap work at EP84.
- Soil boring at EP105-2.
- Conventional drilling at EP26-1.
- Arroyo toad fencing was installed at the EP67 pull sites and EP79-E-C.
- BMP installation at:
 - EP65-1, EP66-E, and EP94-N to EP99-2-N-B.

- Link 5

- During this reporting period, the PAL Levels were as follows: Monday-D, Tuesday-Ev, Wednesday-D, Thursday-D (no work on USFS due to letter from the USFS requiring shut down for potential high winds), Friday-E, and Saturday-C. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

- Dexpan boulder breaking at CP99-2.
- Conventional drilling at CP99-2.
- All conductor and OPGW installed from CP65-1 to CP75-1.
- Hardline haulback, dead-end work, and sagging from CP65-1 to CP75-1.
- Conductor, sock line, and OPGW installation and hardline haulback from CP100-1 to CP109-1.
- Deadend work, insulator installation, and traveler work from CP100-1 to CP109-1.
- Hydromulching at CP101-1 TSAP, CP103-3 TSAP, CP104-1 TSAP, and CP105-1 TSAP.

BLM Land

- Micropile drilling at CP59 and CP61-1.
- Micropile grouting at CP58-1 and CP61-1
- Tower assembly at CP66-2, CP67-3, and CP68-1.
- All conductor and OPGW installed from CP65-1 to CP75-1.
- Hardline haulback, dead-end work, and sagging from CP65-1 to CP75-1.

Non-Federal Land

- Access road construction at:
 - CP29-1-E-B, CP31-2-E, CP31-2-N, CP49-1-PS-N, and CP56-1-PS-E-B.
- Dexpan boulder breaking at CP47-2, CP50-1, CP51-1, CP53-1, and CP55.
- Micropile site preparation at CP53-1, CP76-1, CP77, and CP83.
- Micropile drilling at CP53-1, CP55, CP57, and CP81-1.
- Grouting at CP56-1, CP57, CP78-2, CP79-1, and CP80-2.
- Conventional drilling at CP98-1.
- Various foundation work (cage installation, grounding, etc.) at CP98-1.
- Concrete pouring at CP16-1.
- Form removal and cleanup at CP16-1 and CP98-1.
- Rebar work at CP16-1.
- All conductor and OPGW installed from CP65-1 to CP75-1.
- Hardline haulback, dead-end work, and sagging from CP65-1 to CP75-1.
- Deadend work, insulator installation, and traveler work from CP100-1 to CP109-1.
- BMP installation at:
 - CP16-1, CP31-2-E, CP48-2, CP49-1, CP56-1-PS-E-B, CP70-3, CP76-1, CP78-2, CP81-1, and CP85-1.
- Hydromulching around and disassembling of the radio tower site near CP108.

Miramar

- Access road construction at:
 - CP10, CP11-1, and CP15-1-PS-E
 - Concrete pouring at CP15-1.
 - Form removal and cleanup at CP15-1.
 - BMP installation at CP10, CP11-1, and CP15-1.
- 69kV
 - No work occurred during this reporting period.

Underground Construction (Link 4)

- Revitalization near Bay Meadows and Louise Drive.
- Pre-racking/Racking and cleaning manholes for ABB (and jointing/splicing) at V5L, V19L, V20L, V8R, and V9R.
- Fiber pulling from V12R to V17R and V13L to V17L
- Paving (including paving prep) near V5R to V6R.
- Proofing from V18R to V19R.
- Cable pulling from V1R to Riser and V1R to V2R.
- Erecting scaffolding at EP95 and Loritz Property and Slay riser poles.
- Terminating at Loritz riser pole.
- Grading at Bauer/Slay property and CalTrans bore location.
- Raise manhole necking to grade (also adjusting necking at V12R, V12L and V19R.
- Alpine Creek bore – Finish jack and bore of Alpine Creek.

- Bauer Bridge – Bridge removal preparation.

Suncrest Substation Construction (Link 3)

- Steel erection in the southwest quadrant of the pad.
- Removing forms and scaffolding from the water tank and pouring second layer of shotcrete.
- PAR wire pulling activities continued in the northwest quadrant of the pad.
- Class 2 base placement along Bell Bluff Truck Trail east of the guard shack.
- Soil removal and re-compaction as well as class 2 base placement along Bell Bluff Truck Trail east of the guard shack.
- Wrapping tension band around the water tank.
- Finish grading and class 2 base placement in the 230kV yard.
- Finish grading and class 2 base placement in the northwest quadrant of the pad.
- Crushing class 2 base and select fill material.
- Forming pads for foundations and pouring concrete.
- Trenching for conduit and ground grid in the southwest quadrant.
- BMP maintenance and installation along Bell Bluff Truck Trail and on the substation pad by both detention basins.

Substation Upgrades

- Encina Switchyard
 - Roel worked on forming and backfilling around the newly poured containment pit for the new 230kV transformer.
 - Roel worked on forming and installing rebar to pour additional concrete for containment pit at the new 230kV transformer pad.
 - Roel poured additional concrete for containment pit at the new 230kV transformer pad.
 - Roel formed concrete for containment pit for the transformer pad and worked on backfilling open trenches.
- Imperial Valley (IV)
 - SDG&E ETRAM crew staged equipment in the northwest corner of the substation.
 - SDG&E worked in Bay 4 and erected steel frames and bus supports.
 - The current outage is in effect for the rest of the week to complete the final work.
 - PRAVA worked inside new storage warehouse and electricians worked on wiring.
- San Luis Rey
 - No Sunrise-related work.
- Sycamore Canyon
 - SDG&E Kearny Mesa Construction crews worked on building disconnects for 230kV upgrades.
- Scripps
 - No Sunrise-related work.

Construction Yards

- AER Yard – Helicopter operations, tower assembly, staging for wire stringing materials and crews, dust control, and BMP maintenance.
- Alpine Yard – Materials staging and weed wash station.
- Bartlett-Hauser Yard – Water staging, equipment staging, weed maintenance, dust suppression, staging for road and BMP crews, and weed wash station.
- Barrett Canyon Yard – Helicopter operations, dust suppression, staging for road, BMP, tree trimming, and wire crews.
- Dunaway Yard – No activity.

- El Monte Yard – Crew, equipment, and materials staging, helicopter operations, water staging, and dust suppression.
- Fromm Yard – Tower assembly, helicopter activity, staging for tower erection and wire stringing crews, water staging, and dust suppression.
- Helix Yard – Helicopter operations, grouting operations, equipment and materials staging, crew staging, weed wash station, dust suppression, staging for micropile and wire crews, water staging, and weed maintenance.
- Imperial Valley Yard – No activity.
- Jacumba Valley Ranch (JVR) Yard – Helicopter operations, weed wash station, water and equipment staging, materials staging, staging for micropile, erection and wire stringing crews, crew staging, dust suppression, and hub for coordination of activities within PBHS areas.
- Kreutzkamp Yard – Tower assembly, helicopter operations, staging for road, pilecap and BMP crews, weed wash station, water staging, and dust suppression.
- McCain Valley Yard – Tower assembly, helicopter operations, staging for micropile crews, concrete operations, water staging, and dust suppression.
- Plaster City Yard – Demobilizing office trailers.
- Rough Acres Yard – Helicopter operations, staging for foundation and BMP crews, materials staging, water staging, dust suppression, and weed wash station.
- S2 Yard – Water staging, helicopter activity, tower assembly, staging for erection and wire stringing crews, and dust suppression.
- SWAT Yard – Concrete staging, water staging, helicopter operations, staging for road, conventional foundation, TSAP and wire crews, dust suppression, and weed wash station.
- Sycamore Yard – Weed wash station, dust suppression, water staging, tower assembly, and staging for BMP, road, and conventional foundation crews.
- Thing Valley Yard – Helicopter operations, rock delivery and loading, water staging, and dust suppression.
- Wilson Yard – Staging materials for Suncrest Substation, helicopter operations, staging for micropile and wire crews, dust suppression, water staging, and tower assembly.

Wildlife Reporting

- Peninsular bighorn sheep (PBS) were reported in Mountain Springs Grade on November 27 and December 3, 2011.

The following listed or Species of Special Concern were found dead in Project construction limits during this reporting period:

- Coast Horned Lizard (*Phrynosoma blainvillii*) – One (1) coast horned lizard was found dead at pull site EP200-3.
- Silvery Legless Lizard (*Anniella pulchra pulchra*) – Two (2) silvery legless lizards were found dead; one (1) at EP99 and one (1) at Thing Valley Yard.
- Coast Patch-nosed Snake (*Salvadora hexalepis virgultea*) – One (1) coast patch-nosed snake was found dead on the access road to the SWAT Yard.

The following listed or Species of Special Concern were relocated during construction activities this reporting period:

- Silvery Legless Lizard (*Anniella pulchra pulchra*) – Two (2) silvery legless lizards were relocated from EP99.
- Red Diamond Rattlesnake (*Crotalus ruber*) – Two (2) red diamond rattlesnakes were relocated;

- one (1) from the access road to EP51 and one (1) from CP49 pull site.
- Northwestern San Diego Pocket Mouse (*Chaetodipus fallax fallax*) – One (1) northwestern San Diego pocket mouse was relocated from CP49 pull site.
- Coast Horned Lizard (*Phrynosoma blainvillii*) – One (1) coast horned lizard was relocated from the entrance road to Suncrest Substation.

Spills/Hazardous Waste

- No reportable spills occurred outside of the USFS during this reporting period.
- Minor leaks, drips, and releases on USFS lands were submitted to the USFS in a weekly HazMat log.

Customer Complaints

- No customer complaints were received during this reporting period.

Non-Compliances

- USFS Non-Compliance #3 was received on December 2, 2011, due to issues with the Scenery Conservation Plan.

Variances and TEWS

- Variance #34 for work in golden eagle buffer areas was approved on December 2, 2011.

Weather

- Rain events occurred on December 2, 2011 and December 3, 2011.
 - Post-storm totals for December 2, 2011
 - Suncrest and Wilson Yard – 0.50 inches
 - Helix Yard – 0.50 inches
 - Hartung Yard – 0.40 inches
 - CP29 to CP31 – 0.05 inches
 - Post-storm totals for December 3, 2011:
 - EP43 to EP72 – 0.60 inches
 - EP124 to EP141, La Posta Road, and Thing Valley Yard – 0.40 inches
 - Kreutzkamp Yard – 0.60 inches
- BMPs were installed or maintained as needed throughout Project areas. In accordance with the Construction General Permit (CGP), daily site BMP inspections, photos, and appropriate BMPs for stormwater and non-stormwater were implemented. In accordance with the CGP, a post-storm inspection was performed as a result of the qualifying rain events. Failures and shortcomings that were identified in the post-storm inspection have been assessed and repairs/design changes to the BMPs will begin within 72 hours of identification.



Suncrest Substation. *Photo courtesy of Linda Collins.*



Helicopter activity at JVR Yard. *Photo courtesy of Linda Collins.*



Conductor wire at Suncrest. *Photo courtesy of Andrew Borchert.*

Appendices

Peninsular Big Horn Sheep Monitoring Report

Flat-Tailed Horned Lizard Monitoring Report

Raven Control Monitoring Report

Sunrise Powerlink Transmission Project

B-7c Big Horn Sheep

From 11/27/2011 Through 12/03/2011

ENVIRONMENTAL COMPLIANCE

Date	Monitor	Comments
11/27/2011		
STRUCTURE: EP 279 - EP 294		
	DBS Charles E German	Survey EP 279 thru EP 294.No PBHS were observed in flight corridor or flight buffer during surveys. No PBHS were observed to be harassed or harmed. All flights observed appeared to be in compliance
STRUCTURE: EP256-EP263A-2, AER yard		
	DBS Karen Carter	Remarks: No sheep were disturbed during the day's activities.
STRUCTURE: EP263B- EP269		
	DBS Evy Rimbenieks	Activity included a survey of right of way between EP 263B - EP 269. Monitored the ROW throughout the day due to low elevation flights and ground crews being present. No PBHS were observed.
STRUCTURE: EP269- EP281		
	DBS Julia Addison	Activity included a survey of the Westbound lanes. Monitored the ROW throughout the day due to low-elevation flights and ground crews being present. No PBHS were observed during surveys.
STRUCTURE: EP269-EP270		
	DBS Tim Searl	Activity included a survey of the interior roads section west of EP269-EP270 and the access road for EP269. Remarks: No PBHS observed during survey.
STRUCTURE: EP269-EP274		
	DBS Mike R. Rathburn	Remarks: Activity included a survey and monitoring of proposed tower locations EP269-EP274. PBHS were detected near EP271 which resulted in flight restrictions from EP270-EP272. Flight restrictions were lifted at 2:15 pm when the PBHS moved out of flight corridor. Work crew located at EP269 with low elevation helicopter flights. No mitigation measures appeared to be violated.
STRUCTURE: EP269-EP281		
	DBS Angelica Mendoza	Activity included a survey of the right-of-way for proposed tower locations EP269-EP281 by surveying eastbound lane of Highway 8. Monitored the ROW throughout the day due to low-elevation flights and ground crews being present. No PBHS were observed during surveys.
	DBS Mikaila Rimbenieks	Activity included a survey of the westbound flank located between proposed tower locations EP269 - EP281. No PBHS were observed. Monitored the ROW throughout the day due to low elevation flights and ground crews working in the area.
STRUCTURE: EP274 through EP278		
	DBS Gregg M Lukasell	Conducted biological surveys for big horn sheep in EP256 through EP263A. No PBHS were observed. All ground and flight crews were in compliance with mitigation measures/protocol. No PBHS were observed
STRUCTURE: EP300- EP312		
	DBS Julia Addison	Activity included a survey of the Westbound lanes. Monitored the ROW throughout the day due to low-elevation flights and ground crews being present. No PBHS were observed during surveys.

Sunrise Powerlink Transmission Project

B-7c Big Horn Sheep

From 11/27/2011 Through 12/03/2011

ENVIRONMENTAL COMPLIANCE

Date	Monitor	Comments
------	---------	----------

11/28/2011

STRUCTURE: EP 279 - EP 294

DBS Charles E German	Survey EP 279 thru EP 294.No PBHS were observed in flight corridor or flight buffer during surveys. No PBHS were observed to be harassed or harmed. All flights observed appeared to be in compliance
-------------------------	---

STRUCTURE: EP256-EP263A-2, AER yard

DBS Karen Carter	Remarks: No sheep were disturbed during the day's activities.
---------------------	---

STRUCTURE: EP263B-EP267

DBS Angelica Mendoza	Activity included a survey of the right-of-way for proposed tower locations EP263B-EP267. Monitored the ROW throughout the day due to low-elevation flights and ground crews being present. No PBHS were observed during surveys.
-------------------------	---

STRUCTURE: EP269- EP281

DBS Julia Addison	Activity included a survey of the Westbound lanes. Monitored the ROW throughout the day due to low-elevation flights and ground crews being present. No PBHS were observed during surveys.
----------------------	--

STRUCTURE: EP269-EP270

DBS Tim Searl	Activity included a survey of the interior roads section west of EP269-EP270 and the access road for EP269. Remarks: No PBHS observed during survey.
------------------	--

STRUCTURE: EP269-EP273

DBS Mike R. Rathburn	Remarks: Activity included a survey and monitoring of proposed tower locations EP269-EP274. No PBHS were detected on ROW so no restrictions of flight corridor was necessary. Work crews located at EP269,271,272,and 273 plus low elevation helicopter flights. No mitigation measures appeared to be violated.
-------------------------	--

STRUCTURE: EP269-EP281

DBS Mikaila Rimbenieks	Activity included a survey of the westbound flank located between proposed tower locations EP269 - EP281. No PBHS were observed. Monitored the ROW throughout the day due to low elevation flights and ground crews working in the area.
---------------------------	--

STRUCTURE: EP274 through EP278

DBS Gregg M Lukasell	Conducted biological surveys for big horn sheep in EP274 through EP278. No PBHS were observed. All ground and flight crews were in compliance with mitigation measures/protocol.
-------------------------	--

STRUCTURE: EP300- EP312

DBS Julia Addison	Activity included a survey of the Westbound lanes. Monitored the ROW throughout the day due to low-elevation flights and ground crews being present. No PBHS were observed during surveys.
----------------------	--

11/29/2011

STRUCTURE: EP 279 - EP 294

DBS Charles E German	Survey EP 279 thru EP 294.No PBHS were observed in flight corridor or flight buffer during surveys. No PBHS were observed to be harassed or harmed. All flights observed appeared to be in compliance
-------------------------	---

Sunrise Powerlink Transmission Project

B-7c Big Horn Sheep

From 11/27/2011 Through 12/03/2011

ENVIRONMENTAL COMPLIANCE

Date	Monitor	Comments
------	---------	----------

11/29/2011

STRUCTURE: EP256-EP263A-2, AER yard

DBS	Remarks: No sheep were disturbed during the day's activities.
Karen Carter	

STRUCTURE: EP269- EP281

DBS	Activity included a survey of the Westbound lanes. Monitored the ROW throughout the day due to low-elevation flights and ground crews being present. No PBHS were observed during surveys.
Julia Addison	

STRUCTURE: EP269-EP273

DBS	Activity included a survey of EP269-EP273.
Tim Searl	Remarks: No PBHS observed during survey.

STRUCTURE: EP269-EP281

DBS	Activity included a survey of the right-of-way for proposed tower locations EP269-EP281 by surveying eastbound lane of Highway 8. Monitored the ROW throughout the day due to low-elevation flights and ground crews being present. No PBHS were observed during surveys.
Angelica Mendoza	
DBS	Activity included a survey of the westbound flank located between proposed tower locations EP269 - EP281. No PBHS were observed. Monitored the ROW throughout the day due to low elevation flights and ground crews working in the area.
Mikaila Rimbenieks	

STRUCTURE: EP274 through EP278

DBS	Conducted biological surveys for big horn sheep in EP274 through EP278. No PBHS were observed. All ground and flight crews were in compliance with mitigation measures/protocol.
Gregg M Lukasell	

STRUCTURE: EP300- EP312

DBS	Activity included a survey of the Westbound lanes. Monitored the ROW throughout the day due to low-elevation flights and ground crews being present. No PBHS were observed during surveys.
Julia Addison	

STRUCTURE: EP300-EP312

DBS	Remarks: Activity included a survey of Suckle Property and monitoring towers EP300-EP312. No PBHS were detected on ROW, so no restrictions of flight corridor was necessary. Work crew located at EP304,305, and 309. No mitigation measures appeared to be violated.
Mike R. Rathburn	

11/30/2011

STRUCTURE: EP 279 - EP 294

DBS	Survey EP 279 thru EP 294.No PBHS were observed in flight corridor or flight buffer during surveys. No PBHS were observed to be harassed or harmed. All flights observed appeared to be in compliance
Charles E German	

STRUCTURE: EP256-EP263A-2, AER yard

DBS	Remarks: No sheep were disturbed during the day's activities.
Karen Carter	

Sunrise Powerlink Transmission Project

B-7c Big Horn Sheep

From 11/27/2011 Through 12/03/2011

ENVIRONMENTAL COMPLIANCE

Date	Monitor	Comments
11/30/2011		
STRUCTURE: EP269-EP273		
DBS Tim Searl		Activity included a survey of EP269-EP273. Remarks: No PBHS observed during survey.
STRUCTURE: EP269-EP281		
DBS Angelica Mendoza		Activity included a survey of the right-of-way for proposed tower locations EP269-EP281 by surveying eastbound lane of Highway 8. Monitored the ROW throughout the day due to low-elevation flights and ground crews being present. No PBHS were observed during surveys.
DBS Mikaila Rimbenieks		Activity included a survey of the westbound flank located between proposed tower locations EP269 - EP281. No PBHS were observed. Monitored the ROW throughout the day due to low elevation flights and ground crews working in the area.
STRUCTURE: EP274 through EP278		
DBS Gregg M Lukasell		Conducted biological surveys for big horn sheep in EP274 through EP278. No PBHS were observed. All ground and flight crews were in compliance with mitigation measures/protocol.
STRUCTURE: EP300 through EP312		
DBS Arthur Davenport		Peninsular bighorn sheep (PBHS) monitoring. Monitor locations of PBHS in relation to project activities so that harm or harassment of PBHS does not occur. Surveyed EP300 through EP312 and eastern flank of I-8 Island. Provide guidance to other bighorn sheep monitors and coordinate with SDG&E.
STRUCTURE: EP300-EP312		
DBS Mike R. Rathburn		Remarks: Activity included a survey of Suckle Property and monitoring towers EP300-EP312. No PBHS were detected on ROW, so no restrictions of flight corridor was necessary. Work crew located at EP304, 305, and 309. No mitigation measures appeared to be violated.
12/01/2011		
STRUCTURE: EP256-EP263A-2, AER yard		
DBS Karen Carter		Remarks: No sheep were disturbed during the day's activities.
STRUCTURE: EP269-EP273		
DBS Tim Searl		Activity included a survey of EP269-EP273. Remarks: No PBHS observed during survey.
STRUCTURE: EP274 through EP278		
DBS Gregg M Lukasell		Conducted biological surveys for big horn sheep in EP274 through EP278. No PBHS were observed. All ground and flight crews were in compliance with mitigation measures/protocol.
STRUCTURE: EP279 - EP294; EP273 - EP276		
DBS Charles E German		Survey EP 279 thru EP 294.No PBHS were observed in flight corridor or flight buffer during surveys. No PBHS were observed to be harassed or harmed. All flights observed appeared to be in compliance. Survey between EP273 and EP276. No PBHS were observed in flight corridor or flight buffer during surveys.

Sunrise Powerlink Transmission Project

B-7c Big Horn Sheep

From 11/27/2011 Through 12/03/2011

ENVIRONMENTAL COMPLIANCE

Date	Monitor	Comments
------	---------	----------

12/01/2011

STRUCTURE: EP300 through EP312

DBS Arthur Davenport	Peninsular bighorn sheep (PBHS) monitoring. Monitor locations of PBHS in relation to project activities so that harm or harassment of PBHS does not occur. Surveyed EP300 through EP312 and eastern flank of I-8 Island. Provide guidance to other bighorn sheep monitors and coordinate with SDG&E.
-------------------------	--

12/02/2011

STRUCTURE: EP 279 - EP 294

DBS Charles E German	Survey EP 279 thru EP 294. No PBHS were observed in flight corridor or flight buffer during surveys. Monitor Helicopter flights between EP 279 - 294. All flights observed appeared to be in compliance. No PBHS were observed to be harassed or harmed.
-------------------------	--

STRUCTURE: EP256-EP263A-2, AER yard

DBS Karen Carter	Remarks: No sheep were disturbed during the day's activities.
---------------------	---

STRUCTURE: EP263B- EP269

DBS Evy Rimbenieks	Activity included a survey of right of way between EP 263B - EP 269. Monitored the ROW throughout the day due to low elevation flights and ground crews being present. No PBHS were observed.
-----------------------	---

STRUCTURE: EP269- EP281

DBS Julia Addison	Activity included a survey of the Westbound lanes. Monitored the ROW throughout the day due to low-elevation flights and ground crews being present. No PBHS were observed during surveys.
----------------------	--

STRUCTURE: EP269-EP273

DBS Tim Searl	Activity included a survey of EP269-EP273. Remarks: No PBHS observed during survey.
------------------	--

STRUCTURE: EP274 through EP278

DBS Gregg M Lukasell	Conducted biological surveys for big horn sheep in EP274 through EP278. No PBHS were observed. All ground and flight crews were in compliance with mitigation measures/protocol.
-------------------------	--

STRUCTURE: EP300- EP312

DBS Julia Addison	Activity included a survey of the Westbound lanes. Monitored the ROW throughout the day due to low-elevation flights and ground crews being present. No PBHS were observed during surveys.
----------------------	--

STRUCTURE: EP300 through EP312

DBS Arthur Davenport	Peninsular bighorn sheep (PBHS) monitoring. Monitor locations of PBHS in relation to project activities so that harm or harassment of PBHS does not occur. Surveyed EP300 through EP312 and eastern flank of I-8 Island. Provide guidance to other bighorn sheep monitors and coordinate with SDG&E.
-------------------------	--

Sunrise Powerlink Transmission Project

B-7c Big Horn Sheep

From 11/27/2011 Through 12/03/2011

ENVIRONMENTAL COMPLIANCE

Date	Monitor	Comments
12/03/2011		
STRUCTURE: EP 279 - EP 294		
	DBS Charles E German	Survey EP 279 thru EP 294. No PBHS were observed in flight corridor or flight buffer during surveys. Monitor Helicopter flights between EP 279 - 294. All flights observed appeared to be in compliance. No PBHS were observed to be harassed or harmed.
STRUCTURE: EP256-EP263A		
	DBS Arthur Davenport	Peninsular bighorn sheep (PBHS) monitoring. Monitor locations of PBHS in relation to project activities so that harm or harassment of PBHS does not occur. Surveyed EP256 through EP263A and eastern flank of I-8 Island. Provide guidance to other bighorn sheep monitors and coordinate with SDG&E. Remarks: Due to presence of 2 Peninsular bighorn sheep, EP271 through EP273 remained closed to low altitude flights for the day. However, the area remained open to ground crews.
STRUCTURE: EP263B- EP269		
	DBS Evy Rimbenieks	Activity included a survey of right of way between EP 263B - EP 269. Monitored the ROW throughout the day due to low elevation flights and ground crews being present. No PBHS were observed.
STRUCTURE: EP269- EP281		
	DBS Julia Addison	Activity included a survey of the Westbound lanes. Monitored the ROW throughout the day due to low-elevation flights and ground crews being present. No PBHS were observed during surveys.
STRUCTURE: EP269-EP270		
	DBS Mikaila Rimbenieks	Activity included a survey of the old highway 80 access and interior roads located between proposed tower locations EP269 - EP270. No PBHS were observed. Monitored the ROW throughout the day due to low elevation flights and ground crews working in the area.
STRUCTURE: EP274 through EP278		
	DBS Gregg M Lukasell	Conducted biological surveys for big horn sheep in EP274 through EP278. No PBHS were observed. All ground and flight crews were in compliance with mitigation measures/protocol.
STRUCTURE: EP300- EP312		
	DBS Julia Addison	Activity included a survey of the Westbound lanes. Monitored the ROW throughout the day due to low-elevation flights and ground crews being present. No PBHS were observed during surveys.

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
12/3/2011	EP300-EP312	0	Site clearance survey
12/3/2011	EP300-EP312	0	Monitoring construction activities
12/3/2011	EP278-1, EP279-1 & EP280-2	0	Monitoring construction activities
12/3/2011	EP274-EP278	0	Site clearance survey
12/3/2011	EP274-EP278	0	Monitoring construction activities
12/3/2011	EP269-EP270	0	Site clearance survey
12/3/2011	EP269-EP270	0	Monitoring construction activities
12/3/2011	EP269-EP281	0	Site clearance survey
12/3/2011	EP269-EP281	0	Monitoring construction activities
12/3/2011	EP263B-EP269	0	Site clearance survey
12/3/2011	EP263B-EP269	0	Monitoring construction activities
12/3/2011	EP257	0	Monitoring construction activities
12/3/2011	EP256-EP263A	2	Site clearance survey
12/3/2011	EP256-EP263A	Same 2 listed above	Monitoring construction activities
12/3/2011	EP279-EP294	0	Site clearance survey
12/3/2011	EP279-EP294	0	Monitoring construction activities
12/2/2011	EP300-EP312	0	Site clearance survey
12/2/2011	EP300-EP312	0	Monitoring construction activities
12/2/2011	EP300-EP312	0	Site clearance survey
12/2/2011	EP300-EP312	0	Monitoring construction activities
12/2/2011	EP281-GS-BLM-3	0	Monitoring construction activities
12/2/2011	EP280-EP281	0	Monitoring construction activities
12/2/2011	EP274-EP278	0	Site clearance survey
12/2/2011	EP274-EP278	0	Monitoring construction activities
12/2/2011	EP269-EP273	0	Site clearance survey
12/2/2011	EP269-EP281	0	Site clearance survey
12/2/2011	EP269-EP281	0	Monitoring construction activities
12/2/2011	EP263B-EP269	0	Site clearance survey
12/2/2011	EP263B-EP269	0	Monitoring construction activities
12/2/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/2/2011	EP279-EP294	0	Site clearance survey
12/2/2011	EP279-EP294	0	Monitoring construction activities
12/1/2011	EP300-EP312	0	Site clearance survey
12/1/2011	EP279-EP294; EP273-EP276	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
12/1/2011	EP279-EP294; EP273-EP276	0	Monitoring construction activities
12/1/2011	EP274-1, EP275-1	0	Monitoring construction activities
12/1/2011	EP274-EP278	0	Site clearance survey
12/1/2011	EP274-EP278	0	Monitoring construction activities
12/1/2011	EP269-EP273	0	Site clearance survey
12/1/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/30/2011	EP300-EP312	0	Site clearance survey
11/30/2011	EP300-EP312	0	Monitoring construction activities
11/30/2011	EP300-EP312	0	Site clearance survey
11/30/2011	EP274-EP278	0	Site clearance survey
11/30/2011	EP274-EP278	0	Monitoring construction activities
11/30/2011	EP273-1	0	Monitoring construction activities
11/30/2011	EP269-EP281	0	Site clearance survey
11/30/2011	EP269-EP281	0	Monitoring construction activities
11/30/2011	EP269-EP281	0	Site clearance survey
11/30/2011	EP269-EP281	0	Monitoring construction activities
11/30/2011	EP269-EP273	0	Site clearance survey
11/30/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/30/2011	EP279-EP294	0	Site clearance survey
11/30/2011	EP279-EP294	0	Monitoring construction activities
11/29/2011	EP300-EP312	0	Site clearance survey
11/29/2011	EP300-EP312	0	Monitoring construction activities
11/29/2011	EP300-EP312	0	Site clearance survey
11/29/2011	EP300-EP312	0	Monitoring construction activities
11/29/2011	EP274-EP278	0	Site clearance survey
11/29/2011	EP274-EP278	0	Monitoring construction activities
11/29/2011	EP273-1	0	Monitoring construction activities
11/29/2011	EP269-EP281	0	Site clearance survey
11/29/2011	EP269-EP281	0	Monitoring construction activities
11/29/2011	EP269-EP281	0	Site clearance survey
11/29/2011	EP269-EP281	0	Monitoring construction activities
11/29/2011	EP269-EP273	0	Site clearance survey
11/29/2011	EP269-EP281	0	Site clearance survey
11/29/2011	EP269-EP281	0	Monitoring construction activities
11/29/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
11/29/2011	EP279-EP294	0	Site clearance survey
11/29/2011	EP279-EP294	0	Monitoring construction activities
11/28/2011	EP300-EP312	0	Site clearance survey
11/28/2011	EP300-EP312	0	Monitoring construction activities
11/28/2011	EP274-EP278	0	Site clearance survey
11/28/2011	EP274-EP278	0	Monitoring construction activities
11/28/2011	EP273-1	0	Monitoring construction activities
11/28/2011	EP269-EP281	0	Site clearance survey
11/28/2011	EP269-EP281	0	Monitoring construction activities
11/28/2011	EP269-EP273	0	Site clearance survey
11/28/2011	EP269-EP273	0	Monitoring construction activities
11/28/2011	EP269-EP270	0	Site clearance survey
11/28/2011	EP269-EP281	0	Site clearance survey
11/28/2011	EP269-EP281	0	Monitoring construction activities
11/28/2011	EP263B-EP267	0	Site clearance survey
11/28/2011	EP263B-EP267	0	Monitoring construction activities
11/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/28/2011	EP279-EP294	0	Site clearance survey
11/28/2011	EP279-EP294	0	Monitoring construction activities
11/27/2011	EP300-EP312	0	Site clearance survey
11/27/2011	EP300-EP312	0	Monitoring construction activities
11/27/2011	EP279-1 & EP280-2	0	Monitoring construction activities
11/27/2011	EP274-EP278	0	Site clearance survey
11/27/2011	EP274-EP278	0	Monitoring construction activities
11/27/2011	EP269-EP281	0	Site clearance survey
11/27/2011	EP269-EP281	0	Monitoring construction activities
11/27/2011	EP269-EP281	0	Site clearance survey
11/27/2011	EP269-EP281	0	Monitoring construction activities
11/27/2011	EP269-EP274	3	Site clearance survey
11/27/2011	EP269-EP274	Same 3 as noted above	Monitoring construction activities
11/27/2011	EP269-EP270	0	Site clearance survey
11/27/2011	EP269-EP281	0	Site clearance survey
11/27/2011	EP269-EP281	0	Monitoring construction activities
11/27/2011	EP263B-EP269	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
11/27/2011	EP263B-EP269	0	Monitoring construction activities
11/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/27/2011	EP279-EP294	0	Site clearance survey
11/27/2011	EP279-EP294	0	Monitoring construction activities
11/26/2011	EP300-EP312	0	Site clearance survey
11/26/2011	EP300-EP312	0	Monitoring construction activities
11/26/2011	EP274-EP278	0	Site clearance survey
11/26/2011	EP274-EP278	0	Monitoring construction activities
11/26/2011	EP269-EP271	11	Site clearance survey - Six PBS sited approaching EP270 @ 11:30am. At 5:00pm 5 PBS were sited near EP270
11/26/2011	EP269-EP271	Same 11 as noted above	Monitoring construction activities
11/26/2011	EP269-EP273	Same 11 as noted above	Site clearance survey
11/26/2011	EP269-EP273	Same 11 as noted above	Monitoring construction activities
11/26/2011	EP270	Same 11 as noted above	Site clearance survey
11/26/2011	EP269-EP281	0	Site clearance survey
11/26/2011	EP269-EP281	0	Monitoring construction activities
11/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/26/2011	EP279-EP294	0	Site clearance survey
11/25/2011	EP274-EP278	0	Site clearance survey
11/25/2011	EP274-EP278	0	Monitoring construction activities
11/25/2011	EP272	0	Site clearance survey
11/25/2011	EP269-EP273	1	Site clearance survey - 1 Ram was sighted near EP272 in am
11/25/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/25/2011	EP279-EP294	0	Monitoring construction activities
11/24/2011	EP269-EP273	0	Site clearance survey
11/24/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/24/2011	EP279-EP294	0	Site clearance survey
11/23/2011	EP300-EP312, EP269-EP281	0	Site clearance survey
11/23/2011	EP300-EP312, EP269-EP281	0	Monitoring construction activities
11/23/2011	EP274-EP278	0	Site clearance survey
11/23/2011	EP274-EP278	0	Monitoring construction activities
11/23/2011	EP270-2	0	Monitoring construction activities
11/23/2011	EP269-EP273	0	Site clearance survey
11/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/22/2011	EP277-1	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
11/22/2011	EP274-EP278	0	Site clearance survey
11/22/2011	EP269-EP281	0	Site clearance survey
11/22/2011	EP269-EP273	0	Site clearance survey
11/22/2011	EP269-EP270	0	Site clearance survey
11/22/2011	EP269-EP270	0	Monitoring construction activities
11/22/2011	EP269-EP281	0	Site clearance survey
11/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/22/2011	EP279-EP294	0	Site clearance survey
11/22/2011	EP279-EP294	0	Monitoring construction activities
11/21/2011	EP269-EP281	1	Site clearance survey
11/21/2011	EP300-EP312	0	Site clearance survey
11/21/2011	EP300-EP312	0	Monitoring construction activities
11/21/2011	EP300-EP312	0	Site clearance survey
11/21/2011	EP300-EP312	0	Monitoring construction activities
11/21/2011	EP281	0	Monitoring construction activities
11/21/2011	EP276-1-EP270-2	0	Monitoring construction activities
11/21/2011	EP274-EP278	0	Site clearance survey
11/21/2011	EP274-EP278	0	Monitoring construction activities
11/21/2011	EP272	1	Site clearacne surve - 6:45am 1 ram sighted near EP272
11/21/2011	EP269-EP281	0	Site clearance survey
11/21/2011	EP269-EP281	0	Monitoring construction activities
11/21/2011	EP265-2-EP281	0	Monitoring construction activities
11/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/21/2011	EP279-EP294	0	Site clearance survey
11/21/2011	EP279-EP294	0	Monitoring construction activities
11/20/2011	EP300-EP312	0	Site clearance survey
11/20/2011	EP300-EP312	0	Site clearance survey
11/20/2011	EP300-EP312	0	Monitoring construction activities
11/20/2011	EP277-1 and EP272-3	0	Monitoring construction activities
11/20/2011	EP274-EP278	0	Site clearance survey
11/20/2011	EP274-EP278	0	Monitoring construction activities
11/20/2011	EP271	0	Site clearance survey
11/20/2011	EP271	0	Monitoring construction activities
11/20/2011	EP269-EP281	0	Site clearance survey
11/20/2011	EP269-EP281	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
11/20/2011	EP256-EP263A	0	Site clearance survey
11/20/2011	EP256-EP263A	0	Monitoring construction activities
11/19/2011	EP300-EP312	0	Site clearance survey
11/19/2011	EP300-EP312	0	Monitoring construction activities
11/19/2011	EP300-EP312	0	Site clearance survey
11/19/2011	EP300-EP312	0	Monitoring construction activities
11/19/2011	EP281	0	Monitoring construction activities
11/19/2011	EP277-1	0	Monitoring construction activities
11/19/2011	EP274-EP278	0	Site clearance survey
11/19/2011	EP274-EP278	0	Monitoring construction activities
11/19/2011	EP269-EP281	0	Site clearance survey
11/19/2011	EP269-EP281	0	Monitoring construction activities
11/19/2011	EP256-EP263A	0	Site clearance survey
11/19/2011	EP256-EP263A	0	Monitoring construction activities
11/18/2011	EP300-EP312	0	Site clearance survey
11/18/2011	EP300-EP312	0	Monitoring construction activities
11/18/2011	EP281-GS-BLM-3	0	Monitoring construction activities
11/18/2011	EP276-1	0	Monitoring construction activities
11/18/2011	EP274-EP278	0	Site clearance survey
11/18/2011	EP274-EP278	0	Monitoring construction activities
11/18/2011	EP272	16	Site clearance survey-PBS were observed within Devil's Cyn 2 west of EP272 @ ~8:00am. At that time the flight corridor was closed to low-elevation flights from EP271-EP273
11/18/2011	EP272	Same 16 PBS as noted above	Monitoring construction activities
11/18/2011	EP269-EP281	0	Site clearance survey
11/18/2011	EP269-EP281	0	Monitoring construction activities
11/18/2011	EP256-EP263A	0	Site clearance survey
11/18/2011	EP256-EP263A	0	Monitoring construction activities
11/17/2011	EP281-GS-BLM-3 & EP290-GS-NF-40	0	Monitoring construction activities
11/17/2011	EP277-1	0	Monitoring construction activities
11/17/2011	EP271-EP274	0	Site clearance survey
11/17/2011	EP300-EP312	0	Site clearance survey
11/17/2011	EP300-EP312	0	Monitoring construction activities
11/16/2011	EP300-EP312	0	Site clearance survey
11/16/2011	EP300-EP312	0	Monitoring construction activities
11/16/2011	EP276-1	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
11/16/2011	EP272	13	Site clearance survey-PBS were observed ~300 feet west of EP272 at ~7:00am. At that time, low-elevation flights were closed from EP271-EP274
11/16/2011	EP272	Same 13 PBS as noted above	Monitoring construction activities
11/16/2011	EP269-EP281	0	Site clearance survey
11/16/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/16/2011	EP274-EP278	0	Site clearance survey
11/16/2011	EP274-EP278	0	Monitoring construction activities
11/16/2011	EP269-EP281	0	Site clearance survey
11/16/2011	EP269-EP281	0	Monitoring construction activities
11/15/2011	EP269-EP273	0	Site clearance survey
11/15/2011	EP269-EP281	0	Site clearance survey
11/15/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/15/2011	EP274-EP278	0	Site clearance survey
11/15/2011	EP274-EP278	0	Monitoring construction activities
11/15/2011	AER and Fromm CY's	0	Monitoring construction activities
11/14/2011	EP306-EP312	0	Site clearance survey
11/14/2011	EP269-EP273	0	Site clearance survey
11/14/2011	EP263A-2, EP263B-2	0	Monitoring construction activities
11/14/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/14/2011	EP274-EP278	0	Site clearance survey
11/14/2011	EP274-EP278	0	Monitoring construction activities
11/13/2011	EP306-EP312	0	Site clearance survey
11/13/2011	EP300-EP312	0	Site clearance survey
11/13/2011	EP300-EP312	0	Monitoring construction activities
11/13/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/13/2011	EP274-EP278	0	Site clearance survey
11/13/2011	EP274-EP278	0	Monitoring construction activities
11/13/2011	EP269-EP281	0	Site clearance survey
11/13/2011	EP269-EP281	0	Monitoring construction activities
11/12/2011	EP300-EP312	0	Site clearance survey
11/12/2011	EP300-EP312	0	Monitoring construction activities
11/12/2011	EP269-EP281	0	Site clearance survey
11/12/2011	EP269-EP281	0	Monitoring construction activities
11/12/2011	EP263B-2	0	Monitoring construction activities
11/12/2011	EP274-EP278	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
11/12/2011	EP274-EP278	0	Monitoring construction activities
11/12/2011	EP269-EP281	0	Site clearance survey
11/12/2011	EP269-EP281	0	Monitoring construction activities
11/11/2011	EP306-EP312	0	Site clearance survey
11/11/2011	EP300-EP312	0	Monitoring construction activities
11/11/2011	EP269-EP281	0	Site clearance survey
11/11/2011	EP269-EP281	0	Monitoring construction activities
11/11/2011	EP269-EP273	0	Site clearance survey
11/11/2011	EP269-EP270	0	Site clearance survey
11/11/2011	EP269-EP270	0	Monitoring construction activities
11/11/2011	EP263B-EP267	0	Site clearance survey
11/11/2011	EP263B-EP267	0	Monitoring construction activities
11/11/2011	EP274-EP278	0	Site clearance survey
11/11/2011	EP274-EP278	0	Monitoring construction activities
11/11/2011	EP269-EP281	0	Site clearance survey
11/11/2011	EP269-EP281	0	Monitoring construction activities
11/10/2011	EP306-EP312	0	Site clearance survey
11/10/2011	EP269-EP273	0	Site clearance survey
11/10/2011	EP269-EP281	0	Site clearance survey
11/10/2011	EP269-EP281	0	Monitoring construction activities
11/10/2011	EP269-EP270	0	Site clearance survey
11/10/2011	EP269-EP270	0	Monitoring construction activities
11/10/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/10/2011	EP274-EP278	0	Site clearance survey
11/10/2011	EP274-EP278	0	Monitoring construction activities
11/9/2011	Fromm CY	0	Monitoring construction activities
11/9/2011	EP313/EP314 Pullsite	0	Monitoring construction activities
11/9/2011	EP306-EP312	0	Site clearance survey
11/9/2011	EP306	0	Monitoring construction activities
11/9/2011	EP269-EP273	0	Site clearance survey
11/9/2011	EP269-EP281	0	Site clearance survey
11/9/2011	EP269-EP281	0	Monitoring construction activities
11/9/2011	EP265-2	0	Site clearance survey
11/9/2011	EP265-2	0	Monitoring construction activities
11/9/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
11/9/2011	EP274-EP278	0	Site clearance survey
11/9/2011	EP274-EP278	0	Monitoring construction activities
11/9/2011	EP263B-EP267, EP269-EP281	0	Site clearance survey
11/9/2011	EP263B-EP267, EP269-EP281	0	Monitoring construction activities
11/8/2011	EP306-EP312	0	Site clearance survey
11/8/2011	EP300-EP312	0	Site clearance survey
11/8/2011	EP300-EP312	0	Monitoring construction activities
11/8/2011	EP280	0	Monitoring construction activities
11/8/2011	EP272-EP275	0	Site clearance survey
11/8/2011	EP272-EP275	5	Monitoring construction activities
11/8/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/8/2011	EP279-EP294	0	Site clearance survey
11/8/2011	EP279-EP294	0	Monitoring construction activities
11/8/2011	EP274-EP278	0	Site clearance survey
11/8/2011	EP274-EP278	0	Monitoring construction activities
11/8/2011	EP269-EP281	0	Site clearance survey
11/8/2011	EP269-EP281	0	Monitoring construction activities
11/8/2011	EP263B-EP267, EP269-EP281	0	Site clearance survey
11/8/2011	EP263B-EP267, EP269-EP281	0	Monitoring construction activities
11/8/2011	Devils Cyn Bridge	5	Monitoring construction activities
11/7/2011	EP307-EP308	0	Monitoring construction activities
11/7/2011	EP300-EP312	0	Site clearance survey
11/7/2011	EP300-EP312	0	Monitoring construction activities
11/7/2011	EP280	0	Monitoring construction activities
11/7/2011	EP271-EP274	3	Site clearance survey
11/7/2011	EP271-EP274	0	Site clearance survey
11/7/2011	EP271-EP274	5	Site clearance survey
11/7/2011	EP271-EP274	0	Monitoring construction activities
11/7/2011	EP269-EP271	0	Site clearance survey
11/7/2011	EP269-EP271	0	Monitoring construction activities
11/7/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/7/2011	EP278-EP281	0	Site clearance survey
11/7/2011	EP274-EP278	0	Site clearance survey
11/7/2011	EP274-EP278	0	Monitoring construction activities
11/7/2011	EP269-EP281	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
11/7/2011	EP269-EP281	0	Monitoring construction activities
11/7/2011	EP263B-EP267	0	Site clearance survey
11/7/2011	EP263B-EP267	0	Monitoring construction activities
11/6/2011	EP308-EP310	0	Monitoring construction activities
11/6/2011	EP303-2, EP302-1	0	Monitoring construction activities
11/6/2011	EP300-EP312	0	Site clearance survey
11/6/2011	EP300-EP312	0	Monitoring construction activities
11/6/2011	EP300-EP312	0	Site clearance survey
11/6/2011	EP300-EP312	0	Monitoring construction activities
11/6/2011	EP290-EP312, EP269-EP281	0	Site clearance survey
11/6/2011	EP290-EP312, EP269-EP281	0	Monitoring construction activities
11/6/2011	EP279-1	0	Monitoring construction activities
11/6/2011	EP269-EP281	0	Site clearance survey
11/6/2011	EP269-EP281	0	Monitoring construction activities
11/6/2011	EP274-EP278	0	Monitoring construction activities
11/6/2011	EP274-EP278	0	Site clearance survey
11/6/2011	EP269-EP281	0	Monitoring construction activities
11/6/2011	EP269-EP281	0	site clearance survey
11/5/2011	EP300-EP312	0	Site clearance survey
11/5/2011	EP300-EP312	0	Monitoring construction activities
11/5/2011	EP271-2, EP272-3, EP276-1 & EP281	0	Monitoring construction activities
11/5/2011	EP269-EP273	0	Site clearance survey
11/5/2011	EP265-2	0	Monitoring construction activities
11/5/2011	EP256-EP263A	0	Site clearance survey
11/5/2011	EP279-EP294	0	Site clearance survey
11/5/2011	EP279-EP294	0	Monitoring construction activities
11/5/2011	EP277-1	0	Monitoring construction activities
11/5/2011	EP263B-EP267	0	Site clearance survey
11/5/2011	EP263B-EP267	0	Monitoring construction activities
11/4/2011	S2 CY	0	Monitoring construction activities
11/4/2011	EP311, EP310	0	Monitoring construction activities
11/4/2011	EP307	0	Monitoring construction activities
11/4/2011	EP306/EP307 Pullsite	0	Monitoring construction activities
11/4/2011	EP300-EP312	0	Site clearance survey
11/4/2011	EP300-EP312	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
11/4/2011	EP269-EP273	0	Site clearance survey
11/4/2011	EP269-EP271	0	Site clearance survey
11/4/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/4/2011	EP279-EP294	0	Site clearance survey
11/4/2011	EP279-EP294	0	Monitoring construction activities
11/4/2011	EP274-EP278	0	Site clearance survey
11/4/2011	EP274-EP278	0	Monitoring construction activities
11/4/2011	EP263B-EP267	0	Site clearance survey
11/4/2011	EP263B-EP267	0	Monitoring construction activities
11/3/2011	EP311	0	Monitoring construction activities
11/3/2011	EP307	0	Monitoring construction activities
11/3/2011	EP280	0	Monitoring construction activities
11/3/2011	EP279-1	0	Monitoring construction activities
11/3/2011	EP278-1, EP279-1, EP280-1	0	Monitoring construction activities
11/3/2011	EP271-2	0	Monitoring construction activities
11/3/2011	EP269-EP273	0	Site clearance survey
11/3/2011	EP265-2	0	Monitoring construction activities
11/3/2011	EP263B-EP267; EP279-EP312	0	Site clearance survey
11/3/2011	EP261A, EP259-3	0	Monitoring construction activities
11/3/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/3/2011	EP279-EP294	0	Site clearance survey
11/3/2011	EP279-EP294	0	Monitoring construction activities
11/3/2011	EP274-EP278	0	Site clearance survey
11/3/2011	EP274-EP278	0	Monitoring construction activities
11/2/2011	EP269-EP273	0	Site clearance survey
11/2/2011	EP269-EP281	0	Site clearance survey
11/2/2011	EP269-EP281	0	Monitoring construction activities
11/2/2011	EP263B-EP267; EP279-EP312	0	Site clearance survey
11/2/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/2/2011	EP300-EP312; EP274-EP278	0	Site clearance survey
11/2/2011	EP300-EP312; EP274-EP278	0	Monitoring construction activities
11/1/2011	Suckle Property	0	Monitoring construction activities
11/1/2011	EP310 & EP311	0	Monitoring construction activities
11/1/2011	EP300-EP312	0	Site clearance survey
11/1/2011	EP300-EP312	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
11/1/2011	EP279-EP312	0	Site clearance survey
11/1/2011	EP277-1, EP276-1, EP261A, EP259B	0	Monitoring construction activities
11/1/2011	EP275-1	0	Monitoring construction activities
11/1/2011	EP269-EP273	0	Site clearance survey
11/1/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/1/2011	EP274-EP278	0	Site clearance survey
11/1/2011	EP274-EP278	0	Monitoring construction activities
11/1/2011	EP263B, EP267	0	Site clearance survey
11/1/2011	Devil's Canyon Bridge	0	Site clearance survey
11/1/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/31/2011	EP279-EP294	0	Site clearance survey
10/31/2011	EP279-EP294	0	Monitoring construction activities
10/31/2011	EP269-EP281	0	Site clearance survey
10/31/2011	EP269-EP281	0	Monitoring construction activities
10/31/2011	EP269-EP273	0	Site clearance survey
10/31/2011	EP269-EP281	0	Site clearance survey
10/31/2011	EP263A-2, EP266-2	0	Monitoring construction activities
10/31/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/31/2011	EP254-3	0	Monitoring construction activities
10/31/2011	EP305, EP310-1	0	Monitoring construction activities
10/31/2011	EP300-EP312	0	Site clearance survey
10/31/2011	EP300-EP312	0	Monitoring construction activities
10/31/2011	EP274-EP278	0	Site clearance survey
10/31/2011	EP263B-EP267	0	Site clearance survey
10/31/2011	Devil's Canyon Bridge	0	Site clearance survey
10/31/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/31/2011	EP262-4, EP263B-2, EP265-2, EP266-2, EP267-1	0	Monitoring construction activities
10/30/2011	EP300-EP306	0	Site clearance survey
10/30/2011	EP300-EP306	0	Monitoring construction activities
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Monitoring construction activities
10/30/2011	EP269-EP273	0	Site clearance survey
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
10/30/2011	EP269-EP281	0	Monitoring construction activities
10/30/2011	EP269-EP270	0	Site clearance survey
10/30/2011	EP267-2 & EP266-2	0	Monitoring construction activities
10/30/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/30/2011	EP279-EP294	0	Site clearance survey
10/30/2011	EP279-EP294	0	Monitoring construction activities
10/30/2011	EP274-EP278	0	Site clearance survey
10/30/2011	EP274-EP278	0	Monitoring construction activities
10/30/2011	EP263B-EP267	0	Site clearance survey
10/30/2011	Devil's Canyon Bridge	0	Site clearance survey
10/30/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/29/2011	EP300-EP306	0	Site clearance survey
10/29/2011	EP300-EP306	0	Monitoring construction activities
10/29/2011	EP274-EP278	0	Site clearance survey
10/29/2011	EP274-EP278	0	Monitoring construction activities
10/29/2011	EP269-EP273	0	Site clearance survey
10/29/2011	EP269-1	0	Monitoring construction activities
10/29/2011	EP269-EP281	0	Site clearance survey
10/29/2011	EP269-EP281	0	Monitoring construction activities
10/29/2011	EP269-EP281	0	Site clearance survey
10/29/2011	EP269-EP281	0	Monitoring construction activities
10/29/2011	EP269-EP270	0	Site clearance survey
10/29/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/29/2011	EP279-EP294	0	Site clearance survey
10/29/2011	EP279-EP294	0	Monitoring construction activities
10/29/2011	EP263B-EP267	0	Site clearance survey
10/29/2011	Devil's Cyn Bridge (w/in I-8 Island)	1	Morning perimeter survey 7:37 am
10/28/2011	EP300-EP306	0	Site clearance survey
10/28/2011	EP300-EP306	0	Monitoring construction activities
10/28/2011	EP269-EP281	0	Site clearance survey
10/28/2011	EP269-EP281	0	Monitoring construction activities
10/28/2011	EP269-EP273	0	Site clearance survey
10/28/2011	EP269-1	0	Monitoring construction activities
10/28/2011	EP269-EP281	0	Site clearance survey
10/28/2011	EP269-EP281	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
10/28/2011	EP269-EP270	0	Site clearance survey
10/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/28/2011	EP310	0	Monitoring construction activities
10/28/2011	EP279-EP294	0	Site clearance survey
10/28/2011	EP279-EP294	0	Monitoring construction activities
10/28/2011	EP274-EP278	0	Site clearance survey
10/28/2011	EP274-EP278	0	Monitoring construction activities
10/28/2011	EP263B-EP267	0	Site clearance survey
10/28/2011	AER and FROMM CY	0	Monitoring construction activities
10/27/2011	EP273-1 & EP276-1	0	Monitoring construction activities
10/27/2011	EP271-EP272	2	Site clearance survey 7:40 am
10/27/2011	EP271-EP272	0	Monitoring construction activities
10/27/2011	EP269-EP281: EP300-EP306	0	Site clearance survey
10/27/2011	EP269-EP281: EP300-EP306	0	Monitoring construction activities
10/27/2011	EP256-EP263A-2, AER CY	0	Site clearance survey
10/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/27/2011	EP279-EP294	0	Site clearance survey
10/27/2011	EP279-EP294	0	Monitoring construction activities
10/27/2011	EP274-EP278	0	Site clearance survey
10/27/2011	EP274-EP278	0	Monitoring construction activities
10/27/2011	EP269-EP271	0	Monitoring construction activities
10/27/2011	EP263B-EP267	0	Site clearance survey
10/27/2011	AER and FROMM CY	0	Monitoring construction activities
10/26/2011	EP311-1, EP312, EP310	0	Monitoring construction activities
10/26/2011	EP300-EP312	0	Site clearance survey
10/26/2011	EP300-EP312	0	Monitoring construction activities
10/26/2011	EP272-EP273	2	Site clearance survey 10:00 am
10/26/2011	EP272-EP273	0	Monitoring construction activities
10/26/2011	EP269-EP281; EP300-EP306	0	Site clearance survey
10/26/2011	EP269-EP281; EP300-EP306	0	Monitoring construction activities
10/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/26/2011	EP279-EP294	0	Site clearance survey
10/26/2011	EP279-EP294	0	Monitoring construction activities
10/26/2011	EP274-EP278	0	Site clearance survey
10/26/2011	EP274-EP278	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
10/26/2011	EP263B-EP267	0	Site clearance survey
10/25/2011	EP363-EP341, EP299 & EP300	0	Monitoring construction activities
10/25/2011	EP313-EP324	0	Monitoring construction activities
10/25/2011	EP310	0	Monitoring construction activities
10/25/2011	EP300-EP312	0	Site clearance survey
10/25/2011	EP300-EP312	0	Monitoring construction activities
10/25/2011	EP290	0	Monitoring construction activities
10/25/2011	EP269-EP273	0	Site clearance survey
10/25/2011	EP269-EP281; EP300-EP306	0	Site clearance survey
10/25/2011	EP269-EP281; EP300-EP306	0	Monitoring construction activities
10/25/2011	EP311	0	Monitoring construction activities
10/25/2011	EP279-EP294	0	Site clearance survey
10/25/2011	EP263B-EP267	0	Site clearance survey
10/24/2011	EP313-EP322	0	Monitoring construction activities
10/24/2011	EP305, EP306, EP312	0	Monitoring construction activities
10/24/2011	EP300-EP306	0	Site clearance survey
10/24/2011	EP300-EP306	0	Monitoring construction activities
10/24/2011	EP297-EP319	0	Monitoring construction activities
10/24/2011	EP269-EP273	0	Site clearance survey
10/24/2011	EP269-EP273	0	Monitoring construction activities
10/24/2011	EP269-EP281	0	Site clearance survey
10/24/2011	EP269-EP281	0	Monitoring construction activities
10/24/2011	EP279-EP294	0	Site clearance survey
10/24/2011	EP279-EP294	0	Monitoring construction activities
10/24/2011	EP274-EP278	0	Site clearance survey
10/24/2011	EP274-EP278	0	Monitoring construction activities
10/24/2011	EP263B-EP267	0	Site clearance survey
10/23/2011	EP300-EP312	0	Site clearance survey
10/23/2011	EP300-EP312	0	Monitoring construction activities
10/23/2011	EP269-EP273	0	Site clearance survey
10/23/2011	EP269-EP273	0	Monitoring construction activities
10/23/2011	EP269-EP281	0	Site clearance survey
10/23/2011	EP269-EP281	0	Monitoring construction activities
10/23/2011	EP269-EP270	0	Site clearance survey
10/23/2011	EP263B-EP267	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
10/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/23/2011	EP300-EP312	0	Site clearance survey
10/23/2011	EP300-EP312	0	Monitoring construction activities
10/23/2011	EP274-EP278	0	Site clearance survey
10/23/2011	EP274-EP278	0	Monitoring construction activities
10/23/2011	EP269-EP273	0	Site clearance survey
10/23/2011	EP269-EP273	0	Monitoring construction activities
10/22/2011	EP300-EP306	0	Site clearance survey
10/22/2011	EP300-EP306	0	Monitoring construction activity
10/22/2011	EP269-EP281	0	Site clearance survey
10/22/2011	EP269-EP281	0	Monitoring construction activity
10/22/2011	EP269-EP281	0	Site clearance survey
10/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/22/2011	EP274-EP278	0	Site clearance survey
10/22/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP306-EP312	0	Site clearance survey
10/21/2011	EP306-EP312	0	Monitoring construction activity
10/21/2011	EP274-EP278	0	Site clearance survey
10/21/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP269-EP281	0	Site clearance survey
10/21/2011	EP269-EP281	0	Site clearance survey
10/21/2011	EP269-EP281	0	Monitoring construction activity
10/21/2011	EP269-EP270	0	Site clearance survey
10/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/21/2011	EP274-EP278	0	Site clearance survey
10/21/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP269-EP273	0	Site clearance survey
10/21/2011	EP269-EP273	0	Monitoring construction activity
10/20/2011	EP269-EP281	0	Site clearance survey
10/20/2011	EP269	0	Site clearance survey
10/20/2011	EP269	0	Monitoring construction activity
10/20/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/20/2011	EP274-EP278	0	Site clearance survey
10/20/2011	EP274-EP278	0	Monitoring construction activity
10/20/2011	EP269-EP273	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
10/20/2011	EP269-EP273	0	Monitoring construction activity
10/20/2011	EP263B-EP267	0	Site clearance survey
10/20/2011	EP300-EP312	0	Site clearance survey
10/20/2011	EP300-EP312	0	Monitoring construction activity
10/19/2011	EP290-EP312	0	Site clearance survey
10/19/2011	EP290-EP312	0	Monitoring construction activity
10/19/2011	EP269-EP281	0	Site clearance survey
10/19/2011	EP300-EP312	0	Site clearance survey
10/19/2011	EP300-EP312	0	Monitoring construction activity
10/19/2011	EP274-EP278	0	Site clearance survey
10/19/2011	EP274-EP278	0	Monitoring construction activity
10/19/2011	EP269-EP273	0	Site clearance survey
10/19/2011	EP269-EP273	0	Monitoring construction activity
10/19/2011	EP263B-EP267	0	Site clearance survey
10/18/2011	Slay Property	0	Monitoring construction activity
10/18/2011	EP269-EP270	0	Site clearance survey
10/18/2011	EP269-EP270	0	Monitoring construction activity
10/18/2011	EP269-EP281	0	Site clearance survey
10/18/2011	EP269-EP270	0	Site clearance survey
10/18/2011	EP274-EP278	0	Site clearance survey
10/18/2011	EP274-EP278	0	Monitoring construction activity
10/18/2011	EP269-EP273	0	Site clearance survey
10/18/2011	EP269-EP273	0	Monitoring construction activity
10/18/2011	EP263B-EP267	0	Site clearance survey
10/17/2011	Slay Property	0	Site clearance survey
10/17/2011	EP312 & EP314	0	Monitoring construction activity
10/17/2011	EP306-EP312	0	Site clearance survey
10/17/2011	EP306-EP312	0	Afternoon perimeter survey
10/17/2011	EP305	0	Monitoring construction activity
10/17/2011	EP300-EP363	0	Monitoring construction activity
10/17/2011	EP300-EP306	0	Site clearance survey
10/17/2011	EP300-EP306	0	Monitoring construction activity
10/17/2011	EP270-2	0	Monitoring construction activity
10/17/2011	EP269-EP270	0	Site clearance survey
10/17/2011	EP269-EP270	0	Monitoring construction activity

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
10/17/2011	EP269-EP281	0	Site clearance survey
10/17/2011	EP269-EP270	0	Site clearance survey
10/17/2011	EP267-2	0	Monitoring construction activity
10/17/2011	EP261-2	0	Monitoring construction activity
10/17/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/17/2011	EP274-EP278	0	Site clearance survey
10/17/2011	EP274-EP278	0	Monitoring construction activity
10/17/2011	EP269-EP273	0	Site clearance survey
10/17/2011	EP269-EP273	0	Monitoring construction activity
10/17/2011	EP263B-EP267	0	Site clearance survey
10/16/2011	EP306-EP312	0	Site clearance survey
10/16/2011	EP306-EP312	0	Afternoon perimeter survey
10/16/2011	EP300-EP306	0	Site clearance survey
10/16/2011	EP300-EP306	0	Monitoring construction activity
10/16/2011	EP271-2	0	Monitoring construction activity
10/16/2011	EP270-2	0	Monitoring construction activity
10/16/2011	EP269-EP270	0	Site clearance survey
10/16/2011	EP256-EP281	0	Site clearance survey
10/16/2011	EP305	0	Monitoring construction activity
10/16/2011	EP274-EP278	0	Site clearance survey
10/16/2011	EP274-EP278	0	Monitoring construction activity
10/16/2011	EP269-EP273	0	Site clearance survey
10/16/2011	EP269-EP273	0	Monitoring construction activity
10/16/2011	EP263B-EP267	0	Site clearance survey
10/16/2011	EP256-EP263A-2, AER & FROMM CY	0	Site clearance survey
10/16/2011	EP256-EP263A-2, AER & FROMM CY	0	Monitoring construction activity
10/15/2011	Slay Property	0	Site clearance survey
10/15/2011	Slay Property	0	Monitoring construction activities
10/15/2011	EP306-EP312	0	Site clearance survey
10/15/2011	EP306-EP312	0	Afternoon perimeter survey
10/15/2011	EP305	0	Monitoring construction activities
10/15/2011	EP300-EP306	0	Site clearance survey
10/15/2011	EP300-EP306	0	Monitoring construction activities
10/15/2011	EP269-1 AND EP273-1	0	Monitoring construction activities
10/15/2011	EP269-EP281	0	Morning perimeter survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
10/15/2011	EP261-2	0	Monitoring construction activities
10/15/2011	EP274-EP278	0	Site clearance survey
10/15/2011	EP274-EP278	0	Monitoring construction activities
10/15/2011	EP263B-EP267	0	Site clearance survey
10/14/2011	Slay Property	0	Site clearance survey
10/14/2011	Slay Property	0	Monitoring construction activities
10/14/2011	EP310	0	Monitoring construction activities
10/14/2011	EP305	0	Monitoring construction activities
10/14/2011	EP300-EP306	0	Site clearance survey
10/14/2011	EP300-EP306	0	Monitoring construction activities
10/14/2011	EP291-EP301	0	Monitoring construction activities
10/14/2011	EP269 through EP281	0	Site clearance survey
10/14/2011	EP269-EP270	0	Site clearance survey
10/14/2011	EP263B-2	0	Monitoring construction activities
10/14/2011	EP256-EP263A	0	Site clearance survey
10/14/2011	EP256-EP263A	0	Monitoring construction activities
10/14/2011	EP274-EP278	0	Site clearance survey
10/14/2011	EP274-EP278	0	Monitoring construction activities
10/14/2011	EP269-EP273	0	Site clearance survey
10/14/2011	EP269-EP273	0	Monitoring construction activities
10/14/2011	EP263B-EP267	0	Site clearance survey
10/14/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/14/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/13/2011	Slay Property	0	Site clearance survey
10/13/2011	Slay Property	0	Monitoring construction activities
10/13/2011	EP310	0	Monitoring construction activities
10/13/2011	EP306-EP312	0	Site clearance survey
10/13/2011	EP306-EP312	0	Afternoon perimeter survey
10/13/2011	EP293	0	Monitoring construction activities
10/13/2011	EP291-EP301	0	Monitoring construction activities
10/13/2011	EP275-1	0	Monitoring construction activities
10/13/2011	EP269-EP270	0	Site clearance survey
10/13/2011	EP269-EP281	0	Site clearance survey
10/13/2011	EP269-EP270	0	Site clearance survey
10/13/2011	EP266-2	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
10/13/2011	EP274-EP278	0	Site clearance survey
10/13/2011	EP274-EP278	0	Monitoring construction activities
10/13/2011	EP269-EP273	0	Site clearance survey
10/13/2011	EP269-EP273	0	Monitoring construction activities
10/13/2011	EP263B-EP267	0	Site clearance survey
10/13/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/13/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/12/2011	Slay Property	0	Site clearance survey
10/12/2011	Slay Property	0	Monitoring construction activities
10/12/2011	EP306-EP312	0	Site clearance survey
10/12/2011	EP291-EP301	0	Monitoring construction activities
10/12/2011	EP269-EP270	0	Site clearance survey
10/12/2011	EP269-EP281	0	Site clearance survey
10/12/2011	EP269-EP281	0	Monitoring construction activities
10/12/2011	EP269-EP270	0	Site clearance survey
10/12/2011	EP311	0	Monitoring construction activities
10/12/2011	EP274-EP278	0	Site clearance survey
10/12/2011	EP274-EP278	0	Monitoring construction activities
10/12/2011	EP269-EP273	0	Site clearance survey
10/12/2011	EP269-EP273	0	Monitoring construction activities
10/12/2011	EP263B-EP267	0	Site clearance survey
10/12/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/12/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/11/2011	Slay Property	0	Site clearance survey
10/11/2011	Slay Property	0	Monitoring construction activities
10/11/2011	EP311	0	Monitoring construction activities
10/11/2011	EP306-EP312	0	Site clearance survey
10/11/2011	EP306-EP312	0	Afternoon perimeter survey
10/11/2011	EP300-EP306	0	Site clearance survey
10/11/2011	EP291-EP301	0	Monitoring construction activities
10/11/2011	EP269-EP273	0	Site clearance survey
10/11/2011	EP269-EP273	0	Monitoring construction activities
10/11/2011	EP269-EP270	0	Site clearance survey
10/11/2011	EP269-EP270	0	Monitoring construction activities
10/11/2011	EP274-EP278	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
10/11/2011	EP274-EP278	0	Monitoring construction activities
10/11/2011	EP263B-EP267	0	Site clearance survey
10/11/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/11/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/10/2011	Slay Property	0	Site clearance survey
10/10/2011	Slay Property	0	Monitoring construction activities
10/10/2011	EP306-EP312	0	Site clearance survey
10/10/2011	EP306-EP312	0	Afternoon perimeter survey
10/10/2011	EP305	0	Monitoring construction activities
10/10/2011	EP300-EP306	0	Site clearance survey
10/10/2011	EP300-EP306	0	Monitoring construction activities
10/10/2011	EP300-EP306	0	Site clearance survey
10/10/2011	EP291-EP301	0	Monitoring construction activities
10/10/2011	EP269-EP281	9	Sheep were seen entering I-8 Island during Site Clearance survey
10/10/2011	EP269-EP273	0	Site clearance survey
10/10/2011	EP269-EP273	0	Monitoring construction activities
10/10/2011	EP259-3	0	Monitoring construction activities
10/10/2011	EP274-EP278	0	Site clearance survey
10/10/2011	EP274-EP278	0	Monitoring construction activities
10/10/2011	EP263B-EP267	0	Site clearance survey
10/10/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/10/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/9/2011	EP306-EP312	0	Site clearance survey
10/9/2011	EP306-EP312	0	Monitoring construction activities
10/9/2011	EP300-EP306	0	Site clearance survey
10/9/2011	EP300-EP306	0	Monitoring construction activities
10/9/2011	EP300-EP306	0	Site clearance survey
10/9/2011	EP300-EP306	0	Monitoring construction activities
10/9/2011	EP269-EP273	0	Site clearance survey
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP269-EP270	0	Monitoring construction activities
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP256-3	0	Monitoring construction activities
10/9/2011	EP274-EP278	0	Site clearance survey
10/9/2011	EP274-EP278	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP269-EP270	0	Monitoring construction activities
10/9/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/9/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/8/2011	EP300-EP306	0	Site clearance survey
10/8/2011	EP300-EP306	0	Monitoring construction activity
10/8/2011	EP300-EP306	0	Site clearance survey
10/8/2011	EP300-EP306	0	Morning perimeter survey
10/8/2011	EP291-EP301	0	Monitoring construction activity
10/8/2011	EP278-1	0	Monitoring construction activity
10/8/2011	EP269-EP273	0	Site clearance survey
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP269-EP270	0	Monitoring construction activity
10/8/2011	EP269/EP270 Pullsite	0	Monitoring construction activity
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP259-3	0	Monitoring construction activity
10/8/2011	EP274-EP278	0	Site clearance survey
10/8/2011	EP274-EP278	0	Monitoring construction activity
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP269-EP270	0	Monitoring construction activity
10/8/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/8/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/7/2011	Slay Property	0	Site clearance survey
10/7/2011	EP306-EP312	0	Site clearance survey
10/7/2011	EP306-EP312	0	Morning perimeter survey
10/7/2011	EP300-EP306	0	Site clearance survey
10/7/2011	EP300-EP306	0	Monitoring construction activity
10/7/2011	EP300-EP306	0	Site clearance survey
10/7/2011	EP300-EP306	0	Morning perimeter survey
10/7/2011	EP291-EP301	0	Site clearance survey
10/7/2011	EP269-EP273	0	Site clearance survey
10/7/2011	EP269-EP270	0	Site clearance survey
10/7/2011	EP269-EP270	0	Monitoring construction activity
10/7/2011	EP269-EP270	0	Site clearance survey
10/7/2011	EP259-3	0	Monitoring construction activity

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
10/7/2011	EP274-EP278	0	Site clearance survey
10/7/2011	EP274-EP278	0	Monitoring construction activity
10/7/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/7/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/6/2011	Slay Property	0	Site clearance survey
10/6/2011	Slay Property	0	Monitoring construction activity
10/6/2011	EP306-EP312	0	Site clearance survey
10/6/2011	EP306-EP312	0	Monitoring construction activity
10/6/2011	EP291-EP301	0	Site clearance survey
10/6/2011	EP269-EP273	0	Site clearance survey
10/6/2011	EP269-EP270	0	Site clearance survey
10/6/2011	EP269-EP270	0	Monitoring construction activity
10/6/2011	EP269-EP281	0	Site clearance survey
10/6/2011	EP269-EP270	0	Site clearance survey
10/6/2011	EP263B-EP267	0	Site clearance survey
10/6/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/6/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/5/2011	Slay Property	0	Site clearance survey
10/5/2011	Slay Property	0	Monitoring construction activity
10/5/2011	EP303-2	0	Monitoring construction activity
10/5/2011	EP291-EP301	0	Site clearance survey
10/5/2011	EP269-EP273	0	Site clearance survey
10/5/2011	EP269-EP270	0	Site clearance survey
10/5/2011	EP269-EP270	0	Monitoring construction activity
10/5/2011	EP274-EP278	0	Site clearance survey
10/5/2011	EP274-EP278	0	Monitoring construction activity
10/5/2011	EP269-EP281	0	Site clearance survey
10/5/2011	EP269-EP270	0	Site clearance survey
10/5/2011	EP263B-EP267	0	Site clearance survey
10/5/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/5/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/4/2011	Slay Property	0	Site clearance survey
10/4/2011	Slay Property	0	Monitoring construction activity
10/4/2011	EP300-EP306	0	Site clearance survey
10/4/2011	EP300-EP306	0	Monitoring construction activity

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
10/4/2011	EP269-EP273	0	Site clearance survey
10/4/2011	EP269-EP270	0	Site clearance survey
10/4/2011	EP269-EP270	0	Monitoring construction activity
10/4/2011	EP256-EP263A	0	Site clearance survey
10/4/2011	EP274-EP278	0	Site clearance survey
10/4/2011	EP274-EP278	0	Monitoring construction activity
10/4/2011	EP263B-EP267	0	Site clearance survey
10/3/2011	Slay Property	0	Site clearance survey
10/3/2011	Slay Property	0	Monitoring construction activity
10/3/2011	EP300-EP306	0	Site clearance survey
10/3/2011	EP300-EP306	0	Monitoring construction activity
10/3/2011	EP300-EP306	0	Site clearance survey
10/3/2011	EP300-EP306	0	Morning perimeter survey
10/3/2011	EP291-EP341	0	Site clearance survey
10/3/2011	EP279-EP294	0	Site clearance survey
10/3/2011	EP269-EP273	0	Site clearance survey
10/3/2011	EP269-EP273	0	Monitoring construction activity
10/3/2011	EP263B-EP267	0	Site clearance survey
10/3/2011	EP263B-EP267	0	Monitoring construction activity
10/3/2011	EP256-EP263A	0	Site clearance survey
10/3/2011	EP274-EP278	0	Site clearance survey
10/3/2011	EP274-EP278	0	Monitoring construction activity
10/3/2011	EP263B-EP267	0	Site clearance survey
10/2/2011	EP300-EP306	0	Site clearance survey
10/2/2011	EP300-EP306	0	Monitoring construction activity
10/2/2011	EP269-EP281	0	Afternoon perimeter survey
10/2/2011	EP269-EP273	0	Afternoon perimeter survey
10/1/2011	EP300-EP306	0	Site clearance survey
10/1/2011	EP300-EP306	0	Monitoring construction activities
10/1/2011	EP300-EP306	0	Site clearance survey
10/1/2011	EP300-EP306	0	Morning perimeter survey
10/1/2011	EP269-EP273 and EP256-EP261	0	Site clearance survey
10/1/2011	EP269-EP273	0	Site clearance survey
10/1/2011	EP269-EP270	0	Site clearance survey
10/1/2011	EP274-EP278	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
10/1/2011	EP274-EP278	0	Monitoring construction activities
9/30/2011	Slay Property	0	Site clearance survey
9/30/2011	Slay Property	0	Monitoring construction activities
9/30/2011	EP300-EP312	0	Site clearance survey
9/30/2011	EP300-EP312	0	Monitoring construction activities
9/30/2011	EP300-EP306	0	Site clearance survey
9/30/2011	EP300-EP306	0	Monitoring construction activities
9/30/2011	EP291-EP348	0	Monitoring construction activities
9/30/2011	EP290-EP294, EP300-EP312	0	Site clearance survey
9/30/2011	EP290-EP294, EP300-EP312	0	Monitoring construction activities
9/30/2011	EP269-EP273	0	Site clearance survey
9/30/2011	EP269-EP273	0	Monitoring construction activities
9/30/2011	EP269-EP281	0	Site clearance survey
9/30/2011	EP279-EP294	0	Site clearance survey
9/30/2011	EP274-EP278	0	Site clearance survey
9/30/2011	EP274-EP278	0	Monitoring construction activities
9/30/2011	EP263-B-EP267	0	Site clearance survey
9/30/2011	EP256-EP263A, AER, Fromm CY	0	Site clearance survey
9/30/2011	EP256-EP263A, AER, Fromm CY	0	Monitoring construction activities
9/29/2011	Slay Property	0	Site clearance survey
9/29/2011	Slay Property	0	Monitoring construction activities
9/29/2011	EP300-EP312	0	Site clearance survey
9/29/2011	EP300-EP306	0	Site clearance survey
9/29/2011	EP300-EP306	0	Monitoring construction activities
9/29/2011	EP290-EP294, EP300-EP312	0	Site clearance survey
9/29/2011	EP290-EP294, EP300-EP312	0	Monitoring construction activities
9/29/2011	EP269-EP273	0	Site clearance survey
9/29/2011	EP269-EP273	0	Monitoring construction activities
9/29/2011	EP279-EP294	0	Site clearance survey
9/29/2011	EP274-EP278	0	Site clearance survey
9/29/2011	EP274-EP278	0	Monitoring construction activities
9/29/2011	EP263B-EP267	0	Site clearance survey
9/28/2011	Slay Property	0	Site clearance survey
9/28/2011	Slay Property	0	Monitoring construction activities
9/28/2011	EP330-EP291	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
9/28/2011	EP300-EP306	0	Site clearance survey
9/28/2011	EP300-EP306	0	Monitoring construction activities
9/28/2011	EP290-EP294	0	Site clearance survey
9/28/2011	EP290-EP294	0	Monitoring construction activities
9/28/2011	EP269-EP273	0	Site clearance survey
9/28/2011	EP269-EP273	0	Monitoring construction activities
9/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/28/2011	EP279-EP294	0	Site clearance survey
9/28/2011	EP279-EP294	0	Monitoring construction activities
9/28/2011	EP274-EP278	0	Site clearance survey
9/28/2011	EP274-EP278	0	Monitoring construction activities
9/28/2011	EP263B-EP267	0	Site clearance survey
9/27/2011	Slay Property	0	Site clearance survey
9/27/2011	Slay Property	0	Monitoring construction activities
9/27/2011	EP339-EP291	0	Site clearance survey
9/27/2011	EP309	0	Monitoring construction activities
9/27/2011	EP300-EP312	0	Site clearance survey
9/27/2011	EP300-EP312	0	Monitoring construction activities
9/27/2011	EP300-EP306	0	Site clearance survey
9/27/2011	EP278-1	0	Monitoring construction activities
9/27/2011	EP269-EP273	0	Site clearance survey
9/27/2011	EP269-EP273	0	Monitoring construction activities
9/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/27/2011	EP279-EP294	0	Site clearance survey
9/27/2011	EP279-EP294	0	Monitoring construction activities
9/27/2011	EP274-EP278	0	Site clearance survey
9/27/2011	EP274-EP278	0	Monitoring construction activities
9/27/2011	EP263B-EP267	0	Site clearance survey
9/27/2011	AER CY	0	Monitoring construction activities
9/26/2011	EP300-EP306	0	Site clearance survey
9/26/2011	EP300-EP306	0	Monitoring construction activities
9/26/2011	EP300-EP306	0	Site clearance survey
9/26/2011	EP300-EP312	0	Site clearance survey
9/26/2011	EP300-EP312	0	Monitoring construction activities
9/26/2011	EP291-EP301	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
9/26/2011	EP278-1, EP270-2	0	Monitoring construction activities
9/26/2011	EP274-EP278	0	Site clearance survey
9/26/2011	EP274-EP278	0	Monitoring construction activities
9/26/2011	EP269-EP273	0	Site clearance survey
9/26/2011	EP269-EP273	0	Monitoring construction activities
9/26/2011	EP269-EP270	0	Morning perimeter survey
9/26/2011	EP269-EP270	0	Monitoring construction activities
9/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/26/2011	EP279-EP294	0	Site clearance survey
9/26/2011	EP279-EP294	0	Monitoring construction activities
9/26/2011	EP269-EP271, EP256-EP263, AER & Fromm CY	0	Site clearance survey
9/26/2011	EP269-EP271, EP256-EP263, AER & Fromm CY	0	Monitoring construction activities
9/26/2011	EP263B-EP267	0	Site clearance survey
9/26/2011	CP88	0	Site clearance survey
9/26/2011	CP88	0	Monitoring construction activities
9/25/2011	EP300-EP306	0	Site clearance survey
9/25/2011	EP300-EP306	0	Monitoring construction activities
9/25/2011	EP300-EP306	0	Morning perimeter survey
9/25/2011	EP278	0	Monitoring construction activities
9/25/2011	EP274-EP278	0	Site clearance survey
9/25/2011	EP274-EP278	0	Monitoring construction activities
9/25/2011	EP271-2	0	Monitoring construction activities
9/25/2011	EP269-EP270	0	Morning perimeter survey
9/25/2011	EP269-EP270	0	Monitoring construction activities
9/25/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/25/2011	EP279-EP294	0	Site clearance survey
9/25/2011	EP279-EP294	0	Monitoring construction activities
9/25/2011	EP269-EP273	0	Site clearance survey
9/25/2011	EP269-EP273	0	Monitoring construction activities
9/25/2011	EP263B-EP267	0	Site clearance survey
9/24/2011	EP300-EP306	0	Site clearance survey
9/24/2011	EP300-EP306	0	Monitoring construction activities
9/24/2011	EP300-EP306	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
9/24/2011	EP300-EP306	0	Monitoring construction activities
9/24/2011	EP291/EP292 Pullsite	0	Monitoring construction activities
9/24/2011	EP274-EP278	0	Site clearance survey
9/24/2011	EP274-EP278	0	Monitoring construction activities
9/24/2011	EP274	0	Monitoring construction activities
9/24/2011	EP269-EP270	0	Site clearance survey
9/24/2011	EP269-EP270	0	Monitoring construction activities
9/24/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/24/2011	EP279-EP294	0	Site clearance survey
9/24/2011	EP279-EP294	0	Monitoring construction activities
9/24/2011	EP263B-EP267	0	Site clearance survey
9/23/2011	EP300-EP306	0	Site clearance survey
9/23/2011	EP300-EP306	0	Monitoring construction activities
9/23/2011	EP300-EP312	0	Site clearance survey
9/23/2011	EP300-EP312	0	Monitoring construction activities
9/23/2011	EP274-1	0	Monitoring construction activities
9/23/2011	EP269-EP271	0	Site clearance survey
9/23/2011	EP269-EP271	0	Monitoring construction activities
9/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/23/2011	EP279-EP294	0	Site clearance survey
9/23/2011	EP279-EP294	0	Monitoring construction activities
9/23/2011	EP278-1	0	Monitoring construction activities
9/23/2011	EP263B-EP267	0	Site clearance survey
9/22/2011	EP300-EP312	0	Site clearance survey
9/22/2011	EP300-EP312	0	Monitoring construction activities
9/22/2011	EP300-EP306	0	Site clearance survey
9/22/2011	EP300-EP306	0	Monitoring construction activities
9/22/2011	EP274-1	0	Monitoring construction activities
9/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/22/2011	EP279-EP294	0	Site clearance survey
9/22/2011	EP278-1	0	Monitoring construction activities
9/22/2011	EP274-EP278	0	Site clearance survey
9/22/2011	EP274-EP278	0	Monitoring construction activities
9/22/2011	EP263B-EP267	0	Site clearance survey
9/21/2011	EP300-EP306	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
9/21/2011	EP278-1	0	Monitoring construction activities
9/21/2011	EP274-1	0	Monitoring construction activities
9/21/2011	EP269-EP271, EP300-EP312	0	Site clearance survey
9/21/2011	EP269-EP271, EP300-EP312	0	Monitoring construction activities
9/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/21/2011	EP279-EP294	0	Site clearance survey
9/21/2011	EP279-EP294	0	Monitoring construction activities
9/21/2011	EP274-EP278	0	Site clearance survey
9/21/2011	EP274-EP278	0	Monitoring construction activities
9/21/2011	EP269-EP281	0	Site clearance survey
9/21/2011	EP269-EP281	0	Monitoring construction activities
9/21/2011	EP263B-EP267	0	Site clearance survey
9/20/2011	EP300-EP306	0	Site clearance survey
9/20/2011	EP278-1	0	Monitoring construction activities
9/20/2011	EP269-EP273	0	Site clearance survey
9/20/2011	EP269-EP273	0	Monitoring construction activities
9/20/2011	EP269-EP271	0	Site clearance survey
9/20/2011	EP269-EP271	0	Monitoring construction activities
9/20/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/20/2011	EP279-EP294	0	Site clearance survey
9/20/2011	EP279-EP294	0	Monitoring construction activities
9/20/2011	EP274-EP278	0	Site clearance survey
9/20/2011	EP274-EP278	0	Monitoring construction activities
9/20/2011	EP269-EP281	0	Site clearance survey
9/20/2011	EP269-EP281	0	Monitoring construction activities
9/20/2011	EP263B-EP267	0	Site clearance survey
9/19/2011	EP269-EP273	0	Site clearance survey
9/19/2011	EP269-EP273	0	Monitoring construction activities
9/19/2011	EP269-EP271	0	Site clearance survey
9/19/2011	EP269-EP271	0	Monitoring construction activities
9/19/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/19/2011	EP279-EP294	0	Site clearance survey
9/19/2011	EP279-EP294	0	Monitoring construction activities
9/19/2011	EP274-EP278	0	Site clearance survey
9/19/2011	EP274-EP278	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
9/19/2011	EP269-EP281	0	Site clearance survey
9/19/2011	EP269-EP281	0	Monitoring construction activities
9/19/2011	EP263B-EP267	0	Site clearance survey
9/18/2011	EP300-EP306	0	Site clearance survey
9/18/2011	EP300-EP312	0	Site clearance survey
9/18/2011	EP300-EP312	0	Monitoring construction activities
9/18/2011	EP269-EP273	0	Site clearance survey
9/18/2011	EP269-EP273	0	Monitoring construction activities
9/18/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/18/2011	EP279-EP294	0	Site clearance survey
9/18/2011	EP279-EP294	0	Monitoring construction activities
9/18/2011	EP274-EP278	0	Site clearance survey
9/18/2011	EP274-EP278	0	Monitoring construction activities
9/18/2011	EP269-EP281	0	Site clearance survey
9/18/2011	I8 Island	9	Afternoon perimeter survey
9/17/2011	EP300-EP306	0	Site clearance survey
9/17/2011	EP300-EP312	0	Site clearance survey
9/17/2011	EP300-EP312	0	Monitoring construction activities
9/17/2011	EP269-EP273	0	Site clearance survey
9/17/2011	EP269-EP273	0	Monitoring construction activities
9/17/2011	EP274-EP278	0	Site clearance survey
9/17/2011	EP274-EP278	0	Monitoring construction activities
9/17/2011	EP269-EP281	0	Site clearance survey
9/17/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/17/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/16/2011	EP300-EP312	0	Site clearance survey
9/16/2011	EP300-EP312	0	Monitoring construction activities
9/16/2011	EP300-EP306	0	Site clearance survey
9/16/2011	EP269-EP273	0	Site clearance survey
9/16/2011	EP269-EP273	0	Monitoring construction activities
9/16/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/16/2011	EP274-EP278	0	Site clearance survey
9/16/2011	EP274-EP278	0	Monitoring construction activities
9/16/2011	EP269-EP281	0	Site clearance survey
9/16/2011	EP263B-EP267	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
9/16/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/16/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/15/2011	EP300-EP312	0	Site clearance survey
9/15/2011	EP300-EP312	0	Monitoring construction activities
9/15/2011	EP300-EP306	0	Site clearance survey
9/15/2011	EP300-EP306	0	Monitoring construction activities
9/15/2011	EP269-EP273	0	Site clearance survey
9/15/2011	EP269-EP273	0	Monitoring construction activities
9/15/2011	EP256-EP263A, AER	0	Monitoring construction activities
9/15/2011	EP274-EP278	0	Site clearance survey
9/15/2011	EP274-EP278	0	Monitoring construction activities
9/15/2011	EP269-EP281	0	Site clearance survey
9/15/2011	EP269-EP281	0	Monitoring construction activities
9/15/2011	EP263B-EP267	0	Site clearance survey
9/14/2011	EP310-3	0	Monitoring construction activities
9/14/2011	EP300-EP312	0	Site clearance survey
9/14/2011	EP300-EP312	0	Monitoring construction activities
9/14/2011	EP300-EP306	0	Morning perimeter survey
9/14/2011	EP274-1	0	Monitoring construction activities
9/14/2011	EP269-EP273	0	Site clearance survey
9/14/2011	EP269-EP273	0	Monitoring construction activities
9/14/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/14/2011	EP274-EP278	0	Site clearance survey
9/14/2011	EP274-EP278	0	Monitoring construction activities
9/14/2011	EP269-EP281	0	Site clearance survey
9/14/2011	EP269-EP281	0	Monitoring construction activities
9/14/2011	EP263B-EP267	0	Site clearance survey
9/13/2011	EP300-EP312	0	Site clearance survey
9/13/2011	EP300-EP312	0	Monitoring construction activities
9/13/2011	EP300-EP306	0	Morning perimeter survey
9/13/2011	EP269-EP273	0	Site clearance survey
9/13/2011	EP269-EP273	0	Monitoring construction activities
9/13/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/13/2011	EP274-EP278	0	Site clearance survey
9/13/2011	EP274-EP278	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
9/13/2011	EP274-EP278	0	Monitoring construction activities
9/13/2011	EP274	0	Monitoring construction activities
9/13/2011	EP269-EP281	0	Site clearance survey
9/13/2011	EP263B-EP267	0	Site clearance survey
9/12/2011	Mountain Springs Grade Road	15	Morning perimeter survey
9/12/2011	EP305-3, EP310	0	Monitoring construction activities
9/12/2011	EP300-EP312	0	Site clearance survey
9/12/2011	EP300-EP312	0	Monitoring construction activities
9/12/2011	EP300-EP306	0	Site clearance survey
9/12/2011	EP300-EP306	0	Monitoring construction activities
9/12/2011	EP269-EP273	0	Site clearance survey
9/12/2011	EP269-EP273	0	Monitoring construction activities
9/12/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/12/2011	EP274-EP278	0	Site clearance survey
9/12/2011	EP274-EP278	0	Monitoring construction activities
9/12/2011	EP274-EP278	0	Monitoring construction activities
9/12/2011	EP274	0	Monitoring construction activities
9/12/2011	EP269-EP281	0	Monitoring construction activities
9/12/2011	EP263B-EP267	0	Site clearance survey
9/11/2011	EP300-EP312	0	Site clearance survey
9/11/2011	EP300-EP312	0	Monitoring construction activities
9/11/2011	EP300-EP306	0	Site clearance survey
9/11/2011	EP300-EP306	0	Monitoring construction activities
9/11/2011	EP271-2	0	Monitoring construction activities
9/11/2011	EP269-EP271	0	Site clearance survey
9/11/2011	EP269-EP271	0	Monitoring construction activities
9/11/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/11/2011	EP274-EP278	0	Site clearance survey
9/11/2011	EP274-EP278	0	Monitoring construction activities
9/11/2011	EP269-EP273	0	Site clearance survey
9/11/2011	EP269-EP273	0	Monitoring construction activities
9/11/2011	EP263B-EP267	0	Site clearance survey
9/11/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/11/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/10/2011	EP300-EP312	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
9/10/2011	EP300-EP312	0	Monitoring construction activities
9/10/2011	EP300-EP306	0	Site clearance survey
9/10/2011	EP300-EP306	0	Monitoring construction activities
9/10/2011	EP269-EP271	0	Site clearance survey
9/10/2011	EP269-EP271	0	Monitoring construction activities
9/10/2011	EP274-EP278	0	Site clearance survey
9/10/2011	EP274-EP278	0	Monitoring construction activities
9/10/2011	EP269-EP273	0	Morning perimeter survey
9/10/2011	EP269-EP273	0	Monitoring construction activities
9/10/2011	EP269-EP273	0	Evening perimeter survey
9/9/2011	EP300-EP312	0	Site clearance survey
9/9/2011	EP300-EP312	0	Monitoring construction activities
9/9/2011	EP300-EP306	0	Site clearance survey
9/9/2011	EP300-EP306	0	Monitoring construction activities
9/9/2011	EP271-2	0	Monitoring construction activities
9/9/2011	EP269-EP271	0	Site clearance survey
9/9/2011	EP269-EP271	0	Monitoring construction activities
9/9/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/9/2011	EP256-EP263A, AER and Fromm yards	0	Site clearance survey
9/9/2011	EP256-EP263A, AER and Fromm yards	0	Monitoring construction activities
9/9/2011	EP274-EP278	0	Site clearance survey
9/9/2011	EP274-EP278	0	Monitoring construction activities
9/9/2011	EP269-EP273	0	Morning perimeter survey
9/9/2011	EP269-EP273	0	Monitoring construction activities
9/9/2011	EP269-EP273	0	Evening perimeter survey
9/8/2011	EP300-EP312	0	Site clearance survey
9/8/2011	EP300-EP312	0	Monitoring construction activities
9/8/2011	EP271-2	0	Monitoring construction activities
9/8/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/8/2011	EP279-EP294	0	Site clearance survey
9/8/2011	EP279-EP294	0	Monitoring construction activities
9/8/2011	EP274-EP278	0	Site clearance survey
9/8/2011	EP274-EP278	0	Monitoring construction activities
9/8/2011	EP263B-EP267	0	Site clearance survey
9/7/2011	EP306-1	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
9/7/2011	EP300-EP312	0	Site clearance survey
9/7/2011	EP300-EP312	0	Monitoring construction activities
9/7/2011	EP300-EP306	0	Site clearance survey
9/7/2011	EP300-EP306	0	Monitoring construction activities
9/7/2011	EP273	0	Monitoring construction activities
9/7/2011	EP269-EP273	0	Site clearance survey
9/7/2011	EP269-EP273	0	Monitoring construction activities
9/7/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/7/2011	EP278-EP294	0	Morning perimeter survey
9/7/2011	EP278-EP294	0	Monitoring construction activities
9/7/2011	EP278-EP294	0	Evening perimeter survey
9/7/2011	EP274-EP278	0	Site clearance survey
9/7/2011	EP274-EP278	0	Monitoring construction activities
9/7/2011	EP263B-EP267	0	Site clearance survey
9/6/2011	EP300-EP312	0	Site clearance survey
9/6/2011	EP300-EP312	0	Monitoring construction activities
9/6/2011	EP273	0	Monitoring construction activities
9/6/2011	EP269-EP273	0	Site clearance survey
9/6/2011	EP269-EP273	0	Monitoring construction activities
9/6/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/6/2011	EP278-EP294	0	Morning perimeter survey
9/6/2011	EP278-EP294	0	Monitoring construction activities
9/6/2011	EP278-EP294	0	Evening perimeter survey
9/6/2011	EP274-EP278	0	Site clearance survey
9/6/2011	EP274-EP278	0	Monitoring construction activities
9/6/2011	EP263B-EP267	0	Site clearance survey
9/5/2011	EP300-EP312	0	Site clearance survey
9/5/2011	EP269-EP273	0	Site clearance survey
9/5/2011	EP269-EP273	0	Monitoring construction activities
9/5/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/5/2011	EP274-EP294	0	Site clearance survey
9/5/2011	EP263B-EP267	0	Site clearance survey
9/4/2011	EP300-EP312	0	Site clearance survey
9/4/2011	EP300-EP312	0	Monitoring construction activities
9/4/2011	EP269/EP270 Pullsite	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
9/4/2011	EP269-EP281	0	Site clearance survey
9/4/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/4/2011	EP256-EP263A, AER and Fromm yards	0	Site clearance survey
9/4/2011	EP256-EP263A, AER and Fromm yards	0	Monitoring construction activities
9/4/2011	EP279-EP294	0	Site clearance survey
9/4/2011	EP279-EP294	0	Monitoring construction activities
9/4/2011	EP274-EP278	0	Site clearance survey
9/4/2011	EP274-EP278	0	Monitoring construction activities
9/4/2011	EP270	0	Site clearance survey
9/4/2011	EP270	0	Monitoring construction activities
9/3/2011	EP300-EP312	0	Monitoring Construction Activities
9/3/2011	EP300-EP312	0	Site clearance survey
9/3/2011	EP300-EP306	0	Monitoring Construction Activities
9/3/2011	EP300-EP306	0	Site clearance survey
9/3/2011	EP271	0	Monitoring Construction Activities
9/3/2011	EP269-EP273	0	Monitoring Construction Activities
9/3/2011	EP269-EP273	0	Site clearance survey
9/3/2011	EP269-EP281	0	Monitoring Construction Activities
9/3/2011	EP256-EP263A, AER and Fromm Yards	0	Monitoring Construction Activities
9/3/2011	EP256-EP263A, AER and Fromm Yards	0	Site clearance survey
9/3/2011	EP278-EP294	0	Evening perimeter survey
9/3/2011	EP278-EP294	0	Monitoring Construction Activities
9/3/2011	EP278-EP294	0	Morning perimeter survey
9/3/2011	EP269-1 & EP269/EP270 Pull site	0	Monitoring Construction Activities
9/2/2011	I-8 Island	9	Evening perimeter survey 4:45pm - 5:08pm
9/2/2011	I-8 Island	12	Morning perimeter survey 8:35am
9/2/2011	EP300-EP312	0	Monitoring Construction Activities
9/2/2011	EP300-EP312	0	Site clearance survey
9/2/2011	EP272 & EP276	0	Monitoring Construction Activities
9/2/2011	EP269-EP273	0	Monitoring Construction Activities
9/2/2011	EP269-EP273	0	Site clearance survey
9/2/2011	EP256-EP263A, AER and Fromm Yards	0	Monitoring Construction Activities
9/2/2011	EP256-EP263A, AER and Fromm Yards	0	Site clearance survey
9/2/2011	EP278-EP294	0	Evening perimeter survey
9/2/2011	EP278-EP294	0	Monitoring Construction Activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
9/2/2011	EP278-EP294	0	Morning perimeter survey
9/2/2011	EP269-EP272	0	Monitoring Construction Activities
9/2/2011	EP269-EP272	0	Site clearance survey
9/2/2011	EP263B-EP267	0	Site clearance survey
9/1/2011	I-8 Island	12	Evening perimeter survey 4:45pm - 5:40pm
9/1/2011	I-8 Island	12	Morning perimeter survey 8:35am
9/1/2011	EP300-EP312	0	Monitoring Construction Activities
9/1/2011	EP300-EP312	0	Site clearance survey
9/1/2011	EP269-EP273	0	Monitoring Construction Activities
9/1/2011	EP269-EP273	0	Site clearance survey
9/1/2011	EP256-EP263A-2	0	Site clearance survey
9/1/2011	EP255	0	Monitoring Construction Activities
9/1/2011	EP300-EP306	0	Site clearance survey
9/1/2011	EP278-EP294	0	Evening perimeter survey
9/1/2011	EP278-EP294	0	Monitoring Construction Activities
9/1/2011	EP278-EP294	0	Morning perimeter survey
9/1/2011	EP269-EP272	0	Monitoring Construction Activities
9/1/2011	EP269-EP272	0	Site clearance survey
9/1/2011	EP263B-EP267	0	Site clearance survey
8/31/2011	I-8 Island	0	Site clearance survey
8/31/2011	EP308	0	Monitoring Construction Activities
8/31/2011	EP300-EP312	0	Monitoring Construction Activities
8/31/2011	EP300-EP312	0	Site clearance survey
8/31/2011	EP269-EP273	0	Monitoring Construction Activities
8/31/2011	EP269-EP273	0	Site clearance survey
8/31/2011	EP300-EP306	0	Site clearance survey
8/31/2011	EP278-EP294	0	Evening perimeter survey
8/31/2011	EP278-EP294	0	Monitoring Construction Activities
8/31/2011	EP278-EP294	0	Morning perimeter survey
8/31/2011	EP269-EP272	0	Monitoring Construction Activities
8/31/2011	EP263B-EP267	0	Site clearance survey
8/30/2011	I-8 Island	16	Evening perimeter survey 4:30pm
8/30/2011	I-8 Island	9	Morning perimeter survey 9:10am - 9:30am
8/30/2011	EP300-EP312	0	Monitoring Construction Activities
8/30/2011	EP300-EP312	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
8/30/2011	EP269-EP273	0	Monitoring Construction Activities
8/30/2011	EP269-EP273	0	Site clearance survey
8/30/2011	EP300-EP306	0	Site clearance survey
8/30/2011	EP278-EP294	0	Evening perimeter survey
8/30/2011	EP278-EP294	0	Monitoring Construction Activities
8/30/2011	EP278-EP294	0	Morning perimeter survey
8/30/2011	EP274-EP278	0	Monitoring Construction Activities
8/30/2011	EP274-EP278	0	Site clearance survey
8/30/2011	EP269-EP272	0	Monitoring Construction Activities
8/30/2011	EP269-EP272	0	Site clearance survey
8/30/2011	EP263B-EP267	0	Site clearance survey
8/29/2011	I-8 Island	4	Morning perimeter survey 8:55am
8/29/2011	I-8 Island	12	Evening perimeter survey 4:35pm to 5:00pm
8/29/2011	EP300-EP312	0	Monitoring Construction Activities
8/29/2011	EP300-EP312	0	Site clearance survey
8/29/2011	EP278-2	0	Monitoring Construction Activities
8/29/2011	EP269-EP273	0	Monitoring Construction Activities
8/29/2011	EP269-EP273	0	Site clearance survey
8/29/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/29/2011	EP300-EP306	0	Site clearance survey
8/29/2011	EP274-EP278	0	Monitoring Construction Activities
8/29/2011	EP274-EP278	0	Site clearance survey
8/29/2011	EP269-EP272	0	Monitoring Construction Activities
8/29/2011	EP269-EP272	0	Site clearance survey
8/29/2011	EP263B-EP267	0	Site clearance survey
8/28/2011	I-8 Island	15	Morning perimeter survey @9:22am
8/28/2011	EP305	0	Monitoring Construction Activities
8/28/2011	EP281	0	Monitoring Construction Activities
8/28/2011	EP273	0	Monitoring Construction Activities
8/28/2011	EP269-EP273	0	Monitoring Construction Activities
8/28/2011	EP269-EP273	0	Site clearance survey
8/28/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/28/2011	EP300-EP306	0	Morning perimeter survey
8/28/2011	EP278-EP294	0	Evening perimeter survey
8/28/2011	EP278-EP294	0	Monitoring Construction Activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
8/28/2011	EP278-EP294	0	Morning perimeter survey
8/28/2011	EP274-EP278	0	Monitoring Construction Activities
8/28/2011	EP274-EP278	0	Site clearance survey
8/28/2011	EP269-EP272	0	Monitoring Construction Activities
8/28/2011	EP269-EP272	0	Site clearance survey
8/28/2011	EP263-B, EP267	0	Site clearance survey
8/27/2011	I-8 Island	0	Site clearance survey
8/27/2011	EP305	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Site clearance survey
8/27/2011	I-8 Island	0	Morning perimeter survey
8/27/2011	EP305	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Site clearance survey
8/27/2011	EP300-EP306, EP269-EP273	0	Monitoring Construction Activities
8/27/2011	EP272-3	0	Monitoring Construction Activities
8/27/2011	EP261	0	Monitoring Construction Activities
8/27/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/27/2011	EP278-EP294	0	Site clearance survey
8/27/2011	EP278-EP294	0	Monitoring Construction Activities
8/27/2011	EP274-EP278	0	Site clearance survey
8/27/2011	EP274-EP278	0	Monitoring Construction Activities
8/27/2011	EP269-EP272	0	Monitoring Construction Activities
8/27/2011	EP269-EP272	0	Site clearance survey
8/27/2011	EP263B-EP267	0	Site clearance survey
8/26/2011	I-8 Island	0	Morning perimeter survey
8/26/2011	EP269-EP273	0	Monitoring Construction Activities
8/26/2011	EP269-EP273	0	Morning perimeter survey
8/26/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/26/2011	EP300-EP306	0	Monitoring Construction Activities
8/26/2011	EP278-EP294	0	Evening perimeter survey
8/26/2011	EP278-EP294	0	Monitoring Construction Activities
8/26/2011	EP278-EP294	0	Morning perimeter survey
8/26/2011	EP274-EP278	0	Monitoring Construction Activities
8/26/2011	EP274-EP278	0	Site clearance survey
8/26/2011	EP269-EP272	0	Monitoring Construction Activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
8/26/2011	EP269-EP272	0	Morning perimeter survey
8/25/2011	I-8 Island	0	Morning perimeter survey
8/25/2011	EP269-EP273	0	Monitoring Construction Activities
8/25/2011	EP269-EP273	0	Morning perimeter survey
8/25/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/25/2011	EP278-EP294	0	Evening perimeter survey
8/25/2011	EP278-EP294	0	Monitoring Construction Activities
8/25/2011	EP278-EP294	0	Morning perimeter survey
8/25/2011	EP274-EP278	0	Monitoring Construction Activities
8/25/2011	EP274-EP278	0	Site clearance survey
8/25/2011	EP270-EP272	0	Site clearance survey
8/25/2011	EP269-EP272	0	Monitoring Construction Activities
8/25/2011	EP269-EP272	0	Morning perimeter survey
8/24/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/24/2011	EP300-EP312, EP263B-EP267	0	Site clearance survey
8/24/2011	EP269-EP273	0	Monitoring Construction Activities
8/24/2011	EP269-EP273	0	Site clearance survey
8/24/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/24/2011	EP278-EP294	0	Evening perimeter survey
8/24/2011	EP278-EP294	0	Monitoring Construction Activities
8/24/2011	EP278-EP294	0	Morning perimeter survey
8/24/2011	EP274-EP278	0	Monitoring Construction Activities
8/24/2011	EP274-EP278	0	Site clearance survey
8/23/2011	I-8 Island	0	Morning perimeter survey
8/23/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/23/2011	EP300-EP312, EP263B-EP267	0	Site clearance survey
8/23/2011	EP269-EP273	0	Monitoring Construction Activities
8/23/2011	EP269-EP273	0	Site clearance survey
8/23/2011	EP278-EP294	0	Evening perimeter survey
8/23/2011	EP278-EP294	0	Monitoring Construction Activities
8/23/2011	EP278-EP294	0	Morning perimeter survey
8/23/2011	EP274-EP278	0	Monitoring Construction Activities
8/23/2011	EP274-EP278	0	Morning perimeter survey
8/23/2011	EP270-EP272	0	Morning perimeter survey
8/23/2011	EP269-EP272	0	Morning perimeter survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
8/22/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/22/2011	EP300-EP312, EP263B-EP267	0	Morning perimeter survey
8/22/2011	EP269-EP273	0	Monitoring Construction Activities
8/22/2011	EP269-EP273	0	Monitoring Construction Activities
8/22/2011	EP269-EP273	0	Morning perimeter survey
8/22/2011	EP263B	0	Monitoring Construction Activities
8/22/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/22/2011	EP291	0	Monitoring Construction Activities
8/22/2011	EP278-EP294	0	Evening perimeter survey
8/22/2011	EP278-EP294	0	Monitoring Construction Activities
8/22/2011	EP278-EP294	0	Morning perimeter survey
8/21/2011	I-8 Island	11	Evening perimeter survey - 6:00pm
8/21/2011	EP269-EP273	0	Site clearance survey
8/21/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/21/2011	EP256-EP263	0	Monitoring Construction Activities
8/21/2011	EP256-EP263	0	Site clearance survey
8/21/2011	EP279-EP294	0	Afternoon clearance survey
8/21/2011	EP274-EP278	0	Evening perimeter survey
8/21/2011	EP269-EP272	0	Evening perimeter survey
8/21/2011	EP263B-EP267	0	Site clearance survey
8/20/2011	I8 and Moutain Spring Rd	3	Morning perimeter survey 9:20am
8/20/2011	I8 and Moutain Spring Rd	4	Evening perimeter survey 6:40pm
8/20/2011	EP300-EP312	0	Monitoring construction activities
8/20/2011	EP300-EP312	0	Site clearance survey
8/20/2011	EP269-EP273	0	Monitoring construction activities
8/20/2011	EP269-EP273	0	Site clearance survey
8/20/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/20/2011	EP300-EP306	0	Morning perimeter survey
8/20/2011	EP274-EP294	0	Monitoring construction activities
8/20/2011	EP274-EP294	0	Site clearance survey
8/20/2011	EP270-EP271	0	Morning perimeter survey
8/20/2011	EP269-EP271	0	Monitoring construction activities
8/20/2011	EP263B-EP267	0	Site clearance survey
8/19/2011	Radiator Water Tower 17	7	Site clearance survey
8/19/2011	EP298, EP300 & EP307	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
8/19/2011	EP296, EP300	0	Monitoring construction activities
8/19/2011	EP296, EP300	0	Site clearance survey
8/19/2011	EP269-EP273	0	Monitoring construction activities
8/19/2011	EP269-EP273	0	Site clearance survey
8/19/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/19/2011	EP291-EP293	0	Monitoring construction activities
8/19/2011	EP279-EP294	0	Monitoring construction activities
8/19/2011	EP274-EP278	0	Monitoring construction activities
8/19/2011	EP274-EP278	0	Site clearance survey
8/19/2011	EP263B-EP267	0	Site clearance survey
8/18/2011	EP269-EP273	0	Monitoring construction activities
8/18/2011	EP269-EP273	0	Site clearance survey
8/18/2011	EP349, EP293	0	Monitoring construction activities
8/18/2011	EP279-EP312	0	Monitoring construction activities
8/18/2011	EP274-EP278	0	Monitoring construction activities
8/18/2011	EP274-EP278	0	Site clearance survey
8/18/2011	EP263B-EP267	0	Site clearance survey
8/17/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/17/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/17/2011	EP269-EP273	0	Monitoring construction activities
8/17/2011	EP269-EP273	0	Site clearance survey
8/17/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/17/2011	EP279-EP294	0	Monitoring construction activities
8/17/2011	EP279-EP294	0	Site clearance survey
8/17/2011	EP274-EP278	0	Monitoring construction activities
8/17/2011	EP274-EP278	0	Site clearance survey
8/17/2011	EP263B-EP267	0	Site clearance survey
8/16/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/16/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/16/2011	EP269-EP273	0	Monitoring construction activities
8/16/2011	EP269-EP273	0	Site clearance survey
8/16/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/16/2011	EP279-EP294	0	Monitoring construction activities
8/16/2011	EP279-EP294	0	Site clearance survey
8/16/2011	EP274-EP278	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
8/16/2011	EP274-EP278	0	Site clearance survey
8/16/2011	EP265	0	Monitoring construction activities
8/16/2011	EP263B-EP267	0	Site clearance survey
8/15/2011	Fromm and AER Construction Yard	0	Monitoring construction activities
8/15/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/15/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/15/2011	EP294	0	Monitoring construction activities
8/15/2011	EP269-EP273	0	Site clearance survey
8/15/2011	EP269-EP273	0	Monitoring construction activities
8/15/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/15/2011	EP279-EP294	0	Monitoring construction activities
8/15/2011	EP279-EP294	0	Site clearance survey
8/15/2011	EP274-EP278	0	Monitoring construction activities
8/15/2011	EP274-EP278	0	Site clearance survey
8/15/2011	EP263B-EP267	0	Site clearance survey
8/14/2011	EP274-EP278	0	Monitoring construction activities
8/14/2011	EP263B-EP267	0	Site clearance survey
8/14/2011	EP274-EP278	0	Evening perimeter survey
8/14/2011	EP279-294	0	Monitoring construction activities
8/14/2011	EP269-EP273	0	Evening perimeter survey
8/14/2011	EP300-EP312	0	Site clearance survey
8/14/2011	EP300-EP312	0	Monitoring construction activities
8/13/2011	Fromm Construction Yard	0	Site clearance survey
8/13/2011	I-8 Island	19	Morning perimeter survey at 9:54am - 10:45am
8/13/2011	I-8 Island	6	Evening perimeter survey at 4:35pm
8/13/2011	EP263B-EP267	0	Site clearance survey
8/13/2011	EP269-EP271	0	Monitoring construction activities
8/13/2011	EP270-EP271	0	Monitoring construction activities
8/13/2011	EP274-EP278	0	Monitoring construction activities
8/13/2011	EP279-294	0	Monitoring construction activities
8/13/2011	EP300-EP306	0	Monitoring construction activities
8/13/2011	EP259B	0	Site clearance survey
8/13/2011	EP269-EP273	0	Monitoring construction activities
8/13/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/13/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
8/12/2011	I-8 Island	26	Evening perimeter survey at 4:25pm - 5:45
8/12/2011	EP263B-EP267	0	Site clearance survey
8/12/2011	EP269-EP271	0	Monitoring construction activities
8/12/2011	EP270-EP271	0	Monitoring construction activities
8/12/2011	EP279-294	0	Monitoring construction activities
8/12/2011	EP300-EP306	0	Monitoring construction activities
8/12/2011	EP300-EP312	0	Monitoring construction activities
8/12/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/12/2011	EP259B	0	Site clearance survey
8/12/2011	EP269-EP273	0	Monitoring construction activities
8/12/2011	EP274-EP278, EP290-EP294	0	Site clearance survey
8/12/2011	EP274-EP278, EP290-EP294	0	Monitoring construction activities
8/12/2011	EP294	0	Monitoring construction activities
8/11/2011	I-8 Island	12	Morning perimeter survey at 10:50am
8/11/2011	I-8 Island	28	Evening perimeter survey at 6:19pm
8/11/2011	EP263B-EP267	0	Site clearance survey
8/11/2011	EP269-EP271	0	Monitoring construction activities
8/11/2011	EP270-EP271	0	Monitoring construction activities
8/11/2011	EP279-294	0	Monitoring construction activities
8/11/2011	EP300-EP306	0	Monitoring construction activities
8/11/2011	EP300-EP312	0	Monitoring construction activities
8/11/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/11/2011	EP259B	0	Site clearance survey
8/11/2011	EP269-EP273	0	Monitoring construction activities
8/11/2011	EP274-EP278	0	Site clearance survey
8/11/2011	EP274-EP278	0	Monitoring construction activities
8/11/2011	EP292-EP356	0	Monitoring construction activities
8/11/2011	EP294	0	Monitoring construction activities
8/10/2011	I-8 Island	16	Evening perimeter survey at 4:55pm - 5:08
8/10/2011	EP263B-EP267	0	Site clearance survey
8/10/2011	EP269-EP271	0	Monitoring construction activities
8/10/2011	EP270-EP271	0	Monitoring construction activities
8/10/2011	EP273	0	Monitoring construction activities
8/10/2011	EP300-EP306	0	Monitoring construction activities
8/10/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
8/10/2011	EP259B	0	Site clearance survey
8/10/2011	EP269-EP273	0	Monitoring construction activities
8/10/2011	EP294	0	Monitoring construction activities
8/10/2011	EP300-EP312	0	Morning perimeter survey
8/10/2011	EP300-EP312	0	Monitoring construction activities
8/10/2011	EP300-EP312	0	Evening perimeter survey
8/10/2011	EP227, EP232, EP258, EP314, EP317, EP348, EP349	0	Site clearance survey
8/9/2011	I-8 Island	3	Morning perimeter survey at 10:30am
8/9/2011	I-8 Island	18	Evening perimeter survey at 4:30pm - 5:06pm
8/9/2011	EP263B-EP267	0	Site clearance survey
8/9/2011	EP269-EP271	0	Monitoring construction activities
8/9/2011	EP270-EP271	0	Monitoring construction activities
8/9/2011	EP270-EP273	0	Monitoring construction activities
8/9/2011	EP274-EP278	0	Monitoring construction activities
8/9/2011	EP279-294	0	Monitoring construction activities
8/9/2011	EP300-EP306	0	Monitoring construction activities
8/9/2011	EP305	0	Monitoring construction activities
8/9/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/9/2011	EP269-EP273	0	Site clearance survey
8/9/2011	EP294	0	Monitoring construction activities
8/9/2011	EP300-EP312	0	Morning perimeter survey
8/9/2011	EP300-EP312	0	Monitoring construction activities
8/9/2011	EP300-EP312	0	Evening perimeter survey
8/8/2011	I-8 Island	4	Morning perimeter survey at 9:45am - 9:55am
8/8/2011	I-8 Island	22	Evening perimeter survey at 4:24pm - 5:14pm
8/8/2011	EP279-294	3	Monitoring construction activities
8/8/2011	EP263B-EP267	0	Site clearance survey
8/8/2011	EP269-EP271	0	Monitoring construction activities
8/8/2011	EP270-EP271	0	Monitoring construction activities
8/8/2011	EP273	0	Monitoring construction activities
8/8/2011	EP274-EP278	0	Monitoring construction activities
8/8/2011	EP300-EP306	0	Monitoring construction activities
8/8/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/8/2011	EP269-EP273	0	Site clearance survey
8/8/2011	EP294	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
8/8/2011	EP300-EP312	0	Morning perimeter survey
8/8/2011	EP300-EP312	0	Monitoring construction activities
8/8/2011	EP300-EP312	0	Evening perimeter survey
8/8/2011	EP301-EP324, EP259-3, EP259B	0	Monitoring construction activities
8/8/2011	EP290-EP300	0	Site clearance survey
8/7/2011	I-8 Island	27	Evening perimeter survey at 6:00pm - 6:45
8/7/2011	EP263B-EP267	0	Site clearance survey
8/7/2011	EP270-EP271	0	Monitoring construction activities
8/7/2011	EP274-EP278	0	Monitoring construction activities
8/7/2011	EP279-294	0	Monitoring construction activities
8/7/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/7/2011	EP269-EP273	0	Evening perimeter survey
8/7/2011	EP300-EP312	0	Evening perimeter survey
8/6/2011	EP278 & EP277	0	Monitoring construction activities
8/6/2011	I-8 Island	12	Afternoon perimeter survey at 1:20pm
8/6/2011	EP263B-EP267	0	Site clearance survey
8/6/2011	EP269-EP271	0	Monitoring construction activities
8/6/2011	EP270-EP271	0	Monitoring construction activities
8/6/2011	EP274-EP278	0	Monitoring construction activities
8/6/2011	EP279-294	0	Monitoring construction activities
8/6/2011	EP300-EP306	0	Monitoring construction activities
8/6/2011	EP262, EP266, EP267	0	Site clearance survey
8/6/2011	EP269-EP273	0	Monitoring construction activities
8/6/2011	EP307-EP315	0	Morning perimeter survey
8/6/2011	EP307-EP316	0	Monitoring construction activities
8/6/2011	EP307-EP317	0	Evening perimeter survey
8/5/2011	EP263B-EP267	0	Site clearance survey
8/5/2011	EP271, EP273, EP274, EP277 and EP278	0	Monitoring construction activities
8/5/2011	EP274-EP278	0	Monitoring construction activities
8/5/2011	EP279-294	0	Monitoring construction activities
8/5/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/5/2011	EP269-EP273	0	Monitoring construction activities
8/5/2011	EP294	0	Monitoring construction activities
8/5/2011	EP307-EP312	0	Morning perimeter survey
8/5/2011	EP307-EP313	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
8/5/2011	EP307-EP314	0	Evening perimeter survey
8/4/2011	I-8 Island	23	Evening perimeter survey at 4:00pm - 4:33pm
8/4/2011	EP263B-EP267	0	Site clearance survey
8/4/2011	EP269-EP271	0	Monitoring construction activities
8/4/2011	EP270-EP271	0	Monitoring construction activities
8/4/2011	EP274-EP278	0	Monitoring construction activities
8/4/2011	EP279-294	0	Monitoring construction activities
8/4/2011	EP300-EP306	0	Monitoring construction activities
8/4/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/4/2011	EP269-EP273	0	Monitoring construction activities
8/4/2011	EP294	0	Monitoring construction activities
8/3/2011	I-8 Island	17	Evening perimeter survey at 5:45pm - 6:05pm
8/3/2011	EP256-EP263	0	Monitoring construction activities
8/3/2011	EP263B-EP267	0	Site clearance survey
8/3/2011	EP269-EP271	0	Monitoring construction activities
8/3/2011	EP270-EP271	0	Monitoring construction activities
8/3/2011	EP274-EP278	0	Monitoring construction activities
8/3/2011	EP279-294	0	Monitoring construction activities
8/3/2011	EP290-EP312	0	Monitoring construction activities
8/3/2011	EP300-EP306	0	Monitoring construction activities
8/3/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/3/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
8/3/2011	EP269-EP273	0	Monitoring construction activities
8/3/2011	EP271	0	Monitoring construction activities
8/3/2011	EP294	0	Monitoring construction activities
8/3/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/3/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/3/2011	I-8 Island	0	Monitoring construction activities
8/2/2011	I-8 Island	12	Morning perimeter survey at 9:50am
8/2/2011	I-8 Island	23	Evening perimeter survey at 4:30pm
8/2/2011	EP263B-EP267	0	Site clearance survey
8/2/2011	EP269-EP271	0	Monitoring construction activities
8/2/2011	EP270-EP271	0	Monitoring construction activities
8/2/2011	EP279-294	0	Monitoring construction activities
8/2/2011	EP300-EP306	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
8/2/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
8/2/2011	EP269-EP273	0	Monitoring construction activities
8/2/2011	EP271 and EP273	0	Monitoring construction activities
8/2/2011	EP273	0	Monitoring construction activities
8/2/2011	EP274-EP278	0	Monitoring construction activities
8/2/2011	EP294	0	Monitoring construction activities
8/1/2011	I-8 Island	19	Morning perimeter survey at 10:00 - 10:20am
8/1/2011	I-8 Island	1	Evening perimeter survey at 4:30pm
8/1/2011	EP263B-EP267	0	Site clearance survey
8/1/2011	EP269-EP271	0	Monitoring construction activities
8/1/2011	EP270-EP271	0	Monitoring construction activities
8/1/2011	EP274-EP278	0	Monitoring construction activities
8/1/2011	EP279-294	0	Monitoring construction activities
8/1/2011	EP290-EP312	0	Monitoring construction activities
8/1/2011	EP300-EP306	0	Monitoring construction activities
8/1/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/1/2011	EP269	0	Monitoring construction activities
8/1/2011	EP269-EP273	0	Monitoring construction activities
8/1/2011	EP272	0	Monitoring construction activities
8/1/2011	EP291 & EP301-EP304	0	Monitoring construction activities
8/1/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/1/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
7/31/2011	I-8 Island	24	Evening perimeter survey at 5:55pm
7/31/2011	EP263B-EP267	0	Site clearance survey
7/31/2011	EP270-EP271	0	Monitoring construction activities
7/31/2011	EP274-EP278	0	Monitoring construction activities
7/31/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/31/2011	EP269-EP273	0	Evening perimeter survey
7/31/2011	EP279-EP294	0	Site clearance survey
7/31/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
7/30/2011	EP271	1	Morning perimeter survey at 7:00am
7/30/2011	EP256-EP263A-2, AER Yard	6	Monitoring during construction activities. These sheep were outside of all work areas and associated buffers and did not impact work.
7/30/2011	I-8 Island	11	Morning perimeter survey at 10:15am - 11:07
7/30/2011	I-8 Island	7	Evening perimeter survey at 4:12pm

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
7/30/2011	EP263B-EP267	0	Site clearance survey
7/30/2011	EP269	0	Site clearance survey
7/30/2011	EP269-EP272	0	Monitoring construction activities
7/30/2011	EP270-EP271	0	Monitoring construction activities
7/30/2011	EP274-EP278	0	Monitoring construction activities
7/30/2011	EP279-294	0	Monitoring construction activities
7/30/2011	EP300-EP306	0	Monitoring construction activities
7/30/2011	EP269	0	Monitoring construction activities
7/30/2011	EP269-EP273	0	Site clearance survey
7/30/2011	EP270-EP271	0	Monitoring construction activities
7/30/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
7/30/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
7/29/2011	I-8 Island	14	Morning perimeter survey at 8:55am
7/29/2011	I-8 Island	2	Evening perimeter survey at 4:00pm
7/29/2011	EP263B-EP267	0	Site clearance survey
7/29/2011	EP269	0	Site clearance survey
7/29/2011	EP269-EP272	0	Monitoring construction activities
7/29/2011	EP270-EP271	0	Monitoring construction activities
7/29/2011	EP274-EP278	0	Monitoring construction activities
7/29/2011	EP279-294	0	Monitoring construction activities
7/29/2011	EP300-EP306	0	Monitoring construction activities
7/29/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/29/2011	EP269	0	Monitoring construction activities
7/29/2011	EP269-EP273	0	Site clearance survey
7/29/2011	EP270	0	Monitoring construction activities
7/29/2011	EP300-EP312	0	Morning perimeter survey
7/29/2011	EP300-EP312	0	Monitoring construction activities
7/29/2011	EP300-EP312	0	Evening perimeter survey
7/29/2011	EP303	0	Monitoring construction activities
7/28/2011	EP269	4	Monitoring during construction activities
7/28/2011	I-8 Island	11	Morning perimeter survey at 9:19am
7/28/2011	I-8 Island	8	Evening perimeter survey at 4:00pm - 4:50pm
7/28/2011	EP279-294	0	Monitoring construction activities
7/28/2011	EP263B-EP267	0	Site clearance survey
7/28/2011	EP269	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
7/28/2011	EP270-EP271	0	Monitoring construction activities
7/28/2011	EP274-EP278	0	Monitoring construction activities
7/28/2011	EP300-EP306	0	Monitoring construction activities
7/28/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/28/2011	EP269	0	Monitoring construction activities
7/28/2011	EP270	0	Monitoring construction activities
7/28/2011	EP300-EP312	0	Morning perimeter survey
7/28/2011	EP300-EP312	0	Monitoring construction activities
7/28/2011	EP300-EP312	0	Evening perimeter survey
7/28/2011	AER CY	0	Site clearance survey
7/27/2011	I-8 Island	13	Evening perimeter survey at 6:30pm - 7:00pm
7/27/2011	EP279-294	0	Monitoring construction activities
7/27/2011	EP263B-EP267	0	Site clearance survey
7/27/2011	EP268 - EP263	0	Monitoring construction activities
7/27/2011	EP269	0	Site clearance survey
7/27/2011	EP270-EP271	0	Monitoring construction activities
7/27/2011	EP274-EP278	0	Monitoring construction activities
7/27/2011	EP300-EP306	0	Monitoring construction activities
7/27/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/27/2011	EP269-EP273	0	Morning perimeter survey
7/27/2011	EP269-EP273	0	Evening perimeter survey
7/27/2011	EP300-EP312	0	Morning perimeter survey
7/27/2011	EP300-EP312	0	Monitoring construction activities
7/27/2011	EP300-EP312	0	Evening perimeter survey
7/26/2011	Devils Canyon Bridge1, Hwy 8	1	Monitoring during construction activities
7/26/2011	I-8 Island	24	Morning perimeter survey at 9:46am - 10:45am
7/26/2011	I-8 Island	7	Evening perimeter survey at 6:17pm - 6:50pm
7/26/2011	EP263B-EP267	0	Site clearance survey
7/26/2011	EP269	0	Site clearance survey
7/26/2011	EP270	0	Monitoring construction activities
7/26/2011	EP274-EP278	0	Monitoring construction activities
7/26/2011	EP279-294	0	Monitoring construction activities
7/26/2011	EP300-EP306	0	Monitoring construction activities
7/26/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/26/2011	EP269-EP273	0	Morning perimeter survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
7/26/2011	EP269-EP273	0	Evening perimeter survey
7/26/2011	EP300-EP312	0	Monitoring construction activities
7/26/2011	EP300-EP312	0	Morning perimeter survey
7/26/2011	EP300-EP312	0	Monitoring construction activities
7/26/2011	EP300-EP312	0	Evening perimeter survey
7/25/2011	I-8 Island	21	Morning perimeter survey at 8:47am
7/25/2011	I-8 Island	20	Evening perimeter survey at 6:37am
7/25/2011	EP263B-EP267	0	Site clearance survey
7/25/2011	EP269	0	Site clearance survey
7/25/2011	EP270	0	Monitoring construction activities
7/25/2011	EP274-EP278	0	Monitoring construction activities
7/25/2011	EP279-294	0	Monitoring construction activities
7/25/2011	EP300-EP306	0	Monitoring construction activities
7/25/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/25/2011	EP269-EP273	0	Morning perimeter survey
7/25/2011	EP269-EP273	0	Evening perimeter survey
7/25/2011	EP300 & EP302	0	Monitoring construction activities
7/25/2011	EP300-EP312	0	Morning perimeter survey
7/25/2011	EP300-EP312	0	Monitoring construction activities
7/25/2011	EP300-EP312	0	Evening perimeter survey
7/25/2011	EP276	0	Monitoring construction activities
7/24/2011	I-8 Island	13	Evening perimeter survey at 6:25pm
7/24/2011	EP263B-EP267	0	Site clearance survey
7/24/2011	EP269	0	Site clearance survey
7/24/2011	EP270	0	Monitoring construction activities
7/24/2011	EP279-294	0	Monitoring construction activities
7/24/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/24/2011	EP269-EP273	0	Evening perimeter survey
7/24/2011	EP274-EP278	0	Evening perimeter survey
7/24/2011	EP300-EP312	0	Evening perimeter survey
7/23/2011	EP263B-EP267	0	Site clearance survey
7/23/2011	EP269	0	Site clearance survey
7/23/2011	EP270	0	Monitoring construction activities
7/23/2011	EP279-294	0	Monitoring construction activities
7/23/2011	EP300-EP312	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
7/23/2011	EP300-EP312	0	Site clearance survey
7/23/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/23/2011	EP269-EP276	0	Morning perimeter survey
7/23/2011	EP274-EP278	0	Morning perimeter survey
7/23/2011	EP274-EP278	0	Evening perimeter survey
7/23/2011	I-8 Island	0	Morning perimeter survey
7/22/2011	I-8 Island	18	Evening perimeter survey at 6:35pm
7/22/2011	EP263B-EP267	0	Site clearance survey
7/22/2011	EP269	0	Site clearance survey
7/22/2011	EP269-EP270	0	Monitoring construction activities
7/22/2011	EP270	0	Monitoring construction activities
7/22/2011	EP300-EP312	0	Monitoring construction activities
7/22/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/22/2011	EP269-EP273	0	Morning perimeter survey
7/22/2011	EP269-EP273	0	Evening perimeter survey
7/22/2011	EP274-EP278	0	Site clearance survey
7/22/2011	EP274-EP278	0	Monitoring construction activities
7/21/2011	I-8 Island	18	Evening perimeter survey at 6:35pm
7/21/2011	EP263B-EP267	0	Site clearance survey
7/21/2011	EP269	0	Site clearance survey
7/21/2011	EP269-EP270	0	Monitoring construction activities
7/21/2011	EP270	0	Monitoring construction activities
7/21/2011	EP279-294	0	Monitoring construction activities
7/21/2011	EP300-EP312	0	Monitoring construction activities
7/21/2011	EP300-EP306	0	Site clearance survey
7/21/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/21/2011	EP269-EP273	0	Morning perimeter survey
7/21/2011	EP269-EP273	0	Evening perimeter survey
7/21/2011	EP274-EP278	0	Morning perimeter survey
7/21/2011	EP274-EP278	0	Evening perimeter survey
7/20/2011	I-8 Island	4	Evening perimeter survey at 6:50pm
7/20/2011	EP269-EP273	0	Morning perimeter survey
7/20/2011	EP269-EP273	0	Evening perimeter survey
7/20/2011	EP263B-EP267	0	Site clearance survey
7/20/2011	EP269	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
7/20/2011	EP270	0	Monitoring construction activities
7/20/2011	EP279-294	0	Monitoring construction activities
7/20/2011	EP300-EP312	0	Monitoring construction activities
7/20/2011	EP300-EP306	0	Site clearance survey
7/20/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/20/2011	EP274-EP278	0	Morning perimeter survey
7/20/2011	EP274-EP278	0	Evening perimeter survey
7/19/2011	I-8 Island	10	Morning perimeter survey at 9:10am
7/19/2011	I-8 Island	17	Evening perimeter survey at 4:00pm - 6:40pm
7/19/2011	EP269-EP273	0	Morning perimeter survey
7/19/2011	EP269-EP273	0	Evening perimeter survey
7/19/2011	EP269	0	Site clearance survey
7/19/2011	EP270	0	Monitoring construction activities
7/19/2011	EP279-294	0	Monitoring construction activities
7/19/2011	EP300-EP312	0	Monitoring construction activities
7/19/2011	EP300-EP306	0	Site clearance survey
7/19/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/19/2011	EP274-EP278	0	Morning perimeter survey
7/19/2011	EP274-EP278	0	Evening perimeter survey
7/19/2011	EP263B-EP267	0	Site clearance survey
7/18/2011	I-8 Island	21	Evening perimeter survey at 7:10pm
7/18/2011	EP263B-EP267	0	Site clearance survey
7/18/2011	EP269	0	Site clearance survey
7/18/2011	EP270	0	Monitoring construction activities
7/18/2011	EP279-294	0	Monitoring construction activities
7/18/2011	EP300-EP312	0	Monitoring construction activities
7/18/2011	EP300-EP306	0	Site clearance survey
7/18/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/18/2011	EP274-EP278	0	Morning perimeter survey
7/18/2011	EP274-EP278	0	Evening perimeter survey
7/18/2011	EP269-EP273	0	Site clearance survey
7/17/2011	I-8 Island	17	Evening perimeter survey at 5:55pm - 6:25
7/17/2011	EP263B-EP267	0	Site clearance survey
7/17/2011	EP269	0	Site clearance survey
7/17/2011	EP270	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
7/17/2011	EP300-EP312	0	Monitoring construction activities
7/17/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/17/2011	EP274-EP278	0	Evening perimeter survey
7/17/2011	EP279-EP294	0	Site clearance survey
7/17/2011	EP269-EP273	0	Site clearance survey
7/16/2011	I-8 Island	1	Morning perimeter survey at 8:35am
7/16/2011	EP263B-EP267	0	Site clearance survey
7/16/2011	EP269	0	Site clearance survey
7/16/2011	EP270	0	Monitoring construction activities
7/16/2011	EP300-EP306	0	Monitoring construction activities
7/16/2011	EP300-EP312	0	Monitoring construction activities
7/16/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/16/2011	EP274-EP278	0	Morning perimeter survey
7/16/2011	EP279-EP294	0	Morning perimeter survey
7/16/2011	EP279-EP294	0	Site clearance survey
7/16/2011	EP279-EP294	0	Monitoring construction activities
7/16/2011	EP269-EP273	0	Site clearance survey
7/15/2011	EP273-1	1	Evening perimeter survey at 4:30pm
7/15/2011	I-8 Island	12	Evening perimeter survey at 6:35pm - 7:00pm
7/15/2011	EP263B-EP267	0	Site clearance survey
7/15/2011	EP269	0	Site clearance survey
7/15/2011	EP270	0	Monitoring construction activities
7/15/2011	EP279-294	0	Monitoring construction activities
7/15/2011	EP300-EP306	0	Monitoring construction activities
7/15/2011	EP300-EP312	0	Monitoring construction activities
7/15/2011	EP256-EP263A-2, AER Yard	0	Site clearance survey
7/15/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/15/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/15/2011	EP269-EP273	0	Site clearance survey
7/15/2011	EP274-EP278	0	Morning perimeter survey
7/15/2011	EP274-EP278	0	Evening perimeter survey
7/14/2011	I-8 Island	3	Evening perimeter survey at 4:10pm
7/14/2011	I-8 Island		7:15am - 9:30am PBHS were at above point
7/14/2011	EP263B-EP267	0	Site clearance survey
7/14/2011	EP269	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
7/14/2011	EP270	0	Monitoring construction activities
7/14/2011	EP279-294	0	Monitoring construction activities
7/14/2011	EP300-EP306	0	Monitoring construction activities
7/14/2011	EP300-EP312	0	Monitoring construction activities
7/14/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/14/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/14/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/14/2011	EP274-EP278	0	Morning perimeter survey
7/14/2011	EP274-EP278	0	Evening perimeter survey
7/14/2011	EP269-EP273	0	Site clearance survey
7/13/2011	I-8 Island	21	Evening perimeter survey at 4:40pm
7/13/2011	EP263B-EP267	0	Site clearance survey
7/13/2011	EP269	0	Site clearance survey
7/13/2011	EP270	0	Monitoring construction activities
7/13/2011	EP279-294	0	Monitoring construction activities
7/13/2011	EP300-EP306	0	Monitoring construction activities
7/13/2011	EP300-EP312	0	Monitoring construction activities
7/13/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/13/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/13/2011	EP269-EP273	0	Site clearance survey
7/12/2011	EP256-EP263A-2, AER Yard	15	Monitoring during construction activities @ 7:40am - 11:00am
7/12/2011	I-8 Island	17	Evening perimeter survey at 4:00pm
7/12/2011	EP263B-EP267	0	Site clearance survey
7/12/2011	EP269	0	Site clearance survey
7/12/2011	EP270	0	Monitoring construction activities
7/12/2011	EP279-294	0	Monitoring construction activities
7/12/2011	EP300-EP306	0	Monitoring construction activities
7/12/2011	EP300-EP312	0	Monitoring construction activities
7/12/2011	EP274-EP278	0	Morning perimeter survey
7/12/2011	EP274-EP278	0	Evening perimeter survey
7/12/2011	EP269-EP273	0	Site clearance survey
7/11/2011	I-8 Island	29	Evening perimeter survey at 4:40pm
7/11/2011	EP263B-EP267	0	Site clearance survey
7/11/2011	EP269	0	Site clearance survey
7/11/2011	EP270	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
7/11/2011	EP279-294	0	Monitoring construction activities
7/11/2011	EP300-EP306	0	Monitoring construction activities
7/11/2011	EP300-EP312	0	Monitoring construction activities
7/11/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/11/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/11/2011	EP269-EP273	0	Site clearance survey
7/11/2011	EP274-EP278	0	Morning perimeter survey
7/11/2011	EP274-EP278	0	Evening perimeter survey
7/10/2011	I-8 Island	8	Perimeter survey
7/10/2011	I-8 Island	20	Monitoring construction activities
7/10/2011	EP269	0	Site clearance survey
7/10/2011	EP270	0	Monitoring construction activities
7/10/2011	EP279-294	0	Monitoring construction activities
7/10/2011	EP300-EP312	0	Monitoring construction activities
7/10/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/10/2011	EP274-EP278, EP265-EP267	0	Site clearance survey
7/9/2011	EP263A-2	11	Evening perimeter survey
7/9/2011	EP263B-EP267	0	Site clearance survey
7/9/2011	EP269-EP274	0	Monitoring construction activities
7/9/2011	EP279-294	0	Monitoring construction activities
7/9/2011	EP300-EP307	0	Monitoring construction activities
7/9/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/9/2011	EP269-EP273	0	Site clearance survey
7/9/2011	EP274-EP278	0	Morning perimeter survey
7/9/2011	EP310	0	Monitoring construction activities
7/8/2011	EP263B-EP267	0	Site clearance survey
7/8/2011	EP300-EP312	0	Monitoring construction activities
7/8/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/8/2011	EP269-EP273	0	Site clearance survey
7/8/2011	EP274-EP278	0	Morning perimeter survey
7/8/2011	EP274-EP278	0	Evening perimeter survey
7/8/2011	EP303	0	Monitoring construction activities
7/8/2011	EP279-EP294	0	Monitoring construction activities
7/7/2011	I-8 Island	8	Evening perimeter survey at 7:00pm
7/7/2011	EP263B-EP267	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
7/7/2011	EP269-EP273	0	Monitoring construction activities
7/7/2011	EP300-EP312	0	Monitoring construction activities
7/7/2011	EP300-EP307	0	Monitoring construction activities
7/7/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/7/2011	EP269-EP273	0	Site clearance survey
7/7/2011	EP274-EP278	0	Morning perimeter survey
7/7/2011	EP274-EP278	0	Evening perimeter survey
7/7/2011	EP303 & EP304	0	Monitoring construction activities
7/7/2011	EP306-EP312	0	Site clearance survey
7/6/2011	EP263A-2	2	Evening perimeter survey
7/6/2011	EP263B-EP267	0	Site clearance survey
7/6/2011	EP269-EP272	0	Monitoring construction activities
7/6/2011	EP300-EP312	0	Monitoring construction activities
7/6/2011	EP300-EP307	0	Monitoring construction activities
7/6/2011	EP303	0	Site clearance survey
7/6/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/6/2011	EP274-EP278	0	Morning perimeter survey
7/6/2011	EP274-EP278	0	Evening perimeter survey
7/6/2011	EP305 to EP304	0	Monitoring construction activities
7/6/2011	I-8 Island	0	Monitoring construction activities
7/6/2011	EP269-EP273	0	Site clearance survey
7/5/2011	EP270	14	Morning perimeter survey at 6:30am - 10:00am
7/5/2011	EP270	9	Evening perimeter survey at 5:00pm
7/5/2011	I-8 Island	7	Evening perimeter survey at 6:20pm
7/5/2011	EP269-EP273	0	Morning perimeter survey
7/5/2011	EP269-EP273	0	Evening perimeter survey
7/5/2011	EP263B-EP267	0	Site clearance survey
7/5/2011	EP269-EP271	0	Monitoring construction activities
7/5/2011	EP300-EP312	0	Monitoring construction activities
7/5/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/5/2011	EP274-EP278	0	Morning perimeter survey
7/5/2011	EP274-EP278	0	Evening perimeter survey
7/5/2011	EP307 to EP305	0	Monitoring construction activities
7/5/2011	I-8 Island	0	Site clearance survey
7/4/2011	EP270	9	Perimeter survey

PBS Monitoring Report - Week Ending 12/03/2011

Date	Location	Number observed	Comments
7/4/2011	EP263B-EP267	0	Site clearance survey
7/4/2011	EP300-EP312	0	Monitoring construction activities
7/4/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/4/2011	EP269-EP273	0	Site clearance survey
7/4/2011	EP274-EP278	0	Evening perimeter survey
7/4/2011	I-8 Island	0	Site clearance survey
7/2/2011	EP263B-EP267	0	Site clearance survey
7/2/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/2/2011	EP269-EP273	0	Site clearance survey
7/2/2011	EP274-EP278	0	Morning perimeter survey
7/2/2011	I-8 Island	0	Site clearance survey
7/1/2011	EP263B-EP267	0	Site clearance survey
7/1/2011	EP300-EP312	0	Monitoring construction activities
7/1/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/1/2011	EP269-EP273	0	Site clearance survey
7/1/2011	EP274-EP278	0	Morning perimeter survey
7/1/2011	EP274-EP278	0	Evening perimeter survey
7/1/2011	I-8 Island	0	Site clearance survey
6/30/2011	EP300-EP312	0	Monitoring construction activities
6/29/2011	EP310-EP312	0	Monitoring construction activities
4/15/2011	EP210, EP211, EP213-EP215, EP217-EP219	0	Monitoring construction activities
3/26/2011	EP105	0	Site clearance survey

Flat Tailed Horned Lizard Counts - Week Ending 12/03/2011

Date	Location	Observed		Injured		Relocated		Dead	
		Day	Night	Day	Night	Day	Night	Day	Night
	Post RCLMP*								
11/1/2011	Dunaway CY					1			
10/13/2011	AR to EP354							1	
9/20/2011	AR btwn EP357 and EP358							1	
9/19/2011	AR btwn EP352 and EP353	1							
9/12/2011	EP325					1			
9/9/2011	AR to EP363	1							
9/6/2011	AR to EP360/361					1			
9/6/2011	EP360					2			
9/6/2011	EP359					1			
9/3/2011	SWPL AR to EP324					1			
9/3/2011	SWPL AR to EP342					1			
9/3/2011	SWPL AR to EP345							1	
9/3/2011	SWPL AR to EP344 and EP345					1			
8/31/2011	EP324					1			
8/31/2011	SWPL AR to EP325-2					1			
8/30/2011	SWPL AR to EP346 and EP347					1			
8/29/2011	SWPL AR to EP353 and EP354							1	
8/29/2011	SWPL AR to EP324							1	
8/27/2011	EP349					1			
8/25/2011	EP360							1	
8/25/2011	Btwn EP320/321					1			
8/24/2011	SWPL AR near EP346					1			
8/23/2011	EP349					1			
8/21/2011	SWPL AR btwn EP344/345					1			
8/21/2011	SWPL AR to EP345							1	
8/19/2011	SWPL AR to EP339					1			
8/20/2011	SWPL AR to IV Sub							1	
8/20/2011	SWPL AR btwn EP346/347					1			
8/19/2011	EP338/339 Pullsite					1			
8/19/2011	EP355/356 Pullsite					1			
8/18/2011	EP347					1			
8/18/2011	SWPL AR to EP353							1	
8/11/2011	SWPL AR by EP348					1			
8/11/2011	EP348/EP349 Pullsite					1			
8/10/2011	EP347					1			
8/8/2011	SWPL AR to EP351					2			
8/6/2011	BLM AR near EP327							1	
8/1/2011	IV Substation Yard	1							
8/1/2011	EP325					1			
8/1/2011	AR to EP345					1			
7/30/2011	EP322					1			
7/28/2011	EP355/EP356 Pullsite					1			
7/27/2011	Near EP316-2	1							

Flat Tailed Horned Lizard Counts - Week Ending 12/03/2011

Date	Location	Observed		Injured		Relocated		Dead	
Post RCLMP*		Day	Night	Day	Night	Day	Night	Day	Night
7/26/2011	SWPL AR to EP344	1							
7/26/2011	EP347					1			
7/26/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/22/2011	AR to IV Sub					1			
7/21/2011	EP360					1			
7/21/2011	AR to EP326					1			
7/19/2011	SWPL AR to IV Sub	1							
7/19/2011	EP353					1			
7/19/2011	AR to Dunaway CY					1			
7/18/2011	EP318					1			
7/17/2011	EP355					1			
7/15/2011	EP359	1							
7/15/2011	EP352	1							
7/15/2011	EP350	1							
7/14/2011	Spur Rd to EP355							1	
7/14/2011	EP322	1							
7/13/2011	EP357	1							
7/12/2011	EP344	1							
7/12/2011	SWPL AR btwn EP348/345							1	
TOTAL POST RCLMP		12	0	0	0	43	0	12	
Prior to RCLMP		Day		Day		Day		Day	
7/11/2011	AR to EP352					2			
7/11/2011	AR to EP345					2			
7/10/2011	EP358					1			
7/10/2011	SWPL AR to EP354					2			
7/9/2011	AR to EP330	1							
7/8/2011	Spur Rd. to EP352	1							
7/7/2011	EP324					1			
7/7/2011	EP355					1			
7/6/2011	SWPL AR btwn EP362/363							1	
7/5/2011	EP354					1			
7/1/2011	AR to EP353	1							
6/30/2011	AR between EP310/311							1	
6/30/2011	EP358	1							
6/30/2011	EP360	1							
6/30/2011	AR to EP312							1	
6/30/2011	EP360							1	
6/27/2011	EP350					1			
6/27/2011	SWPL AR to IV Substation	2							
6/26/2011	IV Substation					1			

Flat Tailed Horned Lizard Counts - Week Ending 12/03/2011

Date	Location	Observed	Injured	Relocated	Dead
6/25/2011	SWPL AR to EP361	1			
6/24/2011	EP359			1	
6/23/2011	SWPL AR to EP360			2	
6/22/2011	SWPL AR to EP355			1	
6/20/2011	EP356	2			
6/20/2011	SWPL AR to EP359	1			
6/20/2011	Near EP356	2			
6/20/2011	AR between EP358/357				1
6/18/2011	AR to Dunaway CY				1
6/17/2011	Near EP322	1			
6/7/2011	Near EP355	1			
6/7/2011	EP361			1	
6/7/2011	AR btwn EP343/EP344				1
6/7/2011	AR between EP324/325				1
6/6/2011	SWPL AR btwn EP344/EP345			1	
6/3/2011	EP359			1	
6/3/2011	SWPL AR EP362			1	
6/2/2011	AR to EP358			1	
6/2/2011	SWPL AR to EP316-2				1
6/2/2011	AR east of EP325				1
6/1/2011	SWPL AR btwn EP319/EP320			1	
6/1/2011	SWPL AR to EP318			1	
5/31/2011	SWPL AR btwn EP359/EP360			1	
5/31/2011	SWPL AR to EP320			1	
5/31/2011	EP360				1
5/27/2011	EP357			1	
5/26/2011	SWPL AR to EP359			1	
5/25/2011	Spur Rd to EP321			1	
5/23/2011	EP323			1	
5/21/2011	EP324			1	
5/20/2011	IV CY			1	
5/20/2011	AR to EP362			1	
5/20/2011	AR btwn EP324/EP325			1	
5/20/2011	SWPL AR btwn EP326/EP327			1	
5/20/2011	IV Substation			3	
5/19/2011	IV Substation			5	
5/19/2011	EP324			1	
5/18/2011	IV Substation Yard			1	
5/18/2011	IV Substation Yard				1
5/17/2011	AR to IV Substation				1
5/16/2011	IV Substation Yard			1	
5/13/2011	SWPL AR Near EP362-1	1			
5/12/2011	AR to EP355			1	
5/11/2011	EP360	1			

Flat Tailed Horned Lizard Counts - Week Ending 12/03/2011					
Date	Location	Observed	Injured	Relocated	Dead
5/11/2011	Dunaway CY	3			
5/11/2011	Dunaway Yard			4	
5/10/2011	EP322	1			
5/10/2011	AR to Dunaway CY	1			
5/9/2011	Dunaway Yard			4	
5/7/2011	EP322	1			
5/7/2011	Spur Road to EP344	1			
5/7/2011	Dunaway Yard			1	
5/6/2011	AR to EP321-1	1			
5/5/2011	AR to EP321-1	1			
5/5/2011	AR to Dunaway CY	2			
5/5/2011	Dunaway Yard			2	
5/4/2011	AR btwn EP343/EP344			1	
5/3/2011	SWPL AR btwn EP320/EP321	1			
4/27/2011	AR to EP322	2			
4/26/2011	EP322	1			
4/25/2011	Plaster City CY	1			
4/20/2011	Plaster City			1	
4/18/2011	Plaster City			1	
4/14/2011	AR to IV Substation	1			
4/2/2011	Dunaway CY	1			
TOTAL PRIOR TO RCLMP		35	0	60	13
YTD		47	0	103	25

*RCLMP refers to the Revised Construction Lighting Mitigation Plan

Raven Control Monitoring Report - Week Ending 12/03/2011

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
12/3/2011	EP281	1		1				no
12/2/2011	IV Substation	1		1				no
12/1/2011	S2 Yard	2					2	no
11/30/2011	S2 Yard	2			2			no
11/29/2011	S2 Yard	2			2			no
11/28/2011	S2 Yard	4			4			no
11/28/2011	EP290-EP301	5		2	3			no
11/27/2011	S2 Yard	1		1				no
11/26/2011	No ravens observed							
11/25/2011	NO WORK: DAY AFTER THANKSGIVING							
11/24/2011	NO WORK: THANKSGIVING							
11/23/2011	Plaster City Yard	3					3	no
11/22/2011	S2 Yard	4			4			no
11/22/2011	IV Substation	1			1			no
11/21/2011	S2 Yard	4					4	no
11/21/2011	IV Substation	1		1				no
11/21/2011	EP281	2			2			no
11/20/2011	EP360	2			2			no
11/20/2011	IV Substation	2		2				no
11/19/2011	No ravens observed							
11/18/2011	EP358 and IV Substation	2		2				no
11/17/2011	No ravens observed							
11/16/2011	S2 Yard	5			5			no
11/15/2011	EP330-1	2					2	no
11/15/2011	EP304; EP330	1			1			no
11/14/2011	S2 Yard	6			6			no
11/13/2011	No ravens observed							
11/12/2011	Dunaway CY	1			1			no
11/11/2011	Dunaway CY	4					4	no
11/11/2011	S2 Yard	5					5	no
11/10/2011	Fromm CY	2					2	no
11/10/2011	EP355	1		1				no
11/9/2011	Dunaway CY	1			1			no
11/8/2011	S2 Yard	5			5			no
11/8/2011	Dunaway CY	2			2			no
11/7/2011	S2 Yard	3					3	no
11/7/2011	EP308-EP310	1					1	no
11/7/2011	EP301 Pullsite	7		6	1			no
11/6/2011	No ravens observed							
11/5/2011	S2 Yard	7			7			no
11/5/2011	IV Substation	1			1			no
11/4/2011	S2 Yard	5			5			no
11/3/2011	S2 Yard	5			3		2	no
11/3/2011	IV Substation	1			1			no
11/3/2011	Fromm CY	1				1		no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
11/3/2011	EP303 and EP302	2			2			no
11/3/2011	EP281	2			2			no
11/2/2011	S2 Yard	4			4			no
11/2/2011	IV Substation	1		1				no
11/2/2011	EP305, EP310, EP311	1		1				no
11/1/2011	S2 Yard	2			2			no
11/1/2011	IV Substation	1		1				no
11/1/2011	EP305 and EP312	1			1			no
10/31/2011	S2 Yard	5			5			no
10/31/2011	AER and Fromm CY	1				1		no
10/30/2011	No ravens observed							
10/29/2011	IV Substation	3		3				no
10/28/2011	IV Substation	1		1				no
10/28/2011	EP256, EP357 & EP358	5		5				no
10/27/2011	EP356, EP358 & EP362	2		2				no
10/27/2011	EP305, EP307, EP310-EP312	1		1				no
10/26/2011	EP306, EP307 & EP310	2		2				no
10/25/2011	IV Substation	1		1				no
10/25/2011	EP310	1		1				no
10/24/2011	S2 Yard	3					3	no
10/24/2011	EP305	1			1			no
10/23/2011	S2 Yard	3			3			no
10/22/2011	No ravens observed							
10/21/2011	Dunaway CY	1			1			no
10/20/2011	S2 Yard	2					2	no
10/20/2011	Dunaway CY	5					5	no
10/19/2011	EP314	1		1				no
10/19/2011	EP290	5		5				no
10/18/2011	No ravens observed							
10/17/2011	EP301	3		3				no
10/16/2011	No ravens observed							
10/15/2011	S2 Yard	2					2	no
10/15/2011	Dunaway CY	1				1		no
10/15/2011	EP315	2					2	no
10/15/2011	EP301	3			3			no
10/14/2011	Fromm CY	3				3		no
10/14/2011	EP305	2		2				no
10/14/2011	EP301	3			3			no
10/13/2011	S2 Yard	2					2	no
10/13/2011	Dunaway CY	5					5	no
10/13/2011	Fromm CY	1					1	no
10/13/2011	EP354-EP363	2			2			no
10/13/2011	EP301	4		4				no
10/12/2011	EP300-EP301	2		2				no
10/11/2011	Plaster City Yard	2			2			no
10/11/2011	IV Substation	2					2	no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
10/10/2011	Fromm CY	2				2		no
10/10/2011	EP359-EP360	2		2				no
10/10/2011	EP355-EP363	2		2				no
10/10/2011	EP301	3		3				no
10/9/2011	S2 Yard	3					3	no
10/9/2011	EP300	6		6				no
10/8/2011	EP357	2			2			no
10/8/2011	EP306	3					3	no
10/7/2011	Dunaway CY	1		1				no
10/7/2011	EP291-EP301	3		3				no
10/6/2011	Fromm CY	2					2	no
10/5/2011	Dunaway CY	2		2				no
10/5/2011	EP303-2	2		2				no
10/4/2011	EP310 & EP311	2		2				no
10/4/2011	EP301	3					3	no
10/4/2011	EP293	2		2				no
10/3/2011	S2 Yard	2					2	no
10/3/2011	Dunaway CY	2			2			no
10/2/2011	EP356-EP363	2		1	1			no
10/1/2011	Plaster City Yard	2					2	no
10/1/2011	EP360	2			2			no
9/30/2011	S2 Yard	2					2	no
9/30/2011	EP355	1		1				no
9/30/2011	EP314	2		2				no
9/30/2011	EP301	2		1	1			no
9/29/2011	EP291/EP292 Pullsite	1			1			no
9/28/2011	EP361	1			1			no
9/27/2011	EP315	2		1	1			no
9/27/2011	EP309	1		1				no
9/27/2011	EP301 & EP304	4		3	1			no
9/27/2011	EP290	1			1			no
9/26/2011	EP362	2			2			no
9/26/2011	Fromm CY	1				1		no
9/25/2011	No ravens observed							
9/24/2011	Plaster City Yard	2					2	no
9/24/2011	EP317	1		1				no
9/24/2011	EP309	1		1				no
9/23/2011	EP362	4			4			no
9/23/2011	EP303	2		2				no
9/22/2011	Fromm CY	1				1		no
9/22/2011	EP303	2		2				no
9/22/2011	EP301	2		2				no
9/22/2011	EP295-EP322	3		3				no
9/21/2011	S2 Yard	3			3			no
9/21/2011	Fromm CY	1					1	no
9/21/2011	EP303	1		1				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
9/20/2011	S2 Yard	2			2			no
9/20/2011	Fromm CY	1				1		no
9/19/2011	S2 Yard	3			3			no
9/19/2011	EP304, EP307, EP309	1		1				no
9/18/2011	S2 Yard	3				3		no
9/18/2011	EP281	1		1				no
9/17/2011	S2 Yard	3					3	no
9/17/2011	EP362	1			1			no
9/17/2011	Fromm CY	3				3		no
9/16/2011	EP363	2			2			no
9/16/2011	Fromm CY	1					1	no
9/16/2011	EP304	2		2				no
9/16/2011	EP290	1		1				no
9/15/2011	S2 Yard	4			4			no
9/15/2011	Fromm CY	3					3	no
9/15/2011	EP296	1		1				no
9/15/2011	EP306	2					2	no
9/15/2011	EP304	1		1				no
9/15/2011	EP301	2		2				no
9/14/2011	Plaster City Yard	1			1			no
9/14/2011	EP361	2			2			no
9/14/2011	Fromm CY	1				1		no
9/14/2011	EP308	1					1	no
9/14/2011	EP301	5		4	1			no
9/14/2011	EP292	3		3				no
9/13/2011	S2 Yard	10			10			no
9/13/2011	EP348	3		3				no
9/13/2011	EP345	2		2				no
9/13/2011	EP326	1					1	no
9/13/2011	EP325	2		2				no
9/13/2011	EP326	1		1				no
9/13/2011	EP304	7		7				no
9/13/2011	EP291	7		7				no
9/12/2011	S2 Yard	3			3			no
9/12/2011	EP350	1		1				no
9/12/2011	EP304	1		1				no
9/12/2011	EP301	1		1				no
9/11/2011	S2 Yard	2				2		no
9/10/2011	S2 Yard	2					2	no
9/9/2011	EP304	1			1			no
9/8/2011	S2 Yard	3					3	no
9/7/2011	S2 Yard	3					3	no
9/6/2011	No ravens observed							
9/5/2011	No ravens observed							
9/4/2011	No ravens observed							
9/3/2011	No ravens observed							

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
9/2/2011	EP348	1		1				no
9/2/2011	S2 Yard	1		1				no
9/2/2011	EP303	1		1				no
9/2/2011	EP363	2		2				1 at IV Sub
9/1/2011	EP303	2					2	no
9/1/2011	EP293	1					1	no
9/1/2011	EP304	2					2	no
8/31/2011	S2 Yard	1		1				no
8/31/2011	EP308	1		1				no
8/31/2011	EP305-3	2					2	no
8/31/2011	EP303	2		2				no
8/30/2011	EP303	1		1				no
8/29/2011	S2 Yard	1		1				no
8/29/2011	EP303	1		1				no
8/28/2011	No ravens observed							
8/27/2011	EP305	3			3			no
8/26/2011	EP301	2		2				no
8/25/2011	S2 Yard	2					2	no
8/25/2011	EP301	2		2				no
8/24/2011	S2 Yard	3				3		no
8/23/2011	EP292-1	3		3				no
8/22/2011	No ravens observed							
8/21/2011	No ravens observed							
8/20/2011	S2 Yard	2				2		no
8/20/2011	EP312	2		2				no
8/20/2011	S2 Yard	2					2	no
8/20/2011	EP312	2		2				no
8/19/2011	EP307	2			2			no
8/19/2011	EP296	1		1				no
8/18/2011	S2 Yard	2				1	1	no
8/18/2011	EP301	Flock		x				no
8/17/2011	S2 Yard	2				1	1	no
8/17/2011	EP301	3			3			no
8/16/2011	S2 Yard	1					1	no
8/16/2011	EP301	1		1				no
8/15/2011	No ravens observed							
8/14/2011	No ravens observed							
8/13/2011	S2 Yard	2					2	no
8/12/2011	IV Substation	2				2		no
8/12/2011	S2 Yard	3				3	3	no
8/11/2011	EP294	4			4			no
8/11/2011	S2 Yard	3				3	3	no
8/10/2011	S2 Yard	3				2	1	no
8/9/2011	S2 Yard	not specified						no
8/8/2011	EP294	2			2			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
8/8/2011	S2 Yard	1						no
8/7/2011	No ravens observed							
8/6/2011	S2 Yard	1						no
8/5/2011	EP301	3		3				no
8/4/2011	S2 Yard	not specified						no
8/3/2011	S2 Yard	2		2				no
8/3/2011	S2 Yard	1						no
8/2/2011	S2 Yard	3					3	no
8/1/2011	EP314	not specified		x				no
7/31/2011	No ravens observed							
7/30/2011	EP314	3		2			1	no
7/30/2011	S2 Yard	1					1	no
7/29/2011	S2 Yard	1						no
7/28/2011	EP319	4	1	2	1			no
7/28/2011	S2 Yard	not specified						no
7/27/2011	S2 Yard	not specified						no
7/26/2011	No ravens observed							
7/25/2011	EP290	1			1			no
7/24/2011	No ravens observed							
7/23/2011	No ravens observed							
7/22/2011	EP290	2		1	1			no
7/21/2011	S2 Yard	1		1				no
7/20/2011	Ocotillo, CA	5						no
7/19/2011	Ocotillo, CA	1						no
7/18/2011	CP40-2	not specified						no
7/18/2011	CP41-2	not specified						no
7/18/2011	CP42-1	not specified						no
7/17/2011	No ravens observed							
7/16/2011	CP42-1	not specified						no
7/15/2011	No ravens observed							
7/14/2011	EP357	not specified						no
7/14/2011	EP358	not specified						no
7/14/2011	EP359	not specified						no
7/14/2011	Plaster City Yard	2		2				no
7/13/2011	EP313-EP314 PS	not specified						no
7/13/2011	S2 Yard	3					3	no
7/12/2011	CP18-1	not specified						no
7/12/2011	CP19-1	not specified						no
7/12/2011	CP22-1	not specified						no
7/11/2011	EP304-EP314	not specified						no
7/10/2011	No ravens observed							
7/9/2011	EP351	not specified						no
7/9/2011	EP353	not specified						no
7/9/2011	EP354	not specified						no
7/9/2011	EP355	not specified						no
7/9/2011	not specified	not specified						no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
7/9/2011	S2 Yard	3					3	no
7/8/2011	EP303	2			1		1	no
7/8/2011	EP303	1		1				no
7/8/2011	S2 Yard	3					3	no
7/1/11-7/7/11	No ravens observed							
6/30/2011	EP300	3		3				no
6/21/11-6/29/11	No ravens observed							
6/20/2011	S2 Yard	2					2	no
6/1/11-6/19/11	No ravens observed							
5/1/11-5/31/11	No ravens observed							
4/22/11-4/30/11	No ravens observed							
4/21/2011	EP341	1	1					no
4/1/11-4/20/11	No ravens observed							
3/1/11-3/31/11	No ravens observed							
2/1/11-2/28/11	No ravens observed							
1/21/11-1/31/11	No ravens observed							
1/21/2011	Rough Acres Yard	not specified						no