

This report provides a summary of environmental monitoring and compliance activities conducted by Burns and McDonnell (BMcD) staff and BMcD subconsultants for the San Diego Gas & Electric (SDG&E) Sunrise Powerlink Project during the above weekly time period.

Training

- SWEAP and PBS training continued for new Project personnel every Tuesday and Thursday. Additional trainings were provided as requested.
- Flat-tailed horned lizard (FTHL) trainings were provided to any new crew members or monitors prior to construction per mitigation measure B-7b and in accordance with the FTHL Rangewide Management Strategy. During morning tailboard meetings, guidelines were provided about recognizing, protecting, and notification requirements for FTHL. FTHL information cards were made available to any crew members or monitors as needed.
- Barefoot banded gecko (BBG) trainings were provided to crews prior to pre-construction activities pursuant to the California Department of Fish and Game (CDFG) 2081 Incidental Take Permit requirements.

Pre/Post Construction

- Staked, flagged, and refreshed work areas near SPL-69-8, CP23 pull site, CP28-1, CP29-1, CP31-2, CP42, CP43-1, CP53-3, CP54-1, CP76-1, EP10-2, EP34-1, EP36-1, EP83, EP83 pull site, EP119-2, EP219-1, EP220-1, EP120-4, and EP134-1.
- Performed post construction impact surveys at EP131, EP141, EP200-3, EP200A-1, EP201-3, EP202-3, EP203-3, EP204-3, EP205-2, EP206-2, EP207, and EP255-2 pull site.
- The ESA Team conducted the following activities during this reporting period:
 - Repaired, refreshed, and maintained the previously installed project signs and ESAs at CP36-1, CP37-2, CP42-1, CP43-1, EP24, EP25, EP27-1, EP28-3, EP79, EP84, EP305, EP306, EP307, EP304 to the west edge of EP308 access road, and EP361-N access road.

Construction

- Monitors were present during construction activities to ensure compliance with mitigation measures as identified in the Final EIR/EIS Mitigation Monitoring, Compliance, and Reporting Program (MMCRP). Archaeologists, Paleontologists, and Native American Monitors were present at sites where required as identified prior to construction activity and as approved in the NTPs. On average, the following number of monitors were on the Project throughout the week:
 - 8 Archaeological Monitors.
 - 124 Biological Monitors.
 - 8 Native American Monitors.
 - 2 Paleontological Monitor.
 - 8 SWPPP Monitors.
- Project staff carpooled to site reviews, kick-off tailgates, and off-site meetings. Construction and traffic control crews were observed carpooling from yards to work areas.

- Deterrents were utilized to discourage bird nest building activities throughout the Project as appropriate. Deterrents are determined depending upon the location and type of possible nesting areas and may include metallic flagging, compact discs, plastic owls, and the presence of biological monitors.

The table below demonstrates the construction progress to date:

OVERHEAD			
Agency	Foundations Completed	Towers Erected	Wire Installed
Non-Federal	106 of 169	61 of 169	23 of 169
Bureau of Land Management	137 of 179	106 of 179	67 of 179
Miramar	7 of 14	3 of 14	0 of 14
US Forest Service	23 of 76	16 of 76	17 of 76
UNDERGROUND			
Agency	Vaults Installed	Trenches Excavated & Backfilled	
Non-Federal	40 of 40	41 of 42	
SUBSTATION UPGRADES			
3 of 7 Completed			
SUNCREST SUBSTATION			
80 Percent Complete			

Overhead Construction

- Link 1
 - Vegetation clearing at EP183, EP189-3, and EP251 south guard structure.
 - Foundation preparation for the regen site at EP215.
 - Final grading at EP292-1, EP293, EP295 to EP304-2, EP307-1 pull site, and EP325-2.
 - A radio repeater was delivered to EP271-2.

- Micropile drilling at EP148-1, EP152-2, EP183, EP184-1, EP188-1, EP194-3, EP195-2, EP196-2, EP228, and EP237-1.
- Micropile cap work at EP223-1, EP259-3, EP259B, EP261-2, EP261A, EP262-4, EP263A-2, EP267-2, EP269-1, EP270-2, and EP272-3.
- Air track drilling at EP170.
- Conventional drilling at EP177, EP185-1, EP189-3, and EP196-2.
- Rebar installation at EP177 and EP185-1.
- Concrete pouring at EP177.
- Tower assembly at EP257, EP259-3, EP259B, EP261-2, EP261A, EP262-4, EP263A-2, EP263B-2, EP264-4, EP265-2, EP266-2, EP267-2, EP270-2, EP271-2, EP272-3, EP273-1, EP275-1, and EP277-1.
- Miscellaneous tower work (anti-climbing guards, bird deterrents, and/or signs) at/from EP269-1, EP295, EP301, EP308 to EP313, and EP322-1 to EP330-1.
- Cleanup at EP255-2, EP256, and EP261A.
- QA/QC at EP255-2, EP257, EP266-2, EP269-1, EP270-2, EP275-1, and EP290.
- Concrete block anchors installed at EP275-1.
- Ground resistance testing at EP259-3, EP259B, EP261-2, EP262-4, EP263A-2, EP263B-2, EP264-4, and EP265-2.
- Mobilization of equipment to EP255-2 pull sites.
- Travelers installed from EP255-2 to EP269-1 pull site and at EP290.
- Insulator work at/from EP255-2 to EP269-1 pull site and EP291-1.
- Sock line pulled and haulback of A-phase from EP269-1 pull site to EP292-1 pull site.
- Sock line, hardline pullback, and conductor on B-phase pulled from EP269-1 pull site to EP292-1 pull site.
- Sock line, hardline pullback, and conductor pulled on C-phase from EP269-1 pull site to EP292-1 pull site.
- Sock line pulled from EP292-1 pull site to EP291.
- Sagging from EP269-1 pull site to EP292-1 pull site.
- Implosive sleeving at EP292-1 pull site.
- Fiber testing and repairs from EP291 through EP363-1.
- BMP installation at:

- EP143-1, EP183, and EP257.
 - BMPs maintained at/from:
 - EP170 to EP220-1 tower sites and spur roads, EP240, and EP257.
 - Trained FTHL monitors, BBG monitors, BHS monitors, and Visible Emission Evaluators (VEEs) were onsite as required.
- Link 2
 - During this reporting period, the PAL Levels were as follows: Monday-A, Tuesday-A, Wednesday-A, Thursday-B, Friday-A, and Saturday-A. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

- Access road construction at:
 - EP12-3-N, EP22-1-PS-N, EP23-2-PS-N, EP35-1-N, EP36-1-N, and EP58-2-N.
- Vegetation clearing at EP12-3, EP17 TSAP, EP28-3 TSAP, EP29-2 TSAP, EP35-1, EP36-1, EP58-2, EP124 TSAP, EP128, EP128 TSAP, EP129, EP129 TSAP, EP142-1 TSAP, and EP143-1 TSAP.
- Gate and barrier installation at EP9-1-N, EP11-3-E, EP24-1-E, EP74-1-E, EP113-5-E, and EP127-N.
- Driveway work at EP24-1-E and EP105-2-E-A.
- Micropile drilling at EP5-2 and EP7-1.
- Soil boring at EP9-1, EP11-3, EP12-3, EP32, EP36-1, and EP112-3.
- Conventional drilling at EP112-3 and EP112A-1.
- Various foundation work (curing, cage installation, etc.) at EP113-5.
- Concrete pouring at EP112A and EP113-5.
- Form removal at EP112A and EP113-5.
- Ground resistance testing at EP125, EP126-1, EP127, and EP130-1.
- Dead-end work at EP132-2 and EP141.
- Clipped in EP140-1.
- Hydromulching at EP132-2, EP134-1, EP137, EP138-2, and EP139-1.
- BMP installation at/from:

- EP9-1-N, EP22-1, EP23-2, EP23-2 pull site, EP23-2-N pull site, EP58-2-N, EP89-1-E, EP128, and EP129.
- BMP maintenance at/from:
 - EP9-1, EP11-3-N, EP12-3-N, EP22-1-PS-N, EP125-E-A to EP138-2-E-A (and associated spur roads), EP125 to EP127, EP129, EP129 TSAP, EP130-1, EP131, EP141, and EP141-E-B.

BLM Land

- Access road construction at:
 - EP58-2-E.
- Conventional drilling at EP39-1 and EP51-1.
- Various foundation work (curing, cage installation, etc.) at EP97, EP98-1, and EP99-2.
- Concrete pouring at EP97 and EP98-1.
- Form removal at EP96, EP98-1, and EP103-2.
- Tower assembly at EP45-1.
- QA/QC at EP42 and EP47-2.
- Marker ball installation from EP42 to EP47-2.
- Arroyo toad fencing was installed between EP75-2-E-A and EP79-E-C.
- BMP maintenance at/from:
 - EP42-N, EP47-2-N pull site to EP53-3-E-B, EP47-2, EP53-3, EP63-E, EP64 to EP83, EP89-1, EP90-1 to EP99-2, and EP99-2-N-A.

Non-Federal Land

- Access road construction at:
 - EP58-2-N, EP58-2-E, and EP105-2-E-B.
- Grading along CY-Kreutzkamp-E and EP93-N.
- Gate crew worked at EP36-1-E.
- Driveway construction at CY-SWAT-E.
- Soil boring at EP32-1.
- Conventional drilling at EP30-2, EP32-1, and EP105-2.
- Various foundation work (curing, cage installation, etc.) at EP104-2.

- Concrete pouring at EP27-1 and EP104-2.
 - Form removal at EP26-1, EP103-2, and EP104-2.
 - Arroyo toad fencing was installed at the EP66-E.
 - BMP installation at:
 - EP58-2-N.
 - BMP maintenance at/from:
 - EP11-3-N, CY-SWAT-E, EP26-1-N, EP26-1-E, EP26-1, EP27-1-E, EP27-1-N, EP27-1, EP30-2, EP32-1, EP54-1, EP62A-1-E, EP64-E, EP89-1, EP89-1 pull site, EP91 to EP99-2, and EP105-2-N.
- Link 5
 - During this reporting period, the PAL Levels were as follows: Monday-A, Tuesday-A, Wednesday-A, Thursday-B, Friday-A, and Saturday-A. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

- Final grading at CP69-2.
- Conventional drilling at CP99-2.
- Sagging, clipping, and dead-end work occurred from CP100-1 to CP109-1.
- Spacers and jumpers installed from CP100-1 to CP109-1.
- BMP maintenance at CP69-2, CP99-2, and CP100-1
- Equipment was demobilized from CP100-1 to CP109-1.
- Cleanup at CP104-1 and CP105-1.

BLM Land

- Micropile drilling at CP59.
- Micropile capping work at CP58-1.

Non-Federal Land

- Vegetation clearing at CP27 TSAP, CP28-1 TSAP, CP32-2 TSAP, CP33A, CP33A TSAP, CP34-2, CP34-2 TSAP, CP35-2, CP48-2, and CP49-1.

- Grading at CP48-2 and CP49-1.
- Final grading at CP70-3.
- Access road construction at CP49-1-N pull site.
- Dexpan boulder breaking at/from CP27 to CP52-2 and CP49-1-N pull site.
- Micropile drilling at CP43-1, CP50-1, CP52, CP54-1, and CP76-1.
- Grouting at CP42-1, CP51-2, and CP53-1.
- Micropile capping work at CP56-1 and CP84.
- Tower assembly from CP16-1 to CP22-1.
- Ground rod installation at CP16-1, CP25-2, and CP26.
- Jumpers installed from CP70-3 to CP75-1.
- Dead-end work from CP100-1 to CP109-1.
- BMP installation at:
 - CP29-1-E-A, CP31-2-E, CP48-2, CP49-1-N pull site, and CP49-1.
- BMP maintenance at:
 - CP56-1-E-B pull site, CP63-3, CP70-3, CP84, and CP98.

Miramar

- Vegetation clearing at CP8-2, CP10, CP11-1, GS-NF-1, GS-NF-4, and GS-NF-6.
- Grading at CP8-2, CP10, and CP11-1.
- Access road construction at:
 - CP6-1-E, CP6-1-N, and CP7-E.
- Conventional drilling at CP3 and CP8-2.
- BMP installation at CP8-2, CP10, and CP11-1.

- 69kV

- Vegetation clearing occurred between Pomerado Road and Sycamore Substation.

Underground Construction (Link 4)

- Revitalization near Bay Meadows and Louise Drive, Tavern Road to South Grade Road, and Alpine Boulevard.

- Relocated mailbox at Loritz driveway.
- Cleaned out BMPs at Alpine and West Victoria.
- Transitions at Alpine Creek, Alpine Boulevard, Honey Hill Ranch to Tavern Road, V10R to V11R, and Alpine Boulevard 2100-2500 blocks.
- Proofing from V10R to V11R.
- Pre-racking/Racking and cleaning manholes for ABB (and jointing/splicing) at V1R, V2R, V7R, V18L, V19L, and V20R.
- Paving at the Loritz driveway entrance.
- Fiber pulling from V8R to V5R and V3R to V6R.
- Milling and setting plates at Viejas Creek.
- Erecting scaffolding at EP95, Loritz, and Slay riser poles.
- Terminating at Loritz riser pole and Slay riser pole.
- Work at Bauer Bridge including BMPs and driveway stabilized.

Suncrest Substation Construction (Link 3)

- Steel erection in the southwest quadrant of the pad.
- Installing tensioning wire wrap on the water tank.
- Crushing class 2 base and select fill material.
- Trenching for conduit and ground grid in the northwest quadrant.
- Repairing/Removing silt fence.
- Finish grading at north and south of the transformers.
- BMP maintenance and repair on substation pad along Bell Bluff Truck Trail.
- SDG&E crews assembling breakers.
- Oil filling activities and pulling vacuum continued on transformers.
- Shooting shotcrete layer on 300,000-gallon water tank.
- Installing insulators in the 500kV yard.
- Wrapping tensioning band around the 300,000-gallon water tank.
- Loading disassembled high line water conveyance pipe onto trucks to be removed from the site.
- Removal of debris piles.

Substation Upgrades

- Encina Switchyard
 - SDG&E relay crews were onsite performing wiring at control house and panel near Bay 10.
 - Roel dropped off material, worked on temporary fence at southern 230kV switchyard, and cleaned up the work area near the new transformer.
 - Alcorn worked on new fence at southern area of switchyard.
- Imperial Valley (IV)

- PRAVA worked inside new storage warehouse
- Electricians worked on wiring.
- Roel worked on concrete pad and driveway approaches at new warehouse and BMP maintenance.
- SDG&E ETRAM crew pulled transmission wire between A frames at the entrance.
- San Luis Rey
 - Wiring on Bank 70.
- Sycamore Canyon
 - SDG&E Kearny Mesa crews built disconnects for 230kV upgrades for Bays 21 and 26 and built steel towers for installation near new 230kV transformer.
- Scripps
 - No Sunrise-related work.

Construction Yards

- Sycamore Yard – Weed wash station, dust suppression, water staging, helicopter operations, tower assembly, and staging for BMP, road, TSAP, pilecap, wire, survey, micropile, erection, brush clearing, and conventional foundation crews.
- Helix Yard – Helicopter operations, water staging, weed wash station, dust suppression, and staging for micropile, pilecap, QC, assembly, tree trimming, and wire crews.
- El Monte Yard – Staging for wire and hooking crews, helicopter operations, water staging, and dust suppression.
- Alpine Yard – Materials staging and weed wash station.
- Wilson Yard – Staging materials for Suncrest Substation, helicopter operations, staging for micropile, BMP, hooking and wire crews, dust suppression, water staging, and tower assembly.
- SWAT Yard – Concrete staging, water staging, helicopter operations, dust suppression, weed wash station, and staging for road, conventional foundation, TSAP, driveway, brush clearing, and wire crews.
- Barrett Canyon Yard – Helicopter operations, dust suppression, staging for BMP, conventional foundation, and wire crews.
- Kreuzkamp Yard – Weed clearing, helicopter operations, staging for road and BMP crews, weed wash station, water staging, and dust suppression.
- Bartlett-Hauser Yard – Water staging, BMP drainage maintenance, weed maintenance, weed wash station, dust suppression, and staging for hooking, gate, driveway, conventional foundation, and BMP crews.
- Thing Valley Yard – Helicopter operations, water staging, dust suppression, and staging for road, gate install, TSAP, BMP, tree trimming, wire, and erection crews.
- McCain Valley Yard – Tower assembly, helicopter operations, staging for conventional foundation crews, water staging, and dust suppression.
- Rough Acres Yard – Helicopter operations, materials staging, water staging, dust suppression, weed wash station, and staging for conventional and micropile foundations, gate, road, and BMP crews.
- Jacumba Valley Ranch (JVR) Yard – Helicopter operations, weed wash station, water staging, dust suppression, hub for coordination of activities within PBS areas, and staging for micropile, QC, road, and erection crews.
- AER Yard – Helicopter operations, staging for grouting operations and micropile crews, and dust control.
- Fromm Yard – Tower assembly, helicopter activity, staging for tower erection, micropile and wire

stringing crews, water staging, dust suppression, and removing slats from yard fence to avoid blow over.

- S2 Yard – Water staging, helicopter activity, tower assembly, dust suppression, and staging for erection, wire stringing, survey, road, QC, and assembly crews.
- Plaster City Yard – Demobilizing office trailers and yard restoration.
- Dunaway Yard – Seeding.
- Imperial Valley Yard – Seeding started and completed.

Wildlife Reporting

- No Peninsular bighorn sheep (PBS) were reported within or around the Right of Way during this reporting period. There were PBS reported approximately 3000 feet from the work areas on December 12, 15, and 16.

The following listed or Species of Special Concern were relocated during construction activities this reporting period:

- Silvery Legless Lizard (*Anniella pulchra pulchra*) – Two (2) silvery legless lizards were relocated from EP12-3.
- Coronado Skink (*Plestidon skiltonianus interparietalis*)- One (1) Coronado skink was relocated from CP33.

Spills/Hazardous Waste

- No reportable spills occurred outside of the USFS during this reporting period.
- Minor leaks, drips, and releases on USFS lands were submitted to the USFS in a weekly HazMat log.

Customer Complaints

- No customer complaints were received during this reporting period.

Non-Compliances

- No non-compliances were received during this reporting period.

Variations and TEWS

- Variance #33 for overhead construction was approved on December 16, 2011.
- BLM DNA#2 for the turnaround to Barrett Canyon Yard, EP63 parking, and temporary parking near EP48 was approved on December 14, 2011.

Weather

- Rain events occurred on December 13, 2011, December 14, 2011, and December 15, 2011.
 - Post-storm totals for December 13, 2011

- Encina Substations – 0.80 inches
- Post-storm totals for December 14, 2011
 - EP120-EP142, La Posta Road, Thing Valley Yard – 1.30 inches
 - EP73-EP119, Bartlett/Hauser Yard – 1.32 inches
 - EP2-EP42 – 1.25 inches
 - EP43-EP72 – 1.65 inches
 - SWAT Yard – 1.25 inches
 - Kreuzkamp Yard – 1.65 inches
 - Suncrest and Wilson Yard – 1.20 inches
 - El Monte Yard – 1.00 inches
 - Helix Yard – 0.90 inches
 - Sycamore Substation – 0.65 inches
 - CP29-CP31 – 0.50 inches
 - CP44 – 0.60 inches
 - 69kV – 0.40 inches
- Post-storm totals for December 15, 2011
 - Jacumba Valley Ranch Yard – 0.75 inches
 - AER Yard and Fromm Yard – 1.15 inches
 - Alpine HQ and Alpine Storage Yard – 1.20 inches
 - CP101-CP109 – 1.20 inches
- BMPs were installed or maintained as needed throughout Project areas. In accordance with the Construction General Permit (CGP), daily site BMP inspections, photos, and appropriate BMPs for stormwater and non-stormwater were implemented. In accordance with the CGP, a post-storm inspection was performed as a result of the qualifying rain events. Failures and shortcomings that were identified in the post-storm inspection have been assessed and repairs/design changes to the BMPs will begin within 72 hours of identification.

Appendices

Peninsular Big Horn Sheep Monitoring Report

Flat-Tailed Horned Lizard Monitoring Report

Raven Control Monitoring Report

Flat Tailed Horned Lizard Counts - Week Ending 12/17/2011

Date	Location	Observed		Injured		Relocated		Dead	
		Day	Night	Day	Night	Day	Night	Day	Night
	Post RCLMP*								
11/1/2011	Dunaway CY					1			
10/13/2011	AR to EP354							1	
9/20/2011	AR btwn EP357 and EP358							1	
9/19/2011	AR btwn EP352 and EP353	1							
9/12/2011	EP325					1			
9/9/2011	AR to EP363	1							
9/6/2011	AR to EP360/361					1			
9/6/2011	EP360					2			
9/6/2011	EP359					1			
9/3/2011	SWPL AR to EP324					1			
9/3/2011	SWPL AR to EP342					1			
9/3/2011	SWPL AR to EP345							1	
9/3/2011	SWPL AR to EP344 and EP345					1			
8/31/2011	EP324					1			
8/31/2011	SWPL AR to EP325-2					1			
8/30/2011	SWPL AR to EP346 and EP347					1			
8/29/2011	SWPL AR to EP353 and EP354							1	
8/29/2011	SWPL AR to EP324							1	
8/27/2011	EP349					1			
8/25/2011	EP360							1	
8/25/2011	Btwn EP320/321					1			
8/24/2011	SWPL AR near EP346					1			
8/23/2011	EP349					1			
8/21/2011	SWPL AR btwn EP344/345					1			
8/21/2011	SWPL AR to EP345							1	
8/19/2011	SWPL AR to EP339					1			
8/20/2011	SWPL AR to IV Sub							1	
8/20/2011	SWPL AR btwn EP346/347					1			
8/19/2011	EP338/339 Pullsite					1			
8/19/2011	EP355/356 Pullsite					1			
8/18/2011	EP347					1			
8/18/2011	SWPL AR to EP353							1	
8/11/2011	SWPL AR by EP348					1			
8/11/2011	EP348/EP349 Pullsite					1			
8/10/2011	EP347					1			
8/8/2011	SWPL AR to EP351					2			
8/6/2011	BLM AR near EP327							1	
8/1/2011	IV Substation Yard	1							
8/1/2011	EP325					1			
8/1/2011	AR to EP345					1			
7/30/2011	EP322					1			
7/28/2011	EP355/EP356 Pullsite					1			
7/27/2011	Near EP316-2	1							

Flat Tailed Horned Lizard Counts - Week Ending 12/17/2011

Date	Location	Observed		Injured		Relocated		Dead	
Post RCLMP*		Day	Night	Day	Night	Day	Night	Day	Night
7/26/2011	SWPL AR to EP344	1							
7/26/2011	EP347					1			
7/26/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/22/2011	AR to IV Sub					1			
7/21/2011	EP360					1			
7/21/2011	AR to EP326					1			
7/19/2011	SWPL AR to IV Sub	1							
7/19/2011	EP353					1			
7/19/2011	AR to Dunaway CY					1			
7/18/2011	EP318					1			
7/17/2011	EP355					1			
7/15/2011	EP359	1							
7/15/2011	EP352	1							
7/15/2011	EP350	1							
7/14/2011	Spur Rd to EP355							1	
7/14/2011	EP322	1							
7/13/2011	EP357	1							
7/12/2011	EP344	1							
7/12/2011	SWPL AR btwn EP348/345							1	
TOTAL POST RCLMP		12	0	0	0	43	0	12	
Prior to RCLMP		Day		Day		Day		Day	
7/11/2011	AR to EP352					2			
7/11/2011	AR to EP345					2			
7/10/2011	EP358					1			
7/10/2011	SWPL AR to EP354					2			
7/9/2011	AR to EP330	1							
7/8/2011	Spur Rd. to EP352	1							
7/7/2011	EP324					1			
7/7/2011	EP355					1			
7/6/2011	SWPL AR btwn EP362/363							1	
7/5/2011	EP354					1			
7/1/2011	AR to EP353	1							
6/30/2011	AR between EP310/311							1	
6/30/2011	EP358	1							
6/30/2011	EP360	1							
6/30/2011	AR to EP312							1	
6/30/2011	EP360							1	
6/27/2011	EP350					1			
6/27/2011	SWPL AR to IV Substation	2							
6/26/2011	IV Substation					1			

Flat Tailed Horned Lizard Counts - Week Ending 12/17/2011

Date	Location	Observed	Injured	Relocated	Dead
6/25/2011	SWPL AR to EP361	1			
6/24/2011	EP359			1	
6/23/2011	SWPL AR to EP360			2	
6/22/2011	SWPL AR to EP355			1	
6/20/2011	EP356	2			
6/20/2011	SWPL AR to EP359	1			
6/20/2011	Near EP356	2			
6/20/2011	AR between EP358/357				1
6/18/2011	AR to Dunaway CY				1
6/17/2011	Near EP322	1			
6/7/2011	Near EP355	1			
6/7/2011	EP361			1	
6/7/2011	AR btwn EP343/EP344				1
6/7/2011	AR between EP324/325				1
6/6/2011	SWPL AR btwn EP344/EP345			1	
6/3/2011	EP359			1	
6/3/2011	SWPL AR EP362			1	
6/2/2011	AR to EP358			1	
6/2/2011	SWPL AR to EP316-2				1
6/2/2011	AR east of EP325				1
6/1/2011	SWPL AR btwn EP319/EP320			1	
6/1/2011	SWPL AR to EP318			1	
5/31/2011	SWPL AR btwn EP359/EP360			1	
5/31/2011	SWPL AR to EP320			1	
5/31/2011	EP360				1
5/27/2011	EP357			1	
5/26/2011	SWPL AR to EP359			1	
5/25/2011	Spur Rd to EP321			1	
5/23/2011	EP323			1	
5/21/2011	EP324			1	
5/20/2011	IV CY			1	
5/20/2011	AR to EP362			1	
5/20/2011	AR btwn EP324/EP325			1	
5/20/2011	SWPL AR btwn EP326/EP327			1	
5/20/2011	IV Substation			3	
5/19/2011	IV Substation			5	
5/19/2011	EP324			1	
5/18/2011	IV Substation Yard			1	
5/18/2011	IV Substation Yard				1
5/17/2011	AR to IV Substation				1
5/16/2011	IV Substation Yard			1	
5/13/2011	SWPL AR Near EP362-1	1			
5/12/2011	AR to EP355			1	
5/11/2011	EP360	1			

Flat Tailed Horned Lizard Counts - Week Ending 12/17/2011					
Date	Location	Observed	Injured	Relocated	Dead
5/11/2011	Dunaway CY	3			
5/11/2011	Dunaway Yard			4	
5/10/2011	EP322	1			
5/10/2011	AR to Dunaway CY	1			
5/9/2011	Dunaway Yard			4	
5/7/2011	EP322	1			
5/7/2011	Spur Road to EP344	1			
5/7/2011	Dunaway Yard			1	
5/6/2011	AR to EP321-1	1			
5/5/2011	AR to EP321-1	1			
5/5/2011	AR to Dunaway CY	2			
5/5/2011	Dunaway Yard			2	
5/4/2011	AR btwn EP343/EP344			1	
5/3/2011	SWPL AR btwn EP320/EP321	1			
4/27/2011	AR to EP322	2			
4/26/2011	EP322	1			
4/25/2011	Plaster City CY	1			
4/20/2011	Plaster City			1	
4/18/2011	Plaster City			1	
4/14/2011	AR to IV Substation	1			
4/2/2011	Dunaway CY	1			
TOTAL PRIOR TO RCLMP		35	0	60	13
YTD		47	0	103	25

*RCLMP refers to the Revised Construction Lighting Mitigation Plan

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
12/17/2011	EP274-EP278	0	Site clearance survey
12/17/2011	EP274-EP278	0	Monitoring construction activities
12/17/2011	EP269-EP281	0	Site clearance survey
12/17/2011	EP269-EP281	0	Monitoring construction activities
12/17/2011	EP269-EP273	0	Site clearance survey
12/17/2011	EP269-EP273	0	Monitoring construction activities
12/17/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
12/17/2011	EP269	0	Monitoring construction activities
12/17/2011	EP263B-EP267	0	Site clearance survey
12/17/2011	EP263B-EP267	0	Monitoring construction activities
12/17/2011	EP279-EP294	0	Site clearance survey
12/17/2011	EP279-EP294	0	Monitoring construction activities
12/17/2011	EP274-EP278	0	Site clearance survey
12/17/2011	EP274-EP278	0	Monitoring construction activities
12/16/2011	EP304-EP295	0	Monitoring construction activities
12/16/2011	EP300-EP312	0	Site clearance survey
12/16/2011	EP300-EP312	0	Monitoring construction activities
12/16/2011	EP269-EP281	0	Site clearance survey
12/16/2011	EP269-EP281	0	Monitoring construction activities
12/16/2011	EP269-EP273	0	Site clearance survey
12/16/2011	EP269-EP273	0	Monitoring construction activities
12/16/2011	EP269	0	Monitoring construction activities
12/16/2011	EP261A	0	Monitoring construction activities
12/16/2011	EP263B-EP269	0	Site clearance survey
12/16/2011	EP263B-EP269	0	Monitoring construction activities
12/15/2011	EP303	0	Monitoring construction activities
12/15/2011	EP300-EP312	0	Site clearance survey
12/15/2011	EP300-EP312	0	Monitoring construction activities
12/15/2011	EP269-EP281	0	Site clearance survey
12/15/2011	EP269-EP281	0	Monitoring construction activities
12/15/2011	EP269-EP273	0	Site clearance survey
12/15/2011	EP269-EP273	0	Monitoring construction activities
12/15/2011	EP267-2	0	Monitoring construction activities
12/15/2011	EP263A-2	0	Monitoring construction activities
12/15/2011	EP279-EP294	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
12/15/2011	EP279-EP294	0	Monitoring construction activities
12/15/2011	EP274-EP278	0	Site clearance survey
12/15/2011	EP274-EP278	0	Monitoring construction activities
12/15/2011	EP269	0	Monitoring construction activities
12/15/2011	EP263B-EP269	0	Site clearance survey
12/15/2011	EP263B-EP269	0	Monitoring construction activities
12/14/2011	EP302	0	Monitoring construction activities
12/14/2011	EP300-EP312	0	Site clearance survey
12/14/2011	EP300-EP312	0	Monitoring construction activities
12/14/2011	EP277-1, EP271-2 and EP270-2	0	Monitoring construction activities
12/14/2011	EP269-EP281	0	Site clearance survey
12/14/2011	EP269-EP281	0	Monitoring construction activities
12/14/2011	EP269-EP270	0	Site clearance survey
12/14/2011	EP269-EP270	0	Monitoring construction activities
12/14/2011	EP269-EP273	0	Site clearance survey
12/14/2011	EP269-EP273	0	Monitoring construction activities
12/14/2011	EP262-4	0	Monitoring construction activities
12/14/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/14/2011	EP279-EP294	0	Site clearance survey
12/14/2011	EP279-EP294	0	Monitoring construction activities
12/14/2011	EP274-EP278	0	Site clearance survey
12/14/2011	EP274-EP278	0	Monitoring construction activities
12/13/2011	EP300-EP312	0	Site clearance survey
12/13/2011	EP300-EP312	0	Monitoring construction activities
12/13/2011	EP269-EP270	0	Site clearance survey
12/13/2011	EP269-EP270	0	Monitoring construction activities
12/13/2011	EP269-EP273	0	Site clearance survey
12/13/2011	EP269-EP273	0	Monitoring construction activities
12/13/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/13/2011	EP256-EP312	0	Monitoring construction activities
12/13/2011	EP279-EP294	0	Site clearance survey
12/13/2011	EP279-EP294	0	Monitoring construction activities
12/13/2011	EP274-EP278	0	Site clearance survey
12/13/2011	EP274-EP278	0	Monitoring construction activities
12/12/2011	EP306/EP307 Pullsite, EP302	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
12/12/2011	EP300-EP312	0	Site clearance survey
12/12/2011	EP300-EP312	0	Monitoring construction activities
12/12/2011	EP300, EP304	0	Monitoring construction activities
12/12/2011	EP291, EP301	0	Monitoring construction activities
12/12/2011	EP269-EP270	0	Site clearance survey
12/12/2011	EP269-EP270	0	Monitoring construction activities
12/12/2011	EP269-EP273	0	Site clearance survey
12/12/2011	EP269-EP273	0	Monitoring construction activities
12/12/2011	EP267-2	0	Monitoring construction activities
12/12/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/12/2011	EP279-EP294	0	Site clearance survey
12/12/2011	EP279-EP294	0	Monitoring construction activities
12/12/2011	EP274-EP278	0	Site clearance survey
12/12/2011	EP274-EP278	0	Monitoring construction activities
12/11/2011	EP291	0	Monitoring construction activities
12/11/2011	EP281, EP280 & EP270-2	0	Monitoring construction activities
12/11/2011	EP273-1 & EP275-1	0	Monitoring construction activities
12/11/2011	EP270-2	0	Monitoring construction activities
12/11/2011	EP269-EP281	0	Site clearance survey
12/11/2011	EP269-EP281	0	Monitoring construction activities
12/11/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
12/11/2011	EP269-EP273	0	Site clearance survey
12/11/2011	EP269-EP273	0	Monitoring construction activities
12/11/2011	EP264-4	0	Monitoring construction activities
12/11/2011	EP263B-EP269	0	Site clearance survey
12/11/2011	EP263A-2 and EP264-4	0	Monitoring construction activities
12/11/2011	EP261A	0	Monitoring construction activities
12/11/2011	EP256-EP263A	0	Site clearance survey
12/11/2011	EP256-EP263A	0	Monitoring construction activities
12/11/2011	EP279-EP294	0	Site clearance survey
12/11/2011	EP279-EP294	0	Monitoring construction activities
12/11/2011	EP274-EP278	0	Site clearance survey
12/11/2011	EP274-EP278	0	Monitoring construction activities
12/10/2011	EP300-EP312	0	Site clearance survey
12/10/2011	EP300-EP312	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
12/10/2011	EP291, EP313, EP330-1, EP339 & EP363	0	Monitoring construction activities
12/10/2011	EP274-EP278	0	Site clearance survey
12/10/2011	EP274-EP278	0	Monitoring construction activities
12/10/2011	EP269-EP270	0	Site clearance survey
12/10/2011	EP269-EP270	0	Monitoring construction activities
12/10/2011	EP269-1, EP271-2, EP282-3 & EP273-1	0	Monitoring construction activities
12/10/2011	EP269-EP281	0	Site clearance survey
12/10/2011	EP269-EP281	0	Monitoring construction activities
12/10/2011	EP269-EP273	0	Site clearance survey
12/10/2011	EP269-EP273	0	Monitoring construction activities
12/10/2011	EP267-2	0	Monitoring construction activities
12/10/2011	EP263B-EP269	0	Site clearance survey
12/10/2011	EP262-4	0	Monitoring construction activities
12/9/2011	EP300-EP312	0	Site clearance survey
12/9/2011	EP300-EP312	0	Monitoring construction activities
12/9/2011	EP274-EP278	0	Site clearance survey
12/9/2011	EP274-EP278	0	Monitoring construction activities
12/9/2011	EP272-3	0	Monitoring construction activities
12/9/2011	EP269-EP281	0	Site clearance survey
12/9/2011	EP269-EP281	0	Monitoring construction activities
12/9/2011	EP269-EP273	0	Site clearance survey
12/9/2011	EP269-EP273	0	Monitoring construction activities
12/9/2011	EP267-2	0	Monitoring construction activities
12/9/2011	EP263B-EP269	0	Site clearance survey
12/9/2011	EP262-4	0	Monitoring construction activities
12/8/2011	EP301	0	Monitoring construction activities
12/8/2011	EP281	0	Monitoring construction activities
12/8/2011	EP272-3	0	Monitoring construction activities
12/8/2011	EP269-EP312	0	Site clearance survey
12/8/2011	EP269-EP273	0	Site clearance survey
12/8/2011	EP267-2	0	Monitoring construction activities
12/8/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/8/2011	EP274-EP278	0	Site clearance survey
12/8/2011	EP274-EP278	0	Monitoring construction activities
12/7/2011	EP301	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
12/7/2011	EP300-EP312	5	Site clearance survey-Observed outside project area
12/7/2011	EP300-EP312	0	Site clearance survey
12/7/2011	EP300-EP312	0	Monitoring construction activities
12/7/2011	EP274-EP278	0	Site clearance survey
12/7/2011	EP274-EP278	0	Monitoring construction activities
12/7/2011	EP269-EP273	0	Site clearance survey
12/7/2011	EP269-EP272	0	Site clearance survey
12/7/2011	EP269-EP281	0	Site clearance survey
12/7/2011	EP269-EP281	0	Monitoring construction activities
12/7/2011	EP259B and EP259-3	0	Monitoring construction activities
12/7/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/6/2011	EP301	0	Monitoring construction activities
12/6/2011	EP300-EP308	0	Monitoring construction activities
12/6/2011	EP300-EP312	0	Site clearance survey
12/6/2011	EP300-EP312	0	Monitoring construction activities
12/6/2011	EP271-2	0	Monitoring construction activities
12/6/2011	EP271-2	0	Monitoring construction activities
12/6/2011	EP269-EP273	0	Site clearance survey
12/6/2011	EP269-EP272	1	Site clearance survey
12/6/2011	EP269-1 to EP255	0	Monitoring construction activities
12/6/2011	EP269-1	0	Monitoring construction activities
12/6/2011	EP269-EP281	0	Site clearance survey
12/6/2011	EP269-EP281	0	Monitoring construction activities
12/6/2011	EP267-2-GS-NF-38	0	Monitoring construction activities
12/6/2011	EP267-2-GS-NF-38	0	Monitoring construction activities
12/6/2011	EP259B	0	Monitoring construction activities
12/6/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/6/2011	EP279-EP294	0	Site clearance survey
12/6/2011	EP279-EP294	0	Monitoring construction activities
12/6/2011	EP274-EP278	1	Site clearance survey-Area remained open to ground crews
12/6/2011	EP274-EP278	Same 1 as noted above	Monitoring construction activities
12/5/2011	EP300-EP312	1	Site clearance survey-Area remained open to ground crews
12/5/2011	EP300-EP312	Same 1 as noted above	Monitoring construction activities
12/5/2011	EP300-EP312	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
12/5/2011	EP300-EP312	0	Monitoring construction activities
12/5/2011	EP275-1, EP276-1	0	Monitoring construction activities
12/5/2011	EP274-EP278	0	Site clearance survey
12/5/2011	EP274-EP278	0	Monitoring construction activities
12/5/2011	EP272	1	Site clearance survey-Ram detected in boudary of low-elevation flight boundary
12/5/2011	EP269-EP272	Same 1 as noted above	Site clearance survey
12/5/2011	EP269-1	0	Monitoring construction activities
12/5/2011	EP269-EP281	0	Site clearance survey
12/5/2011	EP269-EP281	0	Monitoring construction activities
12/5/2011	EP267-2-GS-NF-38	0	Monitoring construction activities
12/5/2011	EP263B-2, EP263A-2, EP262-4 and EP261A	0	Monitoring construction activities
12/5/2011	EP259B	0	Monitoring construction activities
12/5/2011	EP258-3	0	Monitoring construction activities
12/5/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/5/2011	EP279-EP294	0	Site clearance survey
12/5/2011	EP279-EP294	0	Monitoring construction activities
12/4/2011	EP300-EP312	0	Site clearance survey
12/4/2011	EP300-EP312	0	Monitoring construction activities
12/4/2011	EP294	0	Monitoring construction activities
12/4/2011	EP280, EP275-1	0	Monitoring construction activities
12/4/2011	EP274-EP278	0	Site clearance survey
12/4/2011	EP274-EP278	0	Monitoring construction activities
12/4/2011	EP273-1, EP278-1, EP279-1 and EP280	0	Monitoring construction activities
12/4/2011	EP269-1-E	0	Monitoring construction activities
12/4/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
12/4/2011	EP269-EP281	0	Monitoring construction activities
12/4/2011	EP269-EP281	0	Site clearance survey
12/4/2011	EP256-EP263A	1	Site clearance survey-Area remained open to ground crews
12/4/2011	EP279-EP294	0	Monitoring construction activities
12/4/2011	EP279-EP294	0	Site clearance survey
12/4/2011	EP267-2-GS-NF-38	0	Monitoring construction activities
12/3/2011	EP300-EP312	0	Site clearance survey
12/3/2011	EP300-EP312	0	Monitoring construction activities
12/3/2011	EP278-1, EP279-1 & EP280-2	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
12/3/2011	EP274-EP278	0	Site clearance survey
12/3/2011	EP274-EP278	0	Monitoring construction activities
12/3/2011	EP269-EP270	0	Site clearance survey
12/3/2011	EP269-EP270	0	Monitoring construction activities
12/3/2011	EP269-EP281	0	Site clearance survey
12/3/2011	EP269-EP281	0	Monitoring construction activities
12/3/2011	EP263B-EP269	0	Site clearance survey
12/3/2011	EP263B-EP269	0	Monitoring construction activities
12/3/2011	EP257	0	Monitoring construction activities
12/3/2011	EP256-EP263A	2	Site clearance survey
12/3/2011	EP256-EP263A	Same 2 listed above	Monitoring construction activities
12/3/2011	EP279-EP294	0	Site clearance survey
12/3/2011	EP279-EP294	0	Monitoring construction activities
12/2/2011	EP300-EP312	0	Site clearance survey
12/2/2011	EP300-EP312	0	Monitoring construction activities
12/2/2011	EP300-EP312	0	Site clearance survey
12/2/2011	EP300-EP312	0	Monitoring construction activities
12/2/2011	EP281-GS-BLM-3	0	Monitoring construction activities
12/2/2011	EP280-EP281	0	Monitoring construction activities
12/2/2011	EP274-EP278	0	Site clearance survey
12/2/2011	EP274-EP278	0	Monitoring construction activities
12/2/2011	EP269-EP273	0	Site clearance survey
12/2/2011	EP269-EP281	0	Site clearance survey
12/2/2011	EP269-EP281	0	Monitoring construction activities
12/2/2011	EP263B-EP269	0	Site clearance survey
12/2/2011	EP263B-EP269	0	Monitoring construction activities
12/2/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/2/2011	EP279-EP294	0	Site clearance survey
12/2/2011	EP279-EP294	0	Monitoring construction activities
12/1/2011	EP300-EP312	0	Site clearance survey
12/1/2011	EP279-EP294; EP273-EP276	0	Site clearance survey
12/1/2011	EP279-EP294; EP273-EP276	0	Monitoring construction activities
12/1/2011	EP274-1, EP275-1	0	Monitoring construction activities
12/1/2011	EP274-EP278	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
12/1/2011	EP274-EP278	0	Monitoring construction activities
12/1/2011	EP269-EP273	0	Site clearance survey
12/1/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/30/2011	EP300-EP312	0	Site clearance survey
11/30/2011	EP300-EP312	0	Monitoring construction activities
11/30/2011	EP300-EP312	0	Site clearance survey
11/30/2011	EP274-EP278	0	Site clearance survey
11/30/2011	EP274-EP278	0	Monitoring construction activities
11/30/2011	EP273-1	0	Monitoring construction activities
11/30/2011	EP269-EP281	0	Site clearance survey
11/30/2011	EP269-EP281	0	Monitoring construction activities
11/30/2011	EP269-EP281	0	Site clearance survey
11/30/2011	EP269-EP281	0	Monitoring construction activities
11/30/2011	EP269-EP273	0	Site clearance survey
11/30/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/30/2011	EP279-EP294	0	Site clearance survey
11/30/2011	EP279-EP294	0	Monitoring construction activities
11/29/2011	EP300-EP312	0	Site clearance survey
11/29/2011	EP300-EP312	0	Monitoring construction activities
11/29/2011	EP300-EP312	0	Site clearance survey
11/29/2011	EP300-EP312	0	Monitoring construction activities
11/29/2011	EP274-EP278	0	Site clearance survey
11/29/2011	EP274-EP278	0	Monitoring construction activities
11/29/2011	EP273-1	0	Monitoring construction activities
11/29/2011	EP269-EP281	0	Site clearance survey
11/29/2011	EP269-EP281	0	Monitoring construction activities
11/29/2011	EP269-EP281	0	Site clearance survey
11/29/2011	EP269-EP281	0	Monitoring construction activities
11/29/2011	EP269-EP273	0	Site clearance survey
11/29/2011	EP269-EP281	0	Site clearance survey
11/29/2011	EP269-EP281	0	Monitoring construction activities
11/29/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/29/2011	EP279-EP294	0	Site clearance survey
11/29/2011	EP279-EP294	0	Monitoring construction activities
11/28/2011	EP300-EP312	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
11/28/2011	EP300-EP312	0	Monitoring construction activities
11/28/2011	EP274-EP278	0	Site clearance survey
11/28/2011	EP274-EP278	0	Monitoring construction activities
11/28/2011	EP273-1	0	Monitoring construction activities
11/28/2011	EP269-EP281	0	Site clearance survey
11/28/2011	EP269-EP281	0	Monitoring construction activities
11/28/2011	EP269-EP273	0	Site clearance survey
11/28/2011	EP269-EP273	0	Monitoring construction activities
11/28/2011	EP269-EP270	0	Site clearance survey
11/28/2011	EP269-EP281	0	Site clearance survey
11/28/2011	EP269-EP281	0	Monitoring construction activities
11/28/2011	EP263B-EP267	0	Site clearance survey
11/28/2011	EP263B-EP267	0	Monitoring construction activities
11/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/28/2011	EP279-EP294	0	Site clearance survey
11/28/2011	EP279-EP294	0	Monitoring construction activities
11/27/2011	EP300-EP312	0	Site clearance survey
11/27/2011	EP300-EP312	0	Monitoring construction activities
11/27/2011	EP279-1 & EP280-2	0	Monitoring construction activities
11/27/2011	EP274-EP278	0	Site clearance survey
11/27/2011	EP274-EP278	0	Monitoring construction activities
11/27/2011	EP269-EP281	0	Site clearance survey
11/27/2011	EP269-EP281	0	Monitoring construction activities
11/27/2011	EP269-EP281	0	Site clearance survey
11/27/2011	EP269-EP281	0	Monitoring construction activities
11/27/2011	EP269-EP274	3	Site clearance survey
11/27/2011	EP269-EP274	Same 3 as noted above	Monitoring construction activities
11/27/2011	EP269-EP270	0	Site clearance survey
11/27/2011	EP269-EP281	0	Site clearance survey
11/27/2011	EP269-EP281	0	Monitoring construction activities
11/27/2011	EP263B-EP269	0	Site clearance survey
11/27/2011	EP263B-EP269	0	Monitoring construction activities
11/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/27/2011	EP279-EP294	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
11/27/2011	EP279-EP294	0	Monitoring construction activities
11/26/2011	EP300-EP312	0	Site clearance survey
11/26/2011	EP300-EP312	0	Monitoring construction activities
11/26/2011	EP274-EP278	0	Site clearance survey
11/26/2011	EP274-EP278	0	Monitoring construction activities
11/26/2011	EP269-EP271	11	Site clearance survey - Six PBS sited approaching EP270 @ 11:30am. At 5:00pm 5 PBS were sited near EP270
11/26/2011	EP269-EP271	Same 11 as noted above	Monitoring construction activities
11/26/2011	EP269-EP273	Same 11 as noted above	Site clearance survey
11/26/2011	EP269-EP273	Same 11 as noted above	Monitoring construction activities
11/26/2011	EP270	Same 11 as noted above	Site clearance survey
11/26/2011	EP269-EP281	0	Site clearance survey
11/26/2011	EP269-EP281	0	Monitoring construction activities
11/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/26/2011	EP279-EP294	0	Site clearance survey
11/25/2011	EP274-EP278	0	Site clearance survey
11/25/2011	EP274-EP278	0	Monitoring construction activities
11/25/2011	EP272	0	Site clearance survey
11/25/2011	EP269-EP273	1	Site clearance survey - 1 Ram was sighted near EP272 in am
11/25/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/25/2011	EP279-EP294	0	Monitoring construction activities
11/24/2011	EP269-EP273	0	Site clearance survey
11/24/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/24/2011	EP279-EP294	0	Site clearance survey
11/23/2011	EP300-EP312, EP269-EP281	0	Site clearance survey
11/23/2011	EP300-EP312, EP269-EP281	0	Monitoring construction activities
11/23/2011	EP274-EP278	0	Site clearance survey
11/23/2011	EP274-EP278	0	Monitoring construction activities
11/23/2011	EP270-2	0	Monitoring construction activities
11/23/2011	EP269-EP273	0	Site clearance survey
11/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/22/2011	EP277-1	0	Monitoring construction activities
11/22/2011	EP274-EP278	0	Site clearance survey
11/22/2011	EP269-EP281	0	Site clearance survey
11/22/2011	EP269-EP273	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
11/22/2011	EP269-EP270	0	Site clearance survey
11/22/2011	EP269-EP270	0	Monitoring construction activities
11/22/2011	EP269-EP281	0	Site clearance survey
11/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/22/2011	EP279-EP294	0	Site clearance survey
11/22/2011	EP279-EP294	0	Monitoring construction activities
11/21/2011	EP269-EP281	1	Site clearance survey
11/21/2011	EP300-EP312	0	Site clearance survey
11/21/2011	EP300-EP312	0	Monitoring construction activities
11/21/2011	EP300-EP312	0	Site clearance survey
11/21/2011	EP300-EP312	0	Monitoring construction activities
11/21/2011	EP281	0	Monitoring construction activities
11/21/2011	EP276-1-EP270-2	0	Monitoring construction activities
11/21/2011	EP274-EP278	0	Site clearance survey
11/21/2011	EP274-EP278	0	Monitoring construction activities
11/21/2011	EP272	1	Site clearacne surve - 6:45am 1 ram sighted near EP272
11/21/2011	EP269-EP281	0	Site clearance survey
11/21/2011	EP269-EP281	0	Monitoring construction activities
11/21/2011	EP265-2-EP281	0	Monitoring construction activities
11/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/21/2011	EP279-EP294	0	Site clearance survey
11/21/2011	EP279-EP294	0	Monitoring construction activities
11/20/2011	EP300-EP312	0	Site clearance survey
11/20/2011	EP300-EP312	0	Site clearance survey
11/20/2011	EP300-EP312	0	Monitoring construction activities
11/20/2011	EP277-1 and EP272-3	0	Monitoring construction activities
11/20/2011	EP274-EP278	0	Site clearance survey
11/20/2011	EP274-EP278	0	Monitoring construction activities
11/20/2011	EP271	0	Site clearance survey
11/20/2011	EP271	0	Monitoring construction activities
11/20/2011	EP269-EP281	0	Site clearance survey
11/20/2011	EP269-EP281	0	Monitoring construction activities
11/20/2011	EP256-EP263A	0	Site clearance survey
11/20/2011	EP256-EP263A	0	Monitoring construction activities
11/19/2011	EP300-EP312	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
11/19/2011	EP300-EP312	0	Monitoring construction activities
11/19/2011	EP300-EP312	0	Site clearance survey
11/19/2011	EP300-EP312	0	Monitoring construction activities
11/19/2011	EP281	0	Monitoring construction activities
11/19/2011	EP277-1	0	Monitoring construction activities
11/19/2011	EP274-EP278	0	Site clearance survey
11/19/2011	EP274-EP278	0	Monitoring construction activities
11/19/2011	EP269-EP281	0	Site clearance survey
11/19/2011	EP269-EP281	0	Monitoring construction activities
11/19/2011	EP256-EP263A	0	Site clearance survey
11/19/2011	EP256-EP263A	0	Monitoring construction activities
11/18/2011	EP300-EP312	0	Site clearance survey
11/18/2011	EP300-EP312	0	Monitoring construction activities
11/18/2011	EP281-GS-BLM-3	0	Monitoring construction activities
11/18/2011	EP276-1	0	Monitoring construction activities
11/18/2011	EP274-EP278	0	Site clearance survey
11/18/2011	EP274-EP278	0	Monitoring construction activities
11/18/2011	EP272	16	Site clearance survey-PBS were observed within Devil's Cyn 2 west of EP272 @ ~8:00am. At that time the flight corridor was closed to low-elevation flights from EP271-EP273
11/18/2011	EP272	Same 16 PBS as noted above	Monitoring construction activities
11/18/2011	EP269-EP281	0	Site clearance survey
11/18/2011	EP269-EP281	0	Monitoring construction activities
11/18/2011	EP256-EP263A	0	Site clearance survey
11/18/2011	EP256-EP263A	0	Monitoring construction activities
11/17/2011	EP281-GS-BLM-3 & EP290-GS-NF-40	0	Monitoring construction activities
11/17/2011	EP277-1	0	Monitoring construction activities
11/17/2011	EP271-EP274	0	Site clearance survey
11/17/2011	EP300-EP312	0	Site clearance survey
11/17/2011	EP300-EP312	0	Monitoring construction activities
11/16/2011	EP300-EP312	0	Site clearance survey
11/16/2011	EP300-EP312	0	Monitoring construction activities
11/16/2011	EP276-1	0	Monitoring construction activities
11/16/2011	EP272	13	Site clearance survey-PBS were observed ~300 feet west of EP272 at ~7:00am. At that time, low-elevation flights were closed from EP271-EP274
11/16/2011	EP272	Same 13 PBS as noted above	Monitoring construction activities
11/16/2011	EP269-EP281	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
11/16/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/16/2011	EP274-EP278	0	Site clearance survey
11/16/2011	EP274-EP278	0	Monitoring construction activities
11/16/2011	EP269-EP281	0	Site clearance survey
11/16/2011	EP269-EP281	0	Monitoring construction activities
11/15/2011	EP269-EP273	0	Site clearance survey
11/15/2011	EP269-EP281	0	Site clearance survey
11/15/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/15/2011	EP274-EP278	0	Site clearance survey
11/15/2011	EP274-EP278	0	Monitoring construction activities
11/15/2011	AER and Fromm CY's	0	Monitoring construction activities
11/14/2011	EP306-EP312	0	Site clearance survey
11/14/2011	EP269-EP273	0	Site clearance survey
11/14/2011	EP263A-2, EP263B-2	0	Monitoring construction activities
11/14/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/14/2011	EP274-EP278	0	Site clearance survey
11/14/2011	EP274-EP278	0	Monitoring construction activities
11/13/2011	EP306-EP312	0	Site clearance survey
11/13/2011	EP300-EP312	0	Site clearance survey
11/13/2011	EP300-EP312	0	Monitoring construction activities
11/13/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/13/2011	EP274-EP278	0	Site clearance survey
11/13/2011	EP274-EP278	0	Monitoring construction activities
11/13/2011	EP269-EP281	0	Site clearance survey
11/13/2011	EP269-EP281	0	Monitoring construction activities
11/12/2011	EP300-EP312	0	Site clearance survey
11/12/2011	EP300-EP312	0	Monitoring construction activities
11/12/2011	EP269-EP281	0	Site clearance survey
11/12/2011	EP269-EP281	0	Monitoring construction activities
11/12/2011	EP263B-2	0	Monitoring construction activities
11/12/2011	EP274-EP278	0	Site clearance survey
11/12/2011	EP274-EP278	0	Monitoring construction activities
11/12/2011	EP269-EP281	0	Site clearance survey
11/12/2011	EP269-EP281	0	Monitoring construction activities
11/11/2011	EP306-EP312	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
11/11/2011	EP300-EP312	0	Monitoring construction activities
11/11/2011	EP269-EP281	0	Site clearance survey
11/11/2011	EP269-EP281	0	Monitoring construction activities
11/11/2011	EP269-EP273	0	Site clearance survey
11/11/2011	EP269-EP270	0	Site clearance survey
11/11/2011	EP269-EP270	0	Monitoring construction activities
11/11/2011	EP263B-EP267	0	Site clearance survey
11/11/2011	EP263B-EP267	0	Monitoring construction activities
11/11/2011	EP274-EP278	0	Site clearance survey
11/11/2011	EP274-EP278	0	Monitoring construction activities
11/11/2011	EP269-EP281	0	Site clearance survey
11/11/2011	EP269-EP281	0	Monitoring construction activities
11/10/2011	EP306-EP312	0	Site clearance survey
11/10/2011	EP269-EP273	0	Site clearance survey
11/10/2011	EP269-EP281	0	Site clearance survey
11/10/2011	EP269-EP281	0	Monitoring construction activities
11/10/2011	EP269-EP270	0	Site clearance survey
11/10/2011	EP269-EP270	0	Monitoring construction activities
11/10/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/10/2011	EP274-EP278	0	Site clearance survey
11/10/2011	EP274-EP278	0	Monitoring construction activities
11/9/2011	Fromm CY	0	Monitoring construction activities
11/9/2011	EP313/EP314 Pullsite	0	Monitoring construction activities
11/9/2011	EP306-EP312	0	Site clearance survey
11/9/2011	EP306	0	Monitoring construction activities
11/9/2011	EP269-EP273	0	Site clearance survey
11/9/2011	EP269-EP281	0	Site clearance survey
11/9/2011	EP269-EP281	0	Monitoring construction activities
11/9/2011	EP265-2	0	Site clearance survey
11/9/2011	EP265-2	0	Monitoring construction activities
11/9/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/9/2011	EP274-EP278	0	Site clearance survey
11/9/2011	EP274-EP278	0	Monitoring construction activities
11/9/2011	EP263B-EP267, EP269-EP281	0	Site clearance survey
11/9/2011	EP263B-EP267, EP269-EP281	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
11/8/2011	EP306-EP312	0	Site clearance survey
11/8/2011	EP300-EP312	0	Site clearance survey
11/8/2011	EP300-EP312	0	Monitoring construction activities
11/8/2011	EP280	0	Monitoring construction activities
11/8/2011	EP272-EP275	0	Site clearance survey
11/8/2011	EP272-EP275	5	Monitoring construction activities
11/8/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/8/2011	EP279-EP294	0	Site clearance survey
11/8/2011	EP279-EP294	0	Monitoring construction activities
11/8/2011	EP274-EP278	0	Site clearance survey
11/8/2011	EP274-EP278	0	Monitoring construction activities
11/8/2011	EP269-EP281	0	Site clearance survey
11/8/2011	EP269-EP281	0	Monitoring construction activities
11/8/2011	EP263B-EP267, EP269-EP281	0	Site clearance survey
11/8/2011	EP263B-EP267, EP269-EP281	0	Monitoring construction activities
11/8/2011	Devils Cyn Bridge	5	Monitoring construction activities
11/7/2011	EP307-EP308	0	Monitoring construction activities
11/7/2011	EP300-EP312	0	Site clearance survey
11/7/2011	EP300-EP312	0	Monitoring construction activities
11/7/2011	EP280	0	Monitoring construction activities
11/7/2011	EP271-EP274	3	Site clearance survey
11/7/2011	EP271-EP274	0	Site clearance survey
11/7/2011	EP271-EP274	5	Site clearance survey
11/7/2011	EP271-EP274	0	Monitoring construction activities
11/7/2011	EP269-EP271	0	Site clearance survey
11/7/2011	EP269-EP271	0	Monitoring construction activities
11/7/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/7/2011	EP278-EP281	0	Site clearance survey
11/7/2011	EP274-EP278	0	Site clearance survey
11/7/2011	EP274-EP278	0	Monitoring construction activities
11/7/2011	EP269-EP281	0	Site clearance survey
11/7/2011	EP269-EP281	0	Monitoring construction activities
11/7/2011	EP263B-EP267	0	Site clearance survey
11/7/2011	EP263B-EP267	0	Monitoring construction activities
11/6/2011	EP308-EP310	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
11/6/2011	EP303-2, EP302-1	0	Monitoring construction activities
11/6/2011	EP300-EP312	0	Site clearance survey
11/6/2011	EP300-EP312	0	Monitoring construction activities
11/6/2011	EP300-EP312	0	Site clearance survey
11/6/2011	EP300-EP312	0	Monitoring construction activities
11/6/2011	EP290-EP312, EP269-EP281	0	Site clearance survey
11/6/2011	EP290-EP312, EP269-EP281	0	Monitoring construction activities
11/6/2011	EP279-1	0	Monitoring construction activities
11/6/2011	EP269-EP281	0	Site clearance survey
11/6/2011	EP269-EP281	0	Monitoring construction activities
11/6/2011	EP274-EP278	0	Monitoring construction activities
11/6/2011	EP274-EP278	0	Site clearance survey
11/6/2011	EP269-EP281	0	Monitoring construction activities
11/6/2011	EP269-EP281	0	site clearance survey
11/5/2011	EP300-EP312	0	Site clearance survey
11/5/2011	EP300-EP312	0	Monitoring construction activities
11/5/2011	EP271-2, EP272-3, EP276-1 & EP281	0	Monitoring construction activities
11/5/2011	EP269-EP273	0	Site clearance survey
11/5/2011	EP265-2	0	Monitoring construction activities
11/5/2011	EP256-EP263A	0	Site clearance survey
11/5/2011	EP279-EP294	0	Site clearance survey
11/5/2011	EP279-EP294	0	Monitoring construction activities
11/5/2011	EP277-1	0	Monitoring construction activities
11/5/2011	EP263B-EP267	0	Site clearance survey
11/5/2011	EP263B-EP267	0	Monitoring construction activities
11/4/2011	S2 CY	0	Monitoring construction activities
11/4/2011	EP311, EP310	0	Monitoring construction activities
11/4/2011	EP307	0	Monitoring construction activities
11/4/2011	EP306/EP307 Pullsite	0	Monitoring construction activities
11/4/2011	EP300-EP312	0	Site clearance survey
11/4/2011	EP300-EP312	0	Monitoring construction activities
11/4/2011	EP269-EP273	0	Site clearance survey
11/4/2011	EP269-EP271	0	Site clearance survey
11/4/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/4/2011	EP279-EP294	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
11/4/2011	EP279-EP294	0	Monitoring construction activities
11/4/2011	EP274-EP278	0	Site clearance survey
11/4/2011	EP274-EP278	0	Monitoring construction activities
11/4/2011	EP263B-EP267	0	Site clearance survey
11/4/2011	EP263B-EP267	0	Monitoring construction activities
11/3/2011	EP311	0	Monitoring construction activities
11/3/2011	EP307	0	Monitoring construction activities
11/3/2011	EP280	0	Monitoring construction activities
11/3/2011	EP279-1	0	Monitoring construction activities
11/3/2011	EP278-1, EP279-1, EP280-1	0	Monitoring construction activities
11/3/2011	EP271-2	0	Monitoring construction activities
11/3/2011	EP269-EP273	0	Site clearance survey
11/3/2011	EP265-2	0	Monitoring construction activities
11/3/2011	EP263B-EP267; EP279-EP312	0	Site clearance survey
11/3/2011	EP261A, EP259-3	0	Monitoring construction activities
11/3/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/3/2011	EP279-EP294	0	Site clearance survey
11/3/2011	EP279-EP294	0	Monitoring construction activities
11/3/2011	EP274-EP278	0	Site clearance survey
11/3/2011	EP274-EP278	0	Monitoring construction activities
11/2/2011	EP269-EP273	0	Site clearance survey
11/2/2011	EP269-EP281	0	Site clearance survey
11/2/2011	EP269-EP281	0	Monitoring construction activities
11/2/2011	EP263B-EP267; EP279-EP312	0	Site clearance survey
11/2/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/2/2011	EP300-EP312; EP274-EP278	0	Site clearance survey
11/2/2011	EP300-EP312; EP274-EP278	0	Monitoring construction activities
11/1/2011	Suckle Property	0	Monitoring construction activities
11/1/2011	EP310 & EP311	0	Monitoring construction activities
11/1/2011	EP300-EP312	0	Site clearance survey
11/1/2011	EP300-EP312	0	Monitoring construction activities
11/1/2011	EP279-EP312	0	Site clearance survey
11/1/2011	EP277-1, EP276-1, EP261A, EP259B	0	Monitoring construction activities
11/1/2011	EP275-1	0	Monitoring construction activities
11/1/2011	EP269-EP273	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
11/1/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/1/2011	EP274-EP278	0	Site clearance survey
11/1/2011	EP274-EP278	0	Monitoring construction activities
11/1/2011	EP263B, EP267	0	Site clearance survey
11/1/2011	Devil's Canyon Bridge	0	Site clearance survey
11/1/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/31/2011	EP279-EP294	0	Site clearance survey
10/31/2011	EP279-EP294	0	Monitoring construction activities
10/31/2011	EP269-EP281	0	Site clearance survey
10/31/2011	EP269-EP281	0	Monitoring construction activities
10/31/2011	EP269-EP273	0	Site clearance survey
10/31/2011	EP269-EP281	0	Site clearance survey
10/31/2011	EP263A-2, EP266-2	0	Monitoring construction activities
10/31/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/31/2011	EP254-3	0	Monitoring construction activities
10/31/2011	EP305, EP310-1	0	Monitoring construction activities
10/31/2011	EP300-EP312	0	Site clearance survey
10/31/2011	EP300-EP312	0	Monitoring construction activities
10/31/2011	EP274-EP278	0	Site clearance survey
10/31/2011	EP263B-EP267	0	Site clearance survey
10/31/2011	Devil's Canyon Bridge	0	Site clearance survey
10/31/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/31/2011	EP262-4, EP263B-2, EP265-2, EP266-2, EP267-1	0	Monitoring construction activities
10/30/2011	EP300-EP306	0	Site clearance survey
10/30/2011	EP300-EP306	0	Monitoring construction activities
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Monitoring construction activities
10/30/2011	EP269-EP273	0	Site clearance survey
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Monitoring construction activities
10/30/2011	EP269-EP270	0	Site clearance survey
10/30/2011	EP267-2 & EP266-2	0	Monitoring construction activities
10/30/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
10/30/2011	EP279-EP294	0	Site clearance survey
10/30/2011	EP279-EP294	0	Monitoring construction activities
10/30/2011	EP274-EP278	0	Site clearance survey
10/30/2011	EP274-EP278	0	Monitoring construction activities
10/30/2011	EP263B-EP267	0	Site clearance survey
10/30/2011	Devil's Canyon Bridge	0	Site clearance survey
10/30/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/29/2011	EP300-EP306	0	Site clearance survey
10/29/2011	EP300-EP306	0	Monitoring construction activities
10/29/2011	EP274-EP278	0	Site clearance survey
10/29/2011	EP274-EP278	0	Monitoring construction activities
10/29/2011	EP269-EP273	0	Site clearance survey
10/29/2011	EP269-1	0	Monitoring construction activities
10/29/2011	EP269-EP281	0	Site clearance survey
10/29/2011	EP269-EP281	0	Monitoring construction activities
10/29/2011	EP269-EP281	0	Site clearance survey
10/29/2011	EP269-EP281	0	Monitoring construction activities
10/29/2011	EP269-EP270	0	Site clearance survey
10/29/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/29/2011	EP279-EP294	0	Site clearance survey
10/29/2011	EP279-EP294	0	Monitoring construction activities
10/29/2011	EP263B-EP267	0	Site clearance survey
10/29/2011	Devil's Cyn Bridge (w/in I-8 Island)	1	Morning perimeter survey 7:37 am
10/28/2011	EP300-EP306	0	Site clearance survey
10/28/2011	EP300-EP306	0	Monitoring construction activities
10/28/2011	EP269-EP281	0	Site clearance survey
10/28/2011	EP269-EP281	0	Monitoring construction activities
10/28/2011	EP269-EP273	0	Site clearance survey
10/28/2011	EP269-1	0	Monitoring construction activities
10/28/2011	EP269-EP281	0	Site clearance survey
10/28/2011	EP269-EP281	0	Monitoring construction activities
10/28/2011	EP269-EP270	0	Site clearance survey
10/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/28/2011	EP310	0	Monitoring construction activities
10/28/2011	EP279-EP294	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
10/28/2011	EP279-EP294	0	Monitoring construction activities
10/28/2011	EP274-EP278	0	Site clearance survey
10/28/2011	EP274-EP278	0	Monitoring construction activities
10/28/2011	EP263B-EP267	0	Site clearance survey
10/28/2011	AER and FROMM CY	0	Monitoring construction activities
10/27/2011	EP273-1 & EP276-1	0	Monitoring construction activities
10/27/2011	EP271-EP272	2	Site clearance survey 7:40 am
10/27/2011	EP271-EP272	0	Monitoring construction activities
10/27/2011	EP269-EP281; EP300-EP306	0	Site clearance survey
10/27/2011	EP269-EP281; EP300-EP306	0	Monitoring construction activities
10/27/2011	EP256-EP263A-2, AER CY	0	Site clearance survey
10/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/27/2011	EP279-EP294	0	Site clearance survey
10/27/2011	EP279-EP294	0	Monitoring construction activities
10/27/2011	EP274-EP278	0	Site clearance survey
10/27/2011	EP274-EP278	0	Monitoring construction activities
10/27/2011	EP269-EP271	0	Monitoring construction activities
10/27/2011	EP263B-EP267	0	Site clearance survey
10/27/2011	AER and FROMM CY	0	Monitoring construction activities
10/26/2011	EP311-1, EP312, EP310	0	Monitoring construction activities
10/26/2011	EP300-EP312	0	Site clearance survey
10/26/2011	EP300-EP312	0	Monitoring construction activities
10/26/2011	EP272-EP273	2	Site clearance survey 10:00 am
10/26/2011	EP272-EP273	0	Monitoring construction activities
10/26/2011	EP269-EP281; EP300-EP306	0	Site clearance survey
10/26/2011	EP269-EP281; EP300-EP306	0	Monitoring construction activities
10/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/26/2011	EP279-EP294	0	Site clearance survey
10/26/2011	EP279-EP294	0	Monitoring construction activities
10/26/2011	EP274-EP278	0	Site clearance survey
10/26/2011	EP274-EP278	0	Monitoring construction activities
10/26/2011	EP263B-EP267	0	Site clearance survey
10/25/2011	EP363-EP341, EP299 & EP300	0	Monitoring construction activities
10/25/2011	EP313-EP324	0	Monitoring construction activities
10/25/2011	EP310	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
10/25/2011	EP300-EP312	0	Site clearance survey
10/25/2011	EP300-EP312	0	Monitoring construction activities
10/25/2011	EP290	0	Monitoring construction activities
10/25/2011	EP269-EP273	0	Site clearance survey
10/25/2011	EP269-EP281; EP300-EP306	0	Site clearance survey
10/25/2011	EP269-EP281; EP300-EP306	0	Monitoring construction activities
10/25/2011	EP311	0	Monitoring construction activities
10/25/2011	EP279-EP294	0	Site clearance survey
10/25/2011	EP263B-EP267	0	Site clearance survey
10/24/2011	EP313-EP322	0	Monitoring construction activities
10/24/2011	EP305, EP306, EP312	0	Monitoring construction activities
10/24/2011	EP300-EP306	0	Site clearance survey
10/24/2011	EP300-EP306	0	Monitoring construction activities
10/24/2011	EP297-EP319	0	Monitoring construction activities
10/24/2011	EP269-EP273	0	Site clearance survey
10/24/2011	EP269-EP273	0	Monitoring construction activities
10/24/2011	EP269-EP281	0	Site clearance survey
10/24/2011	EP269-EP281	0	Monitoring construction activities
10/24/2011	EP279-EP294	0	Site clearance survey
10/24/2011	EP279-EP294	0	Monitoring construction activities
10/24/2011	EP274-EP278	0	Site clearance survey
10/24/2011	EP274-EP278	0	Monitoring construction activities
10/24/2011	EP263B-EP267	0	Site clearance survey
10/23/2011	EP300-EP312	0	Site clearance survey
10/23/2011	EP300-EP312	0	Monitoring construction activities
10/23/2011	EP269-EP273	0	Site clearance survey
10/23/2011	EP269-EP273	0	Monitoring construction activities
10/23/2011	EP269-EP281	0	Site clearance survey
10/23/2011	EP269-EP281	0	Monitoring construction activities
10/23/2011	EP269-EP270	0	Site clearance survey
10/23/2011	EP263B-EP267	0	Site clearance survey
10/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/23/2011	EP300-EP312	0	Site clearance survey
10/23/2011	EP300-EP312	0	Monitoring construction activities
10/23/2011	EP274-EP278	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
10/23/2011	EP274-EP278	0	Monitoring construction activities
10/23/2011	EP269-EP273	0	Site clearance survey
10/23/2011	EP269-EP273	0	Monitoring construction activities
10/22/2011	EP300-EP306	0	Site clearance survey
10/22/2011	EP300-EP306	0	Monitoring construction activity
10/22/2011	EP269-EP281	0	Site clearance survey
10/22/2011	EP269-EP281	0	Monitoring construction activity
10/22/2011	EP269-EP281	0	Site clearance survey
10/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/22/2011	EP274-EP278	0	Site clearance survey
10/22/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP306-EP312	0	Site clearance survey
10/21/2011	EP306-EP312	0	Monitoring construction activity
10/21/2011	EP274-EP278	0	Site clearance survey
10/21/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP269-EP281	0	Site clearance survey
10/21/2011	EP269-EP281	0	Site clearance survey
10/21/2011	EP269-EP281	0	Monitoring construction activity
10/21/2011	EP269-EP270	0	Site clearance survey
10/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/21/2011	EP274-EP278	0	Site clearance survey
10/21/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP269-EP273	0	Site clearance survey
10/21/2011	EP269-EP273	0	Monitoring construction activity
10/20/2011	EP269-EP281	0	Site clearance survey
10/20/2011	EP269	0	Site clearance survey
10/20/2011	EP269	0	Monitoring construction activity
10/20/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/20/2011	EP274-EP278	0	Site clearance survey
10/20/2011	EP274-EP278	0	Monitoring construction activity
10/20/2011	EP269-EP273	0	Site clearance survey
10/20/2011	EP269-EP273	0	Monitoring construction activity
10/20/2011	EP263B-EP267	0	Site clearance survey
10/20/2011	EP300-EP312	0	Site clearance survey
10/20/2011	EP300-EP312	0	Monitoring construction activity

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
10/19/2011	EP290-EP312	0	Site clearance survey
10/19/2011	EP290-EP312	0	Monitoring construction activity
10/19/2011	EP269-EP281	0	Site clearance survey
10/19/2011	EP300-EP312	0	Site clearance survey
10/19/2011	EP300-EP312	0	Monitoring construction activity
10/19/2011	EP274-EP278	0	Site clearance survey
10/19/2011	EP274-EP278	0	Monitoring construction activity
10/19/2011	EP269-EP273	0	Site clearance survey
10/19/2011	EP269-EP273	0	Monitoring construction activity
10/19/2011	EP263B-EP267	0	Site clearance survey
10/18/2011	Slay Property	0	Monitoring construction activity
10/18/2011	EP269-EP270	0	Site clearance survey
10/18/2011	EP269-EP270	0	Monitoring construction activity
10/18/2011	EP269-EP281	0	Site clearance survey
10/18/2011	EP269-EP270	0	Site clearance survey
10/18/2011	EP274-EP278	0	Site clearance survey
10/18/2011	EP274-EP278	0	Monitoring construction activity
10/18/2011	EP269-EP273	0	Site clearance survey
10/18/2011	EP269-EP273	0	Monitoring construction activity
10/18/2011	EP263B-EP267	0	Site clearance survey
10/17/2011	Slay Property	0	Site clearance survey
10/17/2011	EP312 & EP314	0	Monitoring construction activity
10/17/2011	EP306-EP312	0	Site clearance survey
10/17/2011	EP306-EP312	0	Afternoon perimeter survey
10/17/2011	EP305	0	Monitoring construction activity
10/17/2011	EP300-EP363	0	Monitoring construction activity
10/17/2011	EP300-EP306	0	Site clearance survey
10/17/2011	EP300-EP306	0	Monitoring construction activity
10/17/2011	EP270-2	0	Monitoring construction activity
10/17/2011	EP269-EP270	0	Site clearance survey
10/17/2011	EP269-EP270	0	Monitoring construction activity
10/17/2011	EP269-EP281	0	Site clearance survey
10/17/2011	EP269-EP270	0	Site clearance survey
10/17/2011	EP267-2	0	Monitoring construction activity
10/17/2011	EP261-2	0	Monitoring construction activity

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
10/17/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/17/2011	EP274-EP278	0	Site clearance survey
10/17/2011	EP274-EP278	0	Monitoring construction activity
10/17/2011	EP269-EP273	0	Site clearance survey
10/17/2011	EP269-EP273	0	Monitoring construction activity
10/17/2011	EP263B-EP267	0	Site clearance survey
10/16/2011	EP306-EP312	0	Site clearance survey
10/16/2011	EP306-EP312	0	Afternoon perimeter survey
10/16/2011	EP300-EP306	0	Site clearance survey
10/16/2011	EP300-EP306	0	Monitoring construction activity
10/16/2011	EP271-2	0	Monitoring construction activity
10/16/2011	EP270-2	0	Monitoring construction activity
10/16/2011	EP269-EP270	0	Site clearance survey
10/16/2011	EP256-EP281	0	Site clearance survey
10/16/2011	EP305	0	Monitoring construction activity
10/16/2011	EP274-EP278	0	Site clearance survey
10/16/2011	EP274-EP278	0	Monitoring construction activity
10/16/2011	EP269-EP273	0	Site clearance survey
10/16/2011	EP269-EP273	0	Monitoring construction activity
10/16/2011	EP263B-EP267	0	Site clearance survey
10/16/2011	EP256-EP263A-2, AER & FROMM CY	0	Site clearance survey
10/16/2011	EP256-EP263A-2, AER & FROMM CY	0	Monitoring construction activity
10/15/2011	Slay Property	0	Site clearance survey
10/15/2011	Slay Property	0	Monitoring construction activities
10/15/2011	EP306-EP312	0	Site clearance survey
10/15/2011	EP306-EP312	0	Afternoon perimeter survey
10/15/2011	EP305	0	Monitoring construction activities
10/15/2011	EP300-EP306	0	Site clearance survey
10/15/2011	EP300-EP306	0	Monitoring construction activities
10/15/2011	EP269-1 AND EP273-1	0	Monitoring construction activities
10/15/2011	EP269-EP281	0	Morning perimeter survey
10/15/2011	EP261-2	0	Monitoring construction activities
10/15/2011	EP274-EP278	0	Site clearance survey
10/15/2011	EP274-EP278	0	Monitoring construction activities
10/15/2011	EP263B-EP267	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
10/14/2011	Slay Property	0	Site clearance survey
10/14/2011	Slay Property	0	Monitoring construction activities
10/14/2011	EP310	0	Monitoring construction activities
10/14/2011	EP305	0	Monitoring construction activities
10/14/2011	EP300-EP306	0	Site clearance survey
10/14/2011	EP300-EP306	0	Monitoring construction activities
10/14/2011	EP291-EP301	0	Monitoring construction activities
10/14/2011	EP269 through EP281	0	Site clearance survey
10/14/2011	EP269-EP270	0	Site clearance survey
10/14/2011	EP263B-2	0	Monitoring construction activities
10/14/2011	EP256-EP263A	0	Site clearance survey
10/14/2011	EP256-EP263A	0	Monitoring construction activities
10/14/2011	EP274-EP278	0	Site clearance survey
10/14/2011	EP274-EP278	0	Monitoring construction activities
10/14/2011	EP269-EP273	0	Site clearance survey
10/14/2011	EP269-EP273	0	Monitoring construction activities
10/14/2011	EP263B-EP267	0	Site clearance survey
10/14/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/14/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/13/2011	Slay Property	0	Site clearance survey
10/13/2011	Slay Property	0	Monitoring construction activities
10/13/2011	EP310	0	Monitoring construction activities
10/13/2011	EP306-EP312	0	Site clearance survey
10/13/2011	EP306-EP312	0	Afternoon perimeter survey
10/13/2011	EP293	0	Monitoring construction activities
10/13/2011	EP291-EP301	0	Monitoring construction activities
10/13/2011	EP275-1	0	Monitoring construction activities
10/13/2011	EP269-EP270	0	Site clearance survey
10/13/2011	EP269-EP281	0	Site clearance survey
10/13/2011	EP269-EP270	0	Site clearance survey
10/13/2011	EP266-2	0	Monitoring construction activities
10/13/2011	EP274-EP278	0	Site clearance survey
10/13/2011	EP274-EP278	0	Monitoring construction activities
10/13/2011	EP269-EP273	0	Site clearance survey
10/13/2011	EP269-EP273	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
10/13/2011	EP263B-EP267	0	Site clearance survey
10/13/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/13/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/12/2011	Slay Property	0	Site clearance survey
10/12/2011	Slay Property	0	Monitoring construction activities
10/12/2011	EP306-EP312	0	Site clearance survey
10/12/2011	EP291-EP301	0	Monitoring construction activities
10/12/2011	EP269-EP270	0	Site clearance survey
10/12/2011	EP269-EP281	0	Site clearance survey
10/12/2011	EP269-EP281	0	Monitoring construction activities
10/12/2011	EP269-EP270	0	Site clearance survey
10/12/2011	EP311	0	Monitoring construction activities
10/12/2011	EP274-EP278	0	Site clearance survey
10/12/2011	EP274-EP278	0	Monitoring construction activities
10/12/2011	EP269-EP273	0	Site clearance survey
10/12/2011	EP269-EP273	0	Monitoring construction activities
10/12/2011	EP263B-EP267	0	Site clearance survey
10/12/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/12/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/11/2011	Slay Property	0	Site clearance survey
10/11/2011	Slay Property	0	Monitoring construction activities
10/11/2011	EP311	0	Monitoring construction activities
10/11/2011	EP306-EP312	0	Site clearance survey
10/11/2011	EP306-EP312	0	Afternoon perimeter survey
10/11/2011	EP300-EP306	0	Site clearance survey
10/11/2011	EP291-EP301	0	Monitoring construction activities
10/11/2011	EP269-EP273	0	Site clearance survey
10/11/2011	EP269-EP273	0	Monitoring construction activities
10/11/2011	EP269-EP270	0	Site clearance survey
10/11/2011	EP269-EP270	0	Monitoring construction activities
10/11/2011	EP274-EP278	0	Site clearance survey
10/11/2011	EP274-EP278	0	Monitoring construction activities
10/11/2011	EP263B-EP267	0	Site clearance survey
10/11/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/11/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
10/10/2011	Slay Property	0	Site clearance survey
10/10/2011	Slay Property	0	Monitoring construction activities
10/10/2011	EP306-EP312	0	Site clearance survey
10/10/2011	EP306-EP312	0	Afternoon perimeter survey
10/10/2011	EP305	0	Monitoring construction activities
10/10/2011	EP300-EP306	0	Site clearance survey
10/10/2011	EP300-EP306	0	Monitoring construction activities
10/10/2011	EP300-EP306	0	Site clearance survey
10/10/2011	EP291-EP301	0	Monitoring construction activities
10/10/2011	EP269-EP281	9	Sheep were seen entering I-8 Island during Site Clearance survey
10/10/2011	EP269-EP273	0	Site clearance survey
10/10/2011	EP269-EP273	0	Monitoring construction activities
10/10/2011	EP259-3	0	Monitoring construction activities
10/10/2011	EP274-EP278	0	Site clearance survey
10/10/2011	EP274-EP278	0	Monitoring construction activities
10/10/2011	EP263B-EP267	0	Site clearance survey
10/10/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/10/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/9/2011	EP306-EP312	0	Site clearance survey
10/9/2011	EP306-EP312	0	Monitoring construction activities
10/9/2011	EP300-EP306	0	Site clearance survey
10/9/2011	EP300-EP306	0	Monitoring construction activities
10/9/2011	EP300-EP306	0	Site clearance survey
10/9/2011	EP300-EP306	0	Monitoring construction activities
10/9/2011	EP269-EP273	0	Site clearance survey
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP269-EP270	0	Monitoring construction activities
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP256-3	0	Monitoring construction activities
10/9/2011	EP274-EP278	0	Site clearance survey
10/9/2011	EP274-EP278	0	Monitoring construction activities
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP269-EP270	0	Monitoring construction activities
10/9/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/9/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
10/8/2011	EP300-EP306	0	Site clearance survey
10/8/2011	EP300-EP306	0	Monitoring construction activity
10/8/2011	EP300-EP306	0	Site clearance survey
10/8/2011	EP300-EP306	0	Morning perimeter survey
10/8/2011	EP291-EP301	0	Monitoring construction activity
10/8/2011	EP278-1	0	Monitoring construction activity
10/8/2011	EP269-EP273	0	Site clearance survey
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP269-EP270	0	Monitoring construction activity
10/8/2011	EP269/EP270 Pullsite	0	Monitoring construction activity
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP259-3	0	Monitoring construction activity
10/8/2011	EP274-EP278	0	Site clearance survey
10/8/2011	EP274-EP278	0	Monitoring construction activity
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP269-EP270	0	Monitoring construction activity
10/8/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/8/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/7/2011	Slay Property	0	Site clearance survey
10/7/2011	EP306-EP312	0	Site clearance survey
10/7/2011	EP306-EP312	0	Morning perimeter survey
10/7/2011	EP300-EP306	0	Site clearance survey
10/7/2011	EP300-EP306	0	Monitoring construction activity
10/7/2011	EP300-EP306	0	Site clearance survey
10/7/2011	EP300-EP306	0	Morning perimeter survey
10/7/2011	EP291-EP301	0	Site clearance survey
10/7/2011	EP269-EP273	0	Site clearance survey
10/7/2011	EP269-EP270	0	Site clearance survey
10/7/2011	EP269-EP270	0	Monitoring construction activity
10/7/2011	EP269-EP270	0	Site clearance survey
10/7/2011	EP259-3	0	Monitoring construction activity
10/7/2011	EP274-EP278	0	Site clearance survey
10/7/2011	EP274-EP278	0	Monitoring construction activity
10/7/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/7/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
10/6/2011	Slay Property	0	Site clearance survey
10/6/2011	Slay Property	0	Monitoring construction activity
10/6/2011	EP306-EP312	0	Site clearance survey
10/6/2011	EP306-EP312	0	Monitoring construction activity
10/6/2011	EP291-EP301	0	Site clearance survey
10/6/2011	EP269-EP273	0	Site clearance survey
10/6/2011	EP269-EP270	0	Site clearance survey
10/6/2011	EP269-EP270	0	Monitoring construction activity
10/6/2011	EP269-EP281	0	Site clearance survey
10/6/2011	EP269-EP270	0	Site clearance survey
10/6/2011	EP263B-EP267	0	Site clearance survey
10/6/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/6/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/5/2011	Slay Property	0	Site clearance survey
10/5/2011	Slay Property	0	Monitoring construction activity
10/5/2011	EP303-2	0	Monitoring construction activity
10/5/2011	EP291-EP301	0	Site clearance survey
10/5/2011	EP269-EP273	0	Site clearance survey
10/5/2011	EP269-EP270	0	Site clearance survey
10/5/2011	EP269-EP270	0	Monitoring construction activity
10/5/2011	EP274-EP278	0	Site clearance survey
10/5/2011	EP274-EP278	0	Monitoring construction activity
10/5/2011	EP269-EP281	0	Site clearance survey
10/5/2011	EP269-EP270	0	Site clearance survey
10/5/2011	EP263B-EP267	0	Site clearance survey
10/5/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/5/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/4/2011	Slay Property	0	Site clearance survey
10/4/2011	Slay Property	0	Monitoring construction activity
10/4/2011	EP300-EP306	0	Site clearance survey
10/4/2011	EP300-EP306	0	Monitoring construction activity
10/4/2011	EP269-EP273	0	Site clearance survey
10/4/2011	EP269-EP270	0	Site clearance survey
10/4/2011	EP269-EP270	0	Monitoring construction activity
10/4/2011	EP256-EP263A	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
10/4/2011	EP274-EP278	0	Site clearance survey
10/4/2011	EP274-EP278	0	Monitoring construction activity
10/4/2011	EP263B-EP267	0	Site clearance survey
10/3/2011	Slay Property	0	Site clearance survey
10/3/2011	Slay Property	0	Monitoring construction activity
10/3/2011	EP300-EP306	0	Site clearance survey
10/3/2011	EP300-EP306	0	Monitoring construction activity
10/3/2011	EP300-EP306	0	Site clearance survey
10/3/2011	EP300-EP306	0	Morning perimeter survey
10/3/2011	EP291-EP341	0	Site clearance survey
10/3/2011	EP279-EP294	0	Site clearance survey
10/3/2011	EP269-EP273	0	Site clearance survey
10/3/2011	EP269-EP273	0	Monitoring construction activity
10/3/2011	EP263B-EP267	0	Site clearance survey
10/3/2011	EP263B-EP267	0	Monitoring construction activity
10/3/2011	EP256-EP263A	0	Site clearance survey
10/3/2011	EP274-EP278	0	Site clearance survey
10/3/2011	EP274-EP278	0	Monitoring construction activity
10/3/2011	EP263B-EP267	0	Site clearance survey
10/2/2011	EP300-EP306	0	Site clearance survey
10/2/2011	EP300-EP306	0	Monitoring construction activity
10/2/2011	EP269-EP281	0	Afternoon perimeter survey
10/2/2011	EP269-EP273	0	Afternoon perimeter survey
10/1/2011	EP300-EP306	0	Site clearance survey
10/1/2011	EP300-EP306	0	Monitoring construction activities
10/1/2011	EP300-EP306	0	Site clearance survey
10/1/2011	EP300-EP306	0	Morning perimeter survey
10/1/2011	EP269-EP273 and EP256-EP261	0	Site clearance survey
10/1/2011	EP269-EP273	0	Site clearance survey
10/1/2011	EP269-EP270	0	Site clearance survey
10/1/2011	EP274-EP278	0	Site clearance survey
10/1/2011	EP274-EP278	0	Monitoring construction activities
9/30/2011	Slay Property	0	Site clearance survey
9/30/2011	Slay Property	0	Monitoring construction activities
9/30/2011	EP300-EP312	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
9/30/2011	EP300-EP312	0	Monitoring construction activities
9/30/2011	EP300-EP306	0	Site clearance survey
9/30/2011	EP300-EP306	0	Monitoring construction activities
9/30/2011	EP291-EP348	0	Monitoring construction activities
9/30/2011	EP290-EP294, EP300-EP312	0	Site clearance survey
9/30/2011	EP290-EP294, EP300-EP312	0	Monitoring construction activities
9/30/2011	EP269-EP273	0	Site clearance survey
9/30/2011	EP269-EP273	0	Monitoring construction activities
9/30/2011	EP269-EP281	0	Site clearance survey
9/30/2011	EP279-EP294	0	Site clearance survey
9/30/2011	EP274-EP278	0	Site clearance survey
9/30/2011	EP274-EP278	0	Monitoring construction activities
9/30/2011	EP263-B-EP267	0	Site clearance survey
9/30/2011	EP256-EP263A, AER, Fromm CY	0	Site clearance survey
9/30/2011	EP256-EP263A, AER, Fromm CY	0	Monitoring construction activities
9/29/2011	Slay Property	0	Site clearance survey
9/29/2011	Slay Property	0	Monitoring construction activities
9/29/2011	EP300-EP312	0	Site clearance survey
9/29/2011	EP300-EP306	0	Site clearance survey
9/29/2011	EP300-EP306	0	Monitoring construction activities
9/29/2011	EP290-EP294, EP300-EP312	0	Site clearance survey
9/29/2011	EP290-EP294, EP300-EP312	0	Monitoring construction activities
9/29/2011	EP269-EP273	0	Site clearance survey
9/29/2011	EP269-EP273	0	Monitoring construction activities
9/29/2011	EP279-EP294	0	Site clearance survey
9/29/2011	EP274-EP278	0	Site clearance survey
9/29/2011	EP274-EP278	0	Monitoring construction activities
9/29/2011	EP263B-EP267	0	Site clearance survey
9/28/2011	Slay Property	0	Site clearance survey
9/28/2011	Slay Property	0	Monitoring construction activities
9/28/2011	EP330-EP291	0	Site clearance survey
9/28/2011	EP300-EP306	0	Site clearance survey
9/28/2011	EP300-EP306	0	Monitoring construction activities
9/28/2011	EP290-EP294	0	Site clearance survey
9/28/2011	EP290-EP294	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
9/28/2011	EP269-EP273	0	Site clearance survey
9/28/2011	EP269-EP273	0	Monitoring construction activities
9/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/28/2011	EP279-EP294	0	Site clearance survey
9/28/2011	EP279-EP294	0	Monitoring construction activities
9/28/2011	EP274-EP278	0	Site clearance survey
9/28/2011	EP274-EP278	0	Monitoring construction activities
9/28/2011	EP263B-EP267	0	Site clearance survey
9/27/2011	Slay Property	0	Site clearance survey
9/27/2011	Slay Property	0	Monitoring construction activities
9/27/2011	EP339-EP291	0	Site clearance survey
9/27/2011	EP309	0	Monitoring construction activities
9/27/2011	EP300-EP312	0	Site clearance survey
9/27/2011	EP300-EP312	0	Monitoring construction activities
9/27/2011	EP300-EP306	0	Site clearance survey
9/27/2011	EP278-1	0	Monitoring construction activities
9/27/2011	EP269-EP273	0	Site clearance survey
9/27/2011	EP269-EP273	0	Monitoring construction activities
9/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/27/2011	EP279-EP294	0	Site clearance survey
9/27/2011	EP279-EP294	0	Monitoring construction activities
9/27/2011	EP274-EP278	0	Site clearance survey
9/27/2011	EP274-EP278	0	Monitoring construction activities
9/27/2011	EP263B-EP267	0	Site clearance survey
9/27/2011	AER CY	0	Monitoring construction activities
9/26/2011	EP300-EP306	0	Site clearance survey
9/26/2011	EP300-EP306	0	Monitoring construction activities
9/26/2011	EP300-EP306	0	Site clearance survey
9/26/2011	EP300-EP312	0	Site clearance survey
9/26/2011	EP300-EP312	0	Monitoring construction activities
9/26/2011	EP291-EP301	0	Monitoring construction activities
9/26/2011	EP278-1, EP270-2	0	Monitoring construction activities
9/26/2011	EP274-EP278	0	Site clearance survey
9/26/2011	EP274-EP278	0	Monitoring construction activities
9/26/2011	EP269-EP273	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
9/26/2011	EP269-EP273	0	Monitoring construction activities
9/26/2011	EP269-EP270	0	Morning perimeter survey
9/26/2011	EP269-EP270	0	Monitoring construction activities
9/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/26/2011	EP279-EP294	0	Site clearance survey
9/26/2011	EP279-EP294	0	Monitoring construction activities
9/26/2011	EP269-EP271, EP256-EP263, AER & Fromm CY	0	Site clearance survey
9/26/2011	EP269-EP271, EP256-EP263, AER & Fromm CY	0	Monitoring construction activities
9/26/2011	EP263B-EP267	0	Site clearance survey
9/26/2011	CP88	0	Site clearance survey
9/26/2011	CP88	0	Monitoring construction activities
9/25/2011	EP300-EP306	0	Site clearance survey
9/25/2011	EP300-EP306	0	Monitoring construction activities
9/25/2011	EP300-EP306	0	Morning perimeter survey
9/25/2011	EP278	0	Monitoring construction activities
9/25/2011	EP274-EP278	0	Site clearance survey
9/25/2011	EP274-EP278	0	Monitoring construction activities
9/25/2011	EP271-2	0	Monitoring construction activities
9/25/2011	EP269-EP270	0	Morning perimeter survey
9/25/2011	EP269-EP270	0	Monitoring construction activities
9/25/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/25/2011	EP279-EP294	0	Site clearance survey
9/25/2011	EP279-EP294	0	Monitoring construction activities
9/25/2011	EP269-EP273	0	Site clearance survey
9/25/2011	EP269-EP273	0	Monitoring construction activities
9/25/2011	EP263B-EP267	0	Site clearance survey
9/24/2011	EP300-EP306	0	Site clearance survey
9/24/2011	EP300-EP306	0	Monitoring construction activities
9/24/2011	EP300-EP306	0	Site clearance survey
9/24/2011	EP300-EP306	0	Monitoring construction activities
9/24/2011	EP291/EP292 Pullsite	0	Monitoring construction activities
9/24/2011	EP274-EP278	0	Site clearance survey
9/24/2011	EP274-EP278	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
9/24/2011	EP274	0	Monitoring construction activities
9/24/2011	EP269-EP270	0	Site clearance survey
9/24/2011	EP269-EP270	0	Monitoring construction activities
9/24/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/24/2011	EP279-EP294	0	Site clearance survey
9/24/2011	EP279-EP294	0	Monitoring construction activities
9/24/2011	EP263B-EP267	0	Site clearance survey
9/23/2011	EP300-EP306	0	Site clearance survey
9/23/2011	EP300-EP306	0	Monitoring construction activities
9/23/2011	EP300-EP312	0	Site clearance survey
9/23/2011	EP300-EP312	0	Monitoring construction activities
9/23/2011	EP274-1	0	Monitoring construction activities
9/23/2011	EP269-EP271	0	Site clearance survey
9/23/2011	EP269-EP271	0	Monitoring construction activities
9/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/23/2011	EP279-EP294	0	Site clearance survey
9/23/2011	EP279-EP294	0	Monitoring construction activities
9/23/2011	EP278-1	0	Monitoring construction activities
9/23/2011	EP263B-EP267	0	Site clearance survey
9/22/2011	EP300-EP312	0	Site clearance survey
9/22/2011	EP300-EP312	0	Monitoring construction activities
9/22/2011	EP300-EP306	0	Site clearance survey
9/22/2011	EP300-EP306	0	Monitoring construction activities
9/22/2011	EP274-1	0	Monitoring construction activities
9/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/22/2011	EP279-EP294	0	Site clearance survey
9/22/2011	EP278-1	0	Monitoring construction activities
9/22/2011	EP274-EP278	0	Site clearance survey
9/22/2011	EP274-EP278	0	Monitoring construction activities
9/22/2011	EP263B-EP267	0	Site clearance survey
9/21/2011	EP300-EP306	0	Site clearance survey
9/21/2011	EP278-1	0	Monitoring construction activities
9/21/2011	EP274-1	0	Monitoring construction activities
9/21/2011	EP269-EP271, EP300-EP312	0	Site clearance survey
9/21/2011	EP269-EP271, EP300-EP312	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
9/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/21/2011	EP279-EP294	0	Site clearance survey
9/21/2011	EP279-EP294	0	Monitoring construction activities
9/21/2011	EP274-EP278	0	Site clearance survey
9/21/2011	EP274-EP278	0	Monitoring construction activities
9/21/2011	EP269-EP281	0	Site clearance survey
9/21/2011	EP269-EP281	0	Monitoring construction activities
9/21/2011	EP263B-EP267	0	Site clearance survey
9/20/2011	EP300-EP306	0	Site clearance survey
9/20/2011	EP278-1	0	Monitoring construction activities
9/20/2011	EP269-EP273	0	Site clearance survey
9/20/2011	EP269-EP273	0	Monitoring construction activities
9/20/2011	EP269-EP271	0	Site clearance survey
9/20/2011	EP269-EP271	0	Monitoring construction activities
9/20/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/20/2011	EP279-EP294	0	Site clearance survey
9/20/2011	EP279-EP294	0	Monitoring construction activities
9/20/2011	EP274-EP278	0	Site clearance survey
9/20/2011	EP274-EP278	0	Monitoring construction activities
9/20/2011	EP269-EP281	0	Site clearance survey
9/20/2011	EP269-EP281	0	Monitoring construction activities
9/20/2011	EP263B-EP267	0	Site clearance survey
9/19/2011	EP269-EP273	0	Site clearance survey
9/19/2011	EP269-EP273	0	Monitoring construction activities
9/19/2011	EP269-EP271	0	Site clearance survey
9/19/2011	EP269-EP271	0	Monitoring construction activities
9/19/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/19/2011	EP279-EP294	0	Site clearance survey
9/19/2011	EP279-EP294	0	Monitoring construction activities
9/19/2011	EP274-EP278	0	Site clearance survey
9/19/2011	EP274-EP278	0	Monitoring construction activities
9/19/2011	EP269-EP281	0	Site clearance survey
9/19/2011	EP269-EP281	0	Monitoring construction activities
9/19/2011	EP263B-EP267	0	Site clearance survey
9/18/2011	EP300-EP306	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
9/18/2011	EP300-EP312	0	Site clearance survey
9/18/2011	EP300-EP312	0	Monitoring construction activities
9/18/2011	EP269-EP273	0	Site clearance survey
9/18/2011	EP269-EP273	0	Monitoring construction activities
9/18/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/18/2011	EP279-EP294	0	Site clearance survey
9/18/2011	EP279-EP294	0	Monitoring construction activities
9/18/2011	EP274-EP278	0	Site clearance survey
9/18/2011	EP274-EP278	0	Monitoring construction activities
9/18/2011	EP269-EP281	0	Site clearance survey
9/18/2011	I8 Island	9	Afternoon perimeter survey
9/17/2011	EP300-EP306	0	Site clearance survey
9/17/2011	EP300-EP312	0	Site clearance survey
9/17/2011	EP300-EP312	0	Monitoring construction activities
9/17/2011	EP269-EP273	0	Site clearance survey
9/17/2011	EP269-EP273	0	Monitoring construction activities
9/17/2011	EP274-EP278	0	Site clearance survey
9/17/2011	EP274-EP278	0	Monitoring construction activities
9/17/2011	EP269-EP281	0	Site clearance survey
9/17/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/17/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/16/2011	EP300-EP312	0	Site clearance survey
9/16/2011	EP300-EP312	0	Monitoring construction activities
9/16/2011	EP300-EP306	0	Site clearance survey
9/16/2011	EP269-EP273	0	Site clearance survey
9/16/2011	EP269-EP273	0	Monitoring construction activities
9/16/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/16/2011	EP274-EP278	0	Site clearance survey
9/16/2011	EP274-EP278	0	Monitoring construction activities
9/16/2011	EP269-EP281	0	Site clearance survey
9/16/2011	EP263B-EP267	0	Site clearance survey
9/16/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/16/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/15/2011	EP300-EP312	0	Site clearance survey
9/15/2011	EP300-EP312	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
9/15/2011	EP300-EP306	0	Site clearance survey
9/15/2011	EP300-EP306	0	Monitoring construction activities
9/15/2011	EP269-EP273	0	Site clearance survey
9/15/2011	EP269-EP273	0	Monitoring construction activities
9/15/2011	EP256-EP263A, AER	0	Monitoring construction activities
9/15/2011	EP274-EP278	0	Site clearance survey
9/15/2011	EP274-EP278	0	Monitoring construction activities
9/15/2011	EP269-EP281	0	Site clearance survey
9/15/2011	EP269-EP281	0	Monitoring construction activities
9/15/2011	EP263B-EP267	0	Site clearance survey
9/14/2011	EP310-3	0	Monitoring construction activities
9/14/2011	EP300-EP312	0	Site clearance survey
9/14/2011	EP300-EP312	0	Monitoring construction activities
9/14/2011	EP300-EP306	0	Morning perimeter survey
9/14/2011	EP274-1	0	Monitoring construction activities
9/14/2011	EP269-EP273	0	Site clearance survey
9/14/2011	EP269-EP273	0	Monitoring construction activities
9/14/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/14/2011	EP274-EP278	0	Site clearance survey
9/14/2011	EP274-EP278	0	Monitoring construction activities
9/14/2011	EP269-EP281	0	Site clearance survey
9/14/2011	EP269-EP281	0	Monitoring construction activities
9/14/2011	EP263B-EP267	0	Site clearance survey
9/13/2011	EP300-EP312	0	Site clearance survey
9/13/2011	EP300-EP312	0	Monitoring construction activities
9/13/2011	EP300-EP306	0	Morning perimeter survey
9/13/2011	EP269-EP273	0	Site clearance survey
9/13/2011	EP269-EP273	0	Monitoring construction activities
9/13/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/13/2011	EP274-EP278	0	Site clearance survey
9/13/2011	EP274-EP278	0	Monitoring construction activities
9/13/2011	EP274-EP278	0	Monitoring construction activities
9/13/2011	EP274	0	Monitoring construction activities
9/13/2011	EP269-EP281	0	Site clearance survey
9/13/2011	EP263B-EP267	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
9/12/2011	Mountain Springs Grade Road	15	Morning perimeter survey
9/12/2011	EP305-3, EP310	0	Monitoring construction activities
9/12/2011	EP300-EP312	0	Site clearance survey
9/12/2011	EP300-EP312	0	Monitoring construction activities
9/12/2011	EP300-EP306	0	Site clearance survey
9/12/2011	EP300-EP306	0	Monitoring construction activities
9/12/2011	EP269-EP273	0	Site clearance survey
9/12/2011	EP269-EP273	0	Monitoring construction activities
9/12/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/12/2011	EP274-EP278	0	Site clearance survey
9/12/2011	EP274-EP278	0	Monitoring construction activities
9/12/2011	EP274-EP278	0	Monitoring construction activities
9/12/2011	EP274	0	Monitoring construction activities
9/12/2011	EP269-EP281	0	Monitoring construction activities
9/12/2011	EP263B-EP267	0	Site clearance survey
9/11/2011	EP300-EP312	0	Site clearance survey
9/11/2011	EP300-EP312	0	Monitoring construction activities
9/11/2011	EP300-EP306	0	Site clearance survey
9/11/2011	EP300-EP306	0	Monitoring construction activities
9/11/2011	EP271-2	0	Monitoring construction activities
9/11/2011	EP269-EP271	0	Site clearance survey
9/11/2011	EP269-EP271	0	Monitoring construction activities
9/11/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/11/2011	EP274-EP278	0	Site clearance survey
9/11/2011	EP274-EP278	0	Monitoring construction activities
9/11/2011	EP269-EP273	0	Site clearance survey
9/11/2011	EP269-EP273	0	Monitoring construction activities
9/11/2011	EP263B-EP267	0	Site clearance survey
9/11/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/11/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/10/2011	EP300-EP312	0	Site clearance survey
9/10/2011	EP300-EP312	0	Monitoring construction activities
9/10/2011	EP300-EP306	0	Site clearance survey
9/10/2011	EP300-EP306	0	Monitoring construction activities
9/10/2011	EP269-EP271	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
9/10/2011	EP269-EP271	0	Monitoring construction activities
9/10/2011	EP274-EP278	0	Site clearance survey
9/10/2011	EP274-EP278	0	Monitoring construction activities
9/10/2011	EP269-EP273	0	Morning perimeter survey
9/10/2011	EP269-EP273	0	Monitoring construction activities
9/10/2011	EP269-EP273	0	Evening perimeter survey
9/9/2011	EP300-EP312	0	Site clearance survey
9/9/2011	EP300-EP312	0	Monitoring construction activities
9/9/2011	EP300-EP306	0	Site clearance survey
9/9/2011	EP300-EP306	0	Monitoring construction activities
9/9/2011	EP271-2	0	Monitoring construction activities
9/9/2011	EP269-EP271	0	Site clearance survey
9/9/2011	EP269-EP271	0	Monitoring construction activities
9/9/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/9/2011	EP256-EP263A, AER and Fromm yards	0	Site clearance survey
9/9/2011	EP256-EP263A, AER and Fromm yards	0	Monitoring construction activities
9/9/2011	EP274-EP278	0	Site clearance survey
9/9/2011	EP274-EP278	0	Monitoring construction activities
9/9/2011	EP269-EP273	0	Morning perimeter survey
9/9/2011	EP269-EP273	0	Monitoring construction activities
9/9/2011	EP269-EP273	0	Evening perimeter survey
9/8/2011	EP300-EP312	0	Site clearance survey
9/8/2011	EP300-EP312	0	Monitoring construction activities
9/8/2011	EP271-2	0	Monitoring construction activities
9/8/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/8/2011	EP279-EP294	0	Site clearance survey
9/8/2011	EP279-EP294	0	Monitoring construction activities
9/8/2011	EP274-EP278	0	Site clearance survey
9/8/2011	EP274-EP278	0	Monitoring construction activities
9/8/2011	EP263B-EP267	0	Site clearance survey
9/7/2011	EP306-1	0	Monitoring construction activities
9/7/2011	EP300-EP312	0	Site clearance survey
9/7/2011	EP300-EP312	0	Monitoring construction activities
9/7/2011	EP300-EP306	0	Site clearance survey
9/7/2011	EP300-EP306	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
9/7/2011	EP273	0	Monitoring construction activities
9/7/2011	EP269-EP273	0	Site clearance survey
9/7/2011	EP269-EP273	0	Monitoring construction activities
9/7/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/7/2011	EP278-EP294	0	Morning perimeter survey
9/7/2011	EP278-EP294	0	Monitoring construction activities
9/7/2011	EP278-EP294	0	Evening perimeter survey
9/7/2011	EP274-EP278	0	Site clearance survey
9/7/2011	EP274-EP278	0	Monitoring construction activities
9/7/2011	EP263B-EP267	0	Site clearance survey
9/6/2011	EP300-EP312	0	Site clearance survey
9/6/2011	EP300-EP312	0	Monitoring construction activities
9/6/2011	EP273	0	Monitoring construction activities
9/6/2011	EP269-EP273	0	Site clearance survey
9/6/2011	EP269-EP273	0	Monitoring construction activities
9/6/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/6/2011	EP278-EP294	0	Morning perimeter survey
9/6/2011	EP278-EP294	0	Monitoring construction activities
9/6/2011	EP278-EP294	0	Evening perimeter survey
9/6/2011	EP274-EP278	0	Site clearance survey
9/6/2011	EP274-EP278	0	Monitoring construction activities
9/6/2011	EP263B-EP267	0	Site clearance survey
9/5/2011	EP300-EP312	0	Site clearance survey
9/5/2011	EP269-EP273	0	Site clearance survey
9/5/2011	EP269-EP273	0	Monitoring construction activities
9/5/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/5/2011	EP274-EP294	0	Site clearance survey
9/5/2011	EP263B-EP267	0	Site clearance survey
9/4/2011	EP300-EP312	0	Site clearance survey
9/4/2011	EP300-EP312	0	Monitoring construction activities
9/4/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
9/4/2011	EP269-EP281	0	Site clearance survey
9/4/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/4/2011	EP256-EP263A, AER and Fromm yards	0	Site clearance survey
9/4/2011	EP256-EP263A, AER and Fromm yards	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
9/4/2011	EP279-EP294	0	Site clearance survey
9/4/2011	EP279-EP294	0	Monitoring construction activities
9/4/2011	EP274-EP278	0	Site clearance survey
9/4/2011	EP274-EP278	0	Monitoring construction activities
9/4/2011	EP270	0	Site clearance survey
9/4/2011	EP270	0	Monitoring construction activities
9/3/2011	EP300-EP312	0	Monitoring Construction Activities
9/3/2011	EP300-EP312	0	Site clearance survey
9/3/2011	EP300-EP306	0	Monitoring Construction Activities
9/3/2011	EP300-EP306	0	Site clearance survey
9/3/2011	EP271	0	Monitoring Construction Activities
9/3/2011	EP269-EP273	0	Monitoring Construction Activities
9/3/2011	EP269-EP273	0	Site clearance survey
9/3/2011	EP269-EP281	0	Monitoring Construction Activities
9/3/2011	EP256-EP263A, AER and Fromm Yards	0	Monitoring Construction Activities
9/3/2011	EP256-EP263A, AER and Fromm Yards	0	Site clearance survey
9/3/2011	EP278-EP294	0	Evening perimeter survey
9/3/2011	EP278-EP294	0	Monitoring Construction Activities
9/3/2011	EP278-EP294	0	Morning perimeter survey
9/3/2011	EP269-1 & EP269/EP270 Pull site	0	Monitoring Construction Activities
9/2/2011	I-8 Island	9	Evening perimeter survey 4:45pm - 5:08pm
9/2/2011	I-8 Island	12	Morning perimeter survey 8:35am
9/2/2011	EP300-EP312	0	Monitoring Construction Activities
9/2/2011	EP300-EP312	0	Site clearance survey
9/2/2011	EP272 & EP276	0	Monitoring Construction Activities
9/2/2011	EP269-EP273	0	Monitoring Construction Activities
9/2/2011	EP269-EP273	0	Site clearance survey
9/2/2011	EP256-EP263A, AER and Fromm Yards	0	Monitoring Construction Activities
9/2/2011	EP256-EP263A, AER and Fromm Yards	0	Site clearance survey
9/2/2011	EP278-EP294	0	Evening perimeter survey
9/2/2011	EP278-EP294	0	Monitoring Construction Activities
9/2/2011	EP278-EP294	0	Morning perimeter survey
9/2/2011	EP269-EP272	0	Monitoring Construction Activities
9/2/2011	EP269-EP272	0	Site clearance survey
9/2/2011	EP263B-EP267	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
9/1/2011	I-8 Island	12	Evening perimeter survey 4:45pm - 5:40pm
9/1/2011	I-8 Island	12	Morning perimeter survey 8:35am
9/1/2011	EP300-EP312	0	Monitoring Construction Activities
9/1/2011	EP300-EP312	0	Site clearance survey
9/1/2011	EP269-EP273	0	Monitoring Construction Activities
9/1/2011	EP269-EP273	0	Site clearance survey
9/1/2011	EP256-EP263A-2	0	Site clearance survey
9/1/2011	EP255	0	Monitoring Construction Activities
9/1/2011	EP300-EP306	0	Site clearance survey
9/1/2011	EP278-EP294	0	Evening perimeter survey
9/1/2011	EP278-EP294	0	Monitoring Construction Activities
9/1/2011	EP278-EP294	0	Morning perimeter survey
9/1/2011	EP269-EP272	0	Monitoring Construction Activities
9/1/2011	EP269-EP272	0	Site clearance survey
9/1/2011	EP263B-EP267	0	Site clearance survey
8/31/2011	I-8 Island	0	Site clearance survey
8/31/2011	EP308	0	Monitoring Construction Activities
8/31/2011	EP300-EP312	0	Monitoring Construction Activities
8/31/2011	EP300-EP312	0	Site clearance survey
8/31/2011	EP269-EP273	0	Monitoring Construction Activities
8/31/2011	EP269-EP273	0	Site clearance survey
8/31/2011	EP300-EP306	0	Site clearance survey
8/31/2011	EP278-EP294	0	Evening perimeter survey
8/31/2011	EP278-EP294	0	Monitoring Construction Activities
8/31/2011	EP278-EP294	0	Morning perimeter survey
8/31/2011	EP269-EP272	0	Monitoring Construction Activities
8/31/2011	EP263B-EP267	0	Site clearance survey
8/30/2011	I-8 Island	16	Evening perimeter survey 4:30pm
8/30/2011	I-8 Island	9	Morning perimeter survey 9:10am - 9:30am
8/30/2011	EP300-EP312	0	Monitoring Construction Activities
8/30/2011	EP300-EP312	0	Site clearance survey
8/30/2011	EP269-EP273	0	Monitoring Construction Activities
8/30/2011	EP269-EP273	0	Site clearance survey
8/30/2011	EP300-EP306	0	Site clearance survey
8/30/2011	EP278-EP294	0	Evening perimeter survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
8/30/2011	EP278-EP294	0	Monitoring Construction Activities
8/30/2011	EP278-EP294	0	Morning perimeter survey
8/30/2011	EP274-EP278	0	Monitoring Construction Activities
8/30/2011	EP274-EP278	0	Site clearance survey
8/30/2011	EP269-EP272	0	Monitoring Construction Activities
8/30/2011	EP269-EP272	0	Site clearance survey
8/30/2011	EP263B-EP267	0	Site clearance survey
8/29/2011	I-8 Island	4	Morning perimeter survey 8:55am
8/29/2011	I-8 Island	12	Evening perimeter survey 4:35pm to 5:00pm
8/29/2011	EP300-EP312	0	Monitoring Construction Activities
8/29/2011	EP300-EP312	0	Site clearance survey
8/29/2011	EP278-2	0	Monitoring Construction Activities
8/29/2011	EP269-EP273	0	Monitoring Construction Activities
8/29/2011	EP269-EP273	0	Site clearance survey
8/29/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/29/2011	EP300-EP306	0	Site clearance survey
8/29/2011	EP274-EP278	0	Monitoring Construction Activities
8/29/2011	EP274-EP278	0	Site clearance survey
8/29/2011	EP269-EP272	0	Monitoring Construction Activities
8/29/2011	EP269-EP272	0	Site clearance survey
8/29/2011	EP263B-EP267	0	Site clearance survey
8/28/2011	I-8 Island	15	Morning perimeter survey @9:22am
8/28/2011	EP305	0	Monitoring Construction Activities
8/28/2011	EP281	0	Monitoring Construction Activities
8/28/2011	EP273	0	Monitoring Construction Activities
8/28/2011	EP269-EP273	0	Monitoring Construction Activities
8/28/2011	EP269-EP273	0	Site clearance survey
8/28/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/28/2011	EP300-EP306	0	Morning perimeter survey
8/28/2011	EP278-EP294	0	Evening perimeter survey
8/28/2011	EP278-EP294	0	Monitoring Construction Activities
8/28/2011	EP278-EP294	0	Morning perimeter survey
8/28/2011	EP274-EP278	0	Monitoring Construction Activities
8/28/2011	EP274-EP278	0	Site clearance survey
8/28/2011	EP269-EP272	0	Monitoring Construction Activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
8/28/2011	EP269-EP272	0	Site clearance survey
8/28/2011	EP263-B, EP267	0	Site clearance survey
8/27/2011	I-8 Island	0	Site clearance survey
8/27/2011	EP305	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Site clearance survey
8/27/2011	I-8 Island	0	Morning perimeter survey
8/27/2011	EP305	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Site clearance survey
8/27/2011	EP300-EP306, EP269-EP273	0	Monitoring Construction Activities
8/27/2011	EP272-3	0	Monitoring Construction Activities
8/27/2011	EP261	0	Monitoring Construction Activities
8/27/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/27/2011	EP278-EP294	0	Site clearance survey
8/27/2011	EP278-EP294	0	Monitoring Construction Activities
8/27/2011	EP274-EP278	0	Site clearance survey
8/27/2011	EP274-EP278	0	Monitoring Construction Activities
8/27/2011	EP269-EP272	0	Monitoring Construction Activities
8/27/2011	EP269-EP272	0	Site clearance survey
8/27/2011	EP263B-EP267	0	Site clearance survey
8/26/2011	I-8 Island	0	Morning perimeter survey
8/26/2011	EP269-EP273	0	Monitoring Construction Activities
8/26/2011	EP269-EP273	0	Morning perimeter survey
8/26/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/26/2011	EP300-EP306	0	Monitoring Construction Activities
8/26/2011	EP278-EP294	0	Evening perimeter survey
8/26/2011	EP278-EP294	0	Monitoring Construction Activities
8/26/2011	EP278-EP294	0	Morning perimeter survey
8/26/2011	EP274-EP278	0	Monitoring Construction Activities
8/26/2011	EP274-EP278	0	Site clearance survey
8/26/2011	EP269-EP272	0	Monitoring Construction Activities
8/26/2011	EP269-EP272	0	Morning perimeter survey
8/25/2011	I-8 Island	0	Morning perimeter survey
8/25/2011	EP269-EP273	0	Monitoring Construction Activities
8/25/2011	EP269-EP273	0	Morning perimeter survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
8/25/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/25/2011	EP278-EP294	0	Evening perimeter survey
8/25/2011	EP278-EP294	0	Monitoring Construction Activities
8/25/2011	EP278-EP294	0	Morning perimeter survey
8/25/2011	EP274-EP278	0	Monitoring Construction Activities
8/25/2011	EP274-EP278	0	Site clearance survey
8/25/2011	EP270-EP272	0	Site clearance survey
8/25/2011	EP269-EP272	0	Monitoring Construction Activities
8/25/2011	EP269-EP272	0	Morning perimeter survey
8/24/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/24/2011	EP300-EP312, EP263B-EP267	0	Site clearance survey
8/24/2011	EP269-EP273	0	Monitoring Construction Activities
8/24/2011	EP269-EP273	0	Site clearance survey
8/24/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/24/2011	EP278-EP294	0	Evening perimeter survey
8/24/2011	EP278-EP294	0	Monitoring Construction Activities
8/24/2011	EP278-EP294	0	Morning perimeter survey
8/24/2011	EP274-EP278	0	Monitoring Construction Activities
8/24/2011	EP274-EP278	0	Site clearance survey
8/23/2011	I-8 Island	0	Morning perimeter survey
8/23/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/23/2011	EP300-EP312, EP263B-EP267	0	Site clearance survey
8/23/2011	EP269-EP273	0	Monitoring Construction Activities
8/23/2011	EP269-EP273	0	Site clearance survey
8/23/2011	EP278-EP294	0	Evening perimeter survey
8/23/2011	EP278-EP294	0	Monitoring Construction Activities
8/23/2011	EP278-EP294	0	Morning perimeter survey
8/23/2011	EP274-EP278	0	Monitoring Construction Activities
8/23/2011	EP274-EP278	0	Morning perimeter survey
8/23/2011	EP270-EP272	0	Morning perimeter survey
8/23/2011	EP269-EP272	0	Morning perimeter survey
8/22/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/22/2011	EP300-EP312, EP263B-EP267	0	Morning perimeter survey
8/22/2011	EP269-EP273	0	Monitoring Construction Activities
8/22/2011	EP269-EP273	0	Monitoring Construction Activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
8/22/2011	EP269-EP273	0	Morning perimeter survey
8/22/2011	EP263B	0	Monitoring Construction Activities
8/22/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/22/2011	EP291	0	Monitoring Construction Activities
8/22/2011	EP278-EP294	0	Evening perimeter survey
8/22/2011	EP278-EP294	0	Monitoring Construction Activities
8/22/2011	EP278-EP294	0	Morning perimeter survey
8/21/2011	I-8 Island	11	Evening perimeter survey - 6:00pm
8/21/2011	EP269-EP273	0	Site clearance survey
8/21/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/21/2011	EP256-EP263	0	Monitoring Construction Activities
8/21/2011	EP256-EP263	0	Site clearance survey
8/21/2011	EP279-EP294	0	Afternoon clearance survey
8/21/2011	EP274-EP278	0	Evening perimeter survey
8/21/2011	EP269-EP272	0	Evening perimeter survey
8/21/2011	EP263B-EP267	0	Site clearance survey
8/20/2011	I8 and Moutain Spring Rd	3	Morning perimeter survey 9:20am
8/20/2011	I8 and Moutain Spring Rd	4	Evening perimeter survey 6:40pm
8/20/2011	EP300-EP312	0	Monitoring construction activities
8/20/2011	EP300-EP312	0	Site clearance survey
8/20/2011	EP269-EP273	0	Monitoring construction activities
8/20/2011	EP269-EP273	0	Site clearance survey
8/20/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/20/2011	EP300-EP306	0	Morning perimeter survey
8/20/2011	EP274-EP294	0	Monitoring construction activities
8/20/2011	EP274-EP294	0	Site clearance survey
8/20/2011	EP270-EP271	0	Morning perimeter survey
8/20/2011	EP269-EP271	0	Monitoring construction activities
8/20/2011	EP263B-EP267	0	Site clearance survey
8/19/2011	Radiator Water Tower 17	7	Site clearance survey
8/19/2011	EP298, EP300 & EP307	0	Site clearance survey
8/19/2011	EP296, EP300	0	Monitoring construction activities
8/19/2011	EP296, EP300	0	Site clearance survey
8/19/2011	EP269-EP273	0	Monitoring construction activities
8/19/2011	EP269-EP273	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
8/19/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/19/2011	EP291-EP293	0	Monitoring construction activities
8/19/2011	EP279-EP294	0	Monitoring construction activities
8/19/2011	EP274-EP278	0	Monitoring construction activities
8/19/2011	EP274-EP278	0	Site clearance survey
8/19/2011	EP263B-EP267	0	Site clearance survey
8/18/2011	EP269-EP273	0	Monitoring construction activities
8/18/2011	EP269-EP273	0	Site clearance survey
8/18/2011	EP349, EP293	0	Monitoring construction activities
8/18/2011	EP279-EP312	0	Monitoring construction activities
8/18/2011	EP274-EP278	0	Monitoring construction activities
8/18/2011	EP274-EP278	0	Site clearance survey
8/18/2011	EP263B-EP267	0	Site clearance survey
8/17/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/17/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/17/2011	EP269-EP273	0	Monitoring construction activities
8/17/2011	EP269-EP273	0	Site clearance survey
8/17/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/17/2011	EP279-EP294	0	Monitoring construction activities
8/17/2011	EP279-EP294	0	Site clearance survey
8/17/2011	EP274-EP278	0	Monitoring construction activities
8/17/2011	EP274-EP278	0	Site clearance survey
8/17/2011	EP263B-EP267	0	Site clearance survey
8/16/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/16/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/16/2011	EP269-EP273	0	Monitoring construction activities
8/16/2011	EP269-EP273	0	Site clearance survey
8/16/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/16/2011	EP279-EP294	0	Monitoring construction activities
8/16/2011	EP279-EP294	0	Site clearance survey
8/16/2011	EP274-EP278	0	Monitoring construction activities
8/16/2011	EP274-EP278	0	Site clearance survey
8/16/2011	EP265	0	Monitoring construction activities
8/16/2011	EP263B-EP267	0	Site clearance survey
8/15/2011	Fromm and AER Construction Yard	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
8/15/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/15/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/15/2011	EP294	0	Monitoring construction activities
8/15/2011	EP269-EP273	0	Site clearance survey
8/15/2011	EP269-EP273	0	Monitoring construction activities
8/15/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/15/2011	EP279-EP294	0	Monitoring construction activities
8/15/2011	EP279-EP294	0	Site clearance survey
8/15/2011	EP274-EP278	0	Monitoring construction activities
8/15/2011	EP274-EP278	0	Site clearance survey
8/15/2011	EP263B-EP267	0	Site clearance survey
8/14/2011	EP274-EP278	0	Monitoring construction activities
8/14/2011	EP263B-EP267	0	Site clearance survey
8/14/2011	EP274-EP278	0	Evening perimeter survey
8/14/2011	EP279-294	0	Monitoring construction activities
8/14/2011	EP269-EP273	0	Evening perimeter survey
8/14/2011	EP300-EP312	0	Site clearance survey
8/14/2011	EP300-EP312	0	Monitoring construction activities
8/13/2011	Fromm Construction Yard	0	Site clearance survey
8/13/2011	I-8 Island	19	Morning perimeter survey at 9:54am - 10:45am
8/13/2011	I-8 Island	6	Evening perimeter survey at 4:35pm
8/13/2011	EP263B-EP267	0	Site clearance survey
8/13/2011	EP269-EP271	0	Monitoring construction activities
8/13/2011	EP270-EP271	0	Monitoring construction activities
8/13/2011	EP274-EP278	0	Monitoring construction activities
8/13/2011	EP279-294	0	Monitoring construction activities
8/13/2011	EP300-EP306	0	Monitoring construction activities
8/13/2011	EP259B	0	Site clearance survey
8/13/2011	EP269-EP273	0	Monitoring construction activities
8/13/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/13/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/12/2011	I-8 Island	26	Evening perimeter survey at 4:25pm - 5:45
8/12/2011	EP263B-EP267	0	Site clearance survey
8/12/2011	EP269-EP271	0	Monitoring construction activities
8/12/2011	EP270-EP271	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
8/12/2011	EP279-294	0	Monitoring construction activities
8/12/2011	EP300-EP306	0	Monitoring construction activities
8/12/2011	EP300-EP312	0	Monitoring construction activities
8/12/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/12/2011	EP259B	0	Site clearance survey
8/12/2011	EP269-EP273	0	Monitoring construction activities
8/12/2011	EP274-EP278, EP290-EP294	0	Site clearance survey
8/12/2011	EP274-EP278, EP290-EP294	0	Monitoring construction activities
8/12/2011	EP294	0	Monitoring construction activities
8/11/2011	I-8 Island	12	Morning perimeter survey at 10:50am
8/11/2011	I-8 Island	28	Evening perimeter survey at 6:19pm
8/11/2011	EP263B-EP267	0	Site clearance survey
8/11/2011	EP269-EP271	0	Monitoring construction activities
8/11/2011	EP270-EP271	0	Monitoring construction activities
8/11/2011	EP279-294	0	Monitoring construction activities
8/11/2011	EP300-EP306	0	Monitoring construction activities
8/11/2011	EP300-EP312	0	Monitoring construction activities
8/11/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/11/2011	EP259B	0	Site clearance survey
8/11/2011	EP269-EP273	0	Monitoring construction activities
8/11/2011	EP274-EP278	0	Site clearance survey
8/11/2011	EP274-EP278	0	Monitoring construction activities
8/11/2011	EP292-EP356	0	Monitoring construction activities
8/11/2011	EP294	0	Monitoring construction activities
8/10/2011	I-8 Island	16	Evening perimeter survey at 4:55pm - 5:08
8/10/2011	EP263B-EP267	0	Site clearance survey
8/10/2011	EP269-EP271	0	Monitoring construction activities
8/10/2011	EP270-EP271	0	Monitoring construction activities
8/10/2011	EP273	0	Monitoring construction activities
8/10/2011	EP300-EP306	0	Monitoring construction activities
8/10/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/10/2011	EP259B	0	Site clearance survey
8/10/2011	EP269-EP273	0	Monitoring construction activities
8/10/2011	EP294	0	Monitoring construction activities
8/10/2011	EP300-EP312	0	Morning perimeter survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
8/10/2011	EP300-EP312	0	Monitoring construction activities
8/10/2011	EP300-EP312	0	Evening perimeter survey
8/10/2011	EP227, EP232, EP258, EP314, EP317, EP348, EP349	0	Site clearance survey
8/9/2011	I-8 Island	3	Morning perimeter survey at 10:30am
8/9/2011	I-8 Island	18	Evening perimeter survey at 4:30pm - 5:06pm
8/9/2011	EP263B-EP267	0	Site clearance survey
8/9/2011	EP269-EP271	0	Monitoring construction activities
8/9/2011	EP270-EP271	0	Monitoring construction activities
8/9/2011	EP270-EP273	0	Monitoring construction activities
8/9/2011	EP274-EP278	0	Monitoring construction activities
8/9/2011	EP279-294	0	Monitoring construction activities
8/9/2011	EP300-EP306	0	Monitoring construction activities
8/9/2011	EP305	0	Monitoring construction activities
8/9/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/9/2011	EP269-EP273	0	Site clearance survey
8/9/2011	EP294	0	Monitoring construction activities
8/9/2011	EP300-EP312	0	Morning perimeter survey
8/9/2011	EP300-EP312	0	Monitoring construction activities
8/9/2011	EP300-EP312	0	Evening perimeter survey
8/8/2011	I-8 Island	4	Morning perimeter survey at 9:45am - 9:55am
8/8/2011	I-8 Island	22	Evening perimeter survey at 4:24pm - 5:14pm
8/8/2011	EP279-294	3	Monitoring construction activities
8/8/2011	EP263B-EP267	0	Site clearance survey
8/8/2011	EP269-EP271	0	Monitoring construction activities
8/8/2011	EP270-EP271	0	Monitoring construction activities
8/8/2011	EP273	0	Monitoring construction activities
8/8/2011	EP274-EP278	0	Monitoring construction activities
8/8/2011	EP300-EP306	0	Monitoring construction activities
8/8/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/8/2011	EP269-EP273	0	Site clearance survey
8/8/2011	EP294	0	Monitoring construction activities
8/8/2011	EP300-EP312	0	Morning perimeter survey
8/8/2011	EP300-EP312	0	Monitoring construction activities
8/8/2011	EP300-EP312	0	Evening perimeter survey
8/8/2011	EP301-EP324, EP259-3, EP259B	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
8/8/2011	EP290-EP300	0	Site clearance survey
8/7/2011	I-8 Island	27	Evening perimeter survey at 6:00pm - 6:45
8/7/2011	EP263B-EP267	0	Site clearance survey
8/7/2011	EP270-EP271	0	Monitoring construction activities
8/7/2011	EP274-EP278	0	Monitoring construction activities
8/7/2011	EP279-294	0	Monitoring construction activities
8/7/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/7/2011	EP269-EP273	0	Evening perimeter survey
8/7/2011	EP300-EP312	0	Evening perimeter survey
8/6/2011	EP278 & EP277	0	Monitoring construction activities
8/6/2011	I-8 Island	12	Afternoon perimeter survey at 1:20pm
8/6/2011	EP263B-EP267	0	Site clearance survey
8/6/2011	EP269-EP271	0	Monitoring construction activities
8/6/2011	EP270-EP271	0	Monitoring construction activities
8/6/2011	EP274-EP278	0	Monitoring construction activities
8/6/2011	EP279-294	0	Monitoring construction activities
8/6/2011	EP300-EP306	0	Monitoring construction activities
8/6/2011	EP262, EP266, EP267	0	Site clearance survey
8/6/2011	EP269-EP273	0	Monitoring construction activities
8/6/2011	EP307-EP315	0	Morning perimeter survey
8/6/2011	EP307-EP316	0	Monitoring construction activities
8/6/2011	EP307-EP317	0	Evening perimeter survey
8/5/2011	EP263B-EP267	0	Site clearance survey
8/5/2011	EP271, EP273, EP274, EP277 and EP278	0	Monitoring construction activities
8/5/2011	EP274-EP278	0	Monitoring construction activities
8/5/2011	EP279-294	0	Monitoring construction activities
8/5/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/5/2011	EP269-EP273	0	Monitoring construction activities
8/5/2011	EP294	0	Monitoring construction activities
8/5/2011	EP307-EP312	0	Morning perimeter survey
8/5/2011	EP307-EP313	0	Monitoring construction activities
8/5/2011	EP307-EP314	0	Evening perimeter survey
8/4/2011	I-8 Island	23	Evening perimeter survey at 4:00pm - 4:33pm
8/4/2011	EP263B-EP267	0	Site clearance survey
8/4/2011	EP269-EP271	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
8/4/2011	EP270-EP271	0	Monitoring construction activities
8/4/2011	EP274-EP278	0	Monitoring construction activities
8/4/2011	EP279-294	0	Monitoring construction activities
8/4/2011	EP300-EP306	0	Monitoring construction activities
8/4/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/4/2011	EP269-EP273	0	Monitoring construction activities
8/4/2011	EP294	0	Monitoring construction activities
8/3/2011	I-8 Island	17	Evening perimeter survey at 5:45pm - 6:05pm
8/3/2011	EP256-EP263	0	Monitoring construction activities
8/3/2011	EP263B-EP267	0	Site clearance survey
8/3/2011	EP269-EP271	0	Monitoring construction activities
8/3/2011	EP270-EP271	0	Monitoring construction activities
8/3/2011	EP274-EP278	0	Monitoring construction activities
8/3/2011	EP279-294	0	Monitoring construction activities
8/3/2011	EP290-EP312	0	Monitoring construction activities
8/3/2011	EP300-EP306	0	Monitoring construction activities
8/3/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/3/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
8/3/2011	EP269-EP273	0	Monitoring construction activities
8/3/2011	EP271	0	Monitoring construction activities
8/3/2011	EP294	0	Monitoring construction activities
8/3/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/3/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/3/2011	I-8 Island	0	Monitoring construction activities
8/2/2011	I-8 Island	12	Morning perimeter survey at 9:50am
8/2/2011	I-8 Island	23	Evening perimeter survey at 4:30pm
8/2/2011	EP263B-EP267	0	Site clearance survey
8/2/2011	EP269-EP271	0	Monitoring construction activities
8/2/2011	EP270-EP271	0	Monitoring construction activities
8/2/2011	EP279-294	0	Monitoring construction activities
8/2/2011	EP300-EP306	0	Monitoring construction activities
8/2/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
8/2/2011	EP269-EP273	0	Monitoring construction activities
8/2/2011	EP271 and EP273	0	Monitoring construction activities
8/2/2011	EP273	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
8/2/2011	EP274-EP278	0	Monitoring construction activities
8/2/2011	EP294	0	Monitoring construction activities
8/1/2011	I-8 Island	19	Morning perimeter survey at 10:00 - 10:20am
8/1/2011	I-8 Island	1	Evening perimeter survey at 4:30pm
8/1/2011	EP263B-EP267	0	Site clearance survey
8/1/2011	EP269-EP271	0	Monitoring construction activities
8/1/2011	EP270-EP271	0	Monitoring construction activities
8/1/2011	EP274-EP278	0	Monitoring construction activities
8/1/2011	EP279-294	0	Monitoring construction activities
8/1/2011	EP290-EP312	0	Monitoring construction activities
8/1/2011	EP300-EP306	0	Monitoring construction activities
8/1/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/1/2011	EP269	0	Monitoring construction activities
8/1/2011	EP269-EP273	0	Monitoring construction activities
8/1/2011	EP272	0	Monitoring construction activities
8/1/2011	EP291 & EP301-EP304	0	Monitoring construction activities
8/1/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/1/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
7/31/2011	I-8 Island	24	Evening perimeter survey at 5:55pm
7/31/2011	EP263B-EP267	0	Site clearance survey
7/31/2011	EP270-EP271	0	Monitoring construction activities
7/31/2011	EP274-EP278	0	Monitoring construction activities
7/31/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/31/2011	EP269-EP273	0	Evening perimeter survey
7/31/2011	EP279-EP294	0	Site clearance survey
7/31/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
7/30/2011	EP271	1	Morning perimeter survey at 7:00am
7/30/2011	EP256-EP263A-2, AER Yard	6	Monitoring during construction activities. These sheep were outside of all work areas and associated buffers and did not impact work.
7/30/2011	I-8 Island	11	Morning perimeter survey at 10:15am - 11:07
7/30/2011	I-8 Island	7	Evening perimeter survey at 4:12pm
7/30/2011	EP263B-EP267	0	Site clearance survey
7/30/2011	EP269	0	Site clearance survey
7/30/2011	EP269-EP272	0	Monitoring construction activities
7/30/2011	EP270-EP271	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
7/30/2011	EP274-EP278	0	Monitoring construction activities
7/30/2011	EP279-294	0	Monitoring construction activities
7/30/2011	EP300-EP306	0	Monitoring construction activities
7/30/2011	EP269	0	Monitoring construction activities
7/30/2011	EP269-EP273	0	Site clearance survey
7/30/2011	EP270-EP271	0	Monitoring construction activities
7/30/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
7/30/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
7/29/2011	I-8 Island	14	Morning perimeter survey at 8:55am
7/29/2011	I-8 Island	2	Evening perimeter survey at 4:00pm
7/29/2011	EP263B-EP267	0	Site clearance survey
7/29/2011	EP269	0	Site clearance survey
7/29/2011	EP269-EP272	0	Monitoring construction activities
7/29/2011	EP270-EP271	0	Monitoring construction activities
7/29/2011	EP274-EP278	0	Monitoring construction activities
7/29/2011	EP279-294	0	Monitoring construction activities
7/29/2011	EP300-EP306	0	Monitoring construction activities
7/29/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/29/2011	EP269	0	Monitoring construction activities
7/29/2011	EP269-EP273	0	Site clearance survey
7/29/2011	EP270	0	Monitoring construction activities
7/29/2011	EP300-EP312	0	Morning perimeter survey
7/29/2011	EP300-EP312	0	Monitoring construction activities
7/29/2011	EP300-EP312	0	Evening perimeter survey
7/29/2011	EP303	0	Monitoring construction activities
7/28/2011	EP269	4	Monitoring during construction activities
7/28/2011	I-8 Island	11	Morning perimeter survey at 9:19am
7/28/2011	I-8 Island	8	Evening perimeter survey at 4:00pm - 4:50pm
7/28/2011	EP279-294	0	Monitoring construction activities
7/28/2011	EP263B-EP267	0	Site clearance survey
7/28/2011	EP269	0	Site clearance survey
7/28/2011	EP270-EP271	0	Monitoring construction activities
7/28/2011	EP274-EP278	0	Monitoring construction activities
7/28/2011	EP300-EP306	0	Monitoring construction activities
7/28/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
7/28/2011	EP269	0	Monitoring construction activities
7/28/2011	EP270	0	Monitoring construction activities
7/28/2011	EP300-EP312	0	Morning perimeter survey
7/28/2011	EP300-EP312	0	Monitoring construction activities
7/28/2011	EP300-EP312	0	Evening perimeter survey
7/28/2011	AER CY	0	Site clearance survey
7/27/2011	I-8 Island	13	Evening perimeter survey at 6:30pm - 7:00pm
7/27/2011	EP279-294	0	Monitoring construction activities
7/27/2011	EP263B-EP267	0	Site clearance survey
7/27/2011	EP268 - EP263	0	Monitoring construction activities
7/27/2011	EP269	0	Site clearance survey
7/27/2011	EP270-EP271	0	Monitoring construction activities
7/27/2011	EP274-EP278	0	Monitoring construction activities
7/27/2011	EP300-EP306	0	Monitoring construction activities
7/27/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/27/2011	EP269-EP273	0	Morning perimeter survey
7/27/2011	EP269-EP273	0	Evening perimeter survey
7/27/2011	EP300-EP312	0	Morning perimeter survey
7/27/2011	EP300-EP312	0	Monitoring construction activities
7/27/2011	EP300-EP312	0	Evening perimeter survey
7/26/2011	Devils Canyon Bridge1, Hwy 8	1	Monitoring during construction activities
7/26/2011	I-8 Island	24	Morning perimeter survey at 9:46am - 10:45am
7/26/2011	I-8 Island	7	Evening perimeter survey at 6:17pm - 6:50pm
7/26/2011	EP263B-EP267	0	Site clearance survey
7/26/2011	EP269	0	Site clearance survey
7/26/2011	EP270	0	Monitoring construction activities
7/26/2011	EP274-EP278	0	Monitoring construction activities
7/26/2011	EP279-294	0	Monitoring construction activities
7/26/2011	EP300-EP306	0	Monitoring construction activities
7/26/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/26/2011	EP269-EP273	0	Morning perimeter survey
7/26/2011	EP269-EP273	0	Evening perimeter survey
7/26/2011	EP300-EP312	0	Monitoring construction activities
7/26/2011	EP300-EP312	0	Morning perimeter survey
7/26/2011	EP300-EP312	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
7/26/2011	EP300-EP312	0	Evening perimeter survey
7/25/2011	I-8 Island	21	Morning perimeter survey at 8:47am
7/25/2011	I-8 Island	20	Evening perimeter survey at 6:37am
7/25/2011	EP263B-EP267	0	Site clearance survey
7/25/2011	EP269	0	Site clearance survey
7/25/2011	EP270	0	Monitoring construction activities
7/25/2011	EP274-EP278	0	Monitoring construction activities
7/25/2011	EP279-294	0	Monitoring construction activities
7/25/2011	EP300-EP306	0	Monitoring construction activities
7/25/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/25/2011	EP269-EP273	0	Morning perimeter survey
7/25/2011	EP269-EP273	0	Evening perimeter survey
7/25/2011	EP300 & EP302	0	Monitoring construction activities
7/25/2011	EP300-EP312	0	Morning perimeter survey
7/25/2011	EP300-EP312	0	Monitoring construction activities
7/25/2011	EP300-EP312	0	Evening perimeter survey
7/25/2011	EP276	0	Monitoring construction activities
7/24/2011	I-8 Island	13	Evening perimeter survey at 6:25pm
7/24/2011	EP263B-EP267	0	Site clearance survey
7/24/2011	EP269	0	Site clearance survey
7/24/2011	EP270	0	Monitoring construction activities
7/24/2011	EP279-294	0	Monitoring construction activities
7/24/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/24/2011	EP269-EP273	0	Evening perimeter survey
7/24/2011	EP274-EP278	0	Evening perimeter survey
7/24/2011	EP300-EP312	0	Evening perimeter survey
7/23/2011	EP263B-EP267	0	Site clearance survey
7/23/2011	EP269	0	Site clearance survey
7/23/2011	EP270	0	Monitoring construction activities
7/23/2011	EP279-294	0	Monitoring construction activities
7/23/2011	EP300-EP312	0	Monitoring construction activities
7/23/2011	EP300-EP312	0	Site clearance survey
7/23/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/23/2011	EP269-EP276	0	Morning perimeter survey
7/23/2011	EP274-EP278	0	Morning perimeter survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
7/23/2011	EP274-EP278	0	Evening perimeter survey
7/23/2011	I-8 Island	0	Morning perimeter survey
7/22/2011	I-8 Island	18	Evening perimeter survey at 6:35pm
7/22/2011	EP263B-EP267	0	Site clearance survey
7/22/2011	EP269	0	Site clearance survey
7/22/2011	EP269-EP270	0	Monitoring construction activities
7/22/2011	EP270	0	Monitoring construction activities
7/22/2011	EP300-EP312	0	Monitoring construction activities
7/22/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/22/2011	EP269-EP273	0	Morning perimeter survey
7/22/2011	EP269-EP273	0	Evening perimeter survey
7/22/2011	EP274-EP278	0	Site clearance survey
7/22/2011	EP274-EP278	0	Monitoring construction activities
7/21/2011	I-8 Island	18	Evening perimeter survey at 6:35pm
7/21/2011	EP263B-EP267	0	Site clearance survey
7/21/2011	EP269	0	Site clearance survey
7/21/2011	EP269-EP270	0	Monitoring construction activities
7/21/2011	EP270	0	Monitoring construction activities
7/21/2011	EP279-294	0	Monitoring construction activities
7/21/2011	EP300-EP312	0	Monitoring construction activities
7/21/2011	EP300-EP306	0	Site clearance survey
7/21/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/21/2011	EP269-EP273	0	Morning perimeter survey
7/21/2011	EP269-EP273	0	Evening perimeter survey
7/21/2011	EP274-EP278	0	Morning perimeter survey
7/21/2011	EP274-EP278	0	Evening perimeter survey
7/20/2011	I-8 Island	4	Evening perimeter survey at 6:50pm
7/20/2011	EP269-EP273	0	Morning perimeter survey
7/20/2011	EP269-EP273	0	Evening perimeter survey
7/20/2011	EP263B-EP267	0	Site clearance survey
7/20/2011	EP269	0	Site clearance survey
7/20/2011	EP270	0	Monitoring construction activities
7/20/2011	EP279-294	0	Monitoring construction activities
7/20/2011	EP300-EP312	0	Monitoring construction activities
7/20/2011	EP300-EP306	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
7/20/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/20/2011	EP274-EP278	0	Morning perimeter survey
7/20/2011	EP274-EP278	0	Evening perimeter survey
7/19/2011	I-8 Island	10	Morning perimeter survey at 9:10am
7/19/2011	I-8 Island	17	Evening perimeter survey at 4:00pm - 6:40pm
7/19/2011	EP269-EP273	0	Morning perimeter survey
7/19/2011	EP269-EP273	0	Evening perimeter survey
7/19/2011	EP269	0	Site clearance survey
7/19/2011	EP270	0	Monitoring construction activities
7/19/2011	EP279-294	0	Monitoring construction activities
7/19/2011	EP300-EP312	0	Monitoring construction activities
7/19/2011	EP300-EP306	0	Site clearance survey
7/19/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/19/2011	EP274-EP278	0	Morning perimeter survey
7/19/2011	EP274-EP278	0	Evening perimeter survey
7/19/2011	EP263B-EP267	0	Site clearance survey
7/18/2011	I-8 Island	21	Evening perimeter survey at 7:10pm
7/18/2011	EP263B-EP267	0	Site clearance survey
7/18/2011	EP269	0	Site clearance survey
7/18/2011	EP270	0	Monitoring construction activities
7/18/2011	EP279-294	0	Monitoring construction activities
7/18/2011	EP300-EP312	0	Monitoring construction activities
7/18/2011	EP300-EP306	0	Site clearance survey
7/18/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/18/2011	EP274-EP278	0	Morning perimeter survey
7/18/2011	EP274-EP278	0	Evening perimeter survey
7/18/2011	EP269-EP273	0	Site clearance survey
7/17/2011	I-8 Island	17	Evening perimeter survey at 5:55pm - 6:25
7/17/2011	EP263B-EP267	0	Site clearance survey
7/17/2011	EP269	0	Site clearance survey
7/17/2011	EP270	0	Monitoring construction activities
7/17/2011	EP300-EP312	0	Monitoring construction activities
7/17/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/17/2011	EP274-EP278	0	Evening perimeter survey
7/17/2011	EP279-EP294	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
7/17/2011	EP269-EP273	0	Site clearance survey
7/16/2011	I-8 Island	1	Morning perimeter survey at 8:35am
7/16/2011	EP263B-EP267	0	Site clearance survey
7/16/2011	EP269	0	Site clearance survey
7/16/2011	EP270	0	Monitoring construction activities
7/16/2011	EP300-EP306	0	Monitoring construction activities
7/16/2011	EP300-EP312	0	Monitoring construction activities
7/16/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/16/2011	EP274-EP278	0	Morning perimeter survey
7/16/2011	EP279-EP294	0	Morning perimeter survey
7/16/2011	EP279-EP294	0	Site clearance survey
7/16/2011	EP279-EP294	0	Monitoring construction activities
7/16/2011	EP269-EP273	0	Site clearance survey
7/15/2011	EP273-1	1	Evening perimeter survey at 4:30pm
7/15/2011	I-8 Island	12	Evening perimeter survey at 6:35pm - 7:00pm
7/15/2011	EP263B-EP267	0	Site clearance survey
7/15/2011	EP269	0	Site clearance survey
7/15/2011	EP270	0	Monitoring construction activities
7/15/2011	EP279-294	0	Monitoring construction activities
7/15/2011	EP300-EP306	0	Monitoring construction activities
7/15/2011	EP300-EP312	0	Monitoring construction activities
7/15/2011	EP256-EP263A-2, AER Yard	0	Site clearance survey
7/15/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/15/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/15/2011	EP269-EP273	0	Site clearance survey
7/15/2011	EP274-EP278	0	Morning perimeter survey
7/15/2011	EP274-EP278	0	Evening perimeter survey
7/14/2011	I-8 Island	3	Evening perimeter survey at 4:10pm
7/14/2011	I-8 Island		7:15am - 9:30am PBHS were at above point
7/14/2011	EP263B-EP267	0	Site clearance survey
7/14/2011	EP269	0	Site clearance survey
7/14/2011	EP270	0	Monitoring construction activities
7/14/2011	EP279-294	0	Monitoring construction activities
7/14/2011	EP300-EP306	0	Monitoring construction activities
7/14/2011	EP300-EP312	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
7/14/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/14/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/14/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/14/2011	EP274-EP278	0	Morning perimeter survey
7/14/2011	EP274-EP278	0	Evening perimeter survey
7/14/2011	EP269-EP273	0	Site clearance survey
7/13/2011	I-8 Island	21	Evening perimeter survey at 4:40pm
7/13/2011	EP263B-EP267	0	Site clearance survey
7/13/2011	EP269	0	Site clearance survey
7/13/2011	EP270	0	Monitoring construction activities
7/13/2011	EP279-294	0	Monitoring construction activities
7/13/2011	EP300-EP306	0	Monitoring construction activities
7/13/2011	EP300-EP312	0	Monitoring construction activities
7/13/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/13/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/13/2011	EP269-EP273	0	Site clearance survey
7/12/2011	EP256-EP263A-2, AER Yard	15	Monitoring during construction activities @ 7:40am - 11:00am
7/12/2011	I-8 Island	17	Evening perimeter survey at 4:00pm
7/12/2011	EP263B-EP267	0	Site clearance survey
7/12/2011	EP269	0	Site clearance survey
7/12/2011	EP270	0	Monitoring construction activities
7/12/2011	EP279-294	0	Monitoring construction activities
7/12/2011	EP300-EP306	0	Monitoring construction activities
7/12/2011	EP300-EP312	0	Monitoring construction activities
7/12/2011	EP274-EP278	0	Morning perimeter survey
7/12/2011	EP274-EP278	0	Evening perimeter survey
7/12/2011	EP269-EP273	0	Site clearance survey
7/11/2011	I-8 Island	29	Evening perimeter survey at 4:40pm
7/11/2011	EP263B-EP267	0	Site clearance survey
7/11/2011	EP269	0	Site clearance survey
7/11/2011	EP270	0	Monitoring construction activities
7/11/2011	EP279-294	0	Monitoring construction activities
7/11/2011	EP300-EP306	0	Monitoring construction activities
7/11/2011	EP300-EP312	0	Monitoring construction activities
7/11/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
7/11/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/11/2011	EP269-EP273	0	Site clearance survey
7/11/2011	EP274-EP278	0	Morning perimeter survey
7/11/2011	EP274-EP278	0	Evening perimeter survey
7/10/2011	I-8 Island	8	Perimeter survey
7/10/2011	I-8 Island	20	Monitoring construction activities
7/10/2011	EP269	0	Site clearance survey
7/10/2011	EP270	0	Monitoring construction activities
7/10/2011	EP279-294	0	Monitoring construction activities
7/10/2011	EP300-EP312	0	Monitoring construction activities
7/10/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/10/2011	EP274-EP278, EP265-EP267	0	Site clearance survey
7/9/2011	EP263A-2	11	Evening perimeter survey
7/9/2011	EP263B-EP267	0	Site clearance survey
7/9/2011	EP269-EP274	0	Monitoring construction activities
7/9/2011	EP279-294	0	Monitoring construction activities
7/9/2011	EP300-EP307	0	Monitoring construction activities
7/9/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/9/2011	EP269-EP273	0	Site clearance survey
7/9/2011	EP274-EP278	0	Morning perimeter survey
7/9/2011	EP310	0	Monitoring construction activities
7/8/2011	EP263B-EP267	0	Site clearance survey
7/8/2011	EP300-EP312	0	Monitoring construction activities
7/8/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/8/2011	EP269-EP273	0	Site clearance survey
7/8/2011	EP274-EP278	0	Morning perimeter survey
7/8/2011	EP274-EP278	0	Evening perimeter survey
7/8/2011	EP303	0	Monitoring construction activities
7/8/2011	EP279-EP294	0	Monitoring construction activities
7/7/2011	I-8 Island	8	Evening perimeter survey at 7:00pm
7/7/2011	EP263B-EP267	0	Site clearance survey
7/7/2011	EP269-EP273	0	Monitoring construction activities
7/7/2011	EP300-EP312	0	Monitoring construction activities
7/7/2011	EP300-EP307	0	Monitoring construction activities
7/7/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
7/7/2011	EP269-EP273	0	Site clearance survey
7/7/2011	EP274-EP278	0	Morning perimeter survey
7/7/2011	EP274-EP278	0	Evening perimeter survey
7/7/2011	EP303 & EP304	0	Monitoring construction activities
7/7/2011	EP306-EP312	0	Site clearance survey
7/6/2011	EP263A-2	2	Evening perimeter survey
7/6/2011	EP263B-EP267	0	Site clearance survey
7/6/2011	EP269-EP272	0	Monitoring construction activities
7/6/2011	EP300-EP312	0	Monitoring construction activities
7/6/2011	EP300-EP307	0	Monitoring construction activities
7/6/2011	EP303	0	Site clearance survey
7/6/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/6/2011	EP274-EP278	0	Morning perimeter survey
7/6/2011	EP274-EP278	0	Evening perimeter survey
7/6/2011	EP305 to EP304	0	Monitoring construction activities
7/6/2011	I-8 Island	0	Monitoring construction activities
7/6/2011	EP269-EP273	0	Site clearance survey
7/5/2011	EP270	14	Morning perimeter survey at 6:30am - 10:00am
7/5/2011	EP270	9	Evening perimeter survey at 5:00pm
7/5/2011	I-8 Island	7	Evening perimeter survey at 6:20pm
7/5/2011	EP269-EP273	0	Morning perimeter survey
7/5/2011	EP269-EP273	0	Evening perimeter survey
7/5/2011	EP263B-EP267	0	Site clearance survey
7/5/2011	EP269-EP271	0	Monitoring construction activities
7/5/2011	EP300-EP312	0	Monitoring construction activities
7/5/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/5/2011	EP274-EP278	0	Morning perimeter survey
7/5/2011	EP274-EP278	0	Evening perimeter survey
7/5/2011	EP307 to EP305	0	Monitoring construction activities
7/5/2011	I-8 Island	0	Site clearance survey
7/4/2011	EP270	9	Perimeter survey
7/4/2011	EP263B-EP267	0	Site clearance survey
7/4/2011	EP300-EP312	0	Monitoring construction activities
7/4/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/4/2011	EP269-EP273	0	Site clearance survey

PBS Monitoring Report - Week Ending 12/17/2011

Date	Location	Number observed	Comments
7/4/2011	EP274-EP278	0	Evening perimeter survey
7/4/2011	I-8 Island	0	Site clearance survey
7/2/2011	EP263B-EP267	0	Site clearance survey
7/2/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/2/2011	EP269-EP273	0	Site clearance survey
7/2/2011	EP274-EP278	0	Morning perimeter survey
7/2/2011	I-8 Island	0	Site clearance survey
7/1/2011	EP263B-EP267	0	Site clearance survey
7/1/2011	EP300-EP312	0	Monitoring construction activities
7/1/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/1/2011	EP269-EP273	0	Site clearance survey
7/1/2011	EP274-EP278	0	Morning perimeter survey
7/1/2011	EP274-EP278	0	Evening perimeter survey
7/1/2011	I-8 Island	0	Site clearance survey
6/30/2011	EP300-EP312	0	Monitoring construction activities
6/29/2011	EP310-EP312	0	Monitoring construction activities
4/15/2011	EP210, EP211, EP213-EP215, EP217-EP219	0	Monitoring construction activities
3/26/2011	EP105	0	Site clearance survey

Raven Control Monitoring Report - Week Ending 12/17/2011

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
12/17/2011	EP325	1		1				no
12/17/2011	S2 Yard	3					3	no
12/16/2011	No ravens observed							
12/15/2011	IV Substation	1			1			no
12/15/2011	EP293	2		2				no
12/15/2011	S2 Yard	3					3	no
12/14/2011	S2 Yard	3					3	no
12/13/2011	S2 Yard	2					2	no
12/12/2011	S2 Yard	2					2	no
12/11/2011	S2 Yard	2					2	no
12/10/2011	EP306 & EP306/EP307 Pullsite	3		3				no
12/9/2011	IV Substation	1		1				no
12/9/2011	EP308 & EP306/EP307 Pullsite	2		2				no
12/9/2011	EP291 & EP291/EP292 Pullsite	2		2				no
12/8/2011	S2 Yard	3					3	no
12/8/2011	IV Substation	1		1				no
12/8/2011	EP301	2		2				no
12/8/2011	EP300-EP309	2		2				no
12/8/2011	EP291/EP292 Pullsite	2	2					no
12/8/2011	EP281	2		2				no
12/7/2011	IV Substation	1		1				no
12/7/2011	EP301	1			1			no
12/7/2011	EP291/EP292 Pullsite	1			1			no
12/7/2011	EP281	7		4	2	1		no
12/7/2011	S2 Yard	2			2			no
12/6/2011	S2 Yard	3				3		no
12/6/2011	EP301	2			2			no
12/6/2011	EP281	5		4		1		no
12/5/2011	S2 Yard	2					2	no
12/5/2011	IV Substation	2		2				no
12/5/2011	EP363	2		2				no
12/5/2011	EP281	6		6				no
12/4/2011	S2 Yard	3				3		no
12/4/2011	IV Substation	2		2				no
12/4/2011	Fromm CY	2				1	1	no
12/4/2011	EP294	1		1				no
12/3/2011	EP281	1		1				no
12/2/2011	IV Substation	1		1				no
12/1/2011	S2 Yard	2					2	no
11/30/2011	S2 Yard	2			2			no
11/29/2011	S2 Yard	2			2			no
11/28/2011	S2 Yard	4			4			no
11/28/2011	EP290-EP301	5		2	3			no
11/27/2011	S2 Yard	1		1				no
11/26/2011	No ravens observed							

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
11/25/2011	NO WORK: DAY AFTER THANKSGIVING							
11/24/2011	NO WORK: THANKSGIVING							
11/23/2011	Plaster City Yard	3					3	no
11/22/2011	S2 Yard	4			4			no
11/22/2011	IV Substation	1			1			no
11/21/2011	S2 Yard	4					4	no
11/21/2011	IV Substation	1		1				no
11/21/2011	EP281	2			2			no
11/20/2011	EP360	2			2			no
11/20/2011	IV Substation	2		2				no
11/19/2011	No ravens observed							
11/18/2011	EP358 and IV Substation	2		2				no
11/17/2011	No ravens observed							
11/16/2011	S2 Yard	5			5			no
11/15/2011	EP330-1	2					2	no
11/15/2011	EP304; EP330	1			1			no
11/14/2011	S2 Yard	6			6			no
11/13/2011	No ravens observed							
11/12/2011	Dunaway CY	1			1			no
11/11/2011	Dunaway CY	4					4	no
11/11/2011	S2 Yard	5					5	no
11/10/2011	Fromm CY	2					2	no
11/10/2011	EP355	1		1				no
11/9/2011	Dunaway CY	1			1			no
11/8/2011	S2 Yard	5			5			no
11/8/2011	Dunaway CY	2			2			no
11/7/2011	S2 Yard	3					3	no
11/7/2011	EP308-EP310	1					1	no
11/7/2011	EP301 Pullsite	7		6	1			no
11/6/2011	No ravens observed							
11/5/2011	S2 Yard	7			7			no
11/5/2011	IV Substation	1			1			no
11/4/2011	S2 Yard	5			5			no
11/3/2011	S2 Yard	5			3		2	no
11/3/2011	IV Substation	1			1			no
11/3/2011	Fromm CY	1				1		no
11/3/2011	EP303 and EP302	2			2			no
11/3/2011	EP281	2			2			no
11/2/2011	S2 Yard	4			4			no
11/2/2011	IV Substation	1		1				no
11/2/2011	EP305, EP310, EP311	1		1				no
11/1/2011	S2 Yard	2			2			no
11/1/2011	IV Substation	1		1				no
11/1/2011	EP305 and EP312	1			1			no
10/31/2011	S2 Yard	5			5			no
10/31/2011	AER and Fromm CY	1				1		no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
10/30/2011	No ravens observed							
10/29/2011	IV Substation	3		3				no
10/28/2011	IV Substation	1		1				no
10/28/2011	EP256, EP357 & EP358	5		5				no
10/27/2011	EP356, EP358 & EP362	2		2				no
10/27/2011	EP305, EP307, EP310-EP312	1		1				no
10/26/2011	EP306, EP307 & EP310	2		2				no
10/25/2011	IV Substation	1		1				no
10/25/2011	EP310	1		1				no
10/24/2011	S2 Yard	3					3	no
10/24/2011	EP305	1			1			no
10/23/2011	S2 Yard	3			3			no
10/22/2011	No ravens observed							
10/21/2011	Dunaway CY	1			1			no
10/20/2011	S2 Yard	2					2	no
10/20/2011	Dunaway CY	5					5	no
10/19/2011	EP314	1		1				no
10/19/2011	EP290	5		5				no
10/18/2011	No ravens observed							
10/17/2011	EP301	3		3				no
10/16/2011	No ravens observed							
10/15/2011	S2 Yard	2					2	no
10/15/2011	Dunaway CY	1				1		no
10/15/2011	EP315	2					2	no
10/15/2011	EP301	3			3			no
10/14/2011	Fromm CY	3				3		no
10/14/2011	EP305	2		2				no
10/14/2011	EP301	3			3			no
10/13/2011	S2 Yard	2					2	no
10/13/2011	Dunaway CY	5					5	no
10/13/2011	Fromm CY	1					1	no
10/13/2011	EP354-EP363	2			2			no
10/13/2011	EP301	4		4				no
10/12/2011	EP300-EP301	2		2				no
10/11/2011	Plaster City Yard	2			2			no
10/11/2011	IV Substation	2					2	no
10/10/2011	Fromm CY	2				2		no
10/10/2011	EP359-EP360	2		2				no
10/10/2011	EP355-EP363	2		2				no
10/10/2011	EP301	3		3				no
10/9/2011	S2 Yard	3					3	no
10/9/2011	EP300	6		6				no
10/8/2011	EP357	2			2			no
10/8/2011	EP306	3					3	no
10/7/2011	Dunaway CY	1		1				no
10/7/2011	EP291-EP301	3		3				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
10/6/2011	Fromm CY	2					2	no
10/5/2011	Dunaway CY	2		2				no
10/5/2011	EP303-2	2		2				no
10/4/2011	EP310 & EP311	2		2				no
10/4/2011	EP301	3					3	no
10/4/2011	EP293	2		2				no
10/3/2011	S2 Yard	2					2	no
10/3/2011	Dunaway CY	2			2			no
10/2/2011	EP356-EP363	2		1	1			no
10/1/2011	Plaster City Yard	2					2	no
10/1/2011	EP360	2			2			no
9/30/2011	S2 Yard	2					2	no
9/30/2011	EP355	1		1				no
9/30/2011	EP314	2		2				no
9/30/2011	EP301	2		1	1			no
9/29/2011	EP291/EP292 Pullsite	1			1			no
9/28/2011	EP361	1			1			no
9/27/2011	EP315	2		1	1			no
9/27/2011	EP309	1		1				no
9/27/2011	EP301 & EP304	4		3	1			no
9/27/2011	EP290	1			1			no
9/26/2011	EP362	2			2			no
9/26/2011	Fromm CY	1				1		no
9/25/2011	No ravens observed							
9/24/2011	Plaster City Yard	2					2	no
9/24/2011	EP317	1		1				no
9/24/2011	EP309	1		1				no
9/23/2011	EP362	4			4			no
9/23/2011	EP303	2		2				no
9/22/2011	Fromm CY	1				1		no
9/22/2011	EP303	2		2				no
9/22/2011	EP301	2		2				no
9/22/2011	EP295-EP322	3		3				no
9/21/2011	S2 Yard	3			3			no
9/21/2011	Fromm CY	1					1	no
9/21/2011	EP303	1		1				no
9/20/2011	S2 Yard	2			2			no
9/20/2011	Fromm CY	1				1		no
9/19/2011	S2 Yard	3			3			no
9/19/2011	EP304, EP307, EP309	1		1				no
9/18/2011	S2 Yard	3				3		no
9/18/2011	EP281	1		1				no
9/17/2011	S2 Yard	3					3	no
9/17/2011	EP362	1			1			no
9/17/2011	Fromm CY	3				3		no
9/16/2011	EP363	2			2			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
9/16/2011	Fromm CY	1					1	no
9/16/2011	EP304	2		2				no
9/16/2011	EP290	1		1				no
9/15/2011	S2 Yard	4			4			no
9/15/2011	Fromm CY	3					3	no
9/15/2011	EP296	1		1				no
9/15/2011	EP306	2					2	no
9/15/2011	EP304	1		1				no
9/15/2011	EP301	2		2				no
9/14/2011	Plaster City Yard	1			1			no
9/14/2011	EP361	2			2			no
9/14/2011	Fromm CY	1				1		no
9/14/2011	EP308	1					1	no
9/14/2011	EP301	5		4	1			no
9/14/2011	EP292	3		3				no
9/13/2011	S2 Yard	10			10			no
9/13/2011	EP348	3		3				no
9/13/2011	EP345	2		2				no
9/13/2011	EP326	1					1	no
9/13/2011	EP325	2		2				no
9/13/2011	EP326	1		1				no
9/13/2011	EP304	7		7				no
9/13/2011	EP291	7		7				no
9/12/2011	S2 Yard	3			3			no
9/12/2011	EP350	1		1				no
9/12/2011	EP304	1		1				no
9/12/2011	EP301	1		1				no
9/11/2011	S2 Yard	2				2		no
9/10/2011	S2 Yard	2					2	no
9/9/2011	EP304	1			1			no
9/8/2011	S2 Yard	3					3	no
9/7/2011	S2 Yard	3					3	no
9/6/2011	No ravens observed							
9/5/2011	No ravens observed							
9/4/2011	No ravens observed							
9/3/2011	No ravens observed							
9/2/2011	EP348	1		1				no
9/2/2011	S2 Yard	1		1				no
9/2/2011	EP303	1		1				no
9/2/2011	EP363	2		2				1 at IV Sub
9/1/2011	EP303	2					2	no
9/1/2011	EP293	1					1	no
9/1/2011	EP304	2					2	no
8/31/2011	S2 Yard	1		1				no
8/31/2011	EP308	1		1				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
8/31/2011	EP305-3	2					2	no
8/31/2011	EP303	2		2				no
8/30/2011	EP303	1		1				no
8/29/2011	S2 Yard	1		1				no
8/29/2011	EP303	1		1				no
8/28/2011	No ravens observed							
8/27/2011	EP305	3			3			no
8/26/2011	EP301	2		2				no
8/25/2011	S2 Yard	2					2	no
8/25/2011	EP301	2		2				no
8/24/2011	S2 Yard	3				3		no
8/23/2011	EP292-1	3		3				no
8/22/2011	No ravens observed							
8/21/2011	No ravens observed							
8/20/2011	S2 Yard	2				2		no
8/20/2011	EP312	2		2				no
8/20/2011	S2 Yard	2					2	no
8/20/2011	EP312	2		2				no
8/19/2011	EP307	2			2			no
8/19/2011	EP296	1		1				no
8/18/2011	S2 Yard	2				1	1	no
8/18/2011	EP301	Flock		x				no
8/17/2011	S2 Yard	2				1	1	no
8/17/2011	EP301	3			3			no
8/16/2011	S2 Yard	1					1	no
8/16/2011	EP301	1		1				no
8/15/2011	No ravens observed							
8/14/2011	No ravens observed							
8/13/2011	S2 Yard	2					2	no
8/12/2011	IV Substation	2				2		no
8/12/2011	S2 Yard	3				3	3	no
8/11/2011	EP294	4			4			no
8/11/2011	S2 Yard	3				3	3	no
8/10/2011	S2 Yard	3				2	1	no
8/9/2011	S2 Yard	not specified						no
8/8/2011	EP294	2			2			no
8/8/2011	S2 Yard	1						no
8/7/2011	No ravens observed							
8/6/2011	S2 Yard	1						no
8/5/2011	EP301	3		3				no
8/4/2011	S2 Yard	not specified						no
8/3/2011	S2 Yard	2		2				no
8/3/2011	S2 Yard	1						no
8/2/2011	S2 Yard	3					3	no
8/1/2011	EP314	not specified		x				no
7/31/2011	No ravens observed							

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
7/30/2011	EP314	3		2			1	no
7/30/2011	S2 Yard	1					1	no
7/29/2011	S2 Yard	1						no
7/28/2011	EP319	4	1	2	1			no
7/28/2011	S2 Yard	not specified						no
7/27/2011	S2 Yard	not specified						no
7/26/2011	No ravens observed							
7/25/2011	EP290	1			1			no
7/24/2011	No ravens observed							
7/23/2011	No ravens observed							
7/22/2011	EP290	2		1	1			no
7/21/2011	S2 Yard	1		1				no
7/20/2011	Ocotillo, CA	5						no
7/19/2011	Ocotillo, CA	1						no
7/18/2011	CP40-2	not specified						no
7/18/2011	CP41-2	not specified						no
7/18/2011	CP42-1	not specified						no
7/17/2011	No ravens observed							
7/16/2011	CP42-1	not specified						no
7/15/2011	No ravens observed							
7/14/2011	EP357	not specified						no
7/14/2011	EP358	not specified						no
7/14/2011	EP359	not specified						no
7/14/2011	Plaster City Yard	2		2				no
7/13/2011	EP313-EP314 PS	not specified						no
7/13/2011	S2 Yard	3					3	no
7/12/2011	CP18-1	not specified						no
7/12/2011	CP19-1	not specified						no
7/12/2011	CP22-1	not specified						no
7/11/2011	EP304-EP314	not specified						no
7/10/2011	No ravens observed							
7/9/2011	EP351	not specified						no
7/9/2011	EP353	not specified						no
7/9/2011	EP354	not specified						no
7/9/2011	EP355	not specified						no
7/9/2011	not specified	not specified						no
7/9/2011	S2 Yard	3					3	no
7/8/2011	EP303	2			1		1	no
7/8/2011	EP303	1		1				no
7/8/2011	S2 Yard	3					3	no
7/1/11-7/7/11	No ravens observed							
6/30/2011	EP300	3		3				no
6/21/11-6/29/11	No ravens observed							
6/20/2011	S2 Yard	2					2	no
6/1/11-6/19/11	No ravens observed							
5/1/11-5/31/11	No ravens observed							

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
4/22/11-4/30/11			No ravens observed					
4/21/2011	EP341	1	1					no
4/1/11-4/20/11			No ravens observed					
3/1/11-3/31/11			No ravens observed					
2/1/11-2/28/11			No ravens observed					
1/21/11-1/31/11			No ravens observed					
1/21/2011	Rough Acres Yard	not specified						no