

This report provides a summary of environmental monitoring and compliance activities conducted by Burns and McDonnell (BMcD) staff and BMcD subconsultants for the San Diego Gas & Electric (SDG&E) Sunrise Powerlink Project during the above weekly time period.

### **Training**

- SWEAP and PBS training continued for new Project personnel every Tuesday and Thursday. Additional trainings were provided as requested.
- Flat-tailed horned lizard (FTHL) trainings were provided to any new crew members or monitors prior to construction per mitigation measure B-7b and in accordance with the FTHL Rangewide Management Strategy. During morning tailboard meetings, guidelines were provided about recognizing, protecting, and notification requirements for FTHL. FTHL information cards were made available to any crew members or monitors as needed.
- Barefoot banded gecko (BBG) trainings were provided to crews prior to pre-construction activities pursuant to the California Department of Fish and Game (CDFG) 2081 Incidental Take Permit requirements.

### **Pre/Post Construction**

- Staked, flagged, and refreshed work areas near EP54-1, EP58-2, EP119-2, EP120-4, EP219-1, and EP220-1.
- Additional signs and stakes were repaired as needed. Due to traffic and narrow access roads, broken stakes and run over signs were replaced. Maintenance (e.g., writing over faded signs, reinforcing signs/stakes into the ground, replacing zip ties, and adding additional signs) was performed as needed. The ESA Team conducted the following activities during this reporting period:
  - Repaired, refreshed, replaced, and maintained the previously installed project signs and ESAs at Sycamore, CP17, CP80, CP98, EP22, EP256, and EP288.
  - Installed ESAs and project signs at EP73, EP103-2, and EP173.

### **Construction**

- Monitors were present during construction activities to ensure compliance with mitigation measures as identified in the Final EIR/EIS Mitigation Monitoring, Compliance, and Reporting Program. Archaeologists, Paleontologists, and Native American Monitors were present at sites where required as identified prior to construction activity and as approved in the NTPs. On average, the following number of monitors were on the Project throughout the week:
  - 5 Archaeological Monitors.
  - 89 Biological Monitors.
  - 5 Native American Monitors.
  - 1 Paleontological Monitor.
  - 8 SWPPP Monitors.
- Project staff carpooled to site reviews, kick-off tailgates, and off-site meetings. Construction and traffic control crews were observed carpooling from yards to work areas.
- Deterrents were utilized to discourage bird nest building activities throughout the Project. Deterrents are determined depending upon the location and type of possible nesting areas and

may include metallic flagging, compact discs, plastic owls, and the presence of biological monitors.

The table below demonstrates the construction progress to date:

<b>OVERHEAD</b>			
<b>Agency</b>	<b>Foundations Completed</b>	<b>Towers Erected</b>	<b>Wire Installed</b>
Non-Federal	122 of 169	61 of 169	31 of 169 EP 256 to EP 262-4
Bureau of Land Management	146 of 179	106 of 179	87 of 179 EP269-1 to EP 263A-2
Miramar	13 of 14	4 of 14	0 of 14
US Forest Service	31 of 76	16 of 76	17 of 76
<b>UNDERGROUND</b>			
<b>Agency</b>	<b>Vaults Installed</b>	<b>Trenches Excavated &amp; Backfilled</b>	
Non-Federal	40 of 40	42 of 42	
<b>SUBSTATION UPGRADES</b>			
3 of 7 Completed			
<b>SUNCREST SUBSTATION</b>			
80 Percent Complete			

Overhead Construction

- Link 1
  - Vegetation clearing at EP187-2, EP187-2-N, and EP227 TSAP.
  - Guard structure clearing at EP221-2 and EP239-1.
  - Vegetation clearing for gate installation at EP179 and EP185-1.
  - Grading at EP187-2, EP187-2-N, and EP189-3.
  - Trenching, pouring, and gas line installation for the regen site at EP215.
  - Final grading at/from EP256, EP258-3-N to EP261-2-E, EP269-1-E, EP290, EP291-1, EP292-1 pull site, and EP313-E.
  - Micropile drilling at EP144, EP145, EP147, EP148-1, EP149, EP189-3, and EP237-1 (redrilled).
  - Grouting at EP152-2, EP188-1, EP189-3, EP194-2, EP228, EP236-1, and EP237-1.
  - Micropile cap work at EP261-2, EP261A, EP262-4, EP263A-2, EP263B-2, and EP265-1.

- Conventional drilling at EP170.
  - Various foundation work (curing, cage installation, etc.) at EP170.
  - Tower assembly at EP262-4, EP263A-2, EP263B-2, EP264-4, EP265-2, EP277-1, and EP278-1.
  - Miscellaneous tower work (anti-climbing guards, bird deterrents, and/or signage) at/from EP256 to EP262-4, EP263B-2 to EP267-2, EP269-1, EP270-2, EP271-2, and EP290 to EP302-1.
  - Ground rod installation at EP223-1.
  - Exposed ground rods covered with concrete at EP305-3 and EP310.
  - Temporary ground wires removed from EP290, EP295, and EP301.
  - OPGW pulled from EP255-2 pull site to EP269-1 pull site.
  - Sagging at EP261-2, EP266-2, EP269-1, EP277-1, and EP280.
  - OPGW sagged and clipped in from EP269-1 pull site to EP292-1 pull site.
  - OPGW clipped in at EP259B, EP265-2, EP266-2, EP290, EP291-1, and EP292-1 pull site.
  - Deadend work occurred at EP261-2, EP263A-2, EP263B-2, EP264-4, EP267-2, and EP271-2.
  - Clipping in at EP255-2, EP259-3, EP259B, EP265-2, EP266-2, EP272-3, and EP273-1.
  - Insulator work at EP261-2, EP269-1, EP269-1 pull site, and EP281.
  - Jumpers and spacers installed at EP281, EP290, and EP291-1.
  - Splicing at EP269-1 and EP291-1.
  - Travelers installed at EP270-2.
  - Travelers removed from EP265-2.
  - Jumpers installed at EP263B-2, EP264-4, and EP270-2.
  - Jumpers removed from EP291-1.
  - Marker balls installed at/from EP261-2, EP266-2, EP269-1, EP270-2 to EP271-2, and EP274-1 to EP276-1.
  - Spacers installed at/from EP255-2 to EP256, EP266-2, EP274-1 to EP276-1, EP277-1, EP290, and EP291-1
  - Spacers readjusted between EP261-2, EP269-1, EP279-1, and EP281.
  - BMP installation at EP187.
  - BMPs removed and site stabilization commenced at:
    - EP256, EP256-N, EP257, EP257-E-B, EP257-N, EP259B, EP261A, EP265-2, EP266-2, EP267-2, EP269-1, EP270-2, EP271-2, EP273-1, EP274-1, EP275-1, EP276-1, EP266-2, and EP290 to EP318-1.
  - Guard structure removal at EP281.
  - Helicopter platform removal at EP263B-2.
  - Barefoot-banded gecko exclusionary fencing removed at EP269-1 guard structure, EP270-2, EP273-1, and EP281.
  - Native seed applied at EP300, EP303, EP304, EP306, and EP307.
  - Hydroseeding at EP281 guard structure.
  - Hydromulching at/from EP258-3, EP259B, EP259-3, EP261-2, EP261A to EP264-4, EP270-2, EP271-2, EP273-1 to EP281, EP290, EP291, EP292-1 pull site, EP306-1, EP306-1/EP307-1 pull site, and EP308.
  - Trained FTHL monitors, BBG monitors, BHS monitors, and Visible Emission Evaluators (VEEs) were onsite as required.
- [Link 2](#)
    - During this reporting period, the PAL Levels were as follows: Tuesday-D, Wednesday-D, Thursday-D, Friday-C, and Saturday-D. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

#### USFS Land

- Access road construction at:
  - EP11-3-N, EP12-3-PS-N, EP22-1-PS-N, EP58-2-N through EP63-E, EP76-2-E, EP77-E, EP127-E, and EP129-E-B.
- Vegetation clearing at EP10-2, EP10-2 landing platform site, EP12-3 pull site, EP22-1 pull site, EP58-2, EP58-2-N, EP116-1, and EP116-1-E.
- Grading at EP22-1-PS and GS-USFS-3.
- Grouting at EP3-3, EP4-3, EP5-2, EP6-1, EP7-1, and EP8-2.
- Gate and barrier installation at EP9-1-N, EP11-3-E, and EP113-5-E.
- Driveway work at EP11-3-E.
- Micropile drilling at EP143-1.
- Conventional drilling at EP9-1 and EP12-3.
- Arroyo toad fencing installed between EP77 and EP79.
- BMP maintenance at/from:
  - EP10-2, EP11-3, EP11-3-N, EP12-3, EP12-3-N, EP13-3, EP14-1, EP15, EP16-1, EP17, EP18, EP19-1, EP20-2, EP21-1, EP22-1, EP22-1-PS-N, EP23-2, EP23-2-PS-N, GS-USFS-3, EP24-1, EP28-3, EP29-2, EP33-1, EP34-1, EP35-1, EP36-1, EP37-2, EP112-3 to EP113-5, EP114-2, EP115-1, EP116-1, EP117-2, EP118-2, EP125 to EP131, and EP139 to EP143-1.

#### BLM Land

- Vegetation clearing at EP73-1, EP74-1, EP75-2, EP75-2-E-A, EP75-2-E-B, EP76-2, and EP99-2.
- Access road construction at/from:
  - EP42-N and EP58-2-N to EP63-E.
- Conventional drilling at EP39-1.
- Form removal at EP96, EP97, EP98-1, and EP99-2.
- Arroyo toad fencing installed between EP65-1 and EP68 and along EP68-E.
- BMP maintenance at/from:
  - EP39-1, EP40-1, EP41, EP42, EP69 to EP76-2, and EP89-1 to EP99-2.

#### Non-Federal Land

- Vegetation clearing at GS-NF-14, GS-NF-16, GS-NF-18, GS-NF-21, GS-NF-22, GS-NF-23, GS-NF-24, GS-NF-25, GS-NF-28, GS-NF-29, EP54 REGEN, EP75-2-E-A, EP77, EP77-E, and EP83 pull sites north and south,.
- Access road construction at:
  - EP11-3-N and EP36-1-E.
- Grading along EP12-3-PS and EP12-3-PS-N.
- Tree trimming at EP119-1.
- Conventional drilling at EP105-2.
- Driveway work at 8A-6 (EP30-2 to EP32-1) and 8E-6 (EP89-1).
- Form removal at EP32-1.
- Arroyo toad fencing installed at/from EP65-1 to EP68, EP66-E, and EP75-1 to EP79.
- BMP installation at:
  - EP83 pull site north and south.
- BMP maintenance at/from:
  - EP11-3-N, EP25-2, EP26-1, EP27-1, EP30-2, EP31-1, EP32-1, EP83 pull site north and south, EP77 to EP88-2, and EP119-2.

- Link 5

- During this reporting period, the PAL Levels were as follows: Tuesday-D, Wednesday-D, Thursday-D, Friday-C, and Saturday-D. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

- No work during this reporting period.

BLM Land

- Micropile cap work at CP65-1.
- BMP installation and maintenance at:
  - CP58-1, CP59, CP60, CP61-1, and CP62A

Non-Federal Land

- Vegetation clearing at CP23 pull site north, CP54-1, GS-NF-10, and CP95-1/CP96-1 pull site.
- Grading at CP23 pull site north, CP49-1 pull site, and CP57.
- Access road construction at CP23-E, CP23-PS-N-A, CP23-PS-N-B, CP24-1-N, CP49-1-PS-N, CP57-E-A, CP57-E-B, and CP57-E-C.
- Tree trimming at/from CP80-2 to CP83 and CP54-1.
- Blasting at CP31-2 and CP49-1-PS-N.
- Micropile drilling at CP43-1, CP45-1, CP47-2, CP47A-1, CP48-2, CP83, CP85-1, and CP86.
- Grouting at CP50-1, CP52, CP54-1, CP59, and CP77.
- Micropile cap work at CP50-1, CP71, CP72-2, CP73-1, CP74-2, and CP75-1.
- Conventional drilling at CP29-1 and CP31-2.
- BMP installation and maintenance at:
  - CP23-E, CP24-1, CP29-1, CP29-1-E-A, CP29-1-E-B, CP31-2, CP31-2-E, CP42-1, CP48-2, CP49-1, CP49-1-PS-N, CP57-E-A, CP57-E-B, CP57-E-C, and CP54-1, CP55, CP56-1, CP57, CP57-E-A, CP57-E-B, CP57-E-C, CP62A, CP63-3, and CP64-2.

Miramar

- Conventional drilling at CP11-1.
- Various foundation work (curing, cage installation, etc.) at CP6 and CP7.
- Concrete pouring at CP7, CP10, and CP13-2.
- Forms removed at CP2, CP3, CP6-1, CP9-1, CP13-2, and CP14.
- BMP installation at CP6.

69kV

- Access road improvements, brushing, and BMP installation at Location 17 and from Locations 21 to 23 on the TL639.

- Access road improvements, brushing, and BMP installation at Locations 1 to 3 on the TL6916.

#### Underground Construction (Link 4)

- Label manhole – V7R, V8L, and V10L.
- Work at the Alpine Creek bore site.
- Raise necking – V7R and V7L.
- Sawcut - V7R, V7L, V6R, V6L, V5R, and V5L.
- Revitalization – Tavern Road to 1800 block and Viejas Creek Bridge.
- Install Caltrans fence.
- Pre-racking/Racking and cleaning Manholes for ABB (and Jointing/Splicing) – V2L, V5R, V6R, V7R, V8R, and V18L.
- Clean/Mark manholes – V8L and V10L.
- Fiber pulling – V1L and V1R to the riser poles.
- Bauer Bridge – Bridge work (backfill forms/compaction).
- Erect scaffolding/ termination – Slay property.
- Remove scaffolding and paving – Loritz property.
- BMPs – Baker tanks.
- Jointing – V2L and V18L.

#### Suncrest Substation Construction (Link 3)

- Crushing class 2 base and select fill material.
- Trenching for conduit and ground grid in the southwest quadrant.
- Laying block for the maintenance shelter.
- Hauling topsoil from the substation pad to the adjacent HMMP property.
- Finish grading north and east of the transformers.
- Vegetation clearing on the southeastern corner of the pad.
- Placing rebar prior to pouring concrete in brow ditch
- Installing insulators in the 500kV yard.
- BMP maintenance and repair along the substation pad.
- Backfilling behind the curb along Bell Bluff Truck Trail.
- Backfilling grounding wire.
- Gravel bag and construction debris cleanup along Bell Bluff Truck Trail.

#### Substation Upgrades

##### Encina:

- ROEL took down old fence from 230 kV yard and maintained BMPs.

##### Imperial Valley:

- Prava worked inside new warehouse installing fans and roll-up doors.
- SDG&E ETRAM crews staged equipment and finished stringing wires into substation.

##### Sycamore:

- SDG&E construction crews worked on building out 69 kV rack in southern portion of substation.
- ROEL construction broke out concrete piers and bolts near the new 230 kV transformer so the bolts

could be reset to correct location.

### Construction Yards

- Sycamore Yard – Weed wash station, water supply, dust suppression, helicopter operations, tower assembly, and staging for BMP, road, and clearing crews.
- Helix Yard – Helicopter operations, water staging, weed wash station, dust suppression, and staging for micropile and TSAP crews.
- El Monte Yard – Dust suppression.
- Alpine Yard – Materials staging, weed wash station, and staging for road, gate, and clearing crews.
- Wilson Yard – Staging materials for Suncrest Substation, helicopter operations, dust suppression, water staging, and staging for micropile crews.
- SWAT Yard – Concrete staging, water staging, helicopter operations, dust suppression, weed wash station, and staging for road and BMP crews.
- Barrett Canyon Yard – Helicopter operations and staging for BMP and clearing crews.
- Kreuzkamp Yard – Helicopter operations, weed wash station, water staging, dust suppression, and staging for road and BMP crews.
- Bartlett-Hauser Yard – Water staging, weed wash station, dust suppression, and staging for BMP crews.
- Thing Valley Yard – Water staging, dust suppression, and staging for tree trimming and driveway crews.
- McCain Valley Yard – No activity.
- Rough Acres Yard – Helicopter operations, materials staging, water staging, dust suppression, weed wash station, and staging for micropile and road crews.
- Jacumba Valley Ranch (JVR) Yard – Helicopter operations, weed wash station, water staging, dust suppression, hub for coordination of activities within PBS areas, and staging for micropile and QC crews.
- AER Yard – Helicopter operations, helicopter pad and fence removal, and dust control.
- Fromm Yard – Helicopter activity, material staging, water staging, and dust suppression.
- S2 Yard – Water staging, helicopter activity, dust suppression, and staging for wire, road, and conventional crews.
- Plaster City Yard – Yard decommissioning.
- Dunaway Yard – Seeding completed.
- Imperial Valley Yard – Seeding completed.

### **Wildlife Reporting**

- Peninsular bighorn sheep (PBS) were reported in Mountain Springs Grade on December 26, 27, and 28, 2011

The following listed or Species of Special Concern were found dead in Project construction limits during this reporting period:

- Silver Legless Lizard (*Anniella pulchra pulchra*) – One (1) silvery legless lizard was found dead at EP12-3

The following listed or Species of Special Concern were relocated during construction activities this reporting period:

- Silvery Legless Lizard (*Anniella pulchra pulchra*) – One (1) silvery legless lizard was relocated from EP12-3

### **Spills/Hazardous Waste**

- No reportable spills occurred during this reporting period.

### **Customer Complaints**

- No customer complaints were received during this reporting period.

### **Non-Compliances**

- CPUC Non Compliance #3 was received on December 29, 2011, for repeated violations of the PBHS Construction Monitoring Plan.

### **Variances and TEWS**

- No new variiances or TEWS were approved during this reporting period.

### **Weather**

- No rain events occurred during this reporting period.
- BMPs were installed or maintained as needed throughout Project areas. In accordance with the Construction General Permit (CGP), daily site BMP inspections, and photos, appropriate BMPs for stormwater and non-stormwater were implemented. In accordance with the CGP, a post-storm inspection was performed as a result of the qualifying rain events. Failures and shortcomings that were identified in the post-storm inspection have been assessed and repairs/design changes to the BMPs will begin within 72 hours of identification.



# **Appendices**

Peninsular Big Horn Sheep Monitoring Report

Flat-Tailed Horned Lizard Monitoring Report

Raven Control Monitoring Report

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
12/31/2011	EP300-EP312	0	Site clearance survey
12/31/2011	EP300-EP312	0	Monitoring construction activities
12/31/2011	EP269-EP281	0	Site clearance survey
12/31/2011	EP269-EP281	0	Monitoring construction activities
12/31/2011	EP269-EP273	0	Site clearance survey
12/31/2011	EP269-EP273	0	Monitoring construction activities
12/31/2011	EP269-EP281	0	Site clearance survey
12/31/2011	EP269-EP281	0	Monitoring construction activities
12/31/2011	EP256-EP312	0	Site clearance survey
12/31/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/31/2011	EP279-EP294	0	Site clearance survey
12/31/2011	EP279-EP294	0	Monitoring construction activities
12/31/2011	EP274-EP278	0	Site clearance survey
12/31/2011	EP274-EP278	0	Monitoring construction activities
12/30/2011	EP300-EP312	0	Site clearance survey
12/30/2011	EP269-EP281	0	Site clearance survey
12/30/2011	EP269-273	0	Site clearance survey
12/30/2011	EP269-273	0	Monitoring construction activities
12/30/2011	EP269-EP281	0	Site clearance survey
12/30/2011	EP269-EP281	0	Monitoring construction activities
12/30/2011	EP269	0	Monitoring construction activities
12/30/2011	EP264-4-EP263B-2	0	Monitoring construction activities
12/30/2011	EP256-EP312	0	Site clearance survey
12/30/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/30/2011	EP279-EP294	0	Site clearance survey
12/30/2011	EP279-EP294	0	Monitoring construction activities
12/30/2011	EP274-EP278	0	Site clearance survey
12/30/2011	EP274-EP278	0	Monitoring construction activities
12/29/2011	EP305 & EP310	0	Monitoring construction activities
12/29/2011	EP300-EP312	0	Site clearance survey
12/29/2011	EP300-EP312	0	Monitoring construction activities
12/29/2011	EP272-EP274	0	Site clearance survey
12/29/2011	EP272-EP274	0	Monitoring construction activities
12/29/2011	EP270-2-EP271-2	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
12/29/2011	EP269-EP273	0	Site clearance survey
12/29/2011	EP269-EP273	0	Monitoring construction activities
12/29/2011	EP269-EP281	0	Site clearance survey
12/29/2011	EP269-EP281	0	Monitoring construction activities
12/29/2011	EP269	0	Monitoring construction activities
12/29/2011	EP262-EP263A	0	Site clearance survey
12/29/2011	EP262-EP263A	0	Monitoring construction activities
12/29/2011	EP261-2	0	Monitoring construction activities
12/29/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/29/2011	EP256-EP312	0	Site clearance survey
12/29/2011	EP279-EP294	0	Site clearance survey
12/29/2011	EP279-EP294	0	Monitoring construction activities
12/29/2011	EP274-EP278	0	Site clearance survey
12/29/2011	EP274-EP278	0	Monitoring construction activities
12/28/2011	EP300-EP312	0	Site clearance survey
12/28/2011	EP300-EP312	0	Monitoring construction activities
12/28/2011	EP290-EP291	0	Monitoring construction activities
12/28/2011	EP274-EP278	0	Site clearance survey
12/28/2011	EP274-EP278	0	Monitoring construction activities
12/28/2011	EP272-EP274	0	Site clearance survey
12/28/2011	EP272-EP274	0	Monitoring construction activities
12/28/2011	EP270-EP271	0	Site clearance survey
12/28/2011	EP270-EP271	0	Monitoring construction activities
12/28/2011	EP270-EP272	1	Site clearance survey
12/28/2011	EP269-EP281	0	Site clearance survey
12/28/2011	EP269-EP281	0	Monitoring construction activities
12/28/2011	EP269	0	Monitoring construction activities
12/28/2011	EP264-4	0	Monitoring construction activities
12/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/28/2011	EP279-EP294	0	Site clearance survey
12/28/2011	EP279-EP294	0	Monitoring construction activities
12/27/2011	EP300-EP312	0	Site clearance survey
12/27/2011	EP300-EP312	0	Monitoring construction activities
12/27/2011	EP274-EP278	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
12/27/2011	EP274-EP278	0	Monitoring construction activities
12/27/2011	EP272-EP274	0	Site clearance survey
12/27/2011	EP272-EP274	0	Monitoring construction activities
12/27/2011	EP269-EP273	1	Site clearance survey
12/27/2011	EP269-EP273	Same as above	Monitoring construction activities
12/27/2011	EP269-EP281	0	Site clearance survey
12/27/2011	EP269-EP281	0	Monitoring construction activities
12/27/2011	EP269	0	Monitoring construction activities
12/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/27/2011	EP279-EP294	0	Site clearance survey
12/27/2011	EP279-EP294	0	Monitoring construction activities
12/26/2011	EP281	0	Monitoring construction activities
12/26/2011	EP269	0	Monitoring construction activities
12/26/2011	EP265-2	5	Monitoring construction activities
12/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/25/2011	EP269-EP281	0	Site clearance survey
12/25/2011	EP256-EP312	0	Site clearance survey
12/24/2011	EP300-EP312	0	Site clearance survey
12/24/2011	EP300-EP312	0	Monitoring construction activities
12/24/2011	EP281, EP281GS & EP290	0	Monitoring construction activities
12/24/2011	EP274-EP278	0	Site clearance survey
12/24/2011	EP274-EP278	0	Monitoring construction activities
12/24/2011	EP274-1 & EP275-1	0	Monitoring construction activities
12/24/2011	EP271	0	Site clearance survey
12/24/2011	EP271	0	Monitoring construction activities
12/24/2011	EP270-EP274	13	Site clearance survey
12/24/2011	EP270-EP274	Same as above	Monitoring construction activities
12/24/2011	EP263A-2	0	Monitoring construction activities
12/23/2011	EP300-EP312	0	Site clearance survey
12/23/2011	EP300-EP312	0	Monitoring construction activities
12/23/2011	EP274-EP278	3	Site clearance survey
12/23/2011	EP274-EP278	Same as above	Monitoring construction activities
12/23/2011	EP272-EP277	0	Site clearance survey
12/23/2011	EP272-EP277	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
12/23/2011	EP270-2 & EP271-2	0	Monitoring construction activities
12/23/2011	EP269-EP273	4	Site clearance survey
12/23/2011	EP269-EP273	Same as above	Monitoring construction activities
12/23/2011	EP269-EP271	0	Site clearance survey
12/23/2011	EP269-EP271	0	Monitoring construction activities
12/23/2011	EP269-EP281	0	Site clearance survey
12/23/2011	EP269-EP281	0	Monitoring construction activities
12/23/2011	EP269	0	Monitoring construction activities
12/22/2011	EP304, EP306, EP307, EP314, EP315 & EP317	0	Monitoring construction activities
12/22/2011	EP300-EP312	0	Site clearance survey
12/22/2011	EP300-EP312	0	Monitoring construction activities
12/22/2011	EP278-1 & EP279-1	0	Monitoring construction activities
12/22/2011	EP274-EP278	5	Site clearance survey-Same group as observed at EP271-EP272
12/22/2011	EP274-EP278	Same as above	Monitoring construction activities
12/22/2011	EP272	0	Site clearance survey
12/22/2011	EP272	0	Monitoring construction activities
12/22/2011	EP271-EP272	6	Site clearance survey
12/22/2011	EP271-EP272	Same as above	Monitoring construction activities
12/22/2011	EP269-EP281	0	Site clearance survey
12/22/2011	EP269-EP281	0	Monitoring construction activities
12/22/2011	EP269	0	Monitoring construction activities
12/22/2011	EP263A-2 & EP263B-2	0	Monitoring construction activities
12/22/2011	EP279-EP294	0	Site clearance survey
12/22/2011	EP279-EP294	0	Monitoring construction activities
12/22/2011	EP300-1, EP301 & EP304	0	Monitoring construction activities
12/21/2011	EP305, EP312 & EP317	0	Monitoring construction activities
12/21/2011	EP300-EP312	0	Site clearance survey
12/21/2011	EP300-EP312	0	Monitoring construction activities
12/21/2011	EP277-1	0	Monitoring construction activities
12/21/2011	EP274-EP278	0	Site clearance survey
12/21/2011	EP274-EP278	0	Monitoring construction activities
12/21/2011	EP269-EP272	0	Site clearance survey
12/21/2011	EP269-EP272	0	Monitoring construction activities
12/21/2011	EP269-EP271	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
12/21/2011	EP269-EP271	0	Monitoring construction activities
12/21/2011	EP269-EP281	0	Site clearance survey
12/21/2011	EP269-EP281	0	Monitoring construction activities
12/21/2011	EP269	0	Monitoring construction activities
12/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/21/2011	EP256-EP312	0	Site clearance survey
12/21/2011	EP256-EP312	0	Monitoring construction activities
12/21/2011	EP279-EP294	0	Site clearance survey
12/21/2011	EP279-EP294	0	Monitoring construction activities
12/20/2011	EP300-EP312	0	Site clearance survey
12/20/2011	EP300-EP312	0	Monitoring construction activities
12/20/2011	EP274-EP278	0	Site clearance survey
12/20/2011	EP274-EP278	0	Monitoring construction activities
12/20/2011	EP269-EP273	0	Site clearance survey
12/20/2011	EP269-EP273	0	Monitoring construction activities
12/20/2011	EP269-EP271	0	Site clearance survey
12/20/2011	EP269-EP271	0	Monitoring construction activities
12/20/2011	EP269-EP281	0	Site clearance survey
12/20/2011	EP269-EP281	0	Monitoring construction activities
12/20/2011	EP269	0	Monitoring construction activities
12/20/2011	EP256-EP281	0	Site clearance survey
12/20/2011	EP256-EP281	0	Monitoring construction activities
12/20/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/20/2011	EP300-EP312	0	Site clearance survey
12/20/2011	EP300-EP312	0	Monitoring construction activities
12/20/2011	EP279-EP294	0	Site clearance survey
12/20/2011	EP279-EP294	0	Monitoring construction activities
12/19/2011	EP300-EP312	0	Site clearance survey
12/19/2011	EP300-EP312	0	Monitoring construction activities
12/19/2011	EP269-EP281	0	Site clearance survey
12/19/2011	EP269-EP281	0	Monitoring construction activities
12/19/2011	EP269-EP273	0	Site clearance survey
12/19/2011	EP269-EP273	0	Monitoring construction activities
12/19/2011	EP269-EP271	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
12/19/2011	EP269	0	Monitoring construction activities
12/19/2011	EP262-4, EP263B-2, EP263A-2-EP265-2	0	Monitoring construction activities
12/19/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/19/2011	EP279-EP294	0	Site clearance survey
12/19/2011	EP279-EP294	0	Monitoring construction activities
12/19/2011	EP274-EP278	0	Site clearance survey
12/19/2011	EP274-EP278	0	Monitoring construction activities
12/18/2011	EP300-EP312	0	Site clearance survey
12/18/2011	EP300-EP312	0	Monitoring construction activities
12/18/2011	EP276-1	0	Monitoring construction activities
12/18/2011	EP274-EP278	1	Site clearance survey
12/18/2011	EP274-EP278	Same as above	Monitoring construction activities
12/18/2011	EP274	0	Site clearance survey
12/18/2011	EP271-2	0	Monitoring construction activities
12/18/2011	EP269-EP281	0	Site clearance survey
12/18/2011	EP269-EP281	0	Monitoring construction activities
12/18/2011	EP269-EP273	0	Site clearance survey
12/18/2011	EP269-EP273	0	Monitoring construction activities
12/18/2011	EP269	0	Monitoring construction activities
12/18/2011	EP264-4	0	Monitoring construction activities
12/18/2011	EP263B-2	0	Monitoring construction activities
12/18/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/18/2011	EP255-EP259	0	Monitoring construction activities
12/18/2011	EP279-EP294	0	Site clearance survey
12/18/2011	EP279-EP294	0	Monitoring construction activities
12/17/2011	EP274-EP278	0	Site clearance survey
12/17/2011	EP274-EP278	0	Monitoring construction activities
12/17/2011	EP269-EP281	0	Site clearance survey
12/17/2011	EP269-EP281	0	Monitoring construction activities
12/17/2011	EP269-EP273	0	Site clearance survey
12/17/2011	EP269-EP273	0	Monitoring construction activities
12/17/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
12/17/2011	EP269	0	Monitoring construction activities
12/17/2011	EP263B-EP267	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
12/17/2011	EP263B-EP267	0	Monitoring construction activities
12/17/2011	EP279-EP294	0	Site clearance survey
12/17/2011	EP279-EP294	0	Monitoring construction activities
12/17/2011	EP274-EP278	0	Site clearance survey
12/17/2011	EP274-EP278	0	Monitoring construction activities
12/16/2011	EP304-EP295	0	Monitoring construction activities
12/16/2011	EP300-EP312	0	Site clearance survey
12/16/2011	EP300-EP312	0	Monitoring construction activities
12/16/2011	EP269-EP281	0	Site clearance survey
12/16/2011	EP269-EP281	0	Monitoring construction activities
12/16/2011	EP269-EP273	0	Site clearance survey
12/16/2011	EP269-EP273	0	Monitoring construction activities
12/16/2011	EP269	0	Monitoring construction activities
12/16/2011	EP261A	0	Monitoring construction activities
12/16/2011	EP263B-EP269	0	Site clearance survey
12/16/2011	EP263B-EP269	0	Monitoring construction activities
12/15/2011	EP303	0	Monitoring construction activities
12/15/2011	EP300-EP312	0	Site clearance survey
12/15/2011	EP300-EP312	0	Monitoring construction activities
12/15/2011	EP269-EP281	0	Site clearance survey
12/15/2011	EP269-EP281	0	Monitoring construction activities
12/15/2011	EP269-EP273	0	Site clearance survey
12/15/2011	EP269-EP273	0	Monitoring construction activities
12/15/2011	EP267-2	0	Monitoring construction activities
12/15/2011	EP263A-2	0	Monitoring construction activities
12/15/2011	EP279-EP294	0	Site clearance survey
12/15/2011	EP279-EP294	0	Monitoring construction activities
12/15/2011	EP274-EP278	0	Site clearance survey
12/15/2011	EP274-EP278	0	Monitoring construction activities
12/15/2011	EP269	0	Monitoring construction activities
12/15/2011	EP263B-EP269	0	Site clearance survey
12/15/2011	EP263B-EP269	0	Monitoring construction activities
12/14/2011	EP302	0	Monitoring construction activities
12/14/2011	EP300-EP312	0	Site clearance survey



**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
12/14/2011	EP300-EP312	0	Monitoring construction activities
12/14/2011	EP277-1, EP271-2 and EP270-2	0	Monitoring construction activities
12/14/2011	EP269-EP281	0	Site clearance survey
12/14/2011	EP269-EP281	0	Monitoring construction activities
12/14/2011	EP269-EP270	0	Site clearance survey
12/14/2011	EP269-EP270	0	Monitoring construction activities
12/14/2011	EP269-EP273	0	Site clearance survey
12/14/2011	EP269-EP273	0	Monitoring construction activities
12/14/2011	EP262-4	0	Monitoring construction activities
12/14/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/14/2011	EP279-EP294	0	Site clearance survey
12/14/2011	EP279-EP294	0	Monitoring construction activities
12/14/2011	EP274-EP278	0	Site clearance survey
12/14/2011	EP274-EP278	0	Monitoring construction activities
12/13/2011	EP300-EP312	0	Site clearance survey
12/13/2011	EP300-EP312	0	Monitoring construction activities
12/13/2011	EP269-EP270	0	Site clearance survey
12/13/2011	EP269-EP270	0	Monitoring construction activities
12/13/2011	EP269-EP273	0	Site clearance survey
12/13/2011	EP269-EP273	0	Monitoring construction activities
12/13/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/13/2011	EP256-EP312	0	Monitoring construction activities
12/13/2011	EP279-EP294	0	Site clearance survey
12/13/2011	EP279-EP294	0	Monitoring construction activities
12/13/2011	EP274-EP278	0	Site clearance survey
12/13/2011	EP274-EP278	0	Monitoring construction activities
12/12/2011	EP306/EP307 Pullsite, EP302	0	Monitoring construction activities
12/12/2011	EP300-EP312	0	Site clearance survey
12/12/2011	EP300-EP312	0	Monitoring construction activities
12/12/2011	EP300, EP304	0	Monitoring construction activities
12/12/2011	EP291, EP301	0	Monitoring construction activities
12/12/2011	EP269-EP270	0	Site clearance survey
12/12/2011	EP269-EP270	0	Monitoring construction activities
12/12/2011	EP269-EP273	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
12/12/2011	EP269-EP273	0	Monitoring construction activities
12/12/2011	EP267-2	0	Monitoring construction activities
12/12/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/12/2011	EP279-EP294	0	Site clearance survey
12/12/2011	EP279-EP294	0	Monitoring construction activities
12/12/2011	EP274-EP278	0	Site clearance survey
12/12/2011	EP274-EP278	0	Monitoring construction activities
12/11/2011	EP291	0	Monitoring construction activities
12/11/2011	EP281, EP280 & EP270-2	0	Monitoring construction activities
12/11/2011	EP273-1 & EP275-1	0	Monitoring construction activities
12/11/2011	EP270-2	0	Monitoring construction activities
12/11/2011	EP269-EP281	0	Site clearance survey
12/11/2011	EP269-EP281	0	Monitoring construction activities
12/11/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
12/11/2011	EP269-EP273	0	Site clearance survey
12/11/2011	EP269-EP273	0	Monitoring construction activities
12/11/2011	EP264-4	0	Monitoring construction activities
12/11/2011	EP263B-EP269	0	Site clearance survey
12/11/2011	EP263A-2 and EP264-4	0	Monitoring construction activities
12/11/2011	EP261A	0	Monitoring construction activities
12/11/2011	EP256-EP263A	0	Site clearance survey
12/11/2011	EP256-EP263A	0	Monitoring construction activities
12/11/2011	EP279-EP294	0	Site clearance survey
12/11/2011	EP279-EP294	0	Monitoring construction activities
12/11/2011	EP274-EP278	0	Site clearance survey
12/11/2011	EP274-EP278	0	Monitoring construction activities
12/10/2011	EP300-EP312	0	Site clearance survey
12/10/2011	EP300-EP312	0	Monitoring construction activities
12/10/2011	EP291, EP313, EP330-1, EP339 & EP363	0	Monitoring construction activities
12/10/2011	EP274-EP278	0	Site clearance survey
12/10/2011	EP274-EP278	0	Monitoring construction activities
12/10/2011	EP269-EP270	0	Site clearance survey
12/10/2011	EP269-EP270	0	Monitoring construction activities
12/10/2011	EP269-1, EP271-2, EP282-3 & EP273-1	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
12/10/2011	EP269-EP281	0	Site clearance survey
12/10/2011	EP269-EP281	0	Monitoring construction activities
12/10/2011	EP269-EP273	0	Site clearance survey
12/10/2011	EP269-EP273	0	Monitoring construction activities
12/10/2011	EP267-2	0	Monitoring construction activities
12/10/2011	EP263B-EP269	0	Site clearance survey
12/10/2011	EP262-4	0	Monitoring construction activities
12/9/2011	EP300-EP312	0	Site clearance survey
12/9/2011	EP300-EP312	0	Monitoring construction activities
12/9/2011	EP274-EP278	0	Site clearance survey
12/9/2011	EP274-EP278	0	Monitoring construction activities
12/9/2011	EP272-3	0	Monitoring construction activities
12/9/2011	EP269-EP281	0	Site clearance survey
12/9/2011	EP269-EP281	0	Monitoring construction activities
12/9/2011	EP269-EP273	0	Site clearance survey
12/9/2011	EP269-EP273	0	Monitoring construction activities
12/9/2011	EP267-2	0	Monitoring construction activities
12/9/2011	EP263B-EP269	0	Site clearance survey
12/9/2011	EP262-4	0	Monitoring construction activities
12/8/2011	EP301	0	Monitoring construction activities
12/8/2011	EP281	0	Monitoring construction activities
12/8/2011	EP272-3	0	Monitoring construction activities
12/8/2011	EP269-EP312	0	Site clearance survey
12/8/2011	EP269-EP273	0	Site clearance survey
12/8/2011	EP267-2	0	Monitoring construction activities
12/8/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/8/2011	EP274-EP278	0	Site clearance survey
12/8/2011	EP274-EP278	0	Monitoring construction activities
12/7/2011	EP301	0	Monitoring construction activities
12/7/2011	EP300-EP312	5	Site clearance survey-Observed outside project area
12/7/2011	EP300-EP312	0	Site clearance survey
12/7/2011	EP300-EP312	0	Monitoring construction activities
12/7/2011	EP274-EP278	0	Site clearance survey
12/7/2011	EP274-EP278	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
12/7/2011	EP269-EP273	0	Site clearance survey
12/7/2011	EP269-EP272	0	Site clearance survey
12/7/2011	EP269-EP281	0	Site clearance survey
12/7/2011	EP269-EP281	0	Monitoring construction activities
12/7/2011	EP259B and EP259-3	0	Monitoring construction activities
12/7/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/6/2011	EP301	0	Monitoring construction activities
12/6/2011	EP300-EP308	0	Monitoring construction activities
12/6/2011	EP300-EP312	0	Site clearance survey
12/6/2011	EP300-EP312	0	Monitoring construction activities
12/6/2011	EP271-2	0	Monitoring construction activities
12/6/2011	EP271-2	0	Monitoring construction activities
12/6/2011	EP269-EP273	0	Site clearance survey
12/6/2011	EP269-EP272	1	Site clearance survey
12/6/2011	EP269-1 to EP255	0	Monitoring construction activities
12/6/2011	EP269-1	0	Monitoring construction activities
12/6/2011	EP269-EP281	0	Site clearance survey
12/6/2011	EP269-EP281	0	Monitoring construction activities
12/6/2011	EP267-2-GS-NF-38	0	Monitoring construction activities
12/6/2011	EP267-2-GS-NF-38	0	Monitoring construction activities
12/6/2011	EP259B	0	Monitoring construction activities
12/6/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/6/2011	EP279-EP294	0	Site clearance survey
12/6/2011	EP279-EP294	0	Monitoring construction activities
12/6/2011	EP274-EP278	1	Site clearance survey-Area remained open to ground crews
12/6/2011	EP274-EP278	Same 1 as noted above	Monitoring construction activities
12/5/2011	EP300-EP312	1	Site clearance survey-Area remained open to ground crews
12/5/2011	EP300-EP312	Same 1 as noted above	Monitoring construction activities
12/5/2011	EP300-EP312	0	Site clearance survey
12/5/2011	EP300-EP312	0	Monitoring construction activities
12/5/2011	EP275-1, EP276-1	0	Monitoring construction activities
12/5/2011	EP274-EP278	0	Site clearance survey
12/5/2011	EP274-EP278	0	Monitoring construction activities
12/5/2011	EP272	1	Site clearance survey-Ram detected in boudary of low-elevation flight boundary

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
12/5/2011	EP269-EP272	Same 1 as noted above	Site clearance survey
12/5/2011	EP269-1	0	Monitoring construction activities
12/5/2011	EP269-EP281	0	Site clearance survey
12/5/2011	EP269-EP281	0	Monitoring construction activities
12/5/2011	EP267-2-GS-NF-38	0	Monitoring construction activities
12/5/2011	EP263B-2, EP263A-2, EP262-4 and EP261A	0	Monitoring construction activities
12/5/2011	EP259B	0	Monitoring construction activities
12/5/2011	EP258-3	0	Monitoring construction activities
12/5/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/5/2011	EP279-EP294	0	Site clearance survey
12/5/2011	EP279-EP294	0	Monitoring construction activities
12/4/2011	EP300-EP312	0	Site clearance survey
12/4/2011	EP300-EP312	0	Monitoring construction activities
12/4/2011	EP294	0	Monitoring construction activities
12/4/2011	EP280, EP275-1	0	Monitoring construction activities
12/4/2011	EP274-EP278	0	Site clearance survey
12/4/2011	EP274-EP278	0	Monitoring construction activities
12/4/2011	EP273-1, EP278-1, EP279-1 and EP280	0	Monitoring construction activities
12/4/2011	EP269-1-E	0	Monitoring construction activities
12/4/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
12/4/2011	EP269-EP281	0	Monitoring construction activities
12/4/2011	EP269-EP281	0	Site clearance survey
12/4/2011	EP256-EP263A	1	Site clearance survey-Area remained open to ground crews
12/4/2011	EP279-EP294	0	Monitoring construction activities
12/4/2011	EP279-EP294	0	Site clearance survey
12/4/2011	EP267-2-GS-NF-38	0	Monitoring construction activities
12/3/2011	EP300-EP312	0	Site clearance survey
12/3/2011	EP300-EP312	0	Monitoring construction activities
12/3/2011	EP278-1, EP279-1 & EP280-2	0	Monitoring construction activities
12/3/2011	EP274-EP278	0	Site clearance survey
12/3/2011	EP274-EP278	0	Monitoring construction activities
12/3/2011	EP269-EP270	0	Site clearance survey
12/3/2011	EP269-EP270	0	Monitoring construction activities
12/3/2011	EP269-EP281	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
12/3/2011	EP269-EP281	0	Monitoring construction activities
12/3/2011	EP263B-EP269	0	Site clearance survey
12/3/2011	EP263B-EP269	0	Monitoring construction activities
12/3/2011	EP257	0	Monitoring construction activities
12/3/2011	EP256-EP263A	2	Site clearance survey
12/3/2011	EP256-EP263A	Same 2 listed above	Monitoring construction activities
12/3/2011	EP279-EP294	0	Site clearance survey
12/3/2011	EP279-EP294	0	Monitoring construction activities
12/2/2011	EP300-EP312	0	Site clearance survey
12/2/2011	EP300-EP312	0	Monitoring construction activities
12/2/2011	EP300-EP312	0	Site clearance survey
12/2/2011	EP300-EP312	0	Monitoring construction activities
12/2/2011	EP281-GS-BLM-3	0	Monitoring construction activities
12/2/2011	EP280-EP281	0	Monitoring construction activities
12/2/2011	EP274-EP278	0	Site clearance survey
12/2/2011	EP274-EP278	0	Monitoring construction activities
12/2/2011	EP269-EP273	0	Site clearance survey
12/2/2011	EP269-EP281	0	Site clearance survey
12/2/2011	EP269-EP281	0	Monitoring construction activities
12/2/2011	EP263B-EP269	0	Site clearance survey
12/2/2011	EP263B-EP269	0	Monitoring construction activities
12/2/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/2/2011	EP279-EP294	0	Site clearance survey
12/2/2011	EP279-EP294	0	Monitoring construction activities
12/1/2011	EP300-EP312	0	Site clearance survey
12/1/2011	EP279-EP294; EP273-EP276	0	Site clearance survey
12/1/2011	EP279-EP294; EP273-EP276	0	Monitoring construction activities
12/1/2011	EP274-1, EP275-1	0	Monitoring construction activities
12/1/2011	EP274-EP278	0	Site clearance survey
12/1/2011	EP274-EP278	0	Monitoring construction activities
12/1/2011	EP269-EP273	0	Site clearance survey
12/1/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/30/2011	EP300-EP312	0	Site clearance survey
11/30/2011	EP300-EP312	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
11/30/2011	EP300-EP312	0	Site clearance survey
11/30/2011	EP274-EP278	0	Site clearance survey
11/30/2011	EP274-EP278	0	Monitoring construction activities
11/30/2011	EP273-1	0	Monitoring construction activities
11/30/2011	EP269-EP281	0	Site clearance survey
11/30/2011	EP269-EP281	0	Monitoring construction activities
11/30/2011	EP269-EP281	0	Site clearance survey
11/30/2011	EP269-EP281	0	Monitoring construction activities
11/30/2011	EP269-EP273	0	Site clearance survey
11/30/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/30/2011	EP279-EP294	0	Site clearance survey
11/30/2011	EP279-EP294	0	Monitoring construction activities
11/29/2011	EP300-EP312	0	Site clearance survey
11/29/2011	EP300-EP312	0	Monitoring construction activities
11/29/2011	EP300-EP312	0	Site clearance survey
11/29/2011	EP300-EP312	0	Monitoring construction activities
11/29/2011	EP274-EP278	0	Site clearance survey
11/29/2011	EP274-EP278	0	Monitoring construction activities
11/29/2011	EP273-1	0	Monitoring construction activities
11/29/2011	EP269-EP281	0	Site clearance survey
11/29/2011	EP269-EP281	0	Monitoring construction activities
11/29/2011	EP269-EP281	0	Site clearance survey
11/29/2011	EP269-EP281	0	Monitoring construction activities
11/29/2011	EP269-EP273	0	Site clearance survey
11/29/2011	EP269-EP281	0	Site clearance survey
11/29/2011	EP269-EP281	0	Monitoring construction activities
11/29/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/29/2011	EP279-EP294	0	Site clearance survey
11/29/2011	EP279-EP294	0	Monitoring construction activities
11/28/2011	EP300-EP312	0	Site clearance survey
11/28/2011	EP300-EP312	0	Monitoring construction activities
11/28/2011	EP274-EP278	0	Site clearance survey
11/28/2011	EP274-EP278	0	Monitoring construction activities
11/28/2011	EP273-1	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
11/28/2011	EP269-EP281	0	Site clearance survey
11/28/2011	EP269-EP281	0	Monitoring construction activities
11/28/2011	EP269-EP273	0	Site clearance survey
11/28/2011	EP269-EP273	0	Monitoring construction activities
11/28/2011	EP269-EP270	0	Site clearance survey
11/28/2011	EP269-EP281	0	Site clearance survey
11/28/2011	EP269-EP281	0	Monitoring construction activities
11/28/2011	EP263B-EP267	0	Site clearance survey
11/28/2011	EP263B-EP267	0	Monitoring construction activities
11/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/28/2011	EP279-EP294	0	Site clearance survey
11/28/2011	EP279-EP294	0	Monitoring construction activities
11/27/2011	EP300-EP312	0	Site clearance survey
11/27/2011	EP300-EP312	0	Monitoring construction activities
11/27/2011	EP279-1 & EP280-2	0	Monitoring construction activities
11/27/2011	EP274-EP278	0	Site clearance survey
11/27/2011	EP274-EP278	0	Monitoring construction activities
11/27/2011	EP269-EP281	0	Site clearance survey
11/27/2011	EP269-EP281	0	Monitoring construction activities
11/27/2011	EP269-EP281	0	Site clearance survey
11/27/2011	EP269-EP281	0	Monitoring construction activities
11/27/2011	EP269-EP274	3	Site clearance survey
11/27/2011	EP269-EP274	Same 3 as noted above	Monitoring construction activities
11/27/2011	EP269-EP270	0	Site clearance survey
11/27/2011	EP269-EP281	0	Site clearance survey
11/27/2011	EP269-EP281	0	Monitoring construction activities
11/27/2011	EP263B-EP269	0	Site clearance survey
11/27/2011	EP263B-EP269	0	Monitoring construction activities
11/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/27/2011	EP279-EP294	0	Site clearance survey
11/27/2011	EP279-EP294	0	Monitoring construction activities
11/26/2011	EP300-EP312	0	Site clearance survey
11/26/2011	EP300-EP312	0	Monitoring construction activities
11/26/2011	EP274-EP278	0	Site clearance survey



**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
11/26/2011	EP274-EP278	0	Monitoring construction activities
11/26/2011	EP269-EP271	11	Site clearance survey - Six PBS sited approaching EP270 @ 11:30am. At 5:00pm 5 PBS were sited near EP270
11/26/2011	EP269-EP271	Same 11 as noted above	Monitoring construction activities
11/26/2011	EP269-EP273	Same 11 as noted above	Site clearance survey
11/26/2011	EP269-EP273	Same 11 as noted above	Monitoring construction activities
11/26/2011	EP270	Same 11 as noted above	Site clearance survey
11/26/2011	EP269-EP281	0	Site clearance survey
11/26/2011	EP269-EP281	0	Monitoring construction activities
11/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/26/2011	EP279-EP294	0	Site clearance survey
11/25/2011	EP274-EP278	0	Site clearance survey
11/25/2011	EP274-EP278	0	Monitoring construction activities
11/25/2011	EP272	0	Site clearance survey
11/25/2011	EP269-EP273	1	Site clearance survey - 1 Ram was sighted near EP272 in am
11/25/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/25/2011	EP279-EP294	0	Monitoring construction activities
11/24/2011	EP269-EP273	0	Site clearance survey
11/24/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/24/2011	EP279-EP294	0	Site clearance survey
11/23/2011	EP300-EP312, EP269-EP281	0	Site clearance survey
11/23/2011	EP300-EP312, EP269-EP281	0	Monitoring construction activities
11/23/2011	EP274-EP278	0	Site clearance survey
11/23/2011	EP274-EP278	0	Monitoring construction activities
11/23/2011	EP270-2	0	Monitoring construction activities
11/23/2011	EP269-EP273	0	Site clearance survey
11/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/22/2011	EP277-1	0	Monitoring construction activities
11/22/2011	EP274-EP278	0	Site clearance survey
11/22/2011	EP269-EP281	0	Site clearance survey
11/22/2011	EP269-EP273	0	Site clearance survey
11/22/2011	EP269-EP270	0	Site clearance survey
11/22/2011	EP269-EP270	0	Monitoring construction activities
11/22/2011	EP269-EP281	0	Site clearance survey
11/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
11/22/2011	EP279-EP294	0	Site clearance survey
11/22/2011	EP279-EP294	0	Monitoring construction activities
11/21/2011	EP269-EP281	1	Site clearance survey
11/21/2011	EP300-EP312	0	Site clearance survey
11/21/2011	EP300-EP312	0	Monitoring construction activities
11/21/2011	EP300-EP312	0	Site clearance survey
11/21/2011	EP300-EP312	0	Monitoring construction activities
11/21/2011	EP281	0	Monitoring construction activities
11/21/2011	EP276-1-EP270-2	0	Monitoring construction activities
11/21/2011	EP274-EP278	0	Site clearance survey
11/21/2011	EP274-EP278	0	Monitoring construction activities
11/21/2011	EP272	1	Site clearacne surve - 6:45am 1 ram sighted near EP272
11/21/2011	EP269-EP281	0	Site clearance survey
11/21/2011	EP269-EP281	0	Monitoring construction activities
11/21/2011	EP265-2-EP281	0	Monitoring construction activities
11/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/21/2011	EP279-EP294	0	Site clearance survey
11/21/2011	EP279-EP294	0	Monitoring construction activities
11/20/2011	EP300-EP312	0	Site clearance survey
11/20/2011	EP300-EP312	0	Site clearance survey
11/20/2011	EP300-EP312	0	Monitoring construction activities
11/20/2011	EP277-1 and EP272-3	0	Monitoring construction activities
11/20/2011	EP274-EP278	0	Site clearance survey
11/20/2011	EP274-EP278	0	Monitoring construction activities
11/20/2011	EP271	0	Site clearance survey
11/20/2011	EP271	0	Monitoring construction activities
11/20/2011	EP269-EP281	0	Site clearance survey
11/20/2011	EP269-EP281	0	Monitoring construction activities
11/20/2011	EP256-EP263A	0	Site clearance survey
11/20/2011	EP256-EP263A	0	Monitoring construction activities
11/19/2011	EP300-EP312	0	Site clearance survey
11/19/2011	EP300-EP312	0	Monitoring construction activities
11/19/2011	EP300-EP312	0	Site clearance survey
11/19/2011	EP300-EP312	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
11/19/2011	EP281	0	Monitoring construction activities
11/19/2011	EP277-1	0	Monitoring construction activities
11/19/2011	EP274-EP278	0	Site clearance survey
11/19/2011	EP274-EP278	0	Monitoring construction activities
11/19/2011	EP269-EP281	0	Site clearance survey
11/19/2011	EP269-EP281	0	Monitoring construction activities
11/19/2011	EP256-EP263A	0	Site clearance survey
11/19/2011	EP256-EP263A	0	Monitoring construction activities
11/18/2011	EP300-EP312	0	Site clearance survey
11/18/2011	EP300-EP312	0	Monitoring construction activities
11/18/2011	EP281-GS-BLM-3	0	Monitoring construction activities
11/18/2011	EP276-1	0	Monitoring construction activities
11/18/2011	EP274-EP278	0	Site clearance survey
11/18/2011	EP274-EP278	0	Monitoring construction activities
11/18/2011	EP272	16	Site clearance survey-PBS were observed within Devil's Cyn 2 west of EP272 @ ~8:00am. At that time the flight corridor was closed to low-elevation flights from EP271-EP273
11/18/2011	EP272	Same 16 PBS as noted above	Monitoring construction activities
11/18/2011	EP269-EP281	0	Site clearance survey
11/18/2011	EP269-EP281	0	Monitoring construction activities
11/18/2011	EP256-EP263A	0	Site clearance survey
11/18/2011	EP256-EP263A	0	Monitoring construction activities
11/17/2011	EP281-GS-BLM-3 & EP290-GS-NF-40	0	Monitoring construction activities
11/17/2011	EP277-1	0	Monitoring construction activities
11/17/2011	EP271-EP274	0	Site clearance survey
11/17/2011	EP300-EP312	0	Site clearance survey
11/17/2011	EP300-EP312	0	Monitoring construction activities
11/16/2011	EP300-EP312	0	Site clearance survey
11/16/2011	EP300-EP312	0	Monitoring construction activities
11/16/2011	EP276-1	0	Monitoring construction activities
11/16/2011	EP272	13	Site clearance survey-PBS were observed ~300 feet west of EP272 at ~7:00am. At that time, low-elevation flights were closed from EP271-EP274
11/16/2011	EP272	Same 13 PBS as noted above	Monitoring construction activities
11/16/2011	EP269-EP281	0	Site clearance survey
11/16/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/16/2011	EP274-EP278	0	Site clearance survey
11/16/2011	EP274-EP278	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
11/16/2011	EP269-EP281	0	Site clearance survey
11/16/2011	EP269-EP281	0	Monitoring construction activities
11/15/2011	EP269-EP273	0	Site clearance survey
11/15/2011	EP269-EP281	0	Site clearance survey
11/15/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/15/2011	EP274-EP278	0	Site clearance survey
11/15/2011	EP274-EP278	0	Monitoring construction activities
11/15/2011	AER and Fromm CY's	0	Monitoring construction activities
11/14/2011	EP306-EP312	0	Site clearance survey
11/14/2011	EP269-EP273	0	Site clearance survey
11/14/2011	EP263A-2, EP263B-2	0	Monitoring construction activities
11/14/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/14/2011	EP274-EP278	0	Site clearance survey
11/14/2011	EP274-EP278	0	Monitoring construction activities
11/13/2011	EP306-EP312	0	Site clearance survey
11/13/2011	EP300-EP312	0	Site clearance survey
11/13/2011	EP300-EP312	0	Monitoring construction activities
11/13/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/13/2011	EP274-EP278	0	Site clearance survey
11/13/2011	EP274-EP278	0	Monitoring construction activities
11/13/2011	EP269-EP281	0	Site clearance survey
11/13/2011	EP269-EP281	0	Monitoring construction activities
11/12/2011	EP300-EP312	0	Site clearance survey
11/12/2011	EP300-EP312	0	Monitoring construction activities
11/12/2011	EP269-EP281	0	Site clearance survey
11/12/2011	EP269-EP281	0	Monitoring construction activities
11/12/2011	EP263B-2	0	Monitoring construction activities
11/12/2011	EP274-EP278	0	Site clearance survey
11/12/2011	EP274-EP278	0	Monitoring construction activities
11/12/2011	EP269-EP281	0	Site clearance survey
11/12/2011	EP269-EP281	0	Monitoring construction activities
11/11/2011	EP306-EP312	0	Site clearance survey
11/11/2011	EP300-EP312	0	Monitoring construction activities
11/11/2011	EP269-EP281	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
11/11/2011	EP269-EP281	0	Monitoring construction activities
11/11/2011	EP269-EP273	0	Site clearance survey
11/11/2011	EP269-EP270	0	Site clearance survey
11/11/2011	EP269-EP270	0	Monitoring construction activities
11/11/2011	EP263B-EP267	0	Site clearance survey
11/11/2011	EP263B-EP267	0	Monitoring construction activities
11/11/2011	EP274-EP278	0	Site clearance survey
11/11/2011	EP274-EP278	0	Monitoring construction activities
11/11/2011	EP269-EP281	0	Site clearance survey
11/11/2011	EP269-EP281	0	Monitoring construction activities
11/10/2011	EP306-EP312	0	Site clearance survey
11/10/2011	EP269-EP273	0	Site clearance survey
11/10/2011	EP269-EP281	0	Site clearance survey
11/10/2011	EP269-EP281	0	Monitoring construction activities
11/10/2011	EP269-EP270	0	Site clearance survey
11/10/2011	EP269-EP270	0	Monitoring construction activities
11/10/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/10/2011	EP274-EP278	0	Site clearance survey
11/10/2011	EP274-EP278	0	Monitoring construction activities
11/9/2011	Fromm CY	0	Monitoring construction activities
11/9/2011	EP313/EP314 Pullsite	0	Monitoring construction activities
11/9/2011	EP306-EP312	0	Site clearance survey
11/9/2011	EP306	0	Monitoring construction activities
11/9/2011	EP269-EP273	0	Site clearance survey
11/9/2011	EP269-EP281	0	Site clearance survey
11/9/2011	EP269-EP281	0	Monitoring construction activities
11/9/2011	EP265-2	0	Site clearance survey
11/9/2011	EP265-2	0	Monitoring construction activities
11/9/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/9/2011	EP274-EP278	0	Site clearance survey
11/9/2011	EP274-EP278	0	Monitoring construction activities
11/9/2011	EP263B-EP267, EP269-EP281	0	Site clearance survey
11/9/2011	EP263B-EP267, EP269-EP281	0	Monitoring construction activities
11/8/2011	EP306-EP312	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
11/8/2011	EP300-EP312	0	Site clearance survey
11/8/2011	EP300-EP312	0	Monitoring construction activities
11/8/2011	EP280	0	Monitoring construction activities
11/8/2011	EP272-EP275	0	Site clearance survey
11/8/2011	EP272-EP275	5	Monitoring construction activities
11/8/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/8/2011	EP279-EP294	0	Site clearance survey
11/8/2011	EP279-EP294	0	Monitoring construction activities
11/8/2011	EP274-EP278	0	Site clearance survey
11/8/2011	EP274-EP278	0	Monitoring construction activities
11/8/2011	EP269-EP281	0	Site clearance survey
11/8/2011	EP269-EP281	0	Monitoring construction activities
11/8/2011	EP263B-EP267, EP269-EP281	0	Site clearance survey
11/8/2011	EP263B-EP267, EP269-EP281	0	Monitoring construction activities
11/8/2011	Devils Cyn Bridge	5	Monitoring construction activities
11/7/2011	EP307-EP308	0	Monitoring construction activities
11/7/2011	EP300-EP312	0	Site clearance survey
11/7/2011	EP300-EP312	0	Monitoring construction activities
11/7/2011	EP280	0	Monitoring construction activities
11/7/2011	EP271-EP274	3	Site clearance survey
11/7/2011	EP271-EP274	0	Site clearance survey
11/7/2011	EP271-EP274	5	Site clearance survey
11/7/2011	EP271-EP274	0	Monitoring construction activities
11/7/2011	EP269-EP271	0	Site clearance survey
11/7/2011	EP269-EP271	0	Monitoring construction activities
11/7/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/7/2011	EP278-EP281	0	Site clearance survey
11/7/2011	EP274-EP278	0	Site clearance survey
11/7/2011	EP274-EP278	0	Monitoring construction activities
11/7/2011	EP269-EP281	0	Site clearance survey
11/7/2011	EP269-EP281	0	Monitoring construction activities
11/7/2011	EP263B-EP267	0	Site clearance survey
11/7/2011	EP263B-EP267	0	Monitoring construction activities
11/6/2011	EP308-EP310	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
11/6/2011	EP303-2, EP302-1	0	Monitoring construction activities
11/6/2011	EP300-EP312	0	Site clearance survey
11/6/2011	EP300-EP312	0	Monitoring construction activities
11/6/2011	EP300-EP312	0	Site clearance survey
11/6/2011	EP300-EP312	0	Monitoring construction activities
11/6/2011	EP290-EP312, EP269-EP281	0	Site clearance survey
11/6/2011	EP290-EP312, EP269-EP281	0	Monitoring construction activities
11/6/2011	EP279-1	0	Monitoring construction activities
11/6/2011	EP269-EP281	0	Site clearance survey
11/6/2011	EP269-EP281	0	Monitoring construction activities
11/6/2011	EP274-EP278	0	Monitoring construction activities
11/6/2011	EP274-EP278	0	Site clearance survey
11/6/2011	EP269-EP281	0	Monitoring construction activities
11/6/2011	EP269-EP281	0	site clearance survey
11/5/2011	EP300-EP312	0	Site clearance survey
11/5/2011	EP300-EP312	0	Monitoring construction activities
11/5/2011	EP271-2, EP272-3, EP276-1 & EP281	0	Monitoring construction activities
11/5/2011	EP269-EP273	0	Site clearance survey
11/5/2011	EP265-2	0	Monitoring construction activities
11/5/2011	EP256-EP263A	0	Site clearance survey
11/5/2011	EP279-EP294	0	Site clearance survey
11/5/2011	EP279-EP294	0	Monitoring construction activities
11/5/2011	EP277-1	0	Monitoring construction activities
11/5/2011	EP263B-EP267	0	Site clearance survey
11/5/2011	EP263B-EP267	0	Monitoring construction activities
11/4/2011	S2 CY	0	Monitoring construction activities
11/4/2011	EP311, EP310	0	Monitoring construction activities
11/4/2011	EP307	0	Monitoring construction activities
11/4/2011	EP306/EP307 Pullsite	0	Monitoring construction activities
11/4/2011	EP300-EP312	0	Site clearance survey
11/4/2011	EP300-EP312	0	Monitoring construction activities
11/4/2011	EP269-EP273	0	Site clearance survey
11/4/2011	EP269-EP271	0	Site clearance survey
11/4/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
11/4/2011	EP279-EP294	0	Site clearance survey
11/4/2011	EP279-EP294	0	Monitoring construction activities
11/4/2011	EP274-EP278	0	Site clearance survey
11/4/2011	EP274-EP278	0	Monitoring construction activities
11/4/2011	EP263B-EP267	0	Site clearance survey
11/4/2011	EP263B-EP267	0	Monitoring construction activities
11/3/2011	EP311	0	Monitoring construction activities
11/3/2011	EP307	0	Monitoring construction activities
11/3/2011	EP280	0	Monitoring construction activities
11/3/2011	EP279-1	0	Monitoring construction activities
11/3/2011	EP278-1, EP279-1, EP280-1	0	Monitoring construction activities
11/3/2011	EP271-2	0	Monitoring construction activities
11/3/2011	EP269-EP273	0	Site clearance survey
11/3/2011	EP265-2	0	Monitoring construction activities
11/3/2011	EP263B-EP267; EP279-EP312	0	Site clearance survey
11/3/2011	EP261A, EP259-3	0	Monitoring construction activities
11/3/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/3/2011	EP279-EP294	0	Site clearance survey
11/3/2011	EP279-EP294	0	Monitoring construction activities
11/3/2011	EP274-EP278	0	Site clearance survey
11/3/2011	EP274-EP278	0	Monitoring construction activities
11/2/2011	EP269-EP273	0	Site clearance survey
11/2/2011	EP269-EP281	0	Site clearance survey
11/2/2011	EP269-EP281	0	Monitoring construction activities
11/2/2011	EP263B-EP267; EP279-EP312	0	Site clearance survey
11/2/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/2/2011	EP300-EP312; EP274-EP278	0	Site clearance survey
11/2/2011	EP300-EP312; EP274-EP278	0	Monitoring construction activities
11/1/2011	Suckle Property	0	Monitoring construction activities
11/1/2011	EP310 & EP311	0	Monitoring construction activities
11/1/2011	EP300-EP312	0	Site clearance survey
11/1/2011	EP300-EP312	0	Monitoring construction activities
11/1/2011	EP279-EP312	0	Site clearance survey
11/1/2011	EP277-1, EP276-1, EP261A, EP259B	0	Monitoring construction activities



**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
11/1/2011	EP275-1	0	Monitoring construction activities
11/1/2011	EP269-EP273	0	Site clearance survey
11/1/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/1/2011	EP274-EP278	0	Site clearance survey
11/1/2011	EP274-EP278	0	Monitoring construction activities
11/1/2011	EP263B, EP267	0	Site clearance survey
11/1/2011	Devil's Canyon Bridge	0	Site clearance survey
11/1/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/31/2011	EP279-EP294	0	Site clearance survey
10/31/2011	EP279-EP294	0	Monitoring construction activities
10/31/2011	EP269-EP281	0	Site clearance survey
10/31/2011	EP269-EP281	0	Monitoring construction activities
10/31/2011	EP269-EP273	0	Site clearance survey
10/31/2011	EP269-EP281	0	Site clearance survey
10/31/2011	EP263A-2, EP266-2	0	Monitoring construction activities
10/31/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/31/2011	EP254-3	0	Monitoring construction activities
10/31/2011	EP305, EP310-1	0	Monitoring construction activities
10/31/2011	EP300-EP312	0	Site clearance survey
10/31/2011	EP300-EP312	0	Monitoring construction activities
10/31/2011	EP274-EP278	0	Site clearance survey
10/31/2011	EP263B-EP267	0	Site clearance survey
10/31/2011	Devil's Canyon Bridge	0	Site clearance survey
10/31/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/31/2011	EP262-4, EP263B-2, EP265-2, EP266-2, EP267-1	0	Monitoring construction activities
10/30/2011	EP300-EP306	0	Site clearance survey
10/30/2011	EP300-EP306	0	Monitoring construction activities
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Monitoring construction activities
10/30/2011	EP269-EP273	0	Site clearance survey
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
10/30/2011	EP269-EP270	0	Site clearance survey
10/30/2011	EP267-2 & EP266-2	0	Monitoring construction activities
10/30/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/30/2011	EP279-EP294	0	Site clearance survey
10/30/2011	EP279-EP294	0	Monitoring construction activities
10/30/2011	EP274-EP278	0	Site clearance survey
10/30/2011	EP274-EP278	0	Monitoring construction activities
10/30/2011	EP263B-EP267	0	Site clearance survey
10/30/2011	Devil's Canyon Bridge	0	Site clearance survey
10/30/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/29/2011	EP300-EP306	0	Site clearance survey
10/29/2011	EP300-EP306	0	Monitoring construction activities
10/29/2011	EP274-EP278	0	Site clearance survey
10/29/2011	EP274-EP278	0	Monitoring construction activities
10/29/2011	EP269-EP273	0	Site clearance survey
10/29/2011	EP269-1	0	Monitoring construction activities
10/29/2011	EP269-EP281	0	Site clearance survey
10/29/2011	EP269-EP281	0	Monitoring construction activities
10/29/2011	EP269-EP281	0	Site clearance survey
10/29/2011	EP269-EP281	0	Monitoring construction activities
10/29/2011	EP269-EP270	0	Site clearance survey
10/29/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/29/2011	EP279-EP294	0	Site clearance survey
10/29/2011	EP279-EP294	0	Monitoring construction activities
10/29/2011	EP263B-EP267	0	Site clearance survey
10/29/2011	Devil's Cyn Bridge (w/in I-8 Island)	1	Morning perimeter survey 7:37 am
10/28/2011	EP300-EP306	0	Site clearance survey
10/28/2011	EP300-EP306	0	Monitoring construction activities
10/28/2011	EP269-EP281	0	Site clearance survey
10/28/2011	EP269-EP281	0	Monitoring construction activities
10/28/2011	EP269-EP273	0	Site clearance survey
10/28/2011	EP269-1	0	Monitoring construction activities
10/28/2011	EP269-EP281	0	Site clearance survey
10/28/2011	EP269-EP281	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
10/28/2011	EP269-EP270	0	Site clearance survey
10/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/28/2011	EP310	0	Monitoring construction activities
10/28/2011	EP279-EP294	0	Site clearance survey
10/28/2011	EP279-EP294	0	Monitoring construction activities
10/28/2011	EP274-EP278	0	Site clearance survey
10/28/2011	EP274-EP278	0	Monitoring construction activities
10/28/2011	EP263B-EP267	0	Site clearance survey
10/28/2011	AER and FROMM CY	0	Monitoring construction activities
10/27/2011	EP273-1 & EP276-1	0	Monitoring construction activities
10/27/2011	EP271-EP272	2	Site clearance survey 7:40 am
10/27/2011	EP271-EP272	0	Monitoring construction activities
10/27/2011	EP269-EP281; EP300-EP306	0	Site clearance survey
10/27/2011	EP269-EP281; EP300-EP306	0	Monitoring construction activities
10/27/2011	EP256-EP263A-2, AER CY	0	Site clearance survey
10/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/27/2011	EP279-EP294	0	Site clearance survey
10/27/2011	EP279-EP294	0	Monitoring construction activities
10/27/2011	EP274-EP278	0	Site clearance survey
10/27/2011	EP274-EP278	0	Monitoring construction activities
10/27/2011	EP269-EP271	0	Monitoring construction activities
10/27/2011	EP263B-EP267	0	Site clearance survey
10/27/2011	AER and FROMM CY	0	Monitoring construction activities
10/26/2011	EP311-1, EP312, EP310	0	Monitoring construction activities
10/26/2011	EP300-EP312	0	Site clearance survey
10/26/2011	EP300-EP312	0	Monitoring construction activities
10/26/2011	EP272-EP273	2	Site clearance survey 10:00 am
10/26/2011	EP272-EP273	0	Monitoring construction activities
10/26/2011	EP269-EP281; EP300-EP306	0	Site clearance survey
10/26/2011	EP269-EP281; EP300-EP306	0	Monitoring construction activities
10/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/26/2011	EP279-EP294	0	Site clearance survey
10/26/2011	EP279-EP294	0	Monitoring construction activities
10/26/2011	EP274-EP278	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
10/26/2011	EP274-EP278	0	Monitoring construction activities
10/26/2011	EP263B-EP267	0	Site clearance survey
10/25/2011	EP363-EP341, EP299 & EP300	0	Monitoring construction activities
10/25/2011	EP313-EP324	0	Monitoring construction activities
10/25/2011	EP310	0	Monitoring construction activities
10/25/2011	EP300-EP312	0	Site clearance survey
10/25/2011	EP300-EP312	0	Monitoring construction activities
10/25/2011	EP290	0	Monitoring construction activities
10/25/2011	EP269-EP273	0	Site clearance survey
10/25/2011	EP269-EP281; EP300-EP306	0	Site clearance survey
10/25/2011	EP269-EP281; EP300-EP306	0	Monitoring construction activities
10/25/2011	EP311	0	Monitoring construction activities
10/25/2011	EP279-EP294	0	Site clearance survey
10/25/2011	EP263B-EP267	0	Site clearance survey
10/24/2011	EP313-EP322	0	Monitoring construction activities
10/24/2011	EP305, EP306, EP312	0	Monitoring construction activities
10/24/2011	EP300-EP306	0	Site clearance survey
10/24/2011	EP300-EP306	0	Monitoring construction activities
10/24/2011	EP297-EP319	0	Monitoring construction activities
10/24/2011	EP269-EP273	0	Site clearance survey
10/24/2011	EP269-EP273	0	Monitoring construction activities
10/24/2011	EP269-EP281	0	Site clearance survey
10/24/2011	EP269-EP281	0	Monitoring construction activities
10/24/2011	EP279-EP294	0	Site clearance survey
10/24/2011	EP279-EP294	0	Monitoring construction activities
10/24/2011	EP274-EP278	0	Site clearance survey
10/24/2011	EP274-EP278	0	Monitoring construction activities
10/24/2011	EP263B-EP267	0	Site clearance survey
10/23/2011	EP300-EP312	0	Site clearance survey
10/23/2011	EP300-EP312	0	Monitoring construction activities
10/23/2011	EP269-EP273	0	Site clearance survey
10/23/2011	EP269-EP273	0	Monitoring construction activities
10/23/2011	EP269-EP281	0	Site clearance survey
10/23/2011	EP269-EP281	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
10/23/2011	EP269-EP270	0	Site clearance survey
10/23/2011	EP263B-EP267	0	Site clearance survey
10/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/23/2011	EP300-EP312	0	Site clearance survey
10/23/2011	EP300-EP312	0	Monitoring construction activities
10/23/2011	EP274-EP278	0	Site clearance survey
10/23/2011	EP274-EP278	0	Monitoring construction activities
10/23/2011	EP269-EP273	0	Site clearance survey
10/23/2011	EP269-EP273	0	Monitoring construction activities
10/22/2011	EP300-EP306	0	Site clearance survey
10/22/2011	EP300-EP306	0	Monitoring construction activity
10/22/2011	EP269-EP281	0	Site clearance survey
10/22/2011	EP269-EP281	0	Monitoring construction activity
10/22/2011	EP269-EP281	0	Site clearance survey
10/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/22/2011	EP274-EP278	0	Site clearance survey
10/22/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP306-EP312	0	Site clearance survey
10/21/2011	EP306-EP312	0	Monitoring construction activity
10/21/2011	EP274-EP278	0	Site clearance survey
10/21/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP269-EP281	0	Site clearance survey
10/21/2011	EP269-EP281	0	Site clearance survey
10/21/2011	EP269-EP281	0	Monitoring construction activity
10/21/2011	EP269-EP270	0	Site clearance survey
10/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/21/2011	EP274-EP278	0	Site clearance survey
10/21/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP269-EP273	0	Site clearance survey
10/21/2011	EP269-EP273	0	Monitoring construction activity
10/20/2011	EP269-EP281	0	Site clearance survey
10/20/2011	EP269	0	Site clearance survey
10/20/2011	EP269	0	Monitoring construction activity
10/20/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
10/20/2011	EP274-EP278	0	Site clearance survey
10/20/2011	EP274-EP278	0	Monitoring construction activity
10/20/2011	EP269-EP273	0	Site clearance survey
10/20/2011	EP269-EP273	0	Monitoring construction activity
10/20/2011	EP263B-EP267	0	Site clearance survey
10/20/2011	EP300-EP312	0	Site clearance survey
10/20/2011	EP300-EP312	0	Monitoring construction activity
10/19/2011	EP290-EP312	0	Site clearance survey
10/19/2011	EP290-EP312	0	Monitoring construction activity
10/19/2011	EP269-EP281	0	Site clearance survey
10/19/2011	EP300-EP312	0	Site clearance survey
10/19/2011	EP300-EP312	0	Monitoring construction activity
10/19/2011	EP274-EP278	0	Site clearance survey
10/19/2011	EP274-EP278	0	Monitoring construction activity
10/19/2011	EP269-EP273	0	Site clearance survey
10/19/2011	EP269-EP273	0	Monitoring construction activity
10/19/2011	EP263B-EP267	0	Site clearance survey
10/18/2011	Slay Property	0	Monitoring construction activity
10/18/2011	EP269-EP270	0	Site clearance survey
10/18/2011	EP269-EP270	0	Monitoring construction activity
10/18/2011	EP269-EP281	0	Site clearance survey
10/18/2011	EP269-EP270	0	Site clearance survey
10/18/2011	EP274-EP278	0	Site clearance survey
10/18/2011	EP274-EP278	0	Monitoring construction activity
10/18/2011	EP269-EP273	0	Site clearance survey
10/18/2011	EP269-EP273	0	Monitoring construction activity
10/18/2011	EP263B-EP267	0	Site clearance survey
10/17/2011	Slay Property	0	Site clearance survey
10/17/2011	EP312 & EP314	0	Monitoring construction activity
10/17/2011	EP306-EP312	0	Site clearance survey
10/17/2011	EP306-EP312	0	Afternoon perimeter survey
10/17/2011	EP305	0	Monitoring construction activity
10/17/2011	EP300-EP363	0	Monitoring construction activity
10/17/2011	EP300-EP306	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
10/17/2011	EP300-EP306	0	Monitoring construction activity
10/17/2011	EP270-2	0	Monitoring construction activity
10/17/2011	EP269-EP270	0	Site clearance survey
10/17/2011	EP269-EP270	0	Monitoring construction activity
10/17/2011	EP269-EP281	0	Site clearance survey
10/17/2011	EP269-EP270	0	Site clearance survey
10/17/2011	EP267-2	0	Monitoring construction activity
10/17/2011	EP261-2	0	Monitoring construction activity
10/17/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/17/2011	EP274-EP278	0	Site clearance survey
10/17/2011	EP274-EP278	0	Monitoring construction activity
10/17/2011	EP269-EP273	0	Site clearance survey
10/17/2011	EP269-EP273	0	Monitoring construction activity
10/17/2011	EP263B-EP267	0	Site clearance survey
10/16/2011	EP306-EP312	0	Site clearance survey
10/16/2011	EP306-EP312	0	Afternoon perimeter survey
10/16/2011	EP300-EP306	0	Site clearance survey
10/16/2011	EP300-EP306	0	Monitoring construction activity
10/16/2011	EP271-2	0	Monitoring construction activity
10/16/2011	EP270-2	0	Monitoring construction activity
10/16/2011	EP269-EP270	0	Site clearance survey
10/16/2011	EP256-EP281	0	Site clearance survey
10/16/2011	EP305	0	Monitoring construction activity
10/16/2011	EP274-EP278	0	Site clearance survey
10/16/2011	EP274-EP278	0	Monitoring construction activity
10/16/2011	EP269-EP273	0	Site clearance survey
10/16/2011	EP269-EP273	0	Monitoring construction activity
10/16/2011	EP263B-EP267	0	Site clearance survey
10/16/2011	EP256-EP263A-2, AER & FROMM CY	0	Site clearance survey
10/16/2011	EP256-EP263A-2, AER & FROMM CY	0	Monitoring construction activity
10/15/2011	Slay Property	0	Site clearance survey
10/15/2011	Slay Property	0	Monitoring construction activities
10/15/2011	EP306-EP312	0	Site clearance survey
10/15/2011	EP306-EP312	0	Afternoon perimeter survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
10/15/2011	EP305	0	Monitoring construction activities
10/15/2011	EP300-EP306	0	Site clearance survey
10/15/2011	EP300-EP306	0	Monitoring construction activities
10/15/2011	EP269-1 AND EP273-1	0	Monitoring construction activities
10/15/2011	EP269-EP281	0	Morning perimeter survey
10/15/2011	EP261-2	0	Monitoring construction activities
10/15/2011	EP274-EP278	0	Site clearance survey
10/15/2011	EP274-EP278	0	Monitoring construction activities
10/15/2011	EP263B-EP267	0	Site clearance survey
10/14/2011	Slay Property	0	Site clearance survey
10/14/2011	Slay Property	0	Monitoring construction activities
10/14/2011	EP310	0	Monitoring construction activities
10/14/2011	EP305	0	Monitoring construction activities
10/14/2011	EP300-EP306	0	Site clearance survey
10/14/2011	EP300-EP306	0	Monitoring construction activities
10/14/2011	EP291-EP301	0	Monitoring construction activities
10/14/2011	EP269 through EP281	0	Site clearance survey
10/14/2011	EP269-EP270	0	Site clearance survey
10/14/2011	EP263B-2	0	Monitoring construction activities
10/14/2011	EP256-EP263A	0	Site clearance survey
10/14/2011	EP256-EP263A	0	Monitoring construction activities
10/14/2011	EP274-EP278	0	Site clearance survey
10/14/2011	EP274-EP278	0	Monitoring construction activities
10/14/2011	EP269-EP273	0	Site clearance survey
10/14/2011	EP269-EP273	0	Monitoring construction activities
10/14/2011	EP263B-EP267	0	Site clearance survey
10/14/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/14/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/13/2011	Slay Property	0	Site clearance survey
10/13/2011	Slay Property	0	Monitoring construction activities
10/13/2011	EP310	0	Monitoring construction activities
10/13/2011	EP306-EP312	0	Site clearance survey
10/13/2011	EP306-EP312	0	Afternoon perimeter survey
10/13/2011	EP293	0	Monitoring construction activities



**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
10/13/2011	EP291-EP301	0	Monitoring construction activities
10/13/2011	EP275-1	0	Monitoring construction activities
10/13/2011	EP269-EP270	0	Site clearance survey
10/13/2011	EP269-EP281	0	Site clearance survey
10/13/2011	EP269-EP270	0	Site clearance survey
10/13/2011	EP266-2	0	Monitoring construction activities
10/13/2011	EP274-EP278	0	Site clearance survey
10/13/2011	EP274-EP278	0	Monitoring construction activities
10/13/2011	EP269-EP273	0	Site clearance survey
10/13/2011	EP269-EP273	0	Monitoring construction activities
10/13/2011	EP263B-EP267	0	Site clearance survey
10/13/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/13/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/12/2011	Slay Property	0	Site clearance survey
10/12/2011	Slay Property	0	Monitoring construction activities
10/12/2011	EP306-EP312	0	Site clearance survey
10/12/2011	EP291-EP301	0	Monitoring construction activities
10/12/2011	EP269-EP270	0	Site clearance survey
10/12/2011	EP269-EP281	0	Site clearance survey
10/12/2011	EP269-EP281	0	Monitoring construction activities
10/12/2011	EP269-EP270	0	Site clearance survey
10/12/2011	EP311	0	Monitoring construction activities
10/12/2011	EP274-EP278	0	Site clearance survey
10/12/2011	EP274-EP278	0	Monitoring construction activities
10/12/2011	EP269-EP273	0	Site clearance survey
10/12/2011	EP269-EP273	0	Monitoring construction activities
10/12/2011	EP263B-EP267	0	Site clearance survey
10/12/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/12/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/11/2011	Slay Property	0	Site clearance survey
10/11/2011	Slay Property	0	Monitoring construction activities
10/11/2011	EP311	0	Monitoring construction activities
10/11/2011	EP306-EP312	0	Site clearance survey
10/11/2011	EP306-EP312	0	Afternoon perimeter survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
10/11/2011	EP300-EP306	0	Site clearance survey
10/11/2011	EP291-EP301	0	Monitoring construction activities
10/11/2011	EP269-EP273	0	Site clearance survey
10/11/2011	EP269-EP273	0	Monitoring construction activities
10/11/2011	EP269-EP270	0	Site clearance survey
10/11/2011	EP269-EP270	0	Monitoring construction activities
10/11/2011	EP274-EP278	0	Site clearance survey
10/11/2011	EP274-EP278	0	Monitoring construction activities
10/11/2011	EP263B-EP267	0	Site clearance survey
10/11/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/11/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/10/2011	Slay Property	0	Site clearance survey
10/10/2011	Slay Property	0	Monitoring construction activities
10/10/2011	EP306-EP312	0	Site clearance survey
10/10/2011	EP306-EP312	0	Afternoon perimeter survey
10/10/2011	EP305	0	Monitoring construction activities
10/10/2011	EP300-EP306	0	Site clearance survey
10/10/2011	EP300-EP306	0	Monitoring construction activities
10/10/2011	EP300-EP306	0	Site clearance survey
10/10/2011	EP291-EP301	0	Monitoring construction activities
10/10/2011	EP269-EP281	9	Sheep were seen entering I-8 Island during Site Clearance survey
10/10/2011	EP269-EP273	0	Site clearance survey
10/10/2011	EP269-EP273	0	Monitoring construction activities
10/10/2011	EP259-3	0	Monitoring construction activities
10/10/2011	EP274-EP278	0	Site clearance survey
10/10/2011	EP274-EP278	0	Monitoring construction activities
10/10/2011	EP263B-EP267	0	Site clearance survey
10/10/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/10/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/9/2011	EP306-EP312	0	Site clearance survey
10/9/2011	EP306-EP312	0	Monitoring construction activities
10/9/2011	EP300-EP306	0	Site clearance survey
10/9/2011	EP300-EP306	0	Monitoring construction activities
10/9/2011	EP300-EP306	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
10/9/2011	EP300-EP306	0	Monitoring construction activities
10/9/2011	EP269-EP273	0	Site clearance survey
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP269-EP270	0	Monitoring construction activities
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP256-3	0	Monitoring construction activities
10/9/2011	EP274-EP278	0	Site clearance survey
10/9/2011	EP274-EP278	0	Monitoring construction activities
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP269-EP270	0	Monitoring construction activities
10/9/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/9/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/8/2011	EP300-EP306	0	Site clearance survey
10/8/2011	EP300-EP306	0	Monitoring construction activity
10/8/2011	EP300-EP306	0	Site clearance survey
10/8/2011	EP300-EP306	0	Morning perimeter survey
10/8/2011	EP291-EP301	0	Monitoring construction activity
10/8/2011	EP278-1	0	Monitoring construction activity
10/8/2011	EP269-EP273	0	Site clearance survey
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP269-EP270	0	Monitoring construction activity
10/8/2011	EP269/EP270 Pullsite	0	Monitoring construction activity
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP259-3	0	Monitoring construction activity
10/8/2011	EP274-EP278	0	Site clearance survey
10/8/2011	EP274-EP278	0	Monitoring construction activity
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP269-EP270	0	Monitoring construction activity
10/8/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/8/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/7/2011	Slay Property	0	Site clearance survey
10/7/2011	EP306-EP312	0	Site clearance survey
10/7/2011	EP306-EP312	0	Morning perimeter survey
10/7/2011	EP300-EP306	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
10/7/2011	EP300-EP306	0	Monitoring construction activity
10/7/2011	EP300-EP306	0	Site clearance survey
10/7/2011	EP300-EP306	0	Morning perimeter survey
10/7/2011	EP291-EP301	0	Site clearance survey
10/7/2011	EP269-EP273	0	Site clearance survey
10/7/2011	EP269-EP270	0	Site clearance survey
10/7/2011	EP269-EP270	0	Monitoring construction activity
10/7/2011	EP269-EP270	0	Site clearance survey
10/7/2011	EP259-3	0	Monitoring construction activity
10/7/2011	EP274-EP278	0	Site clearance survey
10/7/2011	EP274-EP278	0	Monitoring construction activity
10/7/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/7/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/6/2011	Slay Property	0	Site clearance survey
10/6/2011	Slay Property	0	Monitoring construction activity
10/6/2011	EP306-EP312	0	Site clearance survey
10/6/2011	EP306-EP312	0	Monitoring construction activity
10/6/2011	EP291-EP301	0	Site clearance survey
10/6/2011	EP269-EP273	0	Site clearance survey
10/6/2011	EP269-EP270	0	Site clearance survey
10/6/2011	EP269-EP270	0	Monitoring construction activity
10/6/2011	EP269-EP281	0	Site clearance survey
10/6/2011	EP269-EP270	0	Site clearance survey
10/6/2011	EP263B-EP267	0	Site clearance survey
10/6/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/6/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/5/2011	Slay Property	0	Site clearance survey
10/5/2011	Slay Property	0	Monitoring construction activity
10/5/2011	EP303-2	0	Monitoring construction activity
10/5/2011	EP291-EP301	0	Site clearance survey
10/5/2011	EP269-EP273	0	Site clearance survey
10/5/2011	EP269-EP270	0	Site clearance survey
10/5/2011	EP269-EP270	0	Monitoring construction activity
10/5/2011	EP274-EP278	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
10/5/2011	EP274-EP278	0	Monitoring construction activity
10/5/2011	EP269-EP281	0	Site clearance survey
10/5/2011	EP269-EP270	0	Site clearance survey
10/5/2011	EP263B-EP267	0	Site clearance survey
10/5/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/5/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/4/2011	Slay Property	0	Site clearance survey
10/4/2011	Slay Property	0	Monitoring construction activity
10/4/2011	EP300-EP306	0	Site clearance survey
10/4/2011	EP300-EP306	0	Monitoring construction activity
10/4/2011	EP269-EP273	0	Site clearance survey
10/4/2011	EP269-EP270	0	Site clearance survey
10/4/2011	EP269-EP270	0	Monitoring construction activity
10/4/2011	EP256-EP263A	0	Site clearance survey
10/4/2011	EP274-EP278	0	Site clearance survey
10/4/2011	EP274-EP278	0	Monitoring construction activity
10/4/2011	EP263B-EP267	0	Site clearance survey
10/3/2011	Slay Property	0	Site clearance survey
10/3/2011	Slay Property	0	Monitoring construction activity
10/3/2011	EP300-EP306	0	Site clearance survey
10/3/2011	EP300-EP306	0	Monitoring construction activity
10/3/2011	EP300-EP306	0	Site clearance survey
10/3/2011	EP300-EP306	0	Morning perimeter survey
10/3/2011	EP291-EP341	0	Site clearance survey
10/3/2011	EP279-EP294	0	Site clearance survey
10/3/2011	EP269-EP273	0	Site clearance survey
10/3/2011	EP269-EP273	0	Monitoring construction activity
10/3/2011	EP263B-EP267	0	Site clearance survey
10/3/2011	EP263B-EP267	0	Monitoring construction activity
10/3/2011	EP256-EP263A	0	Site clearance survey
10/3/2011	EP274-EP278	0	Site clearance survey
10/3/2011	EP274-EP278	0	Monitoring construction activity
10/3/2011	EP263B-EP267	0	Site clearance survey
10/2/2011	EP300-EP306	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
10/2/2011	EP300-EP306	0	Monitoring construction activity
10/2/2011	EP269-EP281	0	Afternoon perimeter survey
10/2/2011	EP269-EP273	0	Afternoon perimeter survey
10/1/2011	EP300-EP306	0	Site clearance survey
10/1/2011	EP300-EP306	0	Monitoring construction activities
10/1/2011	EP300-EP306	0	Site clearance survey
10/1/2011	EP300-EP306	0	Morning perimeter survey
10/1/2011	EP269-EP273 and EP256-EP261	0	Site clearance survey
10/1/2011	EP269-EP273	0	Site clearance survey
10/1/2011	EP269-EP270	0	Site clearance survey
10/1/2011	EP274-EP278	0	Site clearance survey
10/1/2011	EP274-EP278	0	Monitoring construction activities
9/30/2011	Slay Property	0	Site clearance survey
9/30/2011	Slay Property	0	Monitoring construction activities
9/30/2011	EP300-EP312	0	Site clearance survey
9/30/2011	EP300-EP312	0	Monitoring construction activities
9/30/2011	EP300-EP306	0	Site clearance survey
9/30/2011	EP300-EP306	0	Monitoring construction activities
9/30/2011	EP291-EP348	0	Monitoring construction activities
9/30/2011	EP290-EP294, EP300-EP312	0	Site clearance survey
9/30/2011	EP290-EP294, EP300-EP312	0	Monitoring construction activities
9/30/2011	EP269-EP273	0	Site clearance survey
9/30/2011	EP269-EP273	0	Monitoring construction activities
9/30/2011	EP269-EP281	0	Site clearance survey
9/30/2011	EP279-EP294	0	Site clearance survey
9/30/2011	EP274-EP278	0	Site clearance survey
9/30/2011	EP274-EP278	0	Monitoring construction activities
9/30/2011	EP263-B-EP267	0	Site clearance survey
9/30/2011	EP256-EP263A, AER, Fromm CY	0	Site clearance survey
9/30/2011	EP256-EP263A, AER, Fromm CY	0	Monitoring construction activities
9/29/2011	Slay Property	0	Site clearance survey
9/29/2011	Slay Property	0	Monitoring construction activities
9/29/2011	EP300-EP312	0	Site clearance survey
9/29/2011	EP300-EP306	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
9/29/2011	EP300-EP306	0	Monitoring construction activities
9/29/2011	EP290-EP294, EP300-EP312	0	Site clearance survey
9/29/2011	EP290-EP294, EP300-EP312	0	Monitoring construction activities
9/29/2011	EP269-EP273	0	Site clearance survey
9/29/2011	EP269-EP273	0	Monitoring construction activities
9/29/2011	EP279-EP294	0	Site clearance survey
9/29/2011	EP274-EP278	0	Site clearance survey
9/29/2011	EP274-EP278	0	Monitoring construction activities
9/29/2011	EP263B-EP267	0	Site clearance survey
9/28/2011	Slay Property	0	Site clearance survey
9/28/2011	Slay Property	0	Monitoring construction activities
9/28/2011	EP330-EP291	0	Site clearance survey
9/28/2011	EP300-EP306	0	Site clearance survey
9/28/2011	EP300-EP306	0	Monitoring construction activities
9/28/2011	EP290-EP294	0	Site clearance survey
9/28/2011	EP290-EP294	0	Monitoring construction activities
9/28/2011	EP269-EP273	0	Site clearance survey
9/28/2011	EP269-EP273	0	Monitoring construction activities
9/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/28/2011	EP279-EP294	0	Site clearance survey
9/28/2011	EP279-EP294	0	Monitoring construction activities
9/28/2011	EP274-EP278	0	Site clearance survey
9/28/2011	EP274-EP278	0	Monitoring construction activities
9/28/2011	EP263B-EP267	0	Site clearance survey
9/27/2011	Slay Property	0	Site clearance survey
9/27/2011	Slay Property	0	Monitoring construction activities
9/27/2011	EP339-EP291	0	Site clearance survey
9/27/2011	EP309	0	Monitoring construction activities
9/27/2011	EP300-EP312	0	Site clearance survey
9/27/2011	EP300-EP312	0	Monitoring construction activities
9/27/2011	EP300-EP306	0	Site clearance survey
9/27/2011	EP278-1	0	Monitoring construction activities
9/27/2011	EP269-EP273	0	Site clearance survey
9/27/2011	EP269-EP273	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
9/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/27/2011	EP279-EP294	0	Site clearance survey
9/27/2011	EP279-EP294	0	Monitoring construction activities
9/27/2011	EP274-EP278	0	Site clearance survey
9/27/2011	EP274-EP278	0	Monitoring construction activities
9/27/2011	EP263B-EP267	0	Site clearance survey
9/27/2011	AER CY	0	Monitoring construction activities
9/26/2011	EP300-EP306	0	Site clearance survey
9/26/2011	EP300-EP306	0	Monitoring construction activities
9/26/2011	EP300-EP306	0	Site clearance survey
9/26/2011	EP300-EP312	0	Site clearance survey
9/26/2011	EP300-EP312	0	Monitoring construction activities
9/26/2011	EP291-EP301	0	Monitoring construction activities
9/26/2011	EP278-1, EP270-2	0	Monitoring construction activities
9/26/2011	EP274-EP278	0	Site clearance survey
9/26/2011	EP274-EP278	0	Monitoring construction activities
9/26/2011	EP269-EP273	0	Site clearance survey
9/26/2011	EP269-EP273	0	Monitoring construction activities
9/26/2011	EP269-EP270	0	Morning perimeter survey
9/26/2011	EP269-EP270	0	Monitoring construction activities
9/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/26/2011	EP279-EP294	0	Site clearance survey
9/26/2011	EP279-EP294	0	Monitoring construction activities
9/26/2011	EP269-EP271, EP256-EP263, AER & Fromm CY	0	Site clearance survey
9/26/2011	EP269-EP271, EP256-EP263, AER & Fromm CY	0	Monitoring construction activities
9/26/2011	EP263B-EP267	0	Site clearance survey
9/26/2011	CP88	0	Site clearance survey
9/26/2011	CP88	0	Monitoring construction activities
9/25/2011	EP300-EP306	0	Site clearance survey
9/25/2011	EP300-EP306	0	Monitoring construction activities
9/25/2011	EP300-EP306	0	Morning perimeter survey
9/25/2011	EP278	0	Monitoring construction activities



**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
9/25/2011	EP274-EP278	0	Site clearance survey
9/25/2011	EP274-EP278	0	Monitoring construction activities
9/25/2011	EP271-2	0	Monitoring construction activities
9/25/2011	EP269-EP270	0	Morning perimeter survey
9/25/2011	EP269-EP270	0	Monitoring construction activities
9/25/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/25/2011	EP279-EP294	0	Site clearance survey
9/25/2011	EP279-EP294	0	Monitoring construction activities
9/25/2011	EP269-EP273	0	Site clearance survey
9/25/2011	EP269-EP273	0	Monitoring construction activities
9/25/2011	EP263B-EP267	0	Site clearance survey
9/24/2011	EP300-EP306	0	Site clearance survey
9/24/2011	EP300-EP306	0	Monitoring construction activities
9/24/2011	EP300-EP306	0	Site clearance survey
9/24/2011	EP300-EP306	0	Monitoring construction activities
9/24/2011	EP291/EP292 Pullsite	0	Monitoring construction activities
9/24/2011	EP274-EP278	0	Site clearance survey
9/24/2011	EP274-EP278	0	Monitoring construction activities
9/24/2011	EP274	0	Monitoring construction activities
9/24/2011	EP269-EP270	0	Site clearance survey
9/24/2011	EP269-EP270	0	Monitoring construction activities
9/24/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/24/2011	EP279-EP294	0	Site clearance survey
9/24/2011	EP279-EP294	0	Monitoring construction activities
9/24/2011	EP263B-EP267	0	Site clearance survey
9/23/2011	EP300-EP306	0	Site clearance survey
9/23/2011	EP300-EP306	0	Monitoring construction activities
9/23/2011	EP300-EP312	0	Site clearance survey
9/23/2011	EP300-EP312	0	Monitoring construction activities
9/23/2011	EP274-1	0	Monitoring construction activities
9/23/2011	EP269-EP271	0	Site clearance survey
9/23/2011	EP269-EP271	0	Monitoring construction activities
9/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/23/2011	EP279-EP294	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
9/23/2011	EP279-EP294	0	Monitoring construction activities
9/23/2011	EP278-1	0	Monitoring construction activities
9/23/2011	EP263B-EP267	0	Site clearance survey
9/22/2011	EP300-EP312	0	Site clearance survey
9/22/2011	EP300-EP312	0	Monitoring construction activities
9/22/2011	EP300-EP306	0	Site clearance survey
9/22/2011	EP300-EP306	0	Monitoring construction activities
9/22/2011	EP274-1	0	Monitoring construction activities
9/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/22/2011	EP279-EP294	0	Site clearance survey
9/22/2011	EP278-1	0	Monitoring construction activities
9/22/2011	EP274-EP278	0	Site clearance survey
9/22/2011	EP274-EP278	0	Monitoring construction activities
9/22/2011	EP263B-EP267	0	Site clearance survey
9/21/2011	EP300-EP306	0	Site clearance survey
9/21/2011	EP278-1	0	Monitoring construction activities
9/21/2011	EP274-1	0	Monitoring construction activities
9/21/2011	EP269-EP271, EP300-EP312	0	Site clearance survey
9/21/2011	EP269-EP271, EP300-EP312	0	Monitoring construction activities
9/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/21/2011	EP279-EP294	0	Site clearance survey
9/21/2011	EP279-EP294	0	Monitoring construction activities
9/21/2011	EP274-EP278	0	Site clearance survey
9/21/2011	EP274-EP278	0	Monitoring construction activities
9/21/2011	EP269-EP281	0	Site clearance survey
9/21/2011	EP269-EP281	0	Monitoring construction activities
9/21/2011	EP263B-EP267	0	Site clearance survey
9/20/2011	EP300-EP306	0	Site clearance survey
9/20/2011	EP278-1	0	Monitoring construction activities
9/20/2011	EP269-EP273	0	Site clearance survey
9/20/2011	EP269-EP273	0	Monitoring construction activities
9/20/2011	EP269-EP271	0	Site clearance survey
9/20/2011	EP269-EP271	0	Monitoring construction activities
9/20/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
9/20/2011	EP279-EP294	0	Site clearance survey
9/20/2011	EP279-EP294	0	Monitoring construction activities
9/20/2011	EP274-EP278	0	Site clearance survey
9/20/2011	EP274-EP278	0	Monitoring construction activities
9/20/2011	EP269-EP281	0	Site clearance survey
9/20/2011	EP269-EP281	0	Monitoring construction activities
9/20/2011	EP263B-EP267	0	Site clearance survey
9/19/2011	EP269-EP273	0	Site clearance survey
9/19/2011	EP269-EP273	0	Monitoring construction activities
9/19/2011	EP269-EP271	0	Site clearance survey
9/19/2011	EP269-EP271	0	Monitoring construction activities
9/19/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/19/2011	EP279-EP294	0	Site clearance survey
9/19/2011	EP279-EP294	0	Monitoring construction activities
9/19/2011	EP274-EP278	0	Site clearance survey
9/19/2011	EP274-EP278	0	Monitoring construction activities
9/19/2011	EP269-EP281	0	Site clearance survey
9/19/2011	EP269-EP281	0	Monitoring construction activities
9/19/2011	EP263B-EP267	0	Site clearance survey
9/18/2011	EP300-EP306	0	Site clearance survey
9/18/2011	EP300-EP312	0	Site clearance survey
9/18/2011	EP300-EP312	0	Monitoring construction activities
9/18/2011	EP269-EP273	0	Site clearance survey
9/18/2011	EP269-EP273	0	Monitoring construction activities
9/18/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/18/2011	EP279-EP294	0	Site clearance survey
9/18/2011	EP279-EP294	0	Monitoring construction activities
9/18/2011	EP274-EP278	0	Site clearance survey
9/18/2011	EP274-EP278	0	Monitoring construction activities
9/18/2011	EP269-EP281	0	Site clearance survey
9/18/2011	18 Island	9	Afternoon perimeter survey
9/17/2011	EP300-EP306	0	Site clearance survey
9/17/2011	EP300-EP312	0	Site clearance survey
9/17/2011	EP300-EP312	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
9/17/2011	EP269-EP273	0	Site clearance survey
9/17/2011	EP269-EP273	0	Monitoring construction activities
9/17/2011	EP274-EP278	0	Site clearance survey
9/17/2011	EP274-EP278	0	Monitoring construction activities
9/17/2011	EP269-EP281	0	Site clearance survey
9/17/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/17/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/16/2011	EP300-EP312	0	Site clearance survey
9/16/2011	EP300-EP312	0	Monitoring construction activities
9/16/2011	EP300-EP306	0	Site clearance survey
9/16/2011	EP269-EP273	0	Site clearance survey
9/16/2011	EP269-EP273	0	Monitoring construction activities
9/16/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/16/2011	EP274-EP278	0	Site clearance survey
9/16/2011	EP274-EP278	0	Monitoring construction activities
9/16/2011	EP269-EP281	0	Site clearance survey
9/16/2011	EP263B-EP267	0	Site clearance survey
9/16/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/16/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/15/2011	EP300-EP312	0	Site clearance survey
9/15/2011	EP300-EP312	0	Monitoring construction activities
9/15/2011	EP300-EP306	0	Site clearance survey
9/15/2011	EP300-EP306	0	Monitoring construction activities
9/15/2011	EP269-EP273	0	Site clearance survey
9/15/2011	EP269-EP273	0	Monitoring construction activities
9/15/2011	EP256-EP263A, AER	0	Monitoring construction activities
9/15/2011	EP274-EP278	0	Site clearance survey
9/15/2011	EP274-EP278	0	Monitoring construction activities
9/15/2011	EP269-EP281	0	Site clearance survey
9/15/2011	EP269-EP281	0	Monitoring construction activities
9/15/2011	EP263B-EP267	0	Site clearance survey
9/14/2011	EP310-3	0	Monitoring construction activities
9/14/2011	EP300-EP312	0	Site clearance survey
9/14/2011	EP300-EP312	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
9/14/2011	EP300-EP306	0	Morning perimeter survey
9/14/2011	EP274-1	0	Monitoring construction activities
9/14/2011	EP269-EP273	0	Site clearance survey
9/14/2011	EP269-EP273	0	Monitoring construction activities
9/14/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/14/2011	EP274-EP278	0	Site clearance survey
9/14/2011	EP274-EP278	0	Monitoring construction activities
9/14/2011	EP269-EP281	0	Site clearance survey
9/14/2011	EP269-EP281	0	Monitoring construction activities
9/14/2011	EP263B-EP267	0	Site clearance survey
9/13/2011	EP300-EP312	0	Site clearance survey
9/13/2011	EP300-EP312	0	Monitoring construction activities
9/13/2011	EP300-EP306	0	Morning perimeter survey
9/13/2011	EP269-EP273	0	Site clearance survey
9/13/2011	EP269-EP273	0	Monitoring construction activities
9/13/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/13/2011	EP274-EP278	0	Site clearance survey
9/13/2011	EP274-EP278	0	Monitoring construction activities
9/13/2011	EP274-EP278	0	Monitoring construction activities
9/13/2011	EP274	0	Monitoring construction activities
9/13/2011	EP269-EP281	0	Site clearance survey
9/13/2011	EP263B-EP267	0	Site clearance survey
9/12/2011	Mountain Springs Grade Road	15	Morning perimeter survey
9/12/2011	EP305-3, EP310	0	Monitoring construction activities
9/12/2011	EP300-EP312	0	Site clearance survey
9/12/2011	EP300-EP312	0	Monitoring construction activities
9/12/2011	EP300-EP306	0	Site clearance survey
9/12/2011	EP300-EP306	0	Monitoring construction activities
9/12/2011	EP269-EP273	0	Site clearance survey
9/12/2011	EP269-EP273	0	Monitoring construction activities
9/12/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/12/2011	EP274-EP278	0	Site clearance survey
9/12/2011	EP274-EP278	0	Monitoring construction activities
9/12/2011	EP274-EP278	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
9/12/2011	EP274	0	Monitoring construction activities
9/12/2011	EP269-EP281	0	Monitoring construction activities
9/12/2011	EP263B-EP267	0	Site clearance survey
9/11/2011	EP300-EP312	0	Site clearance survey
9/11/2011	EP300-EP312	0	Monitoring construction activities
9/11/2011	EP300-EP306	0	Site clearance survey
9/11/2011	EP300-EP306	0	Monitoring construction activities
9/11/2011	EP271-2	0	Monitoring construction activities
9/11/2011	EP269-EP271	0	Site clearance survey
9/11/2011	EP269-EP271	0	Monitoring construction activities
9/11/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/11/2011	EP274-EP278	0	Site clearance survey
9/11/2011	EP274-EP278	0	Monitoring construction activities
9/11/2011	EP269-EP273	0	Site clearance survey
9/11/2011	EP269-EP273	0	Monitoring construction activities
9/11/2011	EP263B-EP267	0	Site clearance survey
9/11/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/11/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/10/2011	EP300-EP312	0	Site clearance survey
9/10/2011	EP300-EP312	0	Monitoring construction activities
9/10/2011	EP300-EP306	0	Site clearance survey
9/10/2011	EP300-EP306	0	Monitoring construction activities
9/10/2011	EP269-EP271	0	Site clearance survey
9/10/2011	EP269-EP271	0	Monitoring construction activities
9/10/2011	EP274-EP278	0	Site clearance survey
9/10/2011	EP274-EP278	0	Monitoring construction activities
9/10/2011	EP269-EP273	0	Morning perimeter survey
9/10/2011	EP269-EP273	0	Monitoring construction activities
9/10/2011	EP269-EP273	0	Evening perimeter survey
9/9/2011	EP300-EP312	0	Site clearance survey
9/9/2011	EP300-EP312	0	Monitoring construction activities
9/9/2011	EP300-EP306	0	Site clearance survey
9/9/2011	EP300-EP306	0	Monitoring construction activities
9/9/2011	EP271-2	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
9/9/2011	EP269-EP271	0	Site clearance survey
9/9/2011	EP269-EP271	0	Monitoring construction activities
9/9/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/9/2011	EP256-EP263A, AER and Fromm yards	0	Site clearance survey
9/9/2011	EP256-EP263A, AER and Fromm yards	0	Monitoring construction activities
9/9/2011	EP274-EP278	0	Site clearance survey
9/9/2011	EP274-EP278	0	Monitoring construction activities
9/9/2011	EP269-EP273	0	Morning perimeter survey
9/9/2011	EP269-EP273	0	Monitoring construction activities
9/9/2011	EP269-EP273	0	Evening perimeter survey
9/8/2011	EP300-EP312	0	Site clearance survey
9/8/2011	EP300-EP312	0	Monitoring construction activities
9/8/2011	EP271-2	0	Monitoring construction activities
9/8/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/8/2011	EP279-EP294	0	Site clearance survey
9/8/2011	EP279-EP294	0	Monitoring construction activities
9/8/2011	EP274-EP278	0	Site clearance survey
9/8/2011	EP274-EP278	0	Monitoring construction activities
9/8/2011	EP263B-EP267	0	Site clearance survey
9/7/2011	EP306-1	0	Monitoring construction activities
9/7/2011	EP300-EP312	0	Site clearance survey
9/7/2011	EP300-EP312	0	Monitoring construction activities
9/7/2011	EP300-EP306	0	Site clearance survey
9/7/2011	EP300-EP306	0	Monitoring construction activities
9/7/2011	EP273	0	Monitoring construction activities
9/7/2011	EP269-EP273	0	Site clearance survey
9/7/2011	EP269-EP273	0	Monitoring construction activities
9/7/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/7/2011	EP278-EP294	0	Morning perimeter survey
9/7/2011	EP278-EP294	0	Monitoring construction activities
9/7/2011	EP278-EP294	0	Evening perimeter survey
9/7/2011	EP274-EP278	0	Site clearance survey
9/7/2011	EP274-EP278	0	Monitoring construction activities
9/7/2011	EP263B-EP267	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
9/6/2011	EP300-EP312	0	Site clearance survey
9/6/2011	EP300-EP312	0	Monitoring construction activities
9/6/2011	EP273	0	Monitoring construction activities
9/6/2011	EP269-EP273	0	Site clearance survey
9/6/2011	EP269-EP273	0	Monitoring construction activities
9/6/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/6/2011	EP278-EP294	0	Morning perimeter survey
9/6/2011	EP278-EP294	0	Monitoring construction activities
9/6/2011	EP278-EP294	0	Evening perimeter survey
9/6/2011	EP274-EP278	0	Site clearance survey
9/6/2011	EP274-EP278	0	Monitoring construction activities
9/6/2011	EP263B-EP267	0	Site clearance survey
9/5/2011	EP300-EP312	0	Site clearance survey
9/5/2011	EP269-EP273	0	Site clearance survey
9/5/2011	EP269-EP273	0	Monitoring construction activities
9/5/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/5/2011	EP274-EP294	0	Site clearance survey
9/5/2011	EP263B-EP267	0	Site clearance survey
9/4/2011	EP300-EP312	0	Site clearance survey
9/4/2011	EP300-EP312	0	Monitoring construction activities
9/4/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
9/4/2011	EP269-EP281	0	Site clearance survey
9/4/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/4/2011	EP256-EP263A, AER and Fromm yards	0	Site clearance survey
9/4/2011	EP256-EP263A, AER and Fromm yards	0	Monitoring construction activities
9/4/2011	EP279-EP294	0	Site clearance survey
9/4/2011	EP279-EP294	0	Monitoring construction activities
9/4/2011	EP274-EP278	0	Site clearance survey
9/4/2011	EP274-EP278	0	Monitoring construction activities
9/4/2011	EP270	0	Site clearance survey
9/4/2011	EP270	0	Monitoring construction activities
9/3/2011	EP300-EP312	0	Monitoring Construction Activities
9/3/2011	EP300-EP312	0	Site clearance survey
9/3/2011	EP300-EP306	0	Monitoring Construction Activities



**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
9/3/2011	EP300-EP306	0	Site clearance survey
9/3/2011	EP271	0	Monitoring Construction Activities
9/3/2011	EP269-EP273	0	Monitoring Construction Activities
9/3/2011	EP269-EP273	0	Site clearance survey
9/3/2011	EP269-EP281	0	Monitoring Construction Activities
9/3/2011	EP256-EP263A, AER and Fromm Yards	0	Monitoring Construction Activities
9/3/2011	EP256-EP263A, AER and Fromm Yards	0	Site clearance survey
9/3/2011	EP278-EP294	0	Evening perimeter survey
9/3/2011	EP278-EP294	0	Monitoring Construction Activities
9/3/2011	EP278-EP294	0	Morning perimeter survey
9/3/2011	EP269-1 & EP269/EP270 Pull site	0	Monitoring Construction Activities
9/2/2011	I-8 Island	9	Evening perimeter survey 4:45pm - 5:08pm
9/2/2011	I-8 Island	12	Morning perimeter survey 8:35am
9/2/2011	EP300-EP312	0	Monitoring Construction Activities
9/2/2011	EP300-EP312	0	Site clearance survey
9/2/2011	EP272 & EP276	0	Monitoring Construction Activities
9/2/2011	EP269-EP273	0	Monitoring Construction Activities
9/2/2011	EP269-EP273	0	Site clearance survey
9/2/2011	EP256-EP263A, AER and Fromm Yards	0	Monitoring Construction Activities
9/2/2011	EP256-EP263A, AER and Fromm Yards	0	Site clearance survey
9/2/2011	EP278-EP294	0	Evening perimeter survey
9/2/2011	EP278-EP294	0	Monitoring Construction Activities
9/2/2011	EP278-EP294	0	Morning perimeter survey
9/2/2011	EP269-EP272	0	Monitoring Construction Activities
9/2/2011	EP269-EP272	0	Site clearance survey
9/2/2011	EP263B-EP267	0	Site clearance survey
9/1/2011	I-8 Island	12	Evening perimeter survey 4:45pm - 5:40pm
9/1/2011	I-8 Island	12	Morning perimeter survey 8:35am
9/1/2011	EP300-EP312	0	Monitoring Construction Activities
9/1/2011	EP300-EP312	0	Site clearance survey
9/1/2011	EP269-EP273	0	Monitoring Construction Activities
9/1/2011	EP269-EP273	0	Site clearance survey
9/1/2011	EP256-EP263A-2	0	Site clearance survey
9/1/2011	EP255	0	Monitoring Construction Activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
9/1/2011	EP300-EP306	0	Site clearance survey
9/1/2011	EP278-EP294	0	Evening perimeter survey
9/1/2011	EP278-EP294	0	Monitoring Construction Activities
9/1/2011	EP278-EP294	0	Morning perimeter survey
9/1/2011	EP269-EP272	0	Monitoring Construction Activities
9/1/2011	EP269-EP272	0	Site clearance survey
9/1/2011	EP263B-EP267	0	Site clearance survey
8/31/2011	I-8 Island	0	Site clearance survey
8/31/2011	EP308	0	Monitoring Construction Activities
8/31/2011	EP300-EP312	0	Monitoring Construction Activities
8/31/2011	EP300-EP312	0	Site clearance survey
8/31/2011	EP269-EP273	0	Monitoring Construction Activities
8/31/2011	EP269-EP273	0	Site clearance survey
8/31/2011	EP300-EP306	0	Site clearance survey
8/31/2011	EP278-EP294	0	Evening perimeter survey
8/31/2011	EP278-EP294	0	Monitoring Construction Activities
8/31/2011	EP278-EP294	0	Morning perimeter survey
8/31/2011	EP269-EP272	0	Monitoring Construction Activities
8/31/2011	EP263B-EP267	0	Site clearance survey
8/30/2011	I-8 Island	16	Evening perimeter survey 4:30pm
8/30/2011	I-8 Island	9	Morning perimeter survey 9:10am - 9:30am
8/30/2011	EP300-EP312	0	Monitoring Construction Activities
8/30/2011	EP300-EP312	0	Site clearance survey
8/30/2011	EP269-EP273	0	Monitoring Construction Activities
8/30/2011	EP269-EP273	0	Site clearance survey
8/30/2011	EP300-EP306	0	Site clearance survey
8/30/2011	EP278-EP294	0	Evening perimeter survey
8/30/2011	EP278-EP294	0	Monitoring Construction Activities
8/30/2011	EP278-EP294	0	Morning perimeter survey
8/30/2011	EP274-EP278	0	Monitoring Construction Activities
8/30/2011	EP274-EP278	0	Site clearance survey
8/30/2011	EP269-EP272	0	Monitoring Construction Activities
8/30/2011	EP269-EP272	0	Site clearance survey
8/30/2011	EP263B-EP267	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
8/29/2011	I-8 Island	4	Morning perimeter survey 8:55am
8/29/2011	I-8 Island	12	Evening perimeter survey 4:35pm to 5:00pm
8/29/2011	EP300-EP312	0	Monitoring Construction Activities
8/29/2011	EP300-EP312	0	Site clearance survey
8/29/2011	EP278-2	0	Monitoring Construction Activities
8/29/2011	EP269-EP273	0	Monitoring Construction Activities
8/29/2011	EP269-EP273	0	Site clearance survey
8/29/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/29/2011	EP300-EP306	0	Site clearance survey
8/29/2011	EP274-EP278	0	Monitoring Construction Activities
8/29/2011	EP274-EP278	0	Site clearance survey
8/29/2011	EP269-EP272	0	Monitoring Construction Activities
8/29/2011	EP269-EP272	0	Site clearance survey
8/29/2011	EP263B-EP267	0	Site clearance survey
8/28/2011	I-8 Island	15	Morning perimeter survey @9:22am
8/28/2011	EP305	0	Monitoring Construction Activities
8/28/2011	EP281	0	Monitoring Construction Activities
8/28/2011	EP273	0	Monitoring Construction Activities
8/28/2011	EP269-EP273	0	Monitoring Construction Activities
8/28/2011	EP269-EP273	0	Site clearance survey
8/28/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/28/2011	EP300-EP306	0	Morning perimeter survey
8/28/2011	EP278-EP294	0	Evening perimeter survey
8/28/2011	EP278-EP294	0	Monitoring Construction Activities
8/28/2011	EP278-EP294	0	Morning perimeter survey
8/28/2011	EP274-EP278	0	Monitoring Construction Activities
8/28/2011	EP274-EP278	0	Site clearance survey
8/28/2011	EP269-EP272	0	Monitoring Construction Activities
8/28/2011	EP269-EP272	0	Site clearance survey
8/28/2011	EP263-B, EP267	0	Site clearance survey
8/27/2011	I-8 Island	0	Site clearance survey
8/27/2011	EP305	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
8/27/2011	I-8 Island	0	Morning perimeter survey
8/27/2011	EP305	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Site clearance survey
8/27/2011	EP300-EP306, EP269-EP273	0	Monitoring Construction Activities
8/27/2011	EP272-3	0	Monitoring Construction Activities
8/27/2011	EP261	0	Monitoring Construction Activities
8/27/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/27/2011	EP278-EP294	0	Site clearance survey
8/27/2011	EP278-EP294	0	Monitoring Construction Activities
8/27/2011	EP274-EP278	0	Site clearance survey
8/27/2011	EP274-EP278	0	Monitoring Construction Activities
8/27/2011	EP269-EP272	0	Monitoring Construction Activities
8/27/2011	EP269-EP272	0	Site clearance survey
8/27/2011	EP263B-EP267	0	Site clearance survey
8/26/2011	I-8 Island	0	Morning perimeter survey
8/26/2011	EP269-EP273	0	Monitoring Construction Activities
8/26/2011	EP269-EP273	0	Morning perimeter survey
8/26/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/26/2011	EP300-EP306	0	Monitoring Construction Activities
8/26/2011	EP278-EP294	0	Evening perimeter survey
8/26/2011	EP278-EP294	0	Monitoring Construction Activities
8/26/2011	EP278-EP294	0	Morning perimeter survey
8/26/2011	EP274-EP278	0	Monitoring Construction Activities
8/26/2011	EP274-EP278	0	Site clearance survey
8/26/2011	EP269-EP272	0	Monitoring Construction Activities
8/26/2011	EP269-EP272	0	Morning perimeter survey
8/25/2011	I-8 Island	0	Morning perimeter survey
8/25/2011	EP269-EP273	0	Monitoring Construction Activities
8/25/2011	EP269-EP273	0	Morning perimeter survey
8/25/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/25/2011	EP278-EP294	0	Evening perimeter survey
8/25/2011	EP278-EP294	0	Monitoring Construction Activities
8/25/2011	EP278-EP294	0	Morning perimeter survey
8/25/2011	EP274-EP278	0	Monitoring Construction Activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
8/25/2011	EP274-EP278	0	Site clearance survey
8/25/2011	EP270-EP272	0	Site clearance survey
8/25/2011	EP269-EP272	0	Monitoring Construction Activities
8/25/2011	EP269-EP272	0	Morning perimeter survey
8/24/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/24/2011	EP300-EP312, EP263B-EP267	0	Site clearance survey
8/24/2011	EP269-EP273	0	Monitoring Construction Activities
8/24/2011	EP269-EP273	0	Site clearance survey
8/24/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/24/2011	EP278-EP294	0	Evening perimeter survey
8/24/2011	EP278-EP294	0	Monitoring Construction Activities
8/24/2011	EP278-EP294	0	Morning perimeter survey
8/24/2011	EP274-EP278	0	Monitoring Construction Activities
8/24/2011	EP274-EP278	0	Site clearance survey
8/23/2011	I-8 Island	0	Morning perimeter survey
8/23/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/23/2011	EP300-EP312, EP263B-EP267	0	Site clearance survey
8/23/2011	EP269-EP273	0	Monitoring Construction Activities
8/23/2011	EP269-EP273	0	Site clearance survey
8/23/2011	EP278-EP294	0	Evening perimeter survey
8/23/2011	EP278-EP294	0	Monitoring Construction Activities
8/23/2011	EP278-EP294	0	Morning perimeter survey
8/23/2011	EP274-EP278	0	Monitoring Construction Activities
8/23/2011	EP274-EP278	0	Morning perimeter survey
8/23/2011	EP270-EP272	0	Morning perimeter survey
8/23/2011	EP269-EP272	0	Morning perimeter survey
8/22/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/22/2011	EP300-EP312, EP263B-EP267	0	Morning perimeter survey
8/22/2011	EP269-EP273	0	Monitoring Construction Activities
8/22/2011	EP269-EP273	0	Monitoring Construction Activities
8/22/2011	EP269-EP273	0	Morning perimeter survey
8/22/2011	EP263B	0	Monitoring Construction Activities
8/22/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/22/2011	EP291	0	Monitoring Construction Activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
8/22/2011	EP278-EP294	0	Evening perimeter survey
8/22/2011	EP278-EP294	0	Monitoring Construction Activities
8/22/2011	EP278-EP294	0	Morning perimeter survey
8/21/2011	I-8 Island	11	Evening perimeter survey - 6:00pm
8/21/2011	EP269-EP273	0	Site clearance survey
8/21/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/21/2011	EP256-EP263	0	Monitoring Construction Activities
8/21/2011	EP256-EP263	0	Site clearance survey
8/21/2011	EP279-EP294	0	Afternoon clearance survey
8/21/2011	EP274-EP278	0	Evening perimeter survey
8/21/2011	EP269-EP272	0	Evening perimeter survey
8/21/2011	EP263B-EP267	0	Site clearance survey
8/20/2011	I8 and Moutain Spring Rd	3	Morning perimeter survey 9:20am
8/20/2011	I8 and Moutain Spring Rd	4	Evening perimeter survey 6:40pm
8/20/2011	EP300-EP312	0	Monitoring construction activities
8/20/2011	EP300-EP312	0	Site clearance survey
8/20/2011	EP269-EP273	0	Monitoring construction activities
8/20/2011	EP269-EP273	0	Site clearance survey
8/20/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/20/2011	EP300-EP306	0	Morning perimeter survey
8/20/2011	EP274-EP294	0	Monitoring construction activities
8/20/2011	EP274-EP294	0	Site clearance survey
8/20/2011	EP270-EP271	0	Morning perimeter survey
8/20/2011	EP269-EP271	0	Monitoring construction activities
8/20/2011	EP263B-EP267	0	Site clearance survey
8/19/2011	Radiator Water Tower 17	7	Site clearance survey
8/19/2011	EP298, EP300 & EP307	0	Site clearance survey
8/19/2011	EP296, EP300	0	Monitoring construction activities
8/19/2011	EP296, EP300	0	Site clearance survey
8/19/2011	EP269-EP273	0	Monitoring construction activities
8/19/2011	EP269-EP273	0	Site clearance survey
8/19/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/19/2011	EP291-EP293	0	Monitoring construction activities
8/19/2011	EP279-EP294	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
8/19/2011	EP274-EP278	0	Monitoring construction activities
8/19/2011	EP274-EP278	0	Site clearance survey
8/19/2011	EP263B-EP267	0	Site clearance survey
8/18/2011	EP269-EP273	0	Monitoring construction activities
8/18/2011	EP269-EP273	0	Site clearance survey
8/18/2011	EP349, EP293	0	Monitoring construction activities
8/18/2011	EP279-EP312	0	Monitoring construction activities
8/18/2011	EP274-EP278	0	Monitoring construction activities
8/18/2011	EP274-EP278	0	Site clearance survey
8/18/2011	EP263B-EP267	0	Site clearance survey
8/17/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/17/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/17/2011	EP269-EP273	0	Monitoring construction activities
8/17/2011	EP269-EP273	0	Site clearance survey
8/17/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/17/2011	EP279-EP294	0	Monitoring construction activities
8/17/2011	EP279-EP294	0	Site clearance survey
8/17/2011	EP274-EP278	0	Monitoring construction activities
8/17/2011	EP274-EP278	0	Site clearance survey
8/17/2011	EP263B-EP267	0	Site clearance survey
8/16/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/16/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/16/2011	EP269-EP273	0	Monitoring construction activities
8/16/2011	EP269-EP273	0	Site clearance survey
8/16/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/16/2011	EP279-EP294	0	Monitoring construction activities
8/16/2011	EP279-EP294	0	Site clearance survey
8/16/2011	EP274-EP278	0	Monitoring construction activities
8/16/2011	EP274-EP278	0	Site clearance survey
8/16/2011	EP265	0	Monitoring construction activities
8/16/2011	EP263B-EP267	0	Site clearance survey
8/15/2011	Fromm and AER Construction Yard	0	Monitoring construction activities
8/15/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/15/2011	EP300-EP312, EP290-EP294	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
8/15/2011	EP294	0	Monitoring construction activities
8/15/2011	EP269-EP273	0	Site clearance survey
8/15/2011	EP269-EP273	0	Monitoring construction activities
8/15/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/15/2011	EP279-EP294	0	Monitoring construction activities
8/15/2011	EP279-EP294	0	Site clearance survey
8/15/2011	EP274-EP278	0	Monitoring construction activities
8/15/2011	EP274-EP278	0	Site clearance survey
8/15/2011	EP263B-EP267	0	Site clearance survey
8/14/2011	EP274-EP278	0	Monitoring construction activities
8/14/2011	EP263B-EP267	0	Site clearance survey
8/14/2011	EP274-EP278	0	Evening perimeter survey
8/14/2011	EP279-294	0	Monitoring construction activities
8/14/2011	EP269-EP273	0	Evening perimeter survey
8/14/2011	EP300-EP312	0	Site clearance survey
8/14/2011	EP300-EP312	0	Monitoring construction activities
8/13/2011	Fromm Construction Yard	0	Site clearance survey
8/13/2011	I-8 Island	19	Morning perimeter survey at 9:54am - 10:45am
8/13/2011	I-8 Island	6	Evening perimeter survey at 4:35pm
8/13/2011	EP263B-EP267	0	Site clearance survey
8/13/2011	EP269-EP271	0	Monitoring construction activities
8/13/2011	EP270-EP271	0	Monitoring construction activities
8/13/2011	EP274-EP278	0	Monitoring construction activities
8/13/2011	EP279-294	0	Monitoring construction activities
8/13/2011	EP300-EP306	0	Monitoring construction activities
8/13/2011	EP259B	0	Site clearance survey
8/13/2011	EP269-EP273	0	Monitoring construction activities
8/13/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/13/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/12/2011	I-8 Island	26	Evening perimeter survey at 4:25pm - 5:45
8/12/2011	EP263B-EP267	0	Site clearance survey
8/12/2011	EP269-EP271	0	Monitoring construction activities
8/12/2011	EP270-EP271	0	Monitoring construction activities
8/12/2011	EP279-294	0	Monitoring construction activities



**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
8/12/2011	EP300-EP306	0	Monitoring construction activities
8/12/2011	EP300-EP312	0	Monitoring construction activities
8/12/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/12/2011	EP259B	0	Site clearance survey
8/12/2011	EP269-EP273	0	Monitoring construction activities
8/12/2011	EP274-EP278, EP290-EP294	0	Site clearance survey
8/12/2011	EP274-EP278, EP290-EP294	0	Monitoring construction activities
8/12/2011	EP294	0	Monitoring construction activities
8/11/2011	I-8 Island	12	Morning perimeter survey at 10:50am
8/11/2011	I-8 Island	28	Evening perimeter survey at 6:19pm
8/11/2011	EP263B-EP267	0	Site clearance survey
8/11/2011	EP269-EP271	0	Monitoring construction activities
8/11/2011	EP270-EP271	0	Monitoring construction activities
8/11/2011	EP279-294	0	Monitoring construction activities
8/11/2011	EP300-EP306	0	Monitoring construction activities
8/11/2011	EP300-EP312	0	Monitoring construction activities
8/11/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/11/2011	EP259B	0	Site clearance survey
8/11/2011	EP269-EP273	0	Monitoring construction activities
8/11/2011	EP274-EP278	0	Site clearance survey
8/11/2011	EP274-EP278	0	Monitoring construction activities
8/11/2011	EP292-EP356	0	Monitoring construction activities
8/11/2011	EP294	0	Monitoring construction activities
8/10/2011	I-8 Island	16	Evening perimeter survey at 4:55pm - 5:08
8/10/2011	EP263B-EP267	0	Site clearance survey
8/10/2011	EP269-EP271	0	Monitoring construction activities
8/10/2011	EP270-EP271	0	Monitoring construction activities
8/10/2011	EP273	0	Monitoring construction activities
8/10/2011	EP300-EP306	0	Monitoring construction activities
8/10/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/10/2011	EP259B	0	Site clearance survey
8/10/2011	EP269-EP273	0	Monitoring construction activities
8/10/2011	EP294	0	Monitoring construction activities
8/10/2011	EP300-EP312	0	Morning perimeter survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
8/10/2011	EP300-EP312	0	Monitoring construction activities
8/10/2011	EP300-EP312	0	Evening perimeter survey
8/10/2011	EP227, EP232, EP258, EP314, EP317, EP348, EP349	0	Site clearance survey
8/9/2011	I-8 Island	3	Morning perimeter survey at 10:30am
8/9/2011	I-8 Island	18	Evening perimeter survey at 4:30pm - 5:06pm
8/9/2011	EP263B-EP267	0	Site clearance survey
8/9/2011	EP269-EP271	0	Monitoring construction activities
8/9/2011	EP270-EP271	0	Monitoring construction activities
8/9/2011	EP270-EP273	0	Monitoring construction activities
8/9/2011	EP274-EP278	0	Monitoring construction activities
8/9/2011	EP279-294	0	Monitoring construction activities
8/9/2011	EP300-EP306	0	Monitoring construction activities
8/9/2011	EP305	0	Monitoring construction activities
8/9/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/9/2011	EP269-EP273	0	Site clearance survey
8/9/2011	EP294	0	Monitoring construction activities
8/9/2011	EP300-EP312	0	Morning perimeter survey
8/9/2011	EP300-EP312	0	Monitoring construction activities
8/9/2011	EP300-EP312	0	Evening perimeter survey
8/8/2011	I-8 Island	4	Morning perimeter survey at 9:45am - 9:55am
8/8/2011	I-8 Island	22	Evening perimeter survey at 4:24pm - 5:14pm
8/8/2011	EP279-294	3	Monitoring construction activities
8/8/2011	EP263B-EP267	0	Site clearance survey
8/8/2011	EP269-EP271	0	Monitoring construction activities
8/8/2011	EP270-EP271	0	Monitoring construction activities
8/8/2011	EP273	0	Monitoring construction activities
8/8/2011	EP274-EP278	0	Monitoring construction activities
8/8/2011	EP300-EP306	0	Monitoring construction activities
8/8/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/8/2011	EP269-EP273	0	Site clearance survey
8/8/2011	EP294	0	Monitoring construction activities
8/8/2011	EP300-EP312	0	Morning perimeter survey
8/8/2011	EP300-EP312	0	Monitoring construction activities
8/8/2011	EP300-EP312	0	Evening perimeter survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
8/8/2011	EP301-EP324, EP259-3, EP259B	0	Monitoring construction activities
8/8/2011	EP290-EP300	0	Site clearance survey
8/7/2011	I-8 Island	27	Evening perimeter survey at 6:00pm - 6:45
8/7/2011	EP263B-EP267	0	Site clearance survey
8/7/2011	EP270-EP271	0	Monitoring construction activities
8/7/2011	EP274-EP278	0	Monitoring construction activities
8/7/2011	EP279-294	0	Monitoring construction activities
8/7/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/7/2011	EP269-EP273	0	Evening perimeter survey
8/7/2011	EP300-EP312	0	Evening perimeter survey
8/6/2011	EP278 & EP277	0	Monitoring construction activities
8/6/2011	I-8 Island	12	Afternoon perimeter survey at 1:20pm
8/6/2011	EP263B-EP267	0	Site clearance survey
8/6/2011	EP269-EP271	0	Monitoring construction activities
8/6/2011	EP270-EP271	0	Monitoring construction activities
8/6/2011	EP274-EP278	0	Monitoring construction activities
8/6/2011	EP279-294	0	Monitoring construction activities
8/6/2011	EP300-EP306	0	Monitoring construction activities
8/6/2011	EP262, EP266, EP267	0	Site clearance survey
8/6/2011	EP269-EP273	0	Monitoring construction activities
8/6/2011	EP307-EP315	0	Morning perimeter survey
8/6/2011	EP307-EP316	0	Monitoring construction activities
8/6/2011	EP307-EP317	0	Evening perimeter survey
8/5/2011	EP263B-EP267	0	Site clearance survey
8/5/2011	EP271, EP273, EP274, EP277 and EP278	0	Monitoring construction activities
8/5/2011	EP274-EP278	0	Monitoring construction activities
8/5/2011	EP279-294	0	Monitoring construction activities
8/5/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/5/2011	EP269-EP273	0	Monitoring construction activities
8/5/2011	EP294	0	Monitoring construction activities
8/5/2011	EP307-EP312	0	Morning perimeter survey
8/5/2011	EP307-EP313	0	Monitoring construction activities
8/5/2011	EP307-EP314	0	Evening perimeter survey
8/4/2011	I-8 Island	23	Evening perimeter survey at 4:00pm - 4:33pm

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
8/4/2011	EP263B-EP267	0	Site clearance survey
8/4/2011	EP269-EP271	0	Monitoring construction activities
8/4/2011	EP270-EP271	0	Monitoring construction activities
8/4/2011	EP274-EP278	0	Monitoring construction activities
8/4/2011	EP279-294	0	Monitoring construction activities
8/4/2011	EP300-EP306	0	Monitoring construction activities
8/4/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/4/2011	EP269-EP273	0	Monitoring construction activities
8/4/2011	EP294	0	Monitoring construction activities
8/3/2011	I-8 Island	17	Evening perimeter survey at 5:45pm - 6:05pm
8/3/2011	EP256-EP263	0	Monitoring construction activities
8/3/2011	EP263B-EP267	0	Site clearance survey
8/3/2011	EP269-EP271	0	Monitoring construction activities
8/3/2011	EP270-EP271	0	Monitoring construction activities
8/3/2011	EP274-EP278	0	Monitoring construction activities
8/3/2011	EP279-294	0	Monitoring construction activities
8/3/2011	EP290-EP312	0	Monitoring construction activities
8/3/2011	EP300-EP306	0	Monitoring construction activities
8/3/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/3/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
8/3/2011	EP269-EP273	0	Monitoring construction activities
8/3/2011	EP271	0	Monitoring construction activities
8/3/2011	EP294	0	Monitoring construction activities
8/3/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/3/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/3/2011	I-8 Island	0	Monitoring construction activities
8/2/2011	I-8 Island	12	Morning perimeter survey at 9:50am
8/2/2011	I-8 Island	23	Evening perimeter survey at 4:30pm
8/2/2011	EP263B-EP267	0	Site clearance survey
8/2/2011	EP269-EP271	0	Monitoring construction activities
8/2/2011	EP270-EP271	0	Monitoring construction activities
8/2/2011	EP279-294	0	Monitoring construction activities
8/2/2011	EP300-EP306	0	Monitoring construction activities
8/2/2011	EP269/EP270 Pullsite	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
8/2/2011	EP269-EP273	0	Monitoring construction activities
8/2/2011	EP271 and EP273	0	Monitoring construction activities
8/2/2011	EP273	0	Monitoring construction activities
8/2/2011	EP274-EP278	0	Monitoring construction activities
8/2/2011	EP294	0	Monitoring construction activities
8/1/2011	I-8 Island	19	Morning perimeter survey at 10:00 - 10:20am
8/1/2011	I-8 Island	1	Evening perimeter survey at 4:30pm
8/1/2011	EP263B-EP267	0	Site clearance survey
8/1/2011	EP269-EP271	0	Monitoring construction activities
8/1/2011	EP270-EP271	0	Monitoring construction activities
8/1/2011	EP274-EP278	0	Monitoring construction activities
8/1/2011	EP279-294	0	Monitoring construction activities
8/1/2011	EP290-EP312	0	Monitoring construction activities
8/1/2011	EP300-EP306	0	Monitoring construction activities
8/1/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/1/2011	EP269	0	Monitoring construction activities
8/1/2011	EP269-EP273	0	Monitoring construction activities
8/1/2011	EP272	0	Monitoring construction activities
8/1/2011	EP291 & EP301-EP304	0	Monitoring construction activities
8/1/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/1/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
7/31/2011	I-8 Island	24	Evening perimeter survey at 5:55pm
7/31/2011	EP263B-EP267	0	Site clearance survey
7/31/2011	EP270-EP271	0	Monitoring construction activities
7/31/2011	EP274-EP278	0	Monitoring construction activities
7/31/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/31/2011	EP269-EP273	0	Evening perimeter survey
7/31/2011	EP279-EP294	0	Site clearance survey
7/31/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
7/30/2011	EP271	1	Morning perimeter survey at 7:00am
7/30/2011	EP256-EP263A-2, AER Yard	6	Monitoring during construction activities. These sheep were outside of all work areas and associated buffers and did not impact work.
7/30/2011	I-8 Island	11	Morning perimeter survey at 10:15am - 11:07
7/30/2011	I-8 Island	7	Evening perimeter survey at 4:12pm

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
7/30/2011	EP263B-EP267	0	Site clearance survey
7/30/2011	EP269	0	Site clearance survey
7/30/2011	EP269-EP272	0	Monitoring construction activities
7/30/2011	EP270-EP271	0	Monitoring construction activities
7/30/2011	EP274-EP278	0	Monitoring construction activities
7/30/2011	EP279-294	0	Monitoring construction activities
7/30/2011	EP300-EP306	0	Monitoring construction activities
7/30/2011	EP269	0	Monitoring construction activities
7/30/2011	EP269-EP273	0	Site clearance survey
7/30/2011	EP270-EP271	0	Monitoring construction activities
7/30/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
7/30/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
7/29/2011	I-8 Island	14	Morning perimeter survey at 8:55am
7/29/2011	I-8 Island	2	Evening perimeter survey at 4:00pm
7/29/2011	EP263B-EP267	0	Site clearance survey
7/29/2011	EP269	0	Site clearance survey
7/29/2011	EP269-EP272	0	Monitoring construction activities
7/29/2011	EP270-EP271	0	Monitoring construction activities
7/29/2011	EP274-EP278	0	Monitoring construction activities
7/29/2011	EP279-294	0	Monitoring construction activities
7/29/2011	EP300-EP306	0	Monitoring construction activities
7/29/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/29/2011	EP269	0	Monitoring construction activities
7/29/2011	EP269-EP273	0	Site clearance survey
7/29/2011	EP270	0	Monitoring construction activities
7/29/2011	EP300-EP312	0	Morning perimeter survey
7/29/2011	EP300-EP312	0	Monitoring construction activities
7/29/2011	EP300-EP312	0	Evening perimeter survey
7/29/2011	EP303	0	Monitoring construction activities
7/28/2011	EP269	4	Monitoring during construction activities
7/28/2011	I-8 Island	11	Morning perimeter survey at 9:19am
7/28/2011	I-8 Island	8	Evening perimeter survey at 4:00pm - 4:50pm
7/28/2011	EP279-294	0	Monitoring construction activities
7/28/2011	EP263B-EP267	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
7/28/2011	EP269	0	Site clearance survey
7/28/2011	EP270-EP271	0	Monitoring construction activities
7/28/2011	EP274-EP278	0	Monitoring construction activities
7/28/2011	EP300-EP306	0	Monitoring construction activities
7/28/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/28/2011	EP269	0	Monitoring construction activities
7/28/2011	EP270	0	Monitoring construction activities
7/28/2011	EP300-EP312	0	Morning perimeter survey
7/28/2011	EP300-EP312	0	Monitoring construction activities
7/28/2011	EP300-EP312	0	Evening perimeter survey
7/28/2011	AER CY	0	Site clearance survey
7/27/2011	I-8 Island	13	Evening perimeter survey at 6:30pm - 7:00pm
7/27/2011	EP279-294	0	Monitoring construction activities
7/27/2011	EP263B-EP267	0	Site clearance survey
7/27/2011	EP268 - EP263	0	Monitoring construction activities
7/27/2011	EP269	0	Site clearance survey
7/27/2011	EP270-EP271	0	Monitoring construction activities
7/27/2011	EP274-EP278	0	Monitoring construction activities
7/27/2011	EP300-EP306	0	Monitoring construction activities
7/27/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/27/2011	EP269-EP273	0	Morning perimeter survey
7/27/2011	EP269-EP273	0	Evening perimeter survey
7/27/2011	EP300-EP312	0	Morning perimeter survey
7/27/2011	EP300-EP312	0	Monitoring construction activities
7/27/2011	EP300-EP312	0	Evening perimeter survey
7/26/2011	Devils Canyon Bridge1, Hwy 8	1	Monitoring during construction activities
7/26/2011	I-8 Island	24	Morning perimeter survey at 9:46am - 10:45am
7/26/2011	I-8 Island	7	Evening perimeter survey at 6:17pm - 6:50pm
7/26/2011	EP263B-EP267	0	Site clearance survey
7/26/2011	EP269	0	Site clearance survey
7/26/2011	EP270	0	Monitoring construction activities
7/26/2011	EP274-EP278	0	Monitoring construction activities
7/26/2011	EP279-294	0	Monitoring construction activities
7/26/2011	EP300-EP306	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
7/26/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/26/2011	EP269-EP273	0	Morning perimeter survey
7/26/2011	EP269-EP273	0	Evening perimeter survey
7/26/2011	EP300-EP312	0	Monitoring construction activities
7/26/2011	EP300-EP312	0	Morning perimeter survey
7/26/2011	EP300-EP312	0	Monitoring construction activities
7/26/2011	EP300-EP312	0	Evening perimeter survey
7/25/2011	I-8 Island	21	Morning perimeter survey at 8:47am
7/25/2011	I-8 Island	20	Evening perimeter survey at 6:37am
7/25/2011	EP263B-EP267	0	Site clearance survey
7/25/2011	EP269	0	Site clearance survey
7/25/2011	EP270	0	Monitoring construction activities
7/25/2011	EP274-EP278	0	Monitoring construction activities
7/25/2011	EP279-294	0	Monitoring construction activities
7/25/2011	EP300-EP306	0	Monitoring construction activities
7/25/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/25/2011	EP269-EP273	0	Morning perimeter survey
7/25/2011	EP269-EP273	0	Evening perimeter survey
7/25/2011	EP300 & EP302	0	Monitoring construction activities
7/25/2011	EP300-EP312	0	Morning perimeter survey
7/25/2011	EP300-EP312	0	Monitoring construction activities
7/25/2011	EP300-EP312	0	Evening perimeter survey
7/25/2011	EP276	0	Monitoring construction activities
7/24/2011	I-8 Island	13	Evening perimeter survey at 6:25pm
7/24/2011	EP263B-EP267	0	Site clearance survey
7/24/2011	EP269	0	Site clearance survey
7/24/2011	EP270	0	Monitoring construction activities
7/24/2011	EP279-294	0	Monitoring construction activities
7/24/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/24/2011	EP269-EP273	0	Evening perimeter survey
7/24/2011	EP274-EP278	0	Evening perimeter survey
7/24/2011	EP300-EP312	0	Evening perimeter survey
7/23/2011	EP263B-EP267	0	Site clearance survey
7/23/2011	EP269	0	Site clearance survey



**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
7/23/2011	EP270	0	Monitoring construction activities
7/23/2011	EP279-294	0	Monitoring construction activities
7/23/2011	EP300-EP312	0	Monitoring construction activities
7/23/2011	EP300-EP312	0	Site clearance survey
7/23/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/23/2011	EP269-EP276	0	Morning perimeter survey
7/23/2011	EP274-EP278	0	Morning perimeter survey
7/23/2011	EP274-EP278	0	Evening perimeter survey
7/23/2011	I-8 Island	0	Morning perimeter survey
7/22/2011	I-8 Island	18	Evening perimeter survey at 6:35pm
7/22/2011	EP263B-EP267	0	Site clearance survey
7/22/2011	EP269	0	Site clearance survey
7/22/2011	EP269-EP270	0	Monitoring construction activities
7/22/2011	EP270	0	Monitoring construction activities
7/22/2011	EP300-EP312	0	Monitoring construction activities
7/22/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/22/2011	EP269-EP273	0	Morning perimeter survey
7/22/2011	EP269-EP273	0	Evening perimeter survey
7/22/2011	EP274-EP278	0	Site clearance survey
7/22/2011	EP274-EP278	0	Monitoring construction activities
7/21/2011	I-8 Island	18	Evening perimeter survey at 6:35pm
7/21/2011	EP263B-EP267	0	Site clearance survey
7/21/2011	EP269	0	Site clearance survey
7/21/2011	EP269-EP270	0	Monitoring construction activities
7/21/2011	EP270	0	Monitoring construction activities
7/21/2011	EP279-294	0	Monitoring construction activities
7/21/2011	EP300-EP312	0	Monitoring construction activities
7/21/2011	EP300-EP306	0	Site clearance survey
7/21/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/21/2011	EP269-EP273	0	Morning perimeter survey
7/21/2011	EP269-EP273	0	Evening perimeter survey
7/21/2011	EP274-EP278	0	Morning perimeter survey
7/21/2011	EP274-EP278	0	Evening perimeter survey
7/20/2011	I-8 Island	4	Evening perimeter survey at 6:50pm

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
7/20/2011	EP269-EP273	0	Morning perimeter survey
7/20/2011	EP269-EP273	0	Evening perimeter survey
7/20/2011	EP263B-EP267	0	Site clearance survey
7/20/2011	EP269	0	Site clearance survey
7/20/2011	EP270	0	Monitoring construction activities
7/20/2011	EP279-294	0	Monitoring construction activities
7/20/2011	EP300-EP312	0	Monitoring construction activities
7/20/2011	EP300-EP306	0	Site clearance survey
7/20/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/20/2011	EP274-EP278	0	Morning perimeter survey
7/20/2011	EP274-EP278	0	Evening perimeter survey
7/19/2011	I-8 Island	10	Morning perimeter survey at 9:10am
7/19/2011	I-8 Island	17	Evening perimeter survey at 4:00pm - 6:40pm
7/19/2011	EP269-EP273	0	Morning perimeter survey
7/19/2011	EP269-EP273	0	Evening perimeter survey
7/19/2011	EP269	0	Site clearance survey
7/19/2011	EP270	0	Monitoring construction activities
7/19/2011	EP279-294	0	Monitoring construction activities
7/19/2011	EP300-EP312	0	Monitoring construction activities
7/19/2011	EP300-EP306	0	Site clearance survey
7/19/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/19/2011	EP274-EP278	0	Morning perimeter survey
7/19/2011	EP274-EP278	0	Evening perimeter survey
7/19/2011	EP263B-EP267	0	Site clearance survey
7/18/2011	I-8 Island	21	Evening perimeter survey at 7:10pm
7/18/2011	EP263B-EP267	0	Site clearance survey
7/18/2011	EP269	0	Site clearance survey
7/18/2011	EP270	0	Monitoring construction activities
7/18/2011	EP279-294	0	Monitoring construction activities
7/18/2011	EP300-EP312	0	Monitoring construction activities
7/18/2011	EP300-EP306	0	Site clearance survey
7/18/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/18/2011	EP274-EP278	0	Morning perimeter survey
7/18/2011	EP274-EP278	0	Evening perimeter survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
7/18/2011	EP269-EP273	0	Site clearance survey
7/17/2011	I-8 Island	17	Evening perimeter survey at 5:55pm - 6:25
7/17/2011	EP263B-EP267	0	Site clearance survey
7/17/2011	EP269	0	Site clearance survey
7/17/2011	EP270	0	Monitoring construction activities
7/17/2011	EP300-EP312	0	Monitoring construction activities
7/17/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/17/2011	EP274-EP278	0	Evening perimeter survey
7/17/2011	EP279-EP294	0	Site clearance survey
7/17/2011	EP269-EP273	0	Site clearance survey
7/16/2011	I-8 Island	1	Morning perimeter survey at 8:35am
7/16/2011	EP263B-EP267	0	Site clearance survey
7/16/2011	EP269	0	Site clearance survey
7/16/2011	EP270	0	Monitoring construction activities
7/16/2011	EP300-EP306	0	Monitoring construction activities
7/16/2011	EP300-EP312	0	Monitoring construction activities
7/16/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/16/2011	EP274-EP278	0	Morning perimeter survey
7/16/2011	EP279-EP294	0	Morning perimeter survey
7/16/2011	EP279-EP294	0	Site clearance survey
7/16/2011	EP279-EP294	0	Monitoring construction activities
7/16/2011	EP269-EP273	0	Site clearance survey
7/15/2011	EP273-1	1	Evening perimeter survey at 4:30pm
7/15/2011	I-8 Island	12	Evening perimeter survey at 6:35pm - 7:00pm
7/15/2011	EP263B-EP267	0	Site clearance survey
7/15/2011	EP269	0	Site clearance survey
7/15/2011	EP270	0	Monitoring construction activities
7/15/2011	EP279-294	0	Monitoring construction activities
7/15/2011	EP300-EP306	0	Monitoring construction activities
7/15/2011	EP300-EP312	0	Monitoring construction activities
7/15/2011	EP256-EP263A-2, AER Yard	0	Site clearance survey
7/15/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/15/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/15/2011	EP269-EP273	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
7/15/2011	EP274-EP278	0	Morning perimeter survey
7/15/2011	EP274-EP278	0	Evening perimeter survey
7/14/2011	I-8 Island	3	Evening perimeter survey at 4:10pm
7/14/2011	I-8 Island		7:15am - 9:30am PBHS were at above point
7/14/2011	EP263B-EP267	0	Site clearance survey
7/14/2011	EP269	0	Site clearance survey
7/14/2011	EP270	0	Monitoring construction activities
7/14/2011	EP279-294	0	Monitoring construction activities
7/14/2011	EP300-EP306	0	Monitoring construction activities
7/14/2011	EP300-EP312	0	Monitoring construction activities
7/14/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/14/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/14/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/14/2011	EP274-EP278	0	Morning perimeter survey
7/14/2011	EP274-EP278	0	Evening perimeter survey
7/14/2011	EP269-EP273	0	Site clearance survey
7/13/2011	I-8 Island	21	Evening perimeter survey at 4:40pm
7/13/2011	EP263B-EP267	0	Site clearance survey
7/13/2011	EP269	0	Site clearance survey
7/13/2011	EP270	0	Monitoring construction activities
7/13/2011	EP279-294	0	Monitoring construction activities
7/13/2011	EP300-EP306	0	Monitoring construction activities
7/13/2011	EP300-EP312	0	Monitoring construction activities
7/13/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/13/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/13/2011	EP269-EP273	0	Site clearance survey
7/12/2011	EP256-EP263A-2, AER Yard	15	Monitoring during construction activities @ 7:40am - 11:00am
7/12/2011	I-8 Island	17	Evening perimeter survey at 4:00pm
7/12/2011	EP263B-EP267	0	Site clearance survey
7/12/2011	EP269	0	Site clearance survey
7/12/2011	EP270	0	Monitoring construction activities
7/12/2011	EP279-294	0	Monitoring construction activities
7/12/2011	EP300-EP306	0	Monitoring construction activities
7/12/2011	EP300-EP312	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
7/12/2011	EP274-EP278	0	Morning perimeter survey
7/12/2011	EP274-EP278	0	Evening perimeter survey
7/12/2011	EP269-EP273	0	Site clearance survey
7/11/2011	I-8 Island	29	Evening perimeter survey at 4:40pm
7/11/2011	EP263B-EP267	0	Site clearance survey
7/11/2011	EP269	0	Site clearance survey
7/11/2011	EP270	0	Monitoring construction activities
7/11/2011	EP279-294	0	Monitoring construction activities
7/11/2011	EP300-EP306	0	Monitoring construction activities
7/11/2011	EP300-EP312	0	Monitoring construction activities
7/11/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/11/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/11/2011	EP269-EP273	0	Site clearance survey
7/11/2011	EP274-EP278	0	Morning perimeter survey
7/11/2011	EP274-EP278	0	Evening perimeter survey
7/10/2011	I-8 Island	8	Perimeter survey
7/10/2011	I-8 Island	20	Monitoring construction activities
7/10/2011	EP269	0	Site clearance survey
7/10/2011	EP270	0	Monitoring construction activities
7/10/2011	EP279-294	0	Monitoring construction activities
7/10/2011	EP300-EP312	0	Monitoring construction activities
7/10/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/10/2011	EP274-EP278, EP265-EP267	0	Site clearance survey
7/9/2011	EP263A-2	11	Evening perimeter survey
7/9/2011	EP263B-EP267	0	Site clearance survey
7/9/2011	EP269-EP274	0	Monitoring construction activities
7/9/2011	EP279-294	0	Monitoring construction activities
7/9/2011	EP300-EP307	0	Monitoring construction activities
7/9/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/9/2011	EP269-EP273	0	Site clearance survey
7/9/2011	EP274-EP278	0	Morning perimeter survey
7/9/2011	EP310	0	Monitoring construction activities
7/8/2011	EP263B-EP267	0	Site clearance survey
7/8/2011	EP300-EP312	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number observed	Comments
7/8/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/8/2011	EP269-EP273	0	Site clearance survey
7/8/2011	EP274-EP278	0	Morning perimeter survey
7/8/2011	EP274-EP278	0	Evening perimeter survey
7/8/2011	EP303	0	Monitoring construction activities
7/8/2011	EP279-EP294	0	Monitoring construction activities
7/7/2011	I-8 Island	8	Evening perimeter survey at 7:00pm
7/7/2011	EP263B-EP267	0	Site clearance survey
7/7/2011	EP269-EP273	0	Monitoring construction activities
7/7/2011	EP300-EP312	0	Monitoring construction activities
7/7/2011	EP300-EP307	0	Monitoring construction activities
7/7/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/7/2011	EP269-EP273	0	Site clearance survey
7/7/2011	EP274-EP278	0	Morning perimeter survey
7/7/2011	EP274-EP278	0	Evening perimeter survey
7/7/2011	EP303 & EP304	0	Monitoring construction activities
7/7/2011	EP306-EP312	0	Site clearance survey
7/6/2011	EP263A-2	2	Evening perimeter survey
7/6/2011	EP263B-EP267	0	Site clearance survey
7/6/2011	EP269-EP272	0	Monitoring construction activities
7/6/2011	EP300-EP312	0	Monitoring construction activities
7/6/2011	EP300-EP307	0	Monitoring construction activities
7/6/2011	EP303	0	Site clearance survey
7/6/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/6/2011	EP274-EP278	0	Morning perimeter survey
7/6/2011	EP274-EP278	0	Evening perimeter survey
7/6/2011	EP305 to EP304	0	Monitoring construction activities
7/6/2011	I-8 Island	0	Monitoring construction activities
7/6/2011	EP269-EP273	0	Site clearance survey
7/5/2011	EP270	14	Morning perimeter survey at 6:30am - 10:00am
7/5/2011	EP270	9	Evening perimeter survey at 5:00pm
7/5/2011	I-8 Island	7	Evening perimeter survey at 6:20pm
7/5/2011	EP269-EP273	0	Morning perimeter survey
7/5/2011	EP269-EP273	0	Evening perimeter survey

**PBS Monitoring Report - Week Ending 12/31/2011**

<b>Date</b>	<b>Location</b>	<b>Number observed</b>	<b>Comments</b>
7/5/2011	EP263B-EP267	0	Site clearance survey
7/5/2011	EP269-EP271	0	Monitoring construction activities
7/5/2011	EP300-EP312	0	Monitoring construction activities
7/5/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/5/2011	EP274-EP278	0	Morning perimeter survey
7/5/2011	EP274-EP278	0	Evening perimeter survey
7/5/2011	EP307 to EP305	0	Monitoring construction activities
7/5/2011	I-8 Island	0	Site clearance survey
7/4/2011	EP270	9	Perimeter survey
7/4/2011	EP263B-EP267	0	Site clearance survey
7/4/2011	EP300-EP312	0	Monitoring construction activities
7/4/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/4/2011	EP269-EP273	0	Site clearance survey
7/4/2011	EP274-EP278	0	Evening perimeter survey
7/4/2011	I-8 Island	0	Site clearance survey
7/2/2011	EP263B-EP267	0	Site clearance survey
7/2/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/2/2011	EP269-EP273	0	Site clearance survey
7/2/2011	EP274-EP278	0	Morning perimeter survey
7/2/2011	I-8 Island	0	Site clearance survey
7/1/2011	EP263B-EP267	0	Site clearance survey
7/1/2011	EP300-EP312	0	Monitoring construction activities
7/1/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/1/2011	EP269-EP273	0	Site clearance survey
7/1/2011	EP274-EP278	0	Morning perimeter survey
7/1/2011	EP274-EP278	0	Evening perimeter survey
7/1/2011	I-8 Island	0	Site clearance survey
6/30/2011	EP300-EP312	0	Monitoring construction activities
6/29/2011	EP310-EP312	0	Monitoring construction activities
4/15/2011	EP210, EP211, EP213-EP215, EP217-EP219	0	Monitoring construction activities
3/26/2011	EP105	0	Site clearance survey

**Flat Tailed Horned Lizard Counts - Week Ending 12/31/2011**

Date	Location	Observed		Injured		Relocated		Dead	
		Day	Night	Day	Night	Day	Night	Day	Night
	Post RCLMP*								
11/1/2011	Dunaway CY					1			
10/13/2011	AR to EP354							1	
9/20/2011	AR btwn EP357 and EP358							1	
9/19/2011	AR btwn EP352 and EP353	1							
9/12/2011	EP325					1			
9/9/2011	AR to EP363	1							
9/6/2011	AR to EP360/361					1			
9/6/2011	EP360					2			
9/6/2011	EP359					1			
9/3/2011	SWPL AR to EP324					1			
9/3/2011	SWPL AR to EP342					1			
9/3/2011	SWPL AR to EP345							1	
9/3/2011	SWPL AR to EP344 and EP345					1			
8/31/2011	EP324					1			
8/31/2011	SWPL AR to EP325-2					1			
8/30/2011	SWPL AR to EP346 and EP347					1			
8/29/2011	SWPL AR to EP353 and EP354							1	
8/29/2011	SWPL AR to EP324							1	
8/27/2011	EP349					1			
8/25/2011	EP360							1	
8/25/2011	Btwn EP320/321					1			
8/24/2011	SWPL AR near EP346					1			
8/23/2011	EP349					1			
8/21/2011	SWPL AR btwn EP344/345					1			
8/21/2011	SWPL AR to EP345							1	
8/19/2011	SWPL AR to EP339					1			
8/20/2011	SWPL AR to IV Sub							1	
8/20/2011	SWPL AR btwn EP346/347					1			
8/19/2011	EP338/339 Pullsite					1			
8/19/2011	EP355/356 Pullsite					1			
8/18/2011	EP347					1			
8/18/2011	SWPL AR to EP353							1	
8/11/2011	SWPL AR by EP348					1			
8/11/2011	EP348/EP349 Pullsite					1			
8/10/2011	EP347					1			
8/8/2011	SWPL AR to EP351					2			
8/6/2011	BLM AR near EP327							1	
8/1/2011	IV Substation Yard	1							
8/1/2011	EP325					1			
8/1/2011	AR to EP345					1			
7/30/2011	EP322					1			
7/28/2011	EP355/EP356 Pullsite					1			
7/27/2011	Near EP316-2	1							



**Flat Tailed Horned Lizard Counts - Week Ending 12/31/2011**

Date	Location	Observed		Injured		Relocated		Dead	
Post RCLMP*		Day	Night	Day	Night	Day	Night	Day	Night
7/26/2011	SWPL AR to EP344	1							
7/26/2011	EP347					1			
7/26/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/22/2011	AR to IV Sub					1			
7/21/2011	EP360					1			
7/21/2011	AR to EP326					1			
7/19/2011	SWPL AR to IV Sub	1							
7/19/2011	EP353					1			
7/19/2011	AR to Dunaway CY					1			
7/18/2011	EP318					1			
7/17/2011	EP355					1			
7/15/2011	EP359	1							
7/15/2011	EP352	1							
7/15/2011	EP350	1							
7/14/2011	Spur Rd to EP355							1	
7/14/2011	EP322	1							
7/13/2011	EP357	1							
7/12/2011	EP344	1							
7/12/2011	SWPL AR btwn EP348/345							1	
<b>TOTAL POST RCLMP</b>		<b>12</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>43</b>	<b>0</b>	<b>12</b>	
Prior to RCLMP		Day		Day		Day		Day	
7/11/2011	AR to EP352					2			
7/11/2011	AR to EP345					2			
7/10/2011	EP358					1			
7/10/2011	SWPL AR to EP354					2			
7/9/2011	AR to EP330	1							
7/8/2011	Spur Rd. to EP352	1							
7/7/2011	EP324					1			
7/7/2011	EP355					1			
7/6/2011	SWPL AR btwn EP362/363							1	
7/5/2011	EP354					1			
7/1/2011	AR to EP353	1							
6/30/2011	AR between EP310/311							1	
6/30/2011	EP358	1							
6/30/2011	EP360	1							
6/30/2011	AR to EP312							1	
6/30/2011	EP360							1	
6/27/2011	EP350					1			
6/27/2011	SWPL AR to IV Substation	2							
6/26/2011	IV Substation					1			

**Flat Tailed Horned Lizard Counts - Week Ending 12/31/2011**

Date	Location	Observed	Injured	Relocated	Dead
6/25/2011	SWPL AR to EP361	1			
6/24/2011	EP359			1	
6/23/2011	SWPL AR to EP360			2	
6/22/2011	SWPL AR to EP355			1	
6/20/2011	EP356	2			
6/20/2011	SWPL AR to EP359	1			
6/20/2011	Near EP356	2			
6/20/2011	AR between EP358/357				1
6/18/2011	AR to Dunaway CY				1
6/17/2011	Near EP322	1			
6/7/2011	Near EP355	1			
6/7/2011	EP361			1	
6/7/2011	AR btwn EP343/EP344				1
6/7/2011	AR between EP324/325				1
6/6/2011	SWPL AR btwn EP344/EP345			1	
6/3/2011	EP359			1	
6/3/2011	SWPL AR EP362			1	
6/2/2011	AR to EP358			1	
6/2/2011	SWPL AR to EP316-2				1
6/2/2011	AR east of EP325				1
6/1/2011	SWPL AR btwn EP319/EP320			1	
6/1/2011	SWPL AR to EP318			1	
5/31/2011	SWPL AR btwn EP359/EP360			1	
5/31/2011	SWPL AR to EP320			1	
5/31/2011	EP360				1
5/27/2011	EP357			1	
5/26/2011	SWPL AR to EP359			1	
5/25/2011	Spur Rd to EP321			1	
5/23/2011	EP323			1	
5/21/2011	EP324			1	
5/20/2011	IV CY			1	
5/20/2011	AR to EP362			1	
5/20/2011	AR btwn EP324/EP325			1	
5/20/2011	SWPL AR btwn EP326/EP327			1	
5/20/2011	IV Substation			3	
5/19/2011	IV Substation			5	
5/19/2011	EP324			1	
5/18/2011	IV Substation Yard			1	
5/18/2011	IV Substation Yard				1
5/17/2011	AR to IV Substation				1
5/16/2011	IV Substation Yard			1	
5/13/2011	SWPL AR Near EP362-1	1			
5/12/2011	AR to EP355			1	
5/11/2011	EP360	1			

Flat Tailed Horned Lizard Counts - Week Ending 12/31/2011					
Date	Location	Observed	Injured	Relocated	Dead
5/11/2011	Dunaway CY	3			
5/11/2011	Dunaway Yard			4	
5/10/2011	EP322	1			
5/10/2011	AR to Dunaway CY	1			
5/9/2011	Dunaway Yard			4	
5/7/2011	EP322	1			
5/7/2011	Spur Road to EP344	1			
5/7/2011	Dunaway Yard			1	
5/6/2011	AR to EP321-1	1			
5/5/2011	AR to EP321-1	1			
5/5/2011	AR to Dunaway CY	2			
5/5/2011	Dunaway Yard			2	
5/4/2011	AR btwn EP343/EP344			1	
5/3/2011	SWPL AR btwn EP320/EP321	1			
4/27/2011	AR to EP322	2			
4/26/2011	EP322	1			
4/25/2011	Plaster City CY	1			
4/20/2011	Plaster City			1	
4/18/2011	Plaster City			1	
4/14/2011	AR to IV Substation	1			
4/2/2011	Dunaway CY	1			
<b>TOTAL PRIOR TO RCLMP</b>		<b>35</b>	<b>0</b>	<b>60</b>	<b>13</b>
<b>YTD</b>		<b>47</b>	<b>0</b>	<b>103</b>	<b>25</b>

\*RCLMP refers to the Revised Construction Lighting Mitigation Plan

**Raven Control Monitoring Report - Week Ending 12/31/2011**

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
12/31/2011	No ravens observed							
12/30/2011	No ravens observed							
12/29/2011	EP313-EP304 & EP295-EP292	2			2			no
12/28/2011	EP294	20			20			no
12/27/2011	EP292	2			2			
12/26/2011	EP292	2					2	no
12/25/2011	No ravens observed							
12/24/2011	EP281, EP281GS & EP290	5		5				no
12/23/2011	No ravens observed							
12/22/2011	EP300-1, EP301 & EP304	3		3				no
12/21/2011	No ravens observed							
12/20/2011	EP290-EP291/EP292 Pullsite	2			2			no
12/19/2011	No ravens observed							
12/18/2011	No ravens observed							
12/17/2011	EP325	1		1				no
12/17/2011	S2 Yard	3					3	no
12/16/2011	No ravens observed							
12/15/2011	IV Substation	1			1			no
12/15/2011	EP293	2		2				no
12/15/2011	S2 Yard	3					3	no
12/14/2011	S2 Yard	3					3	no
12/13/2011	S2 Yard	2					2	no
12/12/2011	S2 Yard	2					2	no
12/11/2011	S2 Yard	2					2	no
12/10/2011	EP306 & EP306/EP307 Pullsite	3		3				no
12/9/2011	IV Substation	1		1				no
12/9/2011	EP308 & EP306/EP307 Pullsite	2		2				no
12/9/2011	EP291 & EP291/EP292 Pullsite	2		2				no
12/8/2011	S2 Yard	3					3	no
12/8/2011	IV Substation	1		1				no
12/8/2011	EP301	2		2				no
12/8/2011	EP300-EP309	2		2				no
12/8/2011	EP291/EP292 Pullsite	2	2					no
12/8/2011	EP281	2		2				no
12/7/2011	IV Substation	1		1				no
12/7/2011	EP301	1			1			no
12/7/2011	EP291/EP292 Pullsite	1			1			no
12/7/2011	EP281	7		4	2	1		no
12/7/2011	S2 Yard	2			2			no
12/6/2011	S2 Yard	3				3		no
12/6/2011	EP301	2			2			no
12/6/2011	EP281	5		4		1		no
12/5/2011	S2 Yard	2					2	no
12/5/2011	IV Substation	2		2				no
12/5/2011	EP363	2		2				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
12/5/2011	EP281	6		6				no
12/4/2011	S2 Yard	3				3		no
12/4/2011	IV Substation	2		2				no
12/4/2011	Fromm CY	2				1	1	no
12/4/2011	EP294	1		1				no
12/3/2011	EP281	1		1				no
12/2/2011	IV Substation	1		1				no
12/1/2011	S2 Yard	2					2	no
11/30/2011	S2 Yard	2			2			no
11/29/2011	S2 Yard	2			2			no
11/28/2011	S2 Yard	4			4			no
11/28/2011	EP290-EP301	5		2	3			no
11/27/2011	S2 Yard	1		1				no
11/26/2011	No ravens observed							
11/25/2011	NO WORK: DAY AFTER THANKSGIVING							
11/24/2011	NO WORK: THANKSGIVING							
11/23/2011	Plaster City Yard	3					3	no
11/22/2011	S2 Yard	4			4			no
11/22/2011	IV Substation	1			1			no
11/21/2011	S2 Yard	4					4	no
11/21/2011	IV Substation	1		1				no
11/21/2011	EP281	2			2			no
11/20/2011	EP360	2			2			no
11/20/2011	IV Substation	2		2				no
11/19/2011	No ravens observed							
11/18/2011	EP358 and IV Substation	2		2				no
11/17/2011	No ravens observed							
11/16/2011	S2 Yard	5			5			no
11/15/2011	EP330-1	2					2	no
11/15/2011	EP304; EP330	1			1			no
11/14/2011	S2 Yard	6			6			no
11/13/2011	No ravens observed							
11/12/2011	Dunaway CY	1			1			no
11/11/2011	Dunaway CY	4					4	no
11/11/2011	S2 Yard	5					5	no
11/10/2011	Fromm CY	2					2	no
11/10/2011	EP355	1		1				no
11/9/2011	Dunaway CY	1			1			no
11/8/2011	S2 Yard	5			5			no
11/8/2011	Dunaway CY	2			2			no
11/7/2011	S2 Yard	3					3	no
11/7/2011	EP308-EP310	1					1	no
11/7/2011	EP301 Pullsite	7		6	1			no
11/6/2011	No ravens observed							
11/5/2011	S2 Yard	7			7			no
11/5/2011	IV Substation	1			1			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
11/4/2011	S2 Yard	5			5			no
11/3/2011	S2 Yard	5			3		2	no
11/3/2011	IV Substation	1			1			no
11/3/2011	Fromm CY	1				1		no
11/3/2011	EP303 and EP302	2			2			no
11/3/2011	EP281	2			2			no
11/2/2011	S2 Yard	4			4			no
11/2/2011	IV Substation	1		1				no
11/2/2011	EP305, EP310, EP311	1		1				no
11/1/2011	S2 Yard	2			2			no
11/1/2011	IV Substation	1		1				no
11/1/2011	EP305 and EP312	1			1			no
10/31/2011	S2 Yard	5			5			no
10/31/2011	AER and Fromm CY	1				1		no
10/30/2011	No ravens observed							
10/29/2011	IV Substation	3		3				no
10/28/2011	IV Substation	1		1				no
10/28/2011	EP256, EP357 & EP358	5		5				no
10/27/2011	EP356, EP358 & EP362	2		2				no
10/27/2011	EP305, EP307, EP310-EP312	1		1				no
10/26/2011	EP306, EP307 & EP310	2		2				no
10/25/2011	IV Substation	1		1				no
10/25/2011	EP310	1		1				no
10/24/2011	S2 Yard	3					3	no
10/24/2011	EP305	1			1			no
10/23/2011	S2 Yard	3			3			no
10/22/2011	No ravens observed							
10/21/2011	Dunaway CY	1			1			no
10/20/2011	S2 Yard	2					2	no
10/20/2011	Dunaway CY	5					5	no
10/19/2011	EP314	1		1				no
10/19/2011	EP290	5		5				no
10/18/2011	No ravens observed							
10/17/2011	EP301	3		3				no
10/16/2011	No ravens observed							
10/15/2011	S2 Yard	2					2	no
10/15/2011	Dunaway CY	1				1		no
10/15/2011	EP315	2					2	no
10/15/2011	EP301	3			3			no
10/14/2011	Fromm CY	3				3		no
10/14/2011	EP305	2		2				no
10/14/2011	EP301	3			3			no
10/13/2011	S2 Yard	2					2	no
10/13/2011	Dunaway CY	5					5	no
10/13/2011	Fromm CY	1					1	no
10/13/2011	EP354-EP363	2			2			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
10/13/2011	EP301	4		4				no
10/12/2011	EP300-EP301	2		2				no
10/11/2011	Plaster City Yard	2			2			no
10/11/2011	IV Substation	2					2	no
10/10/2011	Fromm CY	2				2		no
10/10/2011	EP359-EP360	2		2				no
10/10/2011	EP355-EP363	2		2				no
10/10/2011	EP301	3		3				no
10/9/2011	S2 Yard	3					3	no
10/9/2011	EP300	6		6				no
10/8/2011	EP357	2			2			no
10/8/2011	EP306	3					3	no
10/7/2011	Dunaway CY	1		1				no
10/7/2011	EP291-EP301	3		3				no
10/6/2011	Fromm CY	2					2	no
10/5/2011	Dunaway CY	2		2				no
10/5/2011	EP303-2	2		2				no
10/4/2011	EP310 & EP311	2		2				no
10/4/2011	EP301	3					3	no
10/4/2011	EP293	2		2				no
10/3/2011	S2 Yard	2					2	no
10/3/2011	Dunaway CY	2			2			no
10/2/2011	EP356-EP363	2		1	1			no
10/1/2011	Plaster City Yard	2					2	no
10/1/2011	EP360	2			2			no
9/30/2011	S2 Yard	2					2	no
9/30/2011	EP355	1		1				no
9/30/2011	EP314	2		2				no
9/30/2011	EP301	2		1	1			no
9/29/2011	EP291/EP292 Pullsite	1			1			no
9/28/2011	EP361	1			1			no
9/27/2011	EP315	2		1	1			no
9/27/2011	EP309	1		1				no
9/27/2011	EP301 & EP304	4		3	1			no
9/27/2011	EP290	1			1			no
9/26/2011	EP362	2			2			no
9/26/2011	Fromm CY	1				1		no
9/25/2011	No ravens observed							
9/24/2011	Plaster City Yard	2					2	no
9/24/2011	EP317	1		1				no
9/24/2011	EP309	1		1				no
9/23/2011	EP362	4			4			no
9/23/2011	EP303	2		2				no
9/22/2011	Fromm CY	1				1		no
9/22/2011	EP303	2		2				no
9/22/2011	EP301	2		2				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
9/22/2011	EP295-EP322	3		3				no
9/21/2011	S2 Yard	3			3			no
9/21/2011	Fromm CY	1					1	no
9/21/2011	EP303	1		1				no
9/20/2011	S2 Yard	2			2			no
9/20/2011	Fromm CY	1				1		no
9/19/2011	S2 Yard	3			3			no
9/19/2011	EP304, EP307, EP309	1		1				no
9/18/2011	S2 Yard	3				3		no
9/18/2011	EP281	1		1				no
9/17/2011	S2 Yard	3					3	no
9/17/2011	EP362	1			1			no
9/17/2011	Fromm CY	3				3		no
9/16/2011	EP363	2			2			no
9/16/2011	Fromm CY	1					1	no
9/16/2011	EP304	2		2				no
9/16/2011	EP290	1		1				no
9/15/2011	S2 Yard	4			4			no
9/15/2011	Fromm CY	3					3	no
9/15/2011	EP296	1		1				no
9/15/2011	EP306	2					2	no
9/15/2011	EP304	1		1				no
9/15/2011	EP301	2		2				no
9/14/2011	Plaster City Yard	1			1			no
9/14/2011	EP361	2			2			no
9/14/2011	Fromm CY	1				1		no
9/14/2011	EP308	1					1	no
9/14/2011	EP301	5		4	1			no
9/14/2011	EP292	3		3				no
9/13/2011	S2 Yard	10			10			no
9/13/2011	EP348	3		3				no
9/13/2011	EP345	2		2				no
9/13/2011	EP326	1					1	no
9/13/2011	EP325	2		2				no
9/13/2011	EP326	1		1				no
9/13/2011	EP304	7		7				no
9/13/2011	EP291	7		7				no
9/12/2011	S2 Yard	3			3			no
9/12/2011	EP350	1		1				no
9/12/2011	EP304	1		1				no
9/12/2011	EP301	1		1				no
9/11/2011	S2 Yard	2				2		no
9/10/2011	S2 Yard	2					2	no
9/9/2011	EP304	1			1			no
9/8/2011	S2 Yard	3					3	no
9/7/2011	S2 Yard	3					3	no



Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
9/6/2011			No ravens observed					
9/5/2011			No ravens observed					
9/4/2011			No ravens observed					
9/3/2011			No ravens observed					
9/2/2011	EP348	1		1				no
9/2/2011	S2 Yard	1		1				no
9/2/2011	EP303	1		1				no
9/2/2011	EP363	2		2				1 at IV Sub
9/1/2011	EP303	2					2	no
9/1/2011	EP293	1					1	no
9/1/2011	EP304	2					2	no
8/31/2011	S2 Yard	1		1				no
8/31/2011	EP308	1		1				no
8/31/2011	EP305-3	2					2	no
8/31/2011	EP303	2		2				no
8/30/2011	EP303	1		1				no
8/29/2011	S2 Yard	1		1				no
8/29/2011	EP303	1		1				no
8/28/2011			No ravens observed					
8/27/2011	EP305	3			3			no
8/26/2011	EP301	2		2				no
8/25/2011	S2 Yard	2					2	no
8/25/2011	EP301	2		2				no
8/24/2011	S2 Yard	3				3		no
8/23/2011	EP292-1	3		3				no
8/22/2011			No ravens observed					
8/21/2011			No ravens observed					
8/20/2011	S2 Yard	2				2		no
8/20/2011	EP312	2		2				no
8/20/2011	S2 Yard	2					2	no
8/20/2011	EP312	2		2				no
8/19/2011	EP307	2			2			no
8/19/2011	EP296	1		1				no
8/18/2011	S2 Yard	2				1	1	no
8/18/2011	EP301	Flock		x				no
8/17/2011	S2 Yard	2				1	1	no
8/17/2011	EP301	3			3			no
8/16/2011	S2 Yard	1					1	no
8/16/2011	EP301	1		1				no
8/15/2011			No ravens observed					
8/14/2011			No ravens observed					
8/13/2011	S2 Yard	2					2	no
8/12/2011	IV Substation	2				2		no
8/12/2011	S2 Yard	3				3	3	no
8/11/2011	EP294	4			4			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
8/11/2011	S2 Yard	3				3	3	no
8/10/2011	S2 Yard	3				2	1	no
8/9/2011	S2 Yard	not specified						no
8/8/2011	EP294	2			2			no
8/8/2011	S2 Yard	1						no
8/7/2011	No ravens observed							
8/6/2011	S2 Yard	1						no
8/5/2011	EP301	3		3				no
8/4/2011	S2 Yard	not specified						no
8/3/2011	S2 Yard	2		2				no
8/3/2011	S2 Yard	1						no
8/2/2011	S2 Yard	3					3	no
8/1/2011	EP314	not specified		x				no
7/31/2011	No ravens observed							
7/30/2011	EP314	3		2			1	no
7/30/2011	S2 Yard	1					1	no
7/29/2011	S2 Yard	1						no
7/28/2011	EP319	4	1	2	1			no
7/28/2011	S2 Yard	not specified						no
7/27/2011	S2 Yard	not specified						no
7/26/2011	No ravens observed							
7/25/2011	EP290	1			1			no
7/24/2011	No ravens observed							
7/23/2011	No ravens observed							
7/22/2011	EP290	2		1	1			no
7/21/2011	S2 Yard	1		1				no
7/20/2011	Ocotillo, CA	5						no
7/19/2011	Ocotillo, CA	1						no
7/18/2011	CP40-2	not specified						no
7/18/2011	CP41-2	not specified						no
7/18/2011	CP42-1	not specified						no
7/17/2011	No ravens observed							
7/16/2011	CP42-1	not specified						no
7/15/2011	No ravens observed							
7/14/2011	EP357	not specified						no
7/14/2011	EP358	not specified						no
7/14/2011	EP359	not specified						no
7/14/2011	Plaster City Yard	2		2				no
7/13/2011	EP313-EP314 PS	not specified						no
7/13/2011	S2 Yard	3					3	no
7/12/2011	CP18-1	not specified						no
7/12/2011	CP19-1	not specified						no
7/12/2011	CP22-1	not specified						no
7/11/2011	EP304-EP314	not specified						no
7/10/2011	No ravens observed							
7/9/2011	EP351	not specified						no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
7/9/2011	EP353	not specified						no
7/9/2011	EP354	not specified						no
7/9/2011	EP355	not specified						no
7/9/2011	not specified	not specified						no
7/9/2011	S2 Yard	3					3	no
7/8/2011	EP303	2			1		1	no
7/8/2011	EP303	1		1				no
7/8/2011	S2 Yard	3					3	no
7/1/11-7/7/11	No ravens observed							
6/30/2011	EP300	3		3				no
6/21/11-6/29/11	No ravens observed							
6/20/2011	S2 Yard	2					2	no
6/1/11-6/19/11	No ravens observed							
5/1/11-5/31/11	No ravens observed							
4/22/11-4/30/11	No ravens observed							
4/21/2011	EP341	1	1					no
4/1/11-4/20/11	No ravens observed							
3/1/11-3/31/11	No ravens observed							
2/1/11-2/28/11	No ravens observed							
1/21/11-1/31/11	No ravens observed							
1/21/2011	Rough Acres Yard	not specified						no