

This report provides a summary of environmental monitoring and compliance activities conducted by Burns and McDonnell (BMcD) staff and BMCd subconsultants for the San Diego Gas & Electric (SDG&E) Sunrise Powerlink Project during the above weekly time period.

Training

- SWEAP and PBS training continued for new Project personnel every Tuesday and Thursday. Additional trainings were provided as requested.
- Flat-tailed horned lizard (FTHL) trainings were provided to any new crew members or monitors prior to construction per mitigation measure B-7b and in accordance with the FTHL Rangewide Management Strategy. During morning tailboard meetings, guidelines were provided about recognizing, protecting, and notification requirements for FTHL. FTHL information cards were made available to any crew members or monitors as needed.

Pre/Post Construction

- Avian biologists surveyed for nesting birds prior to work commencing in inactive areas. For sites off of USFS lands, the results of those surveys were submitted to the CPUC/BLM biologist for review and concurrence. For USFS lands, the results of those surveys were submitted to the USFS for review and concurrence. For any active nests found, a buffer was established and no construction activities were permitted within the buffer area without consultation with the CPUC/BLM/USFS biologist. Active nests were mapped and monitored for success or failure and updated on the nest monitoring log.
- Staked, flagged, and refreshed work areas near EP54-2 and EP215.
- Post construction impact survey of structure work area near EP78/EP78A TEWS, EP78A/EP19 access road, EP92 to EP94, EP225-1/EP226-1 pull site, EP226-1, EP227, EP228, EP229, EP230-1, EP231-1, EP231A, EP233-1, and EP234-1.
- Additional signs and stakes were repaired as needed. Due to traffic and narrow access roads, broken stakes and run over signs were replaced. Maintenance (e.g., writing over faded signs, reinforcing signs/stakes in the ground, replacing zip ties, and adding additional signs) was performed as needed. The ESA Team conducted the following activities during this reporting period:
 - Repaired, refreshed, replaced, and maintained the previously installed project signs and ESAs from access road to Helix Yard, access road to EP90, access road to Bartlett Hauser, access road to Kruetzkamp Yard, access road to EP205 thru EP173, access road to Thing Valley, McCain Valley Road towards McCain Yard, access road to EP127, EP129, EP130, access road to EP52, EP47, and EP57.

Construction

- Monitors were present during construction activities to ensure compliance with mitigation measures as identified in the Final EIR/EIS Mitigation Monitoring, Compliance, and Reporting Program. Archaeologists, Paleontologists, and Native American Monitors were present at sites where required as identified prior to construction activity and as approved in the NTPs. On average, the following number of monitors were on the Project throughout the week:
 - 128 Biological monitors.
 - 2 Archaeological monitors.
 - 2 Native American monitors.



Sunrise Powerlink Project
Weekly Report 82 – April 08, 2012 through April 14, 2012



- 8 SWPPP monitors.
- Project staff carpooled to site reviews, kick-off tailgates, and off-site meetings. Construction and traffic control crews were observed carpooling from yards to work areas.
- Deterrents were utilized to discourage bird nest building activities throughout the Project. Deterrents are determined depending upon the location and type of possible nesting areas and may include metallic flagging, compact discs, plastic owls, and the presence of biological monitors.
- The table below demonstrates the construction progress to date:

OVERHEAD			
Agency	Foundations Completed	Towers Erected	Wire Installed
Non-Federal	168 of 169	146 of 169	111 of 169 EP237-1 to EP243
Bureau of Land Management	175 of 179	151 of 179	121 of 179
Miramar	14 of 14	14 of 14	11 of 14
U.S. Forest Service	75 of 76	26 of 76	17 of 76
UNDERGROUND			
Agency	Vaults Installed	Trenches Excavated & Backfilled	
Non-Federal	40 of 40	42 of 42	
SUBSTATION UPGRADES			
3 of 7 Completed			
SUNCREST SUBSTATION			
99 Percent Complete			

Overhead Construction

- Link 1
 - Vegetation maintenance at EP143-1, EP144, EP146, EP147, and EP150.
 - Final grading at/from EP179 to EP181, EP180-N to EP182-N, EP184-1, and EP185-1.
 - Hydro-mulching from EP206-1 to EP209-1.
 - Micropile capping work at EP149-1 and EP152-2.
 - QA/QC at EP196-2, EP252A-1, and EP254-3.
 - Tower assembly at EP145, EP150, EP151, EP152-2, and EP254-3.
 - Fiber splicing at EP215, EP200-3, EP220-1, and EP226-1.
 - Deadend work at EP196-2, EP198-3, and EP255-2.
 - Clipping in at/from EP197-3 to EP199-3, and EP236-1 to EP243/EP244 pull site.
 - Sagging from EP187-2 pull site to EP200-3 pull site and EP236-1 to EP243/EP244 pull site.
 - Spacers installed from EP235-1 to EP242.
 - Sleeving and removal of snubs at EP243/EP244 pull site.
 - OPGW flown and sagged from EP187-2 pull site north to EP200-3 pull site.
 - Conductor flown for B and C phases from EP187-2 pull site to EP200-3 pull site.
 - Clipping in OPGW at EP196-2.
 - Sockline, hardline, and conductor flown for all phases from EP243/EP244 pull site to EP255-2 pull site.
 - Traveler work at EP252-1 and EP253-2.
 - Demobilization of equipment from EP187-2, EP193-1, and EP254-3.
 - Staging equipment at EP255-2 pull site.
Regen work at EP215.
 - Cleanup at EP243/EP244 pull site.
 - Guard structure work at EP243, EP247, EP251, and EP252-1.
 - BMP maintenance at/from:
 - EP148-1, EP170 to EP209-1 (including pull sites), EP175-1-E to EP192-2-E, EP211 to EP215 pull sites, EP217-1 to EP221A (including guard structure and pull sites), EP223-1 to EP229-1 (including pull site), EP231-1 to EP238-1 (including pull site), EP239-1, EP242, EP243 to EP246 (including pull site), EP248-1 to EP255-2 (including pull sites), EP314, EP315-1, EP317, GS-BLM-1A, GS-NF-31, and GS-NF-36.
- Link 2
 - During this reporting period, the PAL levels were as follows: Monday-D, Tuesday-D, Wednesday-A, Thursday-A, Friday-A, and Saturday-A. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

- Access road construction/maintenance at EP78-E.
- Gate work at EP116-1-E.
- Grouting prep at EP28-3 and EP58-2.
- Grouting at EP3-3, EP16-1, and EP21-1.
- Micropile trimming at EP120-4.
Micropile pull testing at EP3-3, EP10-2, EP13-3, EP15, EP16-1, EP21-1, EP23-2, EP35-1, EP58-2, EP114-2, and EP115-1.
- Micropile capping work at EP13-3, EP15, EP108-2, EP110-2, EP111-4, EP115-1, EP120-4, EP120A, EP121-3, EP121A-1, and EP124.

- Tower assembly at EP2-3, EP3-3, EP9-1, EP11-3, EP13-3, EP16-1, EP28-3, EP111-4, EP112-3, and EP113-5.
- QA/QC at EP13-3, EP15, and EP16-1.
- Ground rod installation at EP11-3 and EP12-3.
- Ground resistance testing from EP109-2 to EP111-4.
- BMP maintenance at/from:
 - EP2-3, EP4-3, EP9-1 to EP12-3 (including pull sites and guard structure), EP22-1 to EP24-1, EP28-3, EP29-2, EP33-1 to EP37-2, EP110-2, EP113-5, EP116-1, EP117-2, EP120-4, EP120A, EP121A-1 to EP131 (including pull site), EP125-E-A to EP131-E, EP142-1, and EP143-1.
- Weed abatement at EP124/EP125 pull site, EP127, EP130-1, EP131, and EP131-N.

BLM Land

- Access road construction/maintenance at EP71-E, EP72-E, and EP73-1-E-C.
- Gate work at EP101-2-PS-E.
- Micropile drilling at EP56-4, EP69, and EP70.
- Micropile grouting prep at EP70.
- Micropile grouting at EP56-4, EP63, and EP72.
- Micropile trimming at EP71, EP72, and EP73-1.
- Micropile pull test prep at EP41.
- Micropile pull testing at EP48, EP50, EP74-1, EP75-2, and EP76-2.
- Micropile capping work at EP56-4, EP69, and EP102A-1.
- Ground resistance testing at EP68.
- BMP installation/maintenance at/from:
 - EP39-1, EP40-1, EP42, EP42-N, EP42 pull site, EP47-2, EP47-2 pull site, EP48, EP71 to EP74-1, EP76-2, EP94 to EP101-2 (including pull site and access roads), and EP102A-1 to EP103A.

Non-Federal Land

- Vegetation maintenance from EP91 to EP93 (including access roads).
- Access road construction/maintenance at EP78-E, EP79-E-A, EP79-E-B, and CY-BARTLETT-E.
- Micropile drilling at EP52-1, EP64, and EP77.
- Micropile grouting at EP62A-1.
- Micropile trimming at EP77.
- Micropile pull test prep at EP77.
- Micropile pull test at EP62A-1 and EP78.
- Micropile capping work at EP52-1, EP78, EP78A, and EP82.
- Tower assembly at EP1-3, EP30-2, EP30-2 pull site, EP81, EP83, EP85-2, EP87-1, EP88-2, and EP105-2.
- Ground rod installation at EP81.
- Ground resistance testing at EP65-1, EP87-1, and EP88-2.
- BMP installation/maintenance at/from:
 - EP25-2, EP26-1, EP30-2, EP30-2 pull site, EP31-1, EP32-1, EP67, EP67 pull site, EP77 to EP80 (including pull site), EP82 to EP84 (including pull sites), CY-BARTLETT-E, EP86-1, EP87-1, EP89-1, EP89-1 pull sites, EP91, EP91 pull sites, EP93, EP104-2 to EP107-3, EP119-2, GS-NF-16, GS-NF-17, GS-NF-18, GS-NF-22, and GS-NF-26.
- Weed abatement at EP30-2 pull site.

- Link 5



Sunrise Powerlink Project
Weekly Report 82 – April 08, 2012 through April 14, 2012



- During this reporting period, the PAL Levels were as follows: Monday-D, Tuesday-D, Wednesday-A, Thursday-A, Friday-A, and Saturday-A. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

- BMP maintenance at CP99-2 and CP100-1.

BLM Land

- No work occurred this reporting period.

Non-Federal Land

- Final grade at CP65-1 pull site.
- Grouting at CP83.
- Miscellaneous tower work at/from CP84 to CP86.
- QA/QC at/from CP32-2 to CP33A, CP35-2, CP36-1, CP62-2, and CP84.
- Concrete blocks removed from CP35-2.
- Sock line, haulback, and conductor pulled on all phases from CP49-1 to CP55.
- Sagging from CP49-1 to CP55.
- Spacers installed from CP43-1 to CP49-1.
- OPGW flown from CP48-2 to CP55.
- Cleanup at CP81-1, CP83, and CP86.
- BMP installation and maintenance at:
 - CP16-1 to CP19-1, CP21 to CP27 (including pull sites and guard structure), CP28-1, CP29-1, CP31-2, CP31-2 pull site east, CP32-2, CP33A, EP35-2, EP36-1, CP39-E to 41-2-E, CP37-2 to CP54-1, CP43-1 pull sites, CP43-1 guard structure, CP44-1 guard structure, CP49-1-PS-N, CP54-1, CP55 ARD, CP56-1 pull site, CP57, CP65-1 pull site, CP85-1 to CP88-1 (including pull site), CP95-1, CP95/CP96 pull site, CP96-1, CP98-1, CP109-1, GS-NF-2, and GS-NF-3.
- Restoration at CP65-1 pull site.

Miramar

- Access road construction/maintenance at CP10 and CP11-1.
- Final grade at CP6-1 and CP7.
- BMP installation and maintenance at CP2, CP3, CP3 pull site, CP6-1 to CP9-1, CP12-1, CP14, and CP15-1.

69kV

- No work occurred during this reporting period.

Underground Construction (Link 4)

- Revitalization, BMP Maintenance & Installation, and Grounding – Alpine Blvd.
- Termination Repair – Loritz & Slay properties.
- Sending and Receiving/Cooling Line – CalTrans Bore Site.
- Work inside MH4, MH5, and MH6.
- Racking inside V13L, V15L, and V20.

Suncrest Substation Construction (Link 3)

- Clean-up activities along Bell Bluff Truck Trail.
- Contractor materials clean-up.
- Silt fence clean-up activities along Bell Bluff Truck Trail.



Sunrise Powerlink Project
Weekly Report 82 – April 08, 2012 through April 14, 2012



- Restoring temporary impact area near the office trailer.
- Wiring inside the control shelter.
- Interior work on the warehouse.
- Fence installation around the perimeter of substation pad.
- Spreading class 2 base in the southeast quadrant and finish grading.
- Pouring concrete retaining wall on Bell Bluff Truck Trail near Japatul Valley Road.
- Stripping form on the concrete retaining wall on Bell Bluff Truck Trail.
- Landscape and irrigation installation.
- Electrical testing.
- BMP maintenance and installation during rain events.
- Installation of jute netting on the eastern slopes of the substation pad and on cut slopes.

Substation Upgrades

San Luis Rey:

- Wiring crews working inside the control house.

Encina:

- SDG&E relay and wiring crews performing wiring near the control house.
- SDG&E crews installing a new gas circuit breaker, disconnects, and wiring in Bays 1 – 3
- The oil circuit breakers in Bay 3 east were drained and removed.
- An avian sweep was conducted of the entire switchyard. One inactive stick nest was identified within 200 feet of the current construction activities.

Scripps:

- No Sunrise-related work.

Pomerado:

- Work scheduled to start when crews finish current Encina work package.

Sycamore:

- SDG&E Kearny Mesa crews worked on 69 kV bus upgrades and testing new gas circuit breakers that were placed inside the 69kV rack.
- Wiring for Bank 70 transformer.
- Wire drops to transformers.
- Wiring from rack to transformers.

Imperial Valley:

- No Sunrise-related work.

Construction Yards

- Sycamore Yard – Dust suppression, helicopter operations, water staging, vegetation maintenance, and staging for assembly and road crews.
- Helix Yard – Helicopter operations, weed wash station, dust suppression, and staging for assembly, wire, road, BMP and QC crews.
- El Monte Yard – No activity.
- Alpine Yard – Equipment/Materials staging, water staging, dust suppression, weed wash station, and staging for QC and BMP crews.
- Wilson Yard – Helicopter operations, dust suppression, tower assembly, and staging for assembly

- and erection crews.
- SWAT Yard – Water staging, helicopter operations, dust suppression, weed wash station, tower assembly, and staging for micropile, weed, erection, and BMP crews.
 - Barrett Canyon Yard – No activity.
 - Kreutzkamp Yard – Helicopter operations, weed wash station, water staging, dust suppression, vegetation maintenance, and staging for road, regen, micropile, and BMP crews.
 - Bartlett-Hauser Yard – Water staging, helicopter operations, weed wash station, dust suppression, weed treatment, tower assembly, and staging for micropile, erection, road, QC, and BMP crews.
 - Thing Valley Yard – Helicopter operations, water staging, dust suppression, tower assembly, hauling steel to yard, and staging for QC, weed treatment, and micropile crews.
 - McCain Valley Yard – Helicopter operations, water staging, dust suppression, tower hookers, tower assembly, and hauling steel.
 - Rough Acres Yard – Helicopter operations, water staging, dust suppression, tower assembly, material hauling and staging, weed wash station, and staging for erection, QC, hauling, road, wire, conventional foundation, ESA, vegetation maintenance, micropile, and BMP crews.
 - Jacumba Valley Ranch (JVR) Yard – Helicopter operations, weed wash station, water staging, dust suppression, and staging for QC crews.
 - Plaster City Yard – Restoration largely complete.
 - S2 Yard – No activity, restoration complete.

Wildlife Reporting

The following listed or Species of Special Concern were found dead in Project construction limits during this reporting period:

- Two-striped Garter Snake (*Thamnophis hammondi*) – Three (3) two-striped garter snakes were found dead; two (2) in Kreutzkamp Yard and one (1) in the access road adjacent to EP63.

The following listed or Species of Special Concern were relocated during construction activities this reporting period:

- Two-striped Garter Snake (*Thamnophis hammondi*) – Four (4) two-striped garter snakes were relocated; three (3) from Kreutzkamp Yard and one (1) from the access road to Kreutzkamp Yard.
- Coast Horned Lizard (*Phrynosoma coronatum blainvillii*) – Two (2) coast horned lizards were relocated; one (1) from EP124 and one (1) from EP54.

Spills/Hazardous Waste

- Minor leaks, drips, and releases on USFS lands were submitted to the USFS in a weekly HazMat log.
- No reportable spills occurred outside the USFS during this reporting period.

Customer Complaints

- No customer complaints were received during this reporting period.

Non-Compliances

- CPUC Non Compliance #6 was received on April 13, 2012, for repeatedly carrying loads without appropriate netting.



Variances and TEWS

- No new variiances or TEWS were approved during this reporting period.

Weather

- Rain events occurred from April 9, 2012 to April 14, 2012.
- BMPs were installed or maintained as needed throughout Project areas. In accordance with the Construction General Permit (CGP), daily site BMP inspections, and photos, appropriate BMPs for stormwater and non-stormwater were implemented. Any sites requiring repairs began within 72 hours of identification.

Appendices

Flat-Tailed Horned Lizard Monitoring Report

Raven Control Monitoring Report

Flat Tailed Horned Lizard Counts - Week Ending 04/14/2012

Date	Location	Observed		Injured		Relocated		Dead	
		Day	Night	Day	Night	Day	Night	Day	Night
	Post RCLMP*								
2/23/2012	West side of AR to EP324	1							
11/1/2011	Dunaway CY					1			
10/13/2011	AR to EP354							1	
9/20/2011	AR btwn EP357 and EP358							1	
9/19/2011	AR btwn EP352 and EP353	1							
9/12/2011	EP325					1			
9/9/2011	AR to EP363	1							
9/6/2011	AR to EP360/361					1			
9/6/2011	EP360					2			
9/6/2011	EP359					1			
9/3/2011	SWPL AR to EP324					1			
9/3/2011	SWPL AR to EP342					1			
9/3/2011	SWPL AR to EP345							1	
9/3/2011	SWPL AR to EP344 and EP345					1			
8/31/2011	EP324					1			
8/31/2011	SWPL AR to EP325-2					1			
8/30/2011	SWPL AR to EP346 and EP347					1			
8/29/2011	SWPL AR to EP353 and EP354							1	
8/29/2011	SWPL AR to EP324							1	
8/27/2011	EP349					1			
8/25/2011	EP360							1	
8/25/2011	Btwn EP320/321					1			
8/24/2011	SWPL AR near EP346					1			
8/23/2011	EP349					1			
8/21/2011	SWPL AR btwn EP344/345					1			
8/21/2011	SWPL AR to EP345							1	
8/19/2011	SWPL AR to EP339					1			
8/20/2011	SWPL AR to IV Sub							1	
8/20/2011	SWPL AR btwn EP346/347					1			
8/19/2011	EP338/339 Pullsite					1			
8/19/2011	EP355/356 Pullsite					1			
8/18/2011	EP347					1			
8/18/2011	SWPL AR to EP353							1	
8/11/2011	SWPL AR by EP348					1			
8/11/2011	EP348/EP349 Pullsite					1			
8/10/2011	EP347					1			
8/8/2011	SWPL AR to EP351					2			
8/6/2011	BLM AR near EP327							1	
8/1/2011	IV Substation Yard	1							
8/1/2011	EP325					1			
8/1/2011	AR to EP345					1			
7/30/2011	EP322					1			
7/28/2011	EP355/EP356 Pullsite					1			

Flat Tailed Horned Lizard Counts - Week Ending 04/14/2012

Date	Location	Observed		Injured		Relocated		Dead	
7/27/2011	Near EP316-2	1							
7/26/2011	SWPL AR to EP344	1							
Post RCLMP*		Day	Night	Day	Night	Day	Night	Day	Night
7/26/2011	EP347					1			
7/26/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/22/2011	AR to IV Sub					1			
7/21/2011	EP360					1			
7/21/2011	AR to EP326					1			
7/19/2011	SWPL AR to IV Sub	1							
7/19/2011	EP353					1			
7/19/2011	AR to Dunaway CY					1			
7/18/2011	EP318					1			
7/17/2011	EP355					1			
7/15/2011	EP359	1							
7/15/2011	EP352	1							
7/15/2011	EP350	1							
7/14/2011	Spur Rd to EP355							1	
7/14/2011	EP322	1							
7/13/2011	EP357	1							
7/12/2011	EP344	1							
7/12/2011	SWPL AR btwn EP348/345							1	
TOTAL POST RCLMP		13	0	0	0	43	0	12	
Prior to RCLMP		Day		Day		Day		Day	
7/11/2011	AR to EP352					2			
7/11/2011	AR to EP345					2			
7/10/2011	EP358					1			
7/10/2011	SWPL AR to EP354					2			
7/9/2011	AR to EP330	1							
7/8/2011	Spur Rd. to EP352	1							
7/7/2011	EP324					1			
7/7/2011	EP355					1			
7/6/2011	SWPL AR btwn EP362/363							1	
7/5/2011	EP354					1			
7/1/2011	AR to EP353	1							
6/30/2011	AR between EP310/311							1	
6/30/2011	EP358	1							
6/30/2011	EP360	1							
6/30/2011	AR to EP312							1	
6/30/2011	EP360							1	
6/27/2011	EP350					1			
6/27/2011	SWPL AR to IV Substation	2							

Flat Tailed Horned Lizard Counts - Week Ending 04/14/2012

Date	Location	Observed	Injured	Relocated	Dead
6/26/2011	IV Substation			1	
6/25/2011	SWPL AR to EP361	1			
6/24/2011	EP359			1	
6/23/2011	SWPL AR to EP360			2	
6/22/2011	SWPL AR to EP355			1	
6/20/2011	EP356	2			
6/20/2011	SWPL AR to EP359	1			
6/20/2011	Near EP356	2			
6/20/2011	AR between EP358/357				1
6/18/2011	AR to Dunaway CY				1
6/17/2011	Near EP322	1			
6/7/2011	Near EP355	1			
6/7/2011	EP361			1	
6/7/2011	AR btwn EP343/EP344				1
6/7/2011	AR between EP324/325				1
6/6/2011	SWPL AR btwn EP344/EP345			1	
6/3/2011	EP359			1	
6/3/2011	SWPL AR EP362			1	
6/2/2011	AR to EP358			1	
6/2/2011	SWPL AR to EP316-2				1
6/2/2011	AR east of EP325				1
6/1/2011	SWPL AR btwn EP319/EP320			1	
6/1/2011	SWPL AR to EP318			1	
5/31/2011	SWPL AR btwn EP359/EP360			1	
5/31/2011	SWPL AR to EP320			1	
5/31/2011	EP360				1
5/27/2011	EP357			1	
5/26/2011	SWPL AR to EP359			1	
5/25/2011	Spur Rd to EP321			1	
5/23/2011	EP323			1	
5/21/2011	EP324			1	
5/20/2011	IV CY			1	
5/20/2011	AR to EP362			1	
5/20/2011	AR btwn EP324/EP325			1	
5/20/2011	SWPL AR btwn EP326/EP327			1	
5/20/2011	IV Substation			3	
5/19/2011	IV Substation			5	
5/19/2011	EP324			1	
5/18/2011	IV Substation Yard			1	
5/18/2011	IV Substation Yard				1
5/17/2011	AR to IV Substation				1
5/16/2011	IV Substation Yard			1	
5/13/2011	SWPL AR Near EP362-1	1			
5/12/2011	AR to EP355			1	

Flat Tailed Horned Lizard Counts - Week Ending 04/14/2012					
Date	Location	Observed	Injured	Relocated	Dead
5/11/2011	EP360	1			
5/11/2011	Dunaway CY	3			
5/11/2011	Dunaway Yard			4	
5/10/2011	EP322	1			
5/10/2011	AR to Dunaway CY	1			
5/9/2011	Dunaway Yard			4	
5/7/2011	EP322	1			
5/7/2011	Spur Road to EP344	1			
5/7/2011	Dunaway Yard			1	
5/6/2011	AR to EP321-1	1			
5/5/2011	AR to EP321-1	1			
5/5/2011	AR to Dunaway CY	2			
5/5/2011	Dunaway Yard			2	
5/4/2011	AR btwn EP343/EP344			1	
5/3/2011	SWPL AR btwn EP320/EP321	1			
4/27/2011	AR to EP322	2			
4/26/2011	EP322	1			
4/25/2011	Plaster City CY	1			
4/20/2011	Plaster City			1	
4/18/2011	Plaster City			1	
4/14/2011	AR to IV Substation	1			
4/2/2011	Dunaway CY	1			
TOTAL PRIOR TO RCLMP		35	0	60	13
YTD		48	0	103	25

*RCLMP refers to the Revised Construction Lighting Mitigation Plan

Raven Control Monitoring Report - Week Ending 04/14/2012

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
4/14/2012			No ravens observed					
4/13/2012			No ravens observed					
4/12/2012			No ravens observed					
4/11/2012			No ravens observed					
4/10/2012			No ravens observed					
4/9/2012			No ravens observed					
4/8/2012			No ravens observed					
4/7/2012			No ravens observed					
4/6/2012			No ravens observed					
4/5/2012			No ravens observed					
4/4/2012			No ravens observed					
4/3/2012			No ravens observed					
4/2/2012	S2 Yard	1		1				no
4/1/2012			No ravens observed					
3/31/2012			No ravens observed					
3/30/2012			No ravens observed					
3/29/2012			No ravens observed					
3/28/2012			No ravens observed					
3/27/2012			No ravens observed					
3/26/2012			No ravens observed					
3/25/2012			No ravens observed					
3/24/2012			No ravens observed					
3/23/2012			No ravens observed					
3/22/2012			No ravens observed					
3/21/2012	Plaster City Yard	2			2			no
3/20/2012			No ravens observed					
3/19/2012			No ravens observed					
3/18/2012			No ravens observed					
3/17/2012			No ravens observed					
3/16/2012	EP363	1			1			no
3/15/2012			No ravens observed					
3/14/2012			No ravens observed					
3/13/2012	Plaster City Yard	6		4			2	no
3/12/2012	Plaster City Yard	5		2			3	no
3/11/2012			No ravens observed					
3/10/2012			No ravens observed					
3/9/2012			No ravens observed					
3/8/2012	Plaster City Yard	3		2			1	no
3/8/2012	EP326	2		2				no
3/7/2012	Plaster City Yard	1			1			no
3/6/2012	EP350	1			1			no
3/5/2012			No ravens observed					
3/4/2012			No ravens observed					
3/3/2012			No ravens observed					
3/2/2012	EP352	2			2			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
3/2/2012	Plaster City Yard	1					1	no
3/2/2012	EP357	2		2				no
3/1/2012	No ravens observed							
2/29/2012	EP359-EP362	5		5				no
2/28/2012	EP357 and EP359	3			3			no
2/28/2012	EP349	2	2					no
2/27/2012	No ravens observed							
2/26/2012	EP351	1			1			no
2/25/2012	No ravens observed							
2/24/2012	EP355	3		3				no
2/23/2012	EP355	1		1				no
2/22/2012	EP347	2		2				no
2/22/2012	EP343/EP344 Pullsite	2					2	no
2/21/2012	No ravens observed							
2/20/2012	EP313-EP354	2		2				no
2/19/2012	EP360-EP362	2		2				no
2/18/2012	No ravens observed							
2/17/2012	No ravens observed							
2/16/2012	S2 Yard	3		3				no
2/15/2012	S2 Yard	5		5				no
2/14/2012	S2 Yard	2		2				no
2/13/2012	No ravens observed							
2/12/2012	No ravens observed							
2/11/2012	No ravens observed							
2/10/2012	No ravens observed							
2/9/2012	S2 Yard	2		2				no
2/8/2012	S2 Yard	3		2			1	no
2/7/2012	S2 Yard	3		2			1	no
2/6/2012	S2 Yard	3		2			1	no
2/5/2012	No ravens observed							
2/4/2012	S2 Yard	2			2			no
2/3/2012	No ravens observed							
2/2/2012	Pull site EP338/EP339	2			2			no
2/2/2012	S2 Yard	1		1				no
2/1/2012	Pull site EP338/EP339	3		3				no
1/31/2012	EP330	2		2				no
1/30/2012	No ravens observed							
1/29/2012	No ravens observed							
1/28/2012	No ravens observed							
1/27/2012	Plaster City Yard	2					2	no
1/26/2012	S2 Yard	2		2				no
1/26/2012	EP341	2			2			no
1/26/2012	EP316	2		2				no
1/25/2012	EP324	1		1				no
1/24/2012	No ravens observed							
1/23/2012	No ravens observed							

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
1/22/2012			No ravens observed					
1/21/2012			No ravens observed					
1/20/2012			No ravens observed					
1/19/2012	EP326-EP328	2		2				no
1/18/2012	EP334	1		1				no
1/17/2012	EP329-1	2			2			no
1/16/2012			No ravens observed					
1/15/2012			No ravens observed					
1/14/2012			No ravens observed					
1/13/2012			No ravens observed					
1/12/2012			No ravens observed					
1/11/2012			No ravens observed					
1/10/2012			No ravens observed					
1/9/2012			No ravens observed					
1/8/2012			No ravens observed					
1/7/2012			No ravens observed					
1/6/2012			No ravens observed					
1/5/2012			No ravens observed					
1/4/2012			No ravens observed					
1/3/2012			No ravens observed					
1/2/2012			No ravens observed					
1/1/2012			No ravens observed					
12/31/2011			No ravens observed					
12/30/2011			No ravens observed					
12/29/2011	EP313-EP304 & EP295-EP292	2			2			no
12/28/2011	EP294	20			20			no
12/27/2011	EP292	2			2			
12/26/2011	EP292	2					2	no
12/25/2011			No ravens observed					
12/24/2011	EP281, EP281GS & EP290	5		5				no
12/23/2011			No ravens observed					
12/22/2011	EP300-1, EP301 & EP304	3		3				no
12/21/2011			No ravens observed					
12/20/2011	EP290-EP291/EP292 Pullsite	2			2			no
12/19/2011			No ravens observed					
12/18/2011			No ravens observed					
12/17/2011	EP325	1		1				no
12/17/2011	S2 Yard	3					3	no
12/16/2011			No ravens observed					
12/15/2011	IV Substation	1			1			no
12/15/2011	EP293	2		2				no
12/15/2011	S2 Yard	3					3	no
12/14/2011	S2 Yard	3					3	no
12/13/2011	S2 Yard	2					2	no
12/12/2011	S2 Yard	2					2	no
12/11/2011	S2 Yard	2					2	no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
12/10/2011	EP306 & EP306/EP307 Pullsite	3		3				no
12/9/2011	IV Substation	1		1				no
12/9/2011	EP308 & EP306/EP307 Pullsite	2		2				no
12/9/2011	EP291 & EP291/EP292 Pullsite	2		2				no
12/8/2011	S2 Yard	3					3	no
12/8/2011	IV Substation	1		1				no
12/8/2011	EP301	2		2				no
12/8/2011	EP300-EP309	2		2				no
12/8/2011	EP291/EP292 Pullsite	2	2					no
12/8/2011	EP281	2		2				no
12/7/2011	IV Substation	1		1				no
12/7/2011	EP301	1			1			no
12/7/2011	EP291/EP292 Pullsite	1			1			no
12/7/2011	EP281	7		4	2	1		no
12/7/2011	S2 Yard	2			2			no
12/6/2011	S2 Yard	3				3		no
12/6/2011	EP301	2			2			no
12/6/2011	EP281	5		4		1		no
12/5/2011	S2 Yard	2					2	no
12/5/2011	IV Substation	2		2				no
12/5/2011	EP363	2		2				no
12/5/2011	EP281	6		6				no
12/4/2011	S2 Yard	3				3		no
12/4/2011	IV Substation	2		2				no
12/4/2011	Fromm CY	2				1	1	no
12/4/2011	EP294	1		1				no
12/3/2011	EP281	1		1				no
12/2/2011	IV Substation	1		1				no
12/1/2011	S2 Yard	2					2	no
11/30/2011	S2 Yard	2			2			no
11/29/2011	S2 Yard	2			2			no
11/28/2011	S2 Yard	4			4			no
11/28/2011	EP290-EP301	5		2	3			no
11/27/2011	S2 Yard	1		1				no
11/26/2011	No ravens observed							
11/25/2011	NO WORK: DAY AFTER THANKSGIVING							
11/24/2011	NO WORK: THANKSGIVING							
11/23/2011	Plaster City Yard	3					3	no
11/22/2011	S2 Yard	4			4			no
11/22/2011	IV Substation	1			1			no
11/21/2011	S2 Yard	4					4	no
11/21/2011	IV Substation	1		1				no
11/21/2011	EP281	2			2			no
11/20/2011	EP360	2			2			no
11/20/2011	IV Substation	2		2				no
11/19/2011	No ravens observed							

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
11/18/2011	EP358 and IV Substation	2		2				no
11/17/2011	No ravens observed							
11/16/2011	S2 Yard	5			5			no
11/15/2011	EP330-1	2					2	no
11/15/2011	EP304; EP330	1			1			no
11/14/2011	S2 Yard	6			6			no
11/13/2011	No ravens observed							
11/12/2011	Dunaway CY	1			1			no
11/11/2011	Dunaway CY	4					4	no
11/11/2011	S2 Yard	5					5	no
11/10/2011	Fromm CY	2					2	no
11/10/2011	EP355	1		1				no
11/9/2011	Dunaway CY	1			1			no
11/8/2011	S2 Yard	5			5			no
11/8/2011	Dunaway CY	2			2			no
11/7/2011	S2 Yard	3					3	no
11/7/2011	EP308-EP310	1					1	no
11/7/2011	EP301 Pullsite	7		6	1			no
11/6/2011	No ravens observed							
11/5/2011	S2 Yard	7			7			no
11/5/2011	IV Substation	1			1			no
11/4/2011	S2 Yard	5			5			no
11/3/2011	S2 Yard	5			3		2	no
11/3/2011	IV Substation	1			1			no
11/3/2011	Fromm CY	1				1		no
11/3/2011	EP303 and EP302	2			2			no
11/3/2011	EP281	2			2			no
11/2/2011	S2 Yard	4			4			no
11/2/2011	IV Substation	1		1				no
11/2/2011	EP305, EP310, EP311	1		1				no
11/1/2011	S2 Yard	2			2			no
11/1/2011	IV Substation	1		1				no
11/1/2011	EP305 and EP312	1			1			no
10/31/2011	S2 Yard	5			5			no
10/31/2011	AER and Fromm CY	1				1		no
10/30/2011	No ravens observed							
10/29/2011	IV Substation	3		3				no
10/28/2011	IV Substation	1		1				no
10/28/2011	EP256, EP357 & EP358	5		5				no
10/27/2011	EP356, EP358 & EP362	2		2				no
10/27/2011	EP305, EP307, EP310-EP312	1		1				no
10/26/2011	EP306, EP307 & EP310	2		2				no
10/25/2011	IV Substation	1		1				no
10/25/2011	EP310	1		1				no
10/24/2011	S2 Yard	3					3	no
10/24/2011	EP305	1			1			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
10/23/2011	S2 Yard	3			3			no
10/22/2011	No ravens observed							
10/21/2011	Dunaway CY	1			1			no
10/20/2011	S2 Yard	2					2	no
10/20/2011	Dunaway CY	5					5	no
10/19/2011	EP314	1		1				no
10/19/2011	EP290	5		5				no
10/18/2011	No ravens observed							
10/17/2011	EP301	3		3				no
10/16/2011	No ravens observed							
10/15/2011	S2 Yard	2					2	no
10/15/2011	Dunaway CY	1				1		no
10/15/2011	EP315	2					2	no
10/15/2011	EP301	3			3			no
10/14/2011	Fromm CY	3				3		no
10/14/2011	EP305	2		2				no
10/14/2011	EP301	3			3			no
10/13/2011	S2 Yard	2					2	no
10/13/2011	Dunaway CY	5					5	no
10/13/2011	Fromm CY	1					1	no
10/13/2011	EP354-EP363	2			2			no
10/13/2011	EP301	4		4				no
10/12/2011	EP300-EP301	2		2				no
10/11/2011	Plaster City Yard	2			2			no
10/11/2011	IV Substation	2					2	no
10/10/2011	Fromm CY	2				2		no
10/10/2011	EP359-EP360	2		2				no
10/10/2011	EP355-EP363	2		2				no
10/10/2011	EP301	3		3				no
10/9/2011	S2 Yard	3					3	no
10/9/2011	EP300	6		6				no
10/8/2011	EP357	2			2			no
10/8/2011	EP306	3					3	no
10/7/2011	Dunaway CY	1		1				no
10/7/2011	EP291-EP301	3		3				no
10/6/2011	Fromm CY	2					2	no
10/5/2011	Dunaway CY	2		2				no
10/5/2011	EP303-2	2		2				no
10/4/2011	EP310 & EP311	2		2				no
10/4/2011	EP301	3					3	no
10/4/2011	EP293	2		2				no
10/3/2011	S2 Yard	2					2	no
10/3/2011	Dunaway CY	2			2			no
10/2/2011	EP356-EP363	2		1	1			no
10/1/2011	Plaster City Yard	2					2	no
10/1/2011	EP360	2			2			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
9/30/2011	S2 Yard	2					2	no
9/30/2011	EP355	1		1				no
9/30/2011	EP314	2		2				no
9/30/2011	EP301	2		1	1			no
9/29/2011	EP291/EP292 Pullsite	1			1			no
9/28/2011	EP361	1			1			no
9/27/2011	EP315	2		1	1			no
9/27/2011	EP309	1		1				no
9/27/2011	EP301 & EP304	4		3	1			no
9/27/2011	EP290	1			1			no
9/26/2011	EP362	2			2			no
9/26/2011	Fromm CY	1				1		no
9/25/2011	No ravens observed							
9/24/2011	Plaster City Yard	2					2	no
9/24/2011	EP317	1		1				no
9/24/2011	EP309	1		1				no
9/23/2011	EP362	4			4			no
9/23/2011	EP303	2		2				no
9/22/2011	Fromm CY	1				1		no
9/22/2011	EP303	2		2				no
9/22/2011	EP301	2		2				no
9/22/2011	EP295-EP322	3		3				no
9/21/2011	S2 Yard	3			3			no
9/21/2011	Fromm CY	1					1	no
9/21/2011	EP303	1		1				no
9/20/2011	S2 Yard	2			2			no
9/20/2011	Fromm CY	1				1		no
9/19/2011	S2 Yard	3			3			no
9/19/2011	EP304, EP307, EP309	1		1				no
9/18/2011	S2 Yard	3				3		no
9/18/2011	EP281	1		1				no
9/17/2011	S2 Yard	3					3	no
9/17/2011	EP362	1			1			no
9/17/2011	Fromm CY	3				3		no
9/16/2011	EP363	2			2			no
9/16/2011	Fromm CY	1					1	no
9/16/2011	EP304	2		2				no
9/16/2011	EP290	1		1				no
9/15/2011	S2 Yard	4			4			no
9/15/2011	Fromm CY	3					3	no
9/15/2011	EP296	1		1				no
9/15/2011	EP306	2					2	no
9/15/2011	EP304	1		1				no
9/15/2011	EP301	2		2				no
9/14/2011	Plaster City Yard	1			1			no
9/14/2011	EP361	2			2			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
9/14/2011	Fromm CY	1				1		no
9/14/2011	EP308	1					1	no
9/14/2011	EP301	5		4	1			no
9/14/2011	EP292	3		3				no
9/13/2011	S2 Yard	10			10			no
9/13/2011	EP348	3		3				no
9/13/2011	EP345	2		2				no
9/13/2011	EP326	1					1	no
9/13/2011	EP325	2		2				no
9/13/2011	EP326	1		1				no
9/13/2011	EP304	7		7				no
9/13/2011	EP291	7		7				no
9/12/2011	S2 Yard	3			3			no
9/12/2011	EP350	1		1				no
9/12/2011	EP304	1		1				no
9/12/2011	EP301	1		1				no
9/11/2011	S2 Yard	2				2		no
9/10/2011	S2 Yard	2					2	no
9/9/2011	EP304	1			1			no
9/8/2011	S2 Yard	3					3	no
9/7/2011	S2 Yard	3					3	no
9/6/2011	No ravens observed							
9/5/2011	No ravens observed							
9/4/2011	No ravens observed							
9/3/2011	No ravens observed							
9/2/2011	EP348	1		1				no
9/2/2011	S2 Yard	1		1				no
9/2/2011	EP303	1		1				no
9/2/2011	EP363	2		2				1 at IV Sub
9/1/2011	EP303	2					2	no
9/1/2011	EP293	1					1	no
9/1/2011	EP304	2					2	no
8/31/2011	S2 Yard	1		1				no
8/31/2011	EP308	1		1				no
8/31/2011	EP305-3	2					2	no
8/31/2011	EP303	2		2				no
8/30/2011	EP303	1		1				no
8/29/2011	S2 Yard	1		1				no
8/29/2011	EP303	1		1				no
8/28/2011	No ravens observed							
8/27/2011	EP305	3			3			no
8/26/2011	EP301	2		2				no
8/25/2011	S2 Yard	2					2	no
8/25/2011	EP301	2		2				no
8/24/2011	S2 Yard	3				3		no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
8/23/2011	EP292-1	3		3				no
8/22/2011	No ravens observed							
8/21/2011	No ravens observed							
8/20/2011	S2 Yard	2				2		no
8/20/2011	EP312	2		2				no
8/20/2011	S2 Yard	2					2	no
8/20/2011	EP312	2		2				no
8/19/2011	EP307	2			2			no
8/19/2011	EP296	1		1				no
8/18/2011	S2 Yard	2				1	1	no
8/18/2011	EP301	Flock		x				no
8/17/2011	S2 Yard	2				1	1	no
8/17/2011	EP301	3			3			no
8/16/2011	S2 Yard	1					1	no
8/16/2011	EP301	1		1				no
8/15/2011	No ravens observed							
8/14/2011	No ravens observed							
8/13/2011	S2 Yard	2					2	no
8/12/2011	IV Substation	2				2		no
8/12/2011	S2 Yard	3				3	3	no
8/11/2011	EP294	4			4			no
8/11/2011	S2 Yard	3				3	3	no
8/10/2011	S2 Yard	3				2	1	no
8/9/2011	S2 Yard	not specified						no
8/8/2011	EP294	2			2			no
8/8/2011	S2 Yard	1						no
8/7/2011	No ravens observed							
8/6/2011	S2 Yard	1						no
8/5/2011	EP301	3		3				no
8/4/2011	S2 Yard	not specified						no
8/3/2011	S2 Yard	2		2				no
8/3/2011	S2 Yard	1						no
8/2/2011	S2 Yard	3					3	no
8/1/2011	EP314	not specified		x				no
7/31/2011	No ravens observed							
7/30/2011	EP314	3		2			1	no
7/30/2011	S2 Yard	1					1	no
7/29/2011	S2 Yard	1						no
7/28/2011	EP319	4	1	2	1			no
7/28/2011	S2 Yard	not specified						no
7/27/2011	S2 Yard	not specified						no
7/26/2011	No ravens observed							
7/25/2011	EP290	1			1			no
7/24/2011	No ravens observed							
7/23/2011	No ravens observed							
7/22/2011	EP290	2		1	1			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
7/21/2011	S2 Yard	1		1				no
7/20/2011	Ocotillo, CA	5						no
7/19/2011	Ocotillo, CA	1						no
7/17/2011	No ravens observed							
7/15/2011	No ravens observed							
7/14/2011	EP357	not specified						no
7/14/2011	EP358	not specified						no
7/14/2011	EP359	not specified						no
7/14/2011	Plaster City Yard	2		2				no
7/13/2011	EP313-EP314 PS	not specified						no
7/13/2011	S2 Yard	3					3	no
7/11/2011	EP304-EP314	not specified						no
7/10/2011	No ravens observed							
7/9/2011	EP351	not specified						no
7/9/2011	EP353	not specified						no
7/9/2011	EP354	not specified						no
7/9/2011	EP355	not specified						no
7/9/2011	not specified	not specified						no
7/9/2011	S2 Yard	3					3	no
7/8/2011	EP303	2			1		1	no
7/8/2011	EP303	1		1				no
7/8/2011	S2 Yard	3					3	no
7/1/11-7/7/11	No ravens observed							
6/30/2011	EP300	3		3				no
6/21/11-6/29/11	No ravens observed							
6/20/2011	S2 Yard	2					2	no
6/1/11-6/19/11	No ravens observed							
5/1/11-5/31/11	No ravens observed							
4/22/11-4/30/11	No ravens observed							
4/21/2011	EP341	1	1					no
4/1/11-4/20/11	No ravens observed							
3/1/11-3/31/11	No ravens observed							
2/1/11-2/28/11	No ravens observed							
1/21/11-1/31/11	No ravens observed							
1/21/2011	Rough Acres Yard	not specified						no