

September 6, 2011

I. REPRESENTATIVES, LOCATIONS AND DATES

LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region

- Mr. Richard Alvanez, Cocopah, monitored on August 30 and 31.
- Mr. Cody Elliott, Kumeyaay Native, served as monitor on August 31 and September 1.
- Mr. David Elliott Sr., Kumeyaay Native, served as monitor on September 1.
- Mr. Jonathan Jones of Campo served as monitor on September 1 and 2.
- Ms. Darlene Mack, Campo, served as monitor this week however her reports have yet to be submitted.
- Mr. Albert Quihuis, Campo, served as a monitor on September 1.
- Mr. Santiago Santos, Manzanita, served as monitor for August 29-30 and September 1-3.
- Ms. Veronica Santos, Manzanita, served as monitor for August 29 – September 2.
- Mr. Kenneth M. Stokes, Jr. of Kumeyaay served as monitor on September 1.
- Mr. Daniel Tsosie, Campo, served as monitor from August 29-30 and September 1-2.

LINK 2: Bartlett-Hauser Yard/ Kreutzkamp Yard

- Ms. Vera Tucker served as monitor on August 29 - 31.

LINK 3: Suncrest Substation

- No monitors required at this location for this week.

LINK 4: Alpine Underground

- Mr. Clarence Brown of Viejas served as monitor on August 29, 30, 31 and on September 1 and 2.

LINK 5: Various Locations

- No monitors required at this location for this week.

II. CONSTRUCTION ACTIVITIES

LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region

Activities noted at these locations this week consist of: brush removal, brush clearing, watering, light excavation, trenching, the installation of ESA signage, drilling, wattle installation, and grading.

LINK 2: Bartlett-Hauser Yard

Ms. Tucker noted clearing vegetation, fencing, and sandbagging.

LINK 3: Suncrest Substation

No monitors required at this location for this week.

LINK 4: Alpine Underground

Mr. Brown noted trenching, grading, and excavating.

LINK 5: Various Locations

No monitors required at this location for this week.

III. OBSERVATIONS

LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region

Mr. Thomas reported minor surveying this week. On September 2, Mr. Santos noted five pieces of pottery.

LINK 2: Bartlett-Hauser Yard

On August 29, Ms. Tucker noted a single flake which was removed from the work area and replaced. Mr. Elliott noted minor surveying of selected areas. On September 1, Mr. Stokes noted “While watering road lithics were found, high sensitivity area” and “Lots of cultural items found in area.”

LINK 3: Suncrest Substation

No monitors required at this location for this week.

LINK 4: Alpine Underground

No cultural material observed this week.

LINK 5: Various Locations

No monitors required at this location for this week.

IV. CONCERNS EXPRESSED

LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region

No concerns expressed this week.

LINK 2: Bartlett-Hauser Yard

Mr. Stokes felt the water truck exposing the lithics was important and that the access roads’ locations could’ve been better planned to avoid the artifacts.

LINK 3: Suncrest Substation

No concerns expressed this week.

LINK 4: Alpine Underground

No concerns expressed this week.

LINK 5: Various Locations

No concerns expressed this week.

V. SUMMARY

In general, few concerns were noted in regard to cultural resources.



VI. SUMMARY PREPARER

Hillary Murphy, Project Archaeologist, Tierra Environmental Services, Inc.

Joseph M. Nixon, Senior Anthropologist, Tierra Environmental Services, Inc.

Kyle Stankowski, Associate Archaeologist, Tierra Environmental Services, Inc.