Pacific Gas and Electric Company

SmartMeterTM Complaint Report

## SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No. 1 2 3 4 5 6 7 2	Date 5/7/09 6/9/09 6/25/09 7/1/09	Customer Name {Redacted}	Account {Redacted}	Service City	Core Process	Nature of Complaint	Stotuc
2 3 4 5 6 7	6/9/09 6/25/09 7/1/09	{Redacted}	{Redacted}	<b>L</b> , ,			Status
3 4 5 6 7	6/25/09 7/1/09			Brentwood	Household items affected by SM installation	Under Investigation	Open
4 5 6 7	7/1/09			Citrus Heights	Meter/Module	Under Investigation	Open
5 6 7		-		PARADISE	Meter/Module	Under Investigation	Open
6 7		4		Capay	Other	Under Investigation	Open
7	7/2/09	4		Soda Springs	Scheduling Problems	Under Investigation	Open
	9/18/09	4		Moraga	SmartMeter Customer Communication	Under Investigation	Open
	9/29/09	4		Ahwahnee	Meter/Module	Under Investigation	Open
8	10/15/09	-		Stockton	Household items affected by SM installation	Under Investigation	Open
9	10/26/09	-		Fremont	Other	Under Investigation	Open
10	10/28/09			Vacaville	Wellington Installer	Under Investigation	Open
11	11/10/09			Hillsborough	Customer Denies Access	Under Investigation	Open
12	11/10/09	4		Vacaville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
13	11/12/09			Newark	Meter/Module	Under Investigation	Open
14	11/16/09			Vacaville	Household items affected by SM installation	Under Investigation	Open
15	11/20/09			Fremont	Meter/Module	Under Investigation	Open
16	11/23/09			WOODLAND	Meter/Module	Under Investigation	Open
17	11/24/09			Kingsburg	Meter/Module	Under Investigation	Open
18	11/25/09			Richmond	Network Equipment Installation	Under Investigation	Open
19	11/30/09			Fresno	Household items affected by SM installation	Under Investigation	Open
20	11/30/09			MIRAMONTE	Household items affected by SM installation	Under Investigation	Open
21	12/2/09			Fremont	Power Interruption	Under Investigation	Open
22	12/2/09	-		Redwood City	Household items affected by SM installation	Under Investigation	Open
23	12/3/09	1		Manteca	Household items affected by SM installation	Under Investigation	Open
24	12/3/09			Manteca	Household items affected by SM installation	Under Investigation	Open
25	12/3/09	1		Stockton	Household items affected by SM installation	Under Investigation	Open
26	12/4/09			Hanford	Household items affected by SM installation	Under Investigation	Open
27	12/4/09	1		Napa	Household items affected by SM installation	Under Investigation	Open
28	12/7/09			Napa	Wellington Installer	Under Investigation	Open
29	12/8/09			PIONEER	Household items affected by SM installation	Under Investigation	Open
30	12/9/09	1		Los Altos	Household items affected by SM installation	Under Investigation	Open
31	12/9/09	1		Stockton	Power Interruption	Under Investigation	Open
32	12/11/09	1		MILLBRAE	Power Interruption	Under Investigation	Open
33	12/11/09			Plymouth	Meter/Module	Under Investigation	Open
34	12/11/09			Stockton	Household items affected by SM installation	Under Investigation	Open
35	12/16/09			Mountain View	Scheduling Problems	Under Investigation	Open
36	12/17/09	1	1	Sunnyvale	Meter/Module	Under Investigation	Open
37	12/17/09			Vacaville	Meter/Module	Under Investigation	Open
38	12/18/09			LATHROP	Other	Other	Resolved
39	12/22/09		1	Fremont	Household items affected by SM installation	Under Investigation	Open
40	12/22/09	1		PINE GROVE	Wellington Installer	Under Investigation	Open
40	12/22/09	1		Dublin	Meter/Module	Under Investigation	Open

Page 1 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

200 522

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
42	12/23/09			Sunnyvale	Household items affected by SM installation	Under Investigation	Open
43	12/23/09			Sunnyvale	Household items affected by SM installation	Under Investigation	Open
44	12/23/09			Walnut Creek	SmartMeter Customer Communication	Under Investigation	Open
45	12/29/09			El Granada	Power Interruption	Under Investigation	Open
46	12/29/09			Livermore	Meter/Module	Under Investigation	Open
47	12/29/09			Pleasanton	Household items affected by SM installation	Under Investigation	Open
48	12/30/09			Los Banos	Network Equipment Installation	Under Investigation	Open
49	12/31/09			Livermore	Household items affected by SM installation	Under Investigation	Open
50	12/31/09			Mountain View	Household items affected by SM installation	Under Investigation	Open
51	1/4/10			Menlo Park	Customer Denies Access	Under Investigation	Open
52	1/4/10			Merced	Customer Denies Access	Under Investigation	Open
53	1/5/10			AUBURN	Power Interruption	Under Investigation	Open
54	1/5/10			Sebastopol	Other	Customer does not want a SmartMeter	Resolved
55	1/7/10			Los Altos	Other	Other	Resolved
56	1/8/10			Livermore	Household items affected by SM installation	Under Investigation	Open
57	1/11/10			Burlingame	Household items affected by SM installation	Under Investigation	Open
58	1/11/10			Fairfield	Meter/Module	Under Investigation	Open
59	1/11/10			Livermore	Household items affected by SM installation	Under Investigation	Open
60	1/11/10			√acaville	Meter/Module	Under Investigation	Open
61	1/12/10			Livermore	Power Interruption	Under Investigation	Open
62	1/12/10			Moraga	Household items affected by SM installation	Under Investigation	Open
63	1/12/10			Sunnyvale	Household items affected by SM installation	Under Investigation	Open
64	1/12/10			Berkeley	Customer Denies Access	Customer does not want a SmartMeter	Resolved
65	1/13/10			LODI	Meter/Module	Under Investigation	Open
66	1/14/10			Cupertino	Household items affected by SM installation	Under Investigation	Open
67	1/14/10			Cupertino	Household items affected by SM installation	Under Investigation	Open
68	1/14/10			Dublin	Household items affected by SM installation	Under Investigation	Open
69	1/15/10			Corcoran	Wellington Installer	Under Investigation	Open
70	1/15/10			Dublin	Household items affected by SM installation	Under Investigation	Open
71	1/15/10			Napa	Scheduling Problems	Under Investigation	Open
72	1/15/10			San Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
73	1/16/10			San Jose	Household items affected by SM installation	Under Investigation	Open
74	1/19/10			Martinez	Other	Under Investigation	Open
75	1/19/10			Aptos	Other	Other	Resolved
76	1/19/10			San Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
77	1/20/10			Cupertino	Household items affected by SM installation	Under Investigation	Open
78	1/20/10			Cupertino	Power Interruption	Under Investigation	Open
79	1/22/10			Fremont	Household items affected by SM installation	Under Investigation	Open
80	1/22/10			Sebastopol	Customer Denies Access	Under Investigation	Open
81	1/23/10			Kensington	Household items affected by SM installation	Under Investigation	Open
82	1/25/10			Pinole	SmartMeter Customer Communication	General inquiry on communication	Resolved

Page 2 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

000 5200

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
83	1/26/10	Oustomer Name	Account	American Canyon	Customer Denies Access	Under Investigation	Open
84	1/26/10			Livermore	Customer Denies Access	Under Investigation	Open
85	1/26/10			Madera	Wellington Installer	Under Investigation	Open
86	1/26/10			MONTARA	Meter/Module	Under Investigation	Open
87	1/26/10			Pleasanton	Wellington Installer	Under Investigation	Open
88	1/26/10			San Jose	Household items affected by SM installation	Under Investigation	Open
89	1/26/10			San Jose	Meter/Module	Under Investigation	Open
90	1/26/10			Stockton	Wellington Installer	Under Investigation	Open
91	1/26/10			Sunnyvale	Household items affected by SM installation	Under Investigation	Open
92	1/26/10			Sunnyvale	Household items affected by SM installation	Under Investigation	Open
93	1/26/10			Livermore	Customer Denies Access	Customer does not want a SmartMeter	Resolved
94	1/26/10			Merced	Customer Denies Access	Customer does not want a SmartMeter	Resolved
95	1/26/10			√allejo	Wellington Installer	Other	Resolved
96	1/27/10			Hillsborough	Customer Denies Access	Under Investigation	Open
97	1/27/10			Pleasanton	Wellington Installer	Under Investigation	Open
98	1/27/10			Redwood City	Meter/Module	Under Investigation	Open
99	1/28/10			American Canyon	Wellington Installer	Under Investigation	Open
100	1/28/10			El Sobrante	Wellington Installer	Under Investigation	Open
101	1/28/10			Moraga	Wellington Installer	Under Investigation	Open
102	1/28/10			Pleasanton	Household items affected by SM installation	Under Investigation	Open
103	1/28/10			San Francisco	Power Interruption	Under Investigation	Open
104	1/28/10			San Jose	Household items affected by SM installation	Under Investigation	Open
105	1/28/10			San Jose	Wellington Installer	Under Investigation	Open
106	1/28/10			Sunnyvale	Power Interruption	Under Investigation	Open
107	1/29/10			Cupertino	Household items affected by SM installation	Under Investigation	Open
108	1/29/10			Madera	Wellington Installer	Under Investigation	Open
109	1/29/10			Pinole	Wellington Installer	Under Investigation	Open
110	1/29/10			Richmond	Wellington Installer	Under Investigation	Open
111	1/29/10			Rio Vista	Household items affected by SM installation	Under Investigation	Open
112	1/29/10			San Jose	Household items affected by SM installation	Under Investigation	Open
113	1/29/10			San Jose	Meter/Module	Under Investigation	Open
114	1/29/10			Stockton	Wellington Installer	Under Investigation	Open
115	1/29/10			Sunnyvale	Household items affected by SM installation	Under Investigation	Open
116	1/29/10			Sunnyvale	Wellington Installer	Under Investigation	Open
117	1/29/10			Kensington	Meter/Module	Meter/Module clearance issues	Resolved
118	1/31/10			San Jose	Household items affected by SM installation	Under Investigation	Open
119	1/31/10			San Jose	Household items affected by SM installation	Under Investigation	Open
120	1/31/10			San Jose	Household items affected by SM installation	Under Investigation	Open
121	1/31/10			Bakersfield	Household items affected by SM installation	Other	Resolved
122	1/31/10			Danville	Meter/Module	Meter/Module clearance issues	Resolved
123	2/1/10			El Sobrante	Wellington Installer	Under Investigation	Open

Page 3 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

100

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
124	2/1/10			LA HONDA	Customer Denies Access	Under Investigation	Open
125	2/1/10			Livermore	Household items affected by SM installation	Under Investigation	Open
126	2/1/10			Pleasanton	Meter/Module	Under Investigation	Open
127	2/1/10			San Jose	Power Interruption	Under Investigation	Open
128	2/1/10			San Jose	Power Interruption	Under Investigation	Open
129	2/1/10			√acaville	Meter/Module	Under Investigation	Open
130	2/2/10			San Jose	Household items affected by SM installation	Under Investigation	Open
131	2/3/10			CORDELIA	Wellington Installer	Under Investigation	Open
132	2/3/10			GRATON	Other	Under Investigation	Open
133	2/3/10			Livermore	Household items affected by SM installation	Under Investigation	Open
134	2/3/10			Mountain View	Power Interruption	Under Investigation	Open
135	2/3/10			Pleasanton	Meter/Module	Under Investigation	Open
136	2/3/10			RAYMOND	Wellington Installer	Under Investigation	Open
137	2/4/10			Fresno	Household items affected by SM installation	Under Investigation	Open
138	2/4/10			San Ramon	Power Interruption	Under Investigation	Open
139	2/4/10			Suisun City	Meter/Module	Under Investigation	Open
140	2/5/10			Mountain View	Other	Under Investigation	Open
141	2/5/10			Pleasanton	Meter/Module	Under Investigation	Open
142	2/5/10			San Ramon	Meter/Module	Under Investigation	Open
143	2/8/10			Sonoma	Customer Denies Access	Under Investigation	Open
144	2/9/10			Cupertino	Wellington Installer	Under Investigation	Open
145	2/9/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
146	2/10/10			Berkeley	Customer Denies Access	Under Investigation	Open
147	2/10/10			Berkeley	Wellington Installer	Under Investigation	Open
148	2/10/10			Carmel	Network Equipment Installation	Under Investigation	Open
149	2/10/10			Cupertino	Meter/Module	Under Investigation	Open
150	2/10/10			Cupertino	Power Interruption	Under Investigation	Open
151	2/10/10			Cupertino	Scheduling Problems	Under Investigation	Open
152	2/10/10			NORTH FOLK	Wellington Installer	Under Investigation	Open
153	2/10/10			Rancho Cordova	Meter/Module	Under Investigation	Open
154	2/10/10			San Jose	Wellington Installer	Under Investigation	Open
155	2/10/10			San Ramon	Wellington Installer	Under Investigation	Open
156	2/10/10			√acaville	Household items affected by SM installation	Under Investigation	Open
157	2/11/10			Healdsburg	Customer Denies Access	Under Investigation	Open
158	2/11/10			Livermore	Household items affected by SM installation	Under Investigation	Open
159	2/11/10			Napa	Meter/Module	Under Investigation	Open
160	2/11/10			Sunnyvale	Power Interruption	Under Investigation	Open
161	2/11/10			√ailejo	Wellington Installer	Under Investigation	Open
162	2/12/10			Berkeley	Wellington Installer	Under Investigation	Open
163	2/12/10			San Jose	Power Interruption	Under Investigation	Open
164	2/12/10			San Ramon	Household items affected by SM installation	Under Investigation	Open

Page 4 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

200 52/2

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
165	2/12/10			San Ramon	Household items affected by SM installation	Under Investigation	Open
166	2/12/10			San Ramon	Wellington Installer	Under Investigation	Open
167	2/13/10			Berkeley	Household items affected by SM installation	Under Investigation	Open
168	2/14/10			Sunnyvale	Meter/Module	Under Investigation	Open
169	2/14/10			Walnut Creek	Household items affected by SM installation	Under Investigation	Open
170	2/16/10			Berkeley	Wellington Installer	Under Investigation	Open
171	2/16/10			Cupertino	Wellington Installer	Under Investigation	Open
172	2/16/10			RIPON	Meter/Module	Under Investigation	Open
173	2/16/10			Santa Clara	Meter/Module	Under Investigation	Open
174	2/16/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
175	2/16/10			Sunnyvale	Household items affected by SM installation	Under Investigation	Open
176	2/17/10			Cupertino	Household items affected by SM installation	Under Investigation	Open
177	2/17/10			Forestville	Customer Denies Access	Under Investigation	Open
178	2/17/10			Madera	Wellington Installer	Under Investigation	Open
179	2/17/10			Newark	Household items affected by SM installation	Under Investigation	Open
180	2/17/10			San Jose	Wellington Installer	Under Investigation	Open
181	2/17/10			Sunnyvale	Meter/Module	Under Investigation	Open
182	2/17/10			√allejo	Household items affected by SM installation	Under Investigation	Open
183	2/17/10			√allejo	Wellington Installer	Under Investigation	Open
184	2/17/10			√allejo	Wellington Installer	Under Investigation	Open
185	2/17/10			Walnut Creek	Customer Denies Access	Under Investigation	Open
186	2/17/10			Berkeley	Meter/Module	Meter/Module clearance issues	Resolved
187	2/17/10			San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
188	2/17/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
189	2/17/10			Sunnyvale	Household items affected by SM installation	Damaged Other Household Appliances	Resolved
190	2/18/10			Madera	Wellington Installer	Under Investigation	Open
191	2/18/10			Mariposa	Wellington Installer	Under Investigation	Open
192	2/18/10			Sanger	Scheduling Problems	Under Investigation	Open
193	2/18/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
194	2/18/10			Somerset	Wellington Installer	Under Investigation	Open
195	2/18/10			Los Banos	Other	Other	Resolved
196	2/19/10			American Canyon	Wellington Installer	Under Investigation	Open
197	2/19/10			Mountain View	Household items affected by SM installation	Under Investigation	Open
198	2/19/10			Pleasanton	Household items affected by SM installation	Under Investigation	Open
199	2/19/10			Pleasanton	Meter/Module	Under Investigation	Open
200	2/21/10			Placerville	Customer Denies Access	Under Investigation	Open
201	2/21/10			Pleasanton	Meter/Module	Under Investigation	Open
202	2/21/10			Sunnyvale	Household items affected by SM installation	Under Investigation	Open
203	2/21/10			Berkeley	Household items affected by SM installation	Motion/Sensor Appliance Malfunctioning	Resolved
204	2/21/10			Cupertino	SmartMeter Customer Communication	Other	Resolved
205	2/21/10			San Francisco	Household items affected by SM installation	Damaged Other Household Appliances	Resolved

Page 5 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

	Complaint		_				
No.	Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
206	2/21/10			San Francisco	Wellington Installer	Safety Concern	Resolved
207	2/21/10			San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
208	2/22/10			OCCIDENTAL	Customer Denies Access	Under Investigation	Open
209	2/22/10			Placerville	Wellington Installer	Under Investigation	Open
210	2/22/10			Pleasanton	Wellington Installer	Under Investigation	Open
211	2/22/10			Pleasanton	Wellington Installer	Under Investigation	Open
212	2/22/10			San Jose	Household items affected by SM installation	Under Investigation	Open
213	2/22/10			San Ramon	Meter/Module	Under Investigation	Open
214	2/22/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
215	2/22/10			Sebastopol	Customer Denies Access	Under Investigation	Open
216	2/22/10			Sunnyvale	Power Interruption	Under Investigation	Open
217	2/22/10			Vacaville	Meter/Module	Under Investigation	Open
218	2/22/10			√allejo	Network Equipment Installation	Under Investigation	Open
219	2/23/10			ALTA	Meter/Module	Under Investigation	Open
220	2/23/10			Clayton	Household items affected by SM installation	Under Investigation	Open
221	2/23/10			Cupertino	Household items affected by SM installation	Under Investigation	Open
222	2/23/10			Mariposa	Wellington Installer	Under Investigation	Open
223	2/23/10			San Jose	Household items affected by SM installation	Under Investigation	Open
224	2/23/10			San Jose	Meter/Module	Under Investigation	Open
225	2/23/10			San Pablo	Wellington Installer	Under Investigation	Open
226	2/23/10			Sebastopol	Customer Denies Access	Under Investigation	Open
227	2/24/10			Livermore	Other	Under Investigation	Open
228	2/24/10			Madera	Wellington Installer	Under Investigation	Open
229	2/24/10			Merced	Meter/Module	Under Investigation	Open
230	2/24/10			Mountain View	Household items affected by SM installation	Under Investigation	Open
231	2/24/10			Napa	Wellington Installer	Under Investigation	Open
232	2/24/10			Pollock Pines	Wellington Installer	Under Investigation	Open
233	2/24/10			San Jose	Meter/Module	Under Investigation	Open
234	2/24/10			San Jose	Wellington Installer	Under Investigation	Open
235	2/24/10			Sunnyvale	Household items affected by SM installation	Under Investigation	Open
236	2/25/10			Mountain View	Meter/Module	under Investigation	Open
237	2/25/10			San Jose	Power Interruption	Under Investigation	Open
238	2/25/10			San Pablo	Power Interruption	Under Investigation	Open
239	2/25/10			Richmond	Meter/Module	Other	Resolved
240	2/26/10			AUBURN	SmartMeter Customer Communication	Under Investigation	Open
241	2/26/10			Hercules	Wellington Installer	Under Investigation	Open
242	2/26/10			Mountain View	Household items affected by SM installation	Under Investigation	Open
243	2/26/10			San Anselmo	SmartMeter Customer Communication	Under Investigation	Open
244	2/26/10			San Jose	Household items affected by SM installation	Under Investigation	Open
245	2/26/10			San Jose	Power Interruption	Under Investigation	Open
246	2/26/10			Sebastopol	Customer Denies Access	Under Investigation	Open

Page 6 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

N	Complaint	Customer Name	Account	Consider City	Core Process	Notive of Completed	Status
No. 247	Date 2/27/10	Customer Name	Account	Service City San Ramon	Household items affected by SM installation	Nature of Complaint Under Investigation	
247	3/1/10			Berkeley	Customer Denies Access	Under Investigation	Open Open
240	3/1/10			Fresno	Wellington Installer		Open
249	3/1/10			Livermore	Household items affected by SM installation	Under Investigation	Open
250	3/1/10					Under Investigation	
251	3/1/10			Livermore	Meter/Module	Under Investigation	Open
252	3/1/10			Livermore	Wellington Installer	Under Investigation	Open
				Madera	Other	Under Investigation	Open
254	3/1/10			Martinez	Wellington Installer	Under Investigation	Open
255	3/1/10			San Jose	Meter/Module	Under Investigation	Open
256	3/1/10			San Jose	Power Interruption	Under Investigation	Open
257	3/1/10			San Jose	Wellington Installer	Under Investigation	Open
258	3/1/10			Tracy	Meter/Module	Under Investigation	Open
259	3/1/10			Tracy	Wellington Installer	Under Investigation	Open
260	3/1/10			Tracy	Wellington Installer	Under Investigation	Open
261	3/1/10			√allejo	Wellington Installer	Under Investigation	Open
262	3/1/10			El Dorado	Customer Denies Access	Customer Denies Wellington Access	Resolved
263	3/1/10			√allejo	Customer Denies Access	Customer does not want a SmartMeter	Resolved
264	3/2/10			Berkeley	Customer Denies Access	Under Investigation	Open
265	3/2/10			Dinuba	Customer Denies Access	Under Investigation	Open
266	3/2/10			Kensington	Customer Denies Access	Under Investigation	Open
267	3/2/10			NEWCASTLE	Household items affected by SM installation	Under Investigation	Open
268	3/2/10			Richmond	Wellington Installer	Under Investigation	Open
269	3/3/10			Glen Ellen	Scheduling Problems	Under Investigation	Open
270	3/3/10			LIVINGSTON	Scheduling Problems	Under Investigation	Open
271	3/3/10			Mountain View	Meter/Module	Under Investigation	Open
272	3/3/10			San Jose	Power Interruption	Under Investigation	Open
273	3/3/10			San Pablo	Wellington Installer	Under Investigation	Open
274	3/3/10			Fresno	Customer Denies Access	Customer does not want a SmartMeter	Resolved
275	3/3/10			Rio Vista	Customer Denies Access	Customer does not want a SmartMeter	Resolved
276	3/3/10			San Francisco	Customer Denies Access	Customer does not want a SmartMeter	Resolved
277	3/3/10			Sonoma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
278	3/3/10			Squaw Valley	Customer Denies Access	Customer does not want a SmartMeter	Resolved
279	3/4/10			Berkeley	Customer Denies Access	Under Investigation	Open
280	3/4/10			Danville	Customer Denies Access	Under Investigation	Open
281	3/4/10			El Cerrito	Customer Denies Access	Under Investigation	Open
282	3/4/10			El Cerrito	Meter/Module	Under Investigation	Open
283	3/4/10			Livermore	Wellington Installer	Under Investigation	Open
284	3/4/10			Merced	Customer Denies Access	Under Investigation	Open
285	3/4/10			MOCCASIN	Customer Denies Access		· · · · ·
						Under Investigation	Open
286	3/4/10			Placerville	Customer Denies Access	Under Investigation	Open
287	3/4/10			San Carlos	Customer Denies Access	Under Investigation	Open

Page 7 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
288	3/4/10			San Jose	Household items affected by SM installation	Under Investigation	Open
289	3/4/10			Tracy	Customer Denies Access	Under Investigation	Open
290	3/4/10			Tracy	Household items affected by SM installation	Under Investigation	Open
291	3/4/10			WOODLAND	Power Interruption	Under Investigation	Open
292	3/5/10			Clovis	Customer Denies Access	Under Investigation	Open
293	3/5/10			Cupertino	Power Interruption	Under Investigation	Open
294	3/5/10			Danville	Customer Denies Access	Under Investigation	Open
295	3/5/10			El Cerrito	Customer Denies Access	Under Investigation	Open
296	3/5/10			Livermore	Power Interruption	Under Investigation	Open
297	3/5/10			San Jose	Power Interruption	Under Investigation	Open
298	3/5/10			San Ramon	Household items affected by SM installation	Under Investigation	Open
299	3/5/10			Half Moon Bay	Customer Denies Access	Customer does not want a SmartMeter	Resolved
300	3/5/10			Selma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
301	3/5/10			Shingle Springs	Customer Denies Access	Customer does not want a SmartMeter	Resolved
302	3/7/10			Atwater	Customer Denies Access	Under Investigation	Open
303	3/7/10			Cazadero	Customer Denies Access	Under Investigation	Open
304	3/7/10			Clovis	Customer Denies Access	Under Investigation	Open
305	3/7/10			Hanford	Customer Denies Access	Under Investigation	Open
306	3/7/10			Healdsburg	Customer Denies Access	Under Investigation	Open
307	3/7/10			Loomis	Customer Denies Access	Under Investigation	Open
308	3/7/10			Loomis	Meter/Module	Under Investigation	Open
309	3/7/10			Sanger	Customer Denies Access	Under Investigation	Open
310	3/7/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
311	3/7/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
312	3/7/10			Sebastopol	Customer Denies Access	Under Investigation	Open
313	3/7/10			Somerset	Customer Denies Access	Under Investigation	Open
314	3/7/10			Sonoma	Customer Denies Access	Under Investigation	Open
315	3/7/10			Tracy	Customer Denies Access	Under Investigation	Open
316	3/7/10			Woodlake	Customer Denies Access	Under Investigation	Open
317	3/8/10			Clovis	Customer Denies Access	Under Investigation	Open
318	3/8/10			Cotati	Household items affected by SM installation	Under Investigation	Open
319	3/8/10			Petaluma	Customer Denies Access	Under Investigation	Open
320	3/8/10			San Jose	Customer Denies Access	Under Investigation	Open
321	3/8/10			San Jose	Household items affected by SM installation	Under Investigation	Open
322	3/8/10			San Jose	Power Interruption	Under Investigation	Open
323	3/8/10			San Ramon	Household items affected by SM installation	Under Investigation	Open
324	3/8/10			Sunnyvale	Customer Denies Access	Under Investigation	Open
325	3/8/10			√allejo	Customer Denies Access	Under Investigation	Open
326	3/8/10			GRANITE BAY	Customer Denies Access	Customer does not want a SmartMeter	Resolved
327	3/8/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
328	3/9/10			Berkeley	Customer Denies Access	Under Investigation	Open

Page 8 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
329	3/9/10			Berkeley	Customer Denies Access	Under Investigation	Open
330	3/9/10			Cupertino	Power Interruption	Under Investigation	Open
331	3/9/10			Danville	Customer Denies Access	Under Investigation	Open
332	3/9/10			Livermore	Meter/Module	Under Investigation	Open
333	3/9/10			Madera	Customer Denies Access	Under Investigation	Open
334	3/9/10			Richmond	Customer Denies Access	Under Investigation	Open
335	3/9/10			Richmond	Household items affected by SM installation	Under Investigation	Open
336	3/9/10			San Jose	Customer Denies Access	Under Investigation	Open
337	3/9/10			San Jose	Customer Denies Access	Under Investigation	Open
338	3/9/10			San Jose	Meter/Module	Under Investigation	Open
339	3/9/10			Seaside	Meter/Module	Under Investigation	Open
340	3/9/10			Cloverdale	Customer Denies Access	Customer does not want a SmartMeter	Resolved
341	3/9/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
342	3/10/10			Albany	Wellington Installer	Under Investigation	Open
343	3/10/10			ANGWIN	Wellington Installer	Under Investigation	Open
344	3/10/10			Berkeley	Wellington Installer	Under Investigation	Open
345	3/10/10			Cameron Park	Wellington Installer	Under Investigation	Open
346	3/10/10			Cupertino	Power Interruption	Under Investigation	Open
347	3/10/10			Daly City	Customer Denies Access	Under Investigation	Open
348	3/10/10			El Dorado Hills	Wellington Installer	Under Investigation	Open
349	3/10/10			Half Moon Bay	Customer Denies Access	Under Investigation	Open
350	3/10/10			Lemoore	Wellington Installer	Under Investigation	Open
351	3/10/10			Livermore	Customer Denies Access	Under Investigation	Open
352	3/10/10			Livermore	Household items affected by SM installation	Under Investigation	Open
353	3/10/10			Livermore	Meter/Module	Under Investigation	Open
354	3/10/10			Los Altos	Power Interruption	Under Investigation	Open
355	3/10/10			Martinez	Customer Denies Access	Under Investigation	Open
356	3/10/10			Mountain View	Customer Denies Access	Under Investigation	Open
357	3/10/10			Petaluma	Customer Denies Access	Under Investigation	Open
358	3/10/10			Pleasanton	Meter/Module	Under Investigation	Open
359	3/10/10			San Jose	Customer Denies Access	Under Investigation	Open
360	3/10/10			San Jose	Household items affected by SM installation	Under Investigation	Open
361	3/10/10			San Jose	Household items affected by SM installation	Under Investigation	Open
362	3/10/10			San Jose	Power Interruption	Under Investigation	Open
363	3/10/10			San Jose	Wellington Installer	Under Investigation	Open
364	3/10/10			San Jose	Wellington Installer	Under Investigation	Open
365	3/10/10			San Ramon	Meter/Module	Under Investigation	Open
366	3/10/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
367	3/10/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
368	3/10/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
369	3/10/10			Santa Rosa	Customer Denies Access	Under Investigation	Open

Page 9 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
370	3/10/10	Customer Name	Account	Santa Rosa	Customer Denies Access	Under Investigation	Open
370	3/10/10			Santa Rosa	Household items affected by SM installation	Under Investigation	Open
372	3/10/10			Sonoma	Customer Denies Access	Under Investigation	Open
372	3/10/10			Tracy	Meter/Module	Under Investigation	Open
373	3/10/10			Vallejo	Customer Denies Access	Under Investigation	Open
375	3/10/10			Mount Aukum	Customer Denies Access	Other	Resolved
375	3/10/10			Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
370	3/10/10			Saint Helena	Customer Denies Access	Customer does not want a SmartMeter	Resolved
378	3/10/10			Sunnyvale	Household items affected by SM installation	Motion/Sensor Appliance Malfunctioning	
379	3/11/10			Daly City	Customer Denies Access	Under Investigation	Open
380	3/11/10			San Francisco	Customer Denies Access	Under Investigation	Open
381	3/11/10			San Jose	Customer Denies Access	Under Investigation	Open
382	3/11/10			San Ramon	Customer Denies Access	Under Investigation	Open
383	3/11/10			DOBBINS	Customer Denies Access	Customer does not want a SmartMeter	Resolved
384	3/11/10			Richmond	Customer Denies Access	Other	Resolved
385	3/12/10			Berkeley	Customer Denies Access	Under Investigation	Open
386	3/12/10			GRIDLEY	Meter/Module	Under Investigation	Open
387	3/12/10			Livermore	Customer Denies Access	Under Investigation	Open
388	3/12/10			Livermore	Customer Denies Access	Under Investigation	Open
389	3/12/10			Los Altos	Meter/Module	Under Investigation	Open
390	3/12/10			Pleasanton	Customer Denies Access	Under Investigation	Open
391	3/12/10			San Francisco	Meter/Module	Under Investigation	Open
391	3/12/10			San Jose	Customer Denies Access	Under Investigation	Open
393	3/12/10			San Jose	Customer Denies Access	Under Investigation	Open
393	3/12/10			San Jose	Household items affected by SM installation	Under Investigation	Open
395	3/12/10			San Jose	Wellington Installer	Under Investigation	Open
396	3/12/10			San Ramon	Customer Denies Access	Under Investigation	Open
397	3/12/10			San Ramon	Customer Denies Access	Under Investigation	Open
398	3/12/10			San Ramon	Wellington Installer	Under Investigation	Open
399	3/12/10			Santa Clara	Other	Under Investigation	Open
400	3/12/10			Union City	Meter/Module	Under Investigation	Open
400	3/12/10			Vallejo	Customer Denies Access	Under Investigation	Open
401	3/12/10			√allejo	Wellington Installer	Under Investigation	Open
402	3/12/10			YOUNTVILLE	Power Interruption	Under Investigation	Open
403	3/12/10			Yuba City	Wellington Installer	Under Investigation	Open
404	3/12/10			Benicia	Wellington Installer	Damaged Other Household Appliances	Resolved
405	3/12/10			Fresno	Meter/Module	Meter/Module clearance issues	Resolved
400	3/13/10			Cupertino	Customer Denies Access	Under Investigation	Open
407	3/13/10			El Cerrito	Bad Meter / Module Equipment	Under Investigation	Open
408	3/14/10			Bakersfield	Household items affected by SM installation	Under Investigation	Open
409	3/15/10			Berkeley	Customer Denies Access	Under Investigation	Open
410	3/13/10		I	Derkeley	Customer Denies Access		Open

Page 10 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

	Complaint						
No.	Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
411	3/15/10				Household items affected by SM installation	Under Investigation	Open
412	3/15/10			MADISON	Household items affected by SM installation	Under Investigation	Open
413	3/15/10			Placerville	Customer Denies Access	Under Investigation	Open
414	3/15/10			Pleasanton	Wellington Installer	Under Investigation	Open
415	3/15/10			Redwood City	Wellington Installer	Under Investigation	Open
416	3/15/10			Richmond	Customer Denies Access	Under Investigation	Open
417	3/15/10			Richmond	Customer Denies Access	Under Investigation	Open
418	3/15/10			Richmond	Customer Denies Access	Under Investigation	Open
419	3/15/10			San Jose	Customer Denies Access	Under Investigation	Open
420	3/15/10			Tracy	Customer Denies Access	Under Investigation	Open
421	3/15/10			Tracy	Customer Denies Access	Under Investigation	Open
422	3/15/10			Newark	Customer Denies Access	Customer does not want a SmartMeter	Resolved
423	3/16/10			Angels Camp	Customer Denies Access	Under Investigation	Open
424	3/16/10			El Dorado Hills	Customer Denies Access	Under Investigation	Open
425	3/16/10			Livermore	Customer Denies Access	Under Investigation	Open
426	3/16/10			Livermore	Customer Denies Access	Under Investigation	Open
427	3/16/10			Martinez	Customer Denies Access	Under Investigation	Open
428	3/16/10			Placerville	Customer Denies Access	Under Investigation	Open
429	3/16/10			San Jose	Customer Denies Access	Under Investigation	Open
430	3/16/10			San Jose	Meter/Module	Under Investigation	Open
431	3/16/10			Stockton	Other	Under Investigation	Open
432	3/16/10			Sunnyvale	Customer Denies Access	Under Investigation	Open
433	3/16/10			Tracy	Meter/Module	Under Investigation	Open
434	3/16/10			Walnut Creek	Customer Denies Access	Under Investigation	Open
435	3/16/10			√allejo	Meter/Module	Meter/Module clearance issues	Resolved
436	3/17/10			Berkeley	Wellington Installer	Under Investigation	Open
437	3/17/10			Bodega Bay	Power Interruption	Under Investigation	Open
438	3/17/10			Cupertino	Customer Denies Access	Under Investigation	Open
439	3/17/10			Cupertino	Meter/Module	Under Investigation	Open
440	3/17/10			Livermore	Customer Denies Access	Under Investigation	Open
441	3/17/10			Livermore	Household items affected by SM installation	Under Investigation	Open
442	3/17/10			Los Altos	Customer Denies Access	Under Investigation	Open
443	3/17/10			Napa	Customer Denies Access	Under Investigation	Open
444	3/17/10			Pleasanton	Wellington Installer	Under Investigation	Open
445	3/17/10			Richmond	Customer Denies Access	Under Investigation	Open
446	3/17/10			San Jose	Customer Denies Access	Under Investigation	Open
447	3/17/10			San Jose	Household items affected by SM installation	Under Investigation	Open
448	3/17/10			San Jose	Household items affected by SM installation	Under Investigation	Open
449	3/17/10			San Jose	Wellington Installer	Under Investigation	Open
450	3/17/10			San Ramon	Customer Denies Access	Under Investigation	Open
451	3/17/10			San Ramon	Household items affected by SM installation	Under Investigation	Open
	0,11710	, <b>1</b>			- reserved home another by owninitalition		

Page 11 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name Accou	Int Service City	Core Process	Nature of Complaint	Status
452	3/17/10		Santa Clara	Meter/Module	Under Investigation	Open
453	3/17/10		Sunnyvale	Wellington Installer	Under Investigation	Open
454	3/17/10		Tracy	Customer Denies Access	Under Investigation	Open
455	3/17/10		Tracy	Customer Denies Access	Under Investigation	Open
456	3/17/10		Vacaville	Wellington Installer	Under Investigation	Open
457	3/18/10		Fremont	Power Interruption	Under Investigation	Open
458	3/18/10		Livermore	Customer Denies Access	Under Investigation	Open
459	3/18/10		San Jose	Customer Denies Access	Under Investigation	Open
460	3/18/10		San Jose	Meter/Module	Under Investigation	Open
461	3/18/10		Walnut Creek	Customer Denies Access	Under Investigation	Open
462	3/18/10		Reedley	SmartMeter Customer Communication	Other	Resolved
463	3/19/10		American Canyon	Customer Denies Access	Under Investigation	Open
464	3/19/10		Kensington	Household items affected by SM installation	Under Investigation	Open
465	3/19/10		San Jose	Customer Denies Access	Under Investigation	Open
466	3/19/10		San Ramon	Customer Denies Access	Under Investigation	Open
467	3/19/10		San Ramon	Customer Denies Access	Under Investigation	Open
468	3/19/10		Sanger	Other	Under Investigation	Open
469	3/19/10		Santa Rosa	Customer Denies Access	Under Investigation	Open
470	3/19/10		Santa Rosa	Wellington Installer	Under Investigation	Open
471	3/19/10		Sunnyvale	Power Interruption	Under Investigation	Open
472	3/19/10		Sunnyvale	Wellington Installer	Under Investigation	Open
473	3/19/10		Walnut Creek	Customer Denies Access	Under Investigation	Open
474	3/20/10		Union City	Customer Denies Access	Under Investigation	Open
475	3/20/10		S. San Francisco	Customer Denies Access	Customer does not want a SmartMeter	Resolved
476	3/21/10		Diamond Springs	Meter/Module	Under Investigation	Open
477	3/21/10		Martinez	Customer Denies Access	Under Investigation	Open
478	3/21/10		San Jose	Customer Denies Access	Under Investigation	Open
479	3/22/10		Antioch	Other	Under Investigation	Open
480	3/22/10		Berkeley	Customer Denies Access	Under Investigation	Open
481	3/22/10		Livermore	Customer Denies Access	Under Investigation	Open
482	3/22/10		Los Altos	Customer Denies Access	Under Investigation	Open
483	3/22/10		Martinez	Customer Denies Access	Under Investigation	Open
484	3/22/10		Saint Helena	Other	Under Investigation	Open
485	3/22/10		San Jose	Customer Denies Access	Under Investigation	Open
486	3/22/10		San Jose	Customer Denies Access	Under Investigation	Open
487	3/22/10		San Jose	Customer Denies Access	Under Investigation	Open
488	3/22/10		San Jose	Customer Denies Access	Under Investigation	Open
489	3/22/10		San Jose	Meter/Module	Under Investigation	Open
490	3/22/10		San Jose	Scheduling Problems	Under Investigation	Open
491	3/22/10		Sunnyvale	Household items affected by SM installation	Under Investigation	Open
492	3/22/10		Tracy	Customer Denies Access	Under Investigation	Open

Page 12 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

200 500

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
493	3/22/10	Customer Name	Account		Customer Denies Access	Under Investigation	Open
493	3/22/10			Tracy Tracy	Meter/Module	Under Investigation	Open
494	3/22/10			Tracy Lemoore	Customer Denies Access	Customer does not want a SmartMeter	Resolved
495	3/23/10			Berkeley	Customer Denies Access	Under Investigation	Open
490	3/23/10			Hercules	Customer Denies Access		Open
497	3/23/10			Lafayette	Customer Denies Access	Under Investigation Under Investigation	Open
498	3/23/10			Napa	Customer Denies Access	Under Investigation	Open
500	3/23/10			San Jose	Customer Denies Access	<b>T</b>	Open
500	3/23/10			San Jose	Customer Denies Access	Under Investigation	•
501	3/23/10			San Ramon		Under Investigation	Open Open
502	3/23/10			Santa Rosa	Household items affected by SM installation Customer Denies Access	Under Investigation	
503	3/23/10					Under Investigation Breaker keeps tripping	Open Resolved
504	3/23/10			El Sobrante	Power Interruption		Communication (Constraints of Constraints of Constr
				Berkeley	Wellington Installer	Under Investigation	Open
506	3/24/10			Clayton	Customer Denies Access	Under Investigation	Open
507	3/24/10			Martinez	Customer Denies Access	Under Investigation	Open
508	3/24/10			San Jose	Wellington Installer	Under Investigation	Open
509	3/24/10			Tracy	Customer Denies Access	Under Investigation	Open
510	3/24/10			Vallejo	Wellington Installer	Under Investigation	Open
511	3/25/10			Berkeley	Customer Denies Access	Under Investigation	Open
512	3/25/10			Dublin	Customer Denies Access	Under Investigation	Open
513	3/25/10			El Sobrante	Wellington Installer	Under Investigation	Open
514	3/25/10			Firebaugh	Wellington Installer	Under Investigation	Open
515	3/25/10			Livermore	Power Interruption	Under Investigation	Open
516	3/25/10			Los Altos	Meter/Module	Under Investigation	Open
517	3/25/10			Mariposa	Wellington Installer	Under Investigation	Open
518	3/25/10			MOSS BEACH	Customer Denies Access	Under Investigation	Open
519	3/25/10			PINE GROVE	Household items affected by SM installation	Under Investigation	Open
520	3/25/10			Richmond	Customer Denies Access	Under Investigation	Open
521	3/25/10			Rohnert Park	Customer Denies Access	Under Investigation	Open
522	3/25/10			San Jose	Customer Denies Access	Under Investigation	Open
523	3/25/10			San Jose	Customer Denies Access	Under Investigation	Open
524	3/25/10			San Jose	Meter/Module	Under Investigation	Open
525	3/25/10			San Jose	Other	Under Investigation	Open
526	3/25/10			San Jose	Wellington Installer	Under Investigation	Open
527	3/25/10			San Jose	Wellington Installer	Under Investigation	Open
528	3/25/10			San Jose	Wellington Installer	Under Investigation	Open
529	3/25/10			San Jose	Wellington Installer	Under Investigation	Open
530	3/25/10			San Jose	Wellington Installer	Under Investigation	Open
531	3/25/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
532	3/25/10			Somerset	Customer Denies Access	Under Investigation	Open
533	3/25/10			Walnut Creek	Customer Denies Access	Under Investigation	Open

Page 13 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
534	3/25/10			Benicia	Customer Denies Access	Customer does not want a SmartMeter	Resolved
535	3/25/10			Berkeley	Household items affected by SM installation	Internet/Cable Connection Problem	Resolved
536	3/25/10			Dixon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
537	3/25/10			Guerneville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
538	3/25/10			Placerville	Household items affected by SM installation	Damaged Television	Resolved
539	3/25/10			Sacramento	SmartMeter Customer Communication	UTC/CGI notification concern	Resolved
540	3/25/10			San Jose	Customer Denies Access	Customer Denies Wellington Access	Resolved
541	3/25/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
542	3/26/10			Calistoga	Wellington Installer	Under Investigation	Open
543	3/26/10			Livermore	Household items affected by SM installation	Under Investigation	Open
544	3/26/10			Mariposa	Household items affected by SM installation	Under Investigation	Open
545	3/26/10			Milpitas	Customer Denies Access	Under Investigation	Open
546	3/26/10			Mountain View	Household items affected by SM installation	Under Investigation	Open
547	3/26/10			Rohnert Park	Customer Denies Access	Under Investigation	Open
548	3/26/10			Rohnert Park	Customer Denies Access	Under Investigation	Open
549	3/26/10			San Jose	Customer Denies Access	Under Investigation	Open
550	3/26/10			San Jose	Customer Denies Access	Under Investigation	Open
551	3/26/10			Santa Cruz	Meter/Module	Under Investigation	Open
552	3/26/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
553	3/26/10			Sunnyvale	Household items affected by SM installation	Under Investigation	Open
554	3/26/10			Sunnyvale	Household items affected by SM installation	Under Investigation	Open
555	3/26/10			Vallejo	Wellington Installer	Under Investigation	Open
556	3/26/10			Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
557	3/26/10			Shingle Springs	Customer Denies Access	Customer does not want a SmartMeter	Resolved
558	3/26/10			Vacaville	Meter/Module	Other	Resolved
559	3/27/10			Pinole	Wellington Installer	Under Investigation	Open
560	3/27/10			Pleasanton	Wellington Installer	Under Investigation	Open
561	3/27/10			San Jose	Network Equipment Installation	Under Investigation	Open
562	3/27/10			San Jose	Wellington Installer	Under Investigation	Open
563	3/27/10			San Jose	Wellington Installer	Under Investigation	Open
564	3/27/10			San Pablo	Customer Denies Access	Under Investigation	Open
565	3/27/10			Sonoma	Customer Denies Access	Under Investigation	Open
566	3/27/10			Sunnyvale	Meter/Module	Under Investigation	Open
567	3/27/10			San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
568	3/27/10			Somerset	Customer Denies Access	Customer does not want a SmartMeter	Resolved
569	3/28/10			Citrus Heights	Network Equipment Installation	Under Investigation	Open
570	3/28/10			Oakhurst	Customer Denies Access	Under Investigation	Open
571	3/28/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
572	3/28/10			Tracy	Customer Denies Access	Under Investigation	Open
573	3/28/10			√allejo	Customer Denies Access	Under Investigation	Open
574	3/28/10			√allejo	SmartMeter Customer Communication	Under Investigation	Open
017	5726710	•		v anojo			open

Page 14 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

100

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

038 X.

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
575	3/28/10			Yuba City	Meter/Module	Under Investigation	Open
576	3/29/10			Berkeley	Customer Denies Access	Under Investigation	Open
577	3/29/10			Cotati	Customer Denies Access	Under Investigation	Open
578	3/29/10			Cupertino	Meter/Module	Under Investigation	Open
579	3/29/10			El Dorado Hills	Customer Denies Access	Under Investigation	Open
580	3/29/10			El Dorado Hills	Household items affected by SM installation	Under Investigation	Open
581	3/29/10			Martinez	Customer Denies Access	Under Investigation	Open
582	3/29/10			San Jose	Customer Denies Access	Under Investigation	Open
583	3/29/10			San Jose	Meter/Module	Under Investigation	Open
584	3/29/10			San Jose	Wellington Installer	Under Investigation	Open
585	3/29/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
586	3/29/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
587	3/29/10			Stockton	Meter/Module	Under Investigation	Open
588	3/29/10			Tracy	Customer Denies Access	Under Investigation	Open
589	3/29/10			Tracy	Meter/Module	Under Investigation	Open
590	3/29/10			Walnut Creek	Household items affected by SM installation	Under Investigation	Open
591	3/29/10			WINTERS	Household items affected by SM installation	Under Investigation	Open
592	3/29/10			AROMAS	Customer Denies Access	Customer does not want a SmartMeter	Resolved
593	3/29/10			El Dorado	Customer Denies Access	Customer does not want a SmartMeter	Resolved
594	3/29/10			Oakhurst	Customer Denies Access	Customer does not want a SmartMeter	Resolved
595	3/29/10			Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
596	3/29/10			Redding	Customer Denies Access	Customer Denies Wellington Access	Resolved
597	3/29/10			Redwood City	Customer Denies Access	Customer does not want a SmartMeter	Resolved
598	3/29/10			San Jose	Customer Denies Access	Other	Resolved
599	3/29/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
600	3/29/10			Sonoma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
601	3/29/10			Vallejo	Customer Denies Access	Customer does not want a SmartMeter	Resolved
602	3/30/10			Berkeley	Customer Denies Access	Under Investigation	Open
603	3/30/10			Berkeley	Customer Denies Access	Under Investigation	Open
604	3/30/10			Clayton	Customer Denies Access	Under Investigation	Open
605	3/30/10			Cupertino	Wellington Installer	Under Investigation	Open
606	3/30/10			Daly City	Customer Denies Access	Under Investigation	Open
607	3/30/10			Dublin	Meter/Module	Under Investigation	Open
608	3/30/10			Healdsburg	Customer Denies Access	Under Investigation	Open
609	3/30/10			Los Altos	Household items affected by SM installation	Under Investigation	Open
610	3/30/10			Los Altos	Meter/Module	Under Investigation	Open
611	3/30/10			Merced	Customer Denies Access	Under Investigation	Open
612	3/30/10			Napa	Other	Under Investigation	Open
613	3/30/10			Orosi	Customer Denies Access	Under Investigation	Open
614	3/30/10			S. San Francisco	Meter/Module	Under Investigation	Open
615	3/30/10			San Jose	Customer Denies Access	Under Investigation	Open

200 K

Page 15 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account Service City	Core Process	Nature of Complaint	Status
616	3/30/10		San Jose	Customer Denies Access	Under Investigation	Open
617	3/30/10		San Jose	Household items affected by SM installation	Under Investigation	Open
618	3/30/10		Santa Rosa	Customer Denies Access	Under Investigation	Open
619	3/30/10		Santa Rosa	Customer Denies Access	Under Investigation	Open
620	3/30/10		Santa Rosa	Wellington Installer	Under Investigation	Open
621	3/30/10		Sonoma	Customer Denies Access	Under Investigation	Open
622	3/30/10		Sonoma	Customer Denies Access	Under Investigation	Open
623	3/30/10		Sonoma	Customer Denies Access	Under Investigation	Open
624	3/30/10		Sunnyvale	Power Interruption	Under Investigation	Open
625	3/30/10		Cupertino	Household items affected by SM installation	Damaged Refrigerator	Resolved
626	3/30/10		San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
627	3/30/10		San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
628	3/30/10		San Jose	SmartMeter Customer Communication	Door hanger not left or placed incorrectly	Resolved
629	3/30/10		Santa Clara	Customer Denies Access	Customer does not want a SmartMeter	Resolved
630	3/30/10		Santa Clara	Customer Denies Access	Customer does not want a SmartMeter	Resolved
631	3/30/10		Tracy	Household items affected by SM installation	Other	Resolved
632	3/31/10		Berkeley	Customer Denies Access	Under Investigation	Open
633	3/31/10		Berkeley	Customer Denies Access	Under Investigation	Open
634	3/31/10		Fremont	Customer Denies Access	Under Investigation	Open
635	3/31/10		Guerneville	Customer Denies Access	Under Investigation	Open
636	3/31/10		Half Moon Bay	Wellington Installer	Under Investigation	Open
637	3/31/10		Marysville	Wellington Installer	Under Investigation	Open
638	3/31/10		Milpitas	Customer Denies Access	Under Investigation	Open
639	3/31/10		Napa	Other	Under Investigation	Open
640	3/31/10		Petaluma	Customer Denies Access	Under Investigation	Open
641	3/31/10		Pinole	Customer Denies Access	Under Investigation	Open
642	3/31/10		Rohnert Park	Customer Denies Access	Under Investigation	Open
643	3/31/10		Rohnert Park	Customer Denies Access	Under Investigation	Open
644	3/31/10		Rohnert Park	Customer Denies Access	Under Investigation	Open
645	3/31/10		San Jose	Customer Denies Access	Under Investigation	Open
646	3/31/10		San Jose	Power Interruption	Under Investigation	Open
647	3/31/10		San Jose	Power Interruption	Under Investigation	Open
648	3/31/10		Santa Clara	Customer Denies Access	Under Investigation	Open
649	3/31/10		Santa Rosa	Customer Denies Access	Under Investigation	Open
650	3/31/10		Santa Rosa	Meter/Module	Under Investigation	Open
651	3/31/10		Tracy	Scheduling Problems	Under Investigation	Open
652	3/31/10		√allejo	Customer Denies Access	Under Investigation	Open
653	3/31/10		√allejo	Customer Denies Access	Under Investigation	Open
654	3/31/10		Vallejo	Customer Denies Access	Under Investigation	Open
655	3/31/10		San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
656	3/31/10		San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved

Page 16 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

100

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
657	3/31/10			Santa Clara	Customer Denies Access	Customer does not want a SmartMeter	Resolved
658	4/1/10			Calistoga	Wellington Installer	Under Investigation	Open
659	4/1/10			Danville	Customer Denies Access	Under Investigation	Open
660	4/1/10			Hayward	Household items affected by SM installation	Under Investigation	Open
661	4/1/10			Hercules	Customer Denies Access	Under Investigation	Open
662	4/1/10			Hercules	Customer Denies Access	Under Investigation	Open
663	4/1/10			Lafayette	Scheduling Problems	Under Investigation	Open
664	4/1/10			Livermore	Household items affected by SM installation	Under Investigation	Open
665	4/1/10			Madera	Power Interruption	Under Investigation	Open
666	4/1/10			Petaluma	Customer Denies Access	Under Investigation	Open
667	4/1/10			Richmond	Customer Denies Access	Under Investigation	Open
668	4/1/10			San Jose	Customer Denies Access	Under Investigation	Open
669	4/1/10			San Jose	Customer Denies Access	Under Investigation	Open
670	4/1/10			San Jose	Customer Denies Access	Under Investigation	Open
671	4/1/10			San Jose	Household items affected by SM installation	Under Investigation	Open
672	4/1/10			San Jose	Household items affected by SM installation	Under Investigation	Open
673	4/1/10			San Jose	Meter/Module	Under Investigation	Open
674	4/1/10			San Lorenzo	Customer Denies Access	Under Investigation	Open
675	4/1/10			San Ramon	Customer Denies Access	Under Investigation	Open
676	4/1/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
677	4/1/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
678	4/1/10			Sonoma	Customer Denies Access	Under Investigation	Open
679	4/1/10			Tracy	Customer Denies Access	Under Investigation	Open
680	4/1/10			Tracy	Customer Denies Access	Under Investigation	Open
681	4/1/10			Tracy	Meter/Module	Under Investigation	Open
682	4/1/10			Napa	Power Interruption	Other	Resolved
683	4/1/10			San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
684	4/1/10			San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
685	4/1/10			San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
686	4/1/10			San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
687	4/1/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
688	4/2/10			Brentwood	Customer Denies Access	Under Investigation	Open
689	4/2/10			Danville	Customer Denies Access	Under Investigation	Open
690	4/2/10			Forestville	Customer Denies Access	Under Investigation	Open
691	4/2/10			Mountain View	Customer Denies Access	Under Investigation	Open
692	4/2/10			Petaluma	Customer Denies Access	Under Investigation	Open
693	4/2/10			Richmond	Customer Denies Access	Under Investigation	Open
694	4/2/10			Rohnert Park	Customer Denies Access	Under Investigation	Open
695	4/2/10			San Jose	Customer Denies Access	Under Investigation	Open
696	4/2/10			San Jose	Meter/Module	Under Investigation	Open
697	4/2/10			San Jose	Scheduling Problems	Under Investigation	Open

Page 17 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

100

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
698	4/2/10			San Jose	Wellington Installer	Under Investigation	Open
699	4/2/10			San Jose	Wellington Installer	Under Investigation	Open
700	4/2/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
701	4/2/10			Tracy	Customer Denies Access	Under Investigation	Open
702	4/2/10			√allejo	Other	Under Investigation	Open
703	4/2/10			Richmond	Scheduling Problems	Gas Appliance Not Working	Resolved
704	4/2/10			Yuba City	Customer Denies Access	Customer does not want a SmartMeter	Resolved
705	4/3/10			Milpitas	Customer Denies Access	Under Investigation	Open
706	4/3/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
707	4/3/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
708	4/3/10			Sunnyvale	Other	Under Investigation	Open
709	4/3/10			LATHROP	Meter/Module	Other	Resolved
710	4/5/10			Berkeley	Customer Denies Access	Under Investigation	Open
711	4/5/10			Berkeley	Customer Denies Access	Under Investigation	Open
712	4/5/10			Berkeley	Meter/Module	Under Investigation	Open
713	4/5/10			Campbell	Household items affected by SM installation	Under Investigation	Open
714	4/5/10			Danville	Customer Denies Access	Under Investigation	Open
715	4/5/10			Fowler	Customer Denies Access	Under Investigation	Open
716	4/5/10			KENWOOD	Customer Denies Access	Under Investigation	Open
717	4/5/10			Dakland	Household items affected by SM installation	Under Investigation	Open
718	4/5/10			Pinole	Other	Under Investigation	Open
719	4/5/10			Redding	Wellington Installer	Under Investigation	Open
720	4/5/10			Richmond	Customer Denies Access	Under Investigation	Open
721	4/5/10			San Jose	Customer Denies Access	Under Investigation	Open
722	4/5/10			San Jose	Household items affected by SM installation	Under Investigation	Open
723	4/5/10			San Jose	Household items affected by SM installation	Under Investigation	Open
724	4/5/10			San Jose	Household items affected by SM installation	Under Investigation	Open
725	4/5/10			San Jose	Household items affected by SM installation	Under Investigation	Open
726	4/5/10			San Jose	Wellington Installer	Under Investigation	Open
727	4/5/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
728	4/5/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
729	4/5/10			Santa Rosa	Household items affected by SM installation	Under Investigation	Open
730	4/5/10			Santa Rosa	Wellington Installer	Under Investigation	Open
731	4/5/10			Sonoma	Customer Denies Access	Under Investigation	Open
732	4/5/10			Tracy	Household items affected by SM installation	Under Investigation	Open
733	4/5/10			Vacaville	Other	Under Investigation	Open
734	4/5/10			Walnut Creek	Customer Denies Access	Under Investigation	Open
735	4/5/10			Fremont	Household items affected by SM installation	Partial Power Outage	Resolved
736	4/5/10			Dakland	Household items affected by SM installation	Other	Resolved
737	4/6/10			Berkeley	Customer Denies Access	Under Investigation	Open
738	4/6/10			Berkeley	Wellington Installer	Under Investigation	Open

333

Page 18 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

100

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

S. 197

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
739	4/6/10			Castro Valley	Household items affected by SM installation	Under Investigation	Open
740	4/6/10			Danville	Household items affected by SM installation	Under Investigation	Open
741	4/6/10			GEYSERVILLE	Customer Denies Access	Under Investigation	Open
742	4/6/10			Hanford	Customer Denies Access	Under Investigation	Open
743	4/6/10			Hercules	Customer Denies Access	Under Investigation	Open
744	4/6/10			Lemoore	Customer Denies Access	Under Investigation	Open
745	4/6/10			Los Altos	Household items affected by SM installation	Under Investigation	Open
746	4/6/10			MILL VALLEY	Other	Under Investigation	Open
747	4/6/10			Petaluma	Customer Denies Access	Under Investigation	Open
748	4/6/10			Pleasanton	Customer Denies Access	Under Investigation	Open
749	4/6/10			Richmond	Customer Denies Access	Under Investigation	Open
750	4/6/10			Rohnert Park	Customer Denies Access	Under Investigation	Open
751	4/6/10			Rohnert Park	Customer Denies Access	Under Investigation	Open
752	4/6/10			San Jose	Household items affected by SM installation	Under Investigation	Open
753	4/6/10			San Jose	Meter/Module	Under Investigation	Open
754	4/6/10			San Jose	Power Interruption	Under Investigation	Open
755	4/6/10			San Jose	Power Interruption	Under Investigation	Open
756	4/6/10			San Rafael	Customer Denies Access	Under Investigation	Open
757	4/6/10			Santa Clara	Other	Under Investigation	Open
758	4/6/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
759	4/6/10			Sunnyvale	Scheduling Problems	Under Investigation	Open
760	4/6/10			Tracy	Customer Denies Access	Under Investigation	Open
761	4/6/10			Tracy	Other	Under Investigation	Open
762	4/6/10			Tracy	Wellington Installer	Under Investigation	Open
763	4/6/10			√allejo	Customer Denies Access	Under Investigation	Open
764	4/6/10			VERNALIS	Customer Denies Access	Under Investigation	Open
765	4/6/10			VERNALIS	Customer Denies Access	Under Investigation	Open
766	4/6/10			WINDSOR	Customer Denies Access	Under Investigation	Open
767	4/6/10			Cupertino	Customer Denies Access	Customer does not want a SmartMeter	Resolved
768	4/6/10			Fairfield	Customer Denies Access	Customer does not want a SmartMeter	Resolved
769	4/6/10			Forestville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
770	4/6/10			Pollock Pines	Customer Denies Access	Customer does not want a SmartMeter	Resolved
771	4/6/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
772	4/7/10			Berkeley	Customer Denies Access	Under Investigation	Open
773	4/7/10			Berkeley	Other	Under Investigation	Open
774	4/7/10			Concord	Meter/Module	Under Investigation	Open
775	4/7/10			Dublin	Household items affected by SM installation	Under Investigation	Open
776	4/7/10			El Sobrante	Customer Denies Access	Under Investigation	Open
777	4/7/10			El Sobrante	Customer Denies Access	Under Investigation	Open
778	4/7/10			GRATON	Customer Denies Access	Under Investigation	Open
779	4/7/10			GRATON	Customer Denies Access	Under Investigation	Open

Page 19 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

100

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
780	4/7/10			Guerneville	Customer Denies Access	Under Investigation	Open
781	4/7/10			NVERNESS	Customer Denies Access	Under Investigation	Open
782	4/7/10			Livermore	Customer Denies Access	Under Investigation	Open
783	4/7/10			Pinole	Power Interruption	Under Investigation	Open
784	4/7/10			Richmond	Customer Denies Access	Under Investigation	Open
785	4/7/10			Richmond	Other	Under Investigation	Open
786	4/7/10			Richmond	Scheduling Problems	Under Investigation	Open
787	4/7/10			San Jose	Wellington Installer	Under Investigation	Open
788	4/7/10			San Jose	Wellington Installer	Under Investigation	Open
789	4/7/10			San Ramon	Other	Under Investigation	Open
790	4/7/10			San Ramon	Power Interruption	Under Investigation	Open
791	4/7/10			Sanger	Customer Denies Access	Under Investigation	Open
792	4/7/10			Santa Clara	Wellington Installer	Under Investigation	Open
793	4/7/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
794	4/7/10			Santa Rosa	Household items affected by SM installation	Under Investigation	Open
795	4/7/10			Sebastopol	Customer Denies Access	Under Investigation	Open
796	4/7/10			Sunnyvale	Other	Under Investigation	Open
797	4/7/10			El Dorado Hills	Household items affected by SM installation	Damaged Television	Resolved
798	4/7/10			Forestville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
799	4/7/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
800	4/8/10			Benicia	Household items affected by SM installation	Under Investigation	Open
801	4/8/10			Berkeley	Customer Denies Access	Under Investigation	Open
802	4/8/10			Berkeley	Customer Denies Access	Under Investigation	Open
803	4/8/10			Berkeley	Other	Under Investigation	Open
804	4/8/10			Cupertino	Customer Denies Access	Under Investigation	Open
805	4/8/10			Guerneville	Customer Denies Access	Under Investigation	Open
806	4/8/10			Livermore	Meter/Module	Under Investigation	Open
807	4/8/10			Los Altos	Household items affected by SM installation	Under Investigation	Open
808	4/8/10			Napa	Customer Denies Access	Under Investigation	Open
809	4/8/10			Napa	Household items affected by SM installation	Under Investigation	Open
810	4/8/10			Napa	Household items affected by SM installation	Under Investigation	Open
811	4/8/10			Petaluma	Power Interruption	Under Investigation	Open
812	4/8/10			Pleasanton	Customer Denies Access	Under Investigation	Open
813	4/8/10			Richmond	Household items affected by SM installation	Under Investigation	Open
814	4/8/10			Richmond	Wellington Installer	Under Investigation	Open
815	4/8/10			San Jose	Customer Denies Access	Under Investigation	Open
816	4/8/10			San Jose	Customer Denies Access	Under Investigation	Open
817	4/8/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
818	4/8/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
819	4/8/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
820	4/8/10			Santa Rosa	Customer Denies Access	Under Investigation	Open

Page 20 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
4/8/10	Customer Nume	Recount	Santa Rosa	Customer Denies Access	Under Investigation	Open
4/8/10			Sebastopol	Customer Denies Access	Under Investigation	Open
			•			Open
						Open
						Open
4/8/10			El Dorado Hills	Wellington Installer		Resolved
4/8/10			Fresno	Customer Denies Access		Resolved
						Resolved
						Resolved
						Resolved
						Resolved
						Resolved
						Resolved
			· · · · ·			Resolved
			· · · ·	2		Open
					-	Open
						Open
						Open
						Open
						Open
4/9/10			San Anselmo	× •		Open
4/9/10			Santa Rosa	· ·		Open
4/9/10				Customer Denies Access		Open
			Tiburon		<b>X</b>	Open
			Milpitas			Resolved
4/9/10						Resolved
4/9/10					Other	Resolved
4/9/10			San Jose		Damaged Computer	Resolved
4/9/10			Santa Rosa		Customer does not want a SmartMeter	Resolved
					Customer does not want a SmartMeter	Resolved
4/9/10					Damaged Other Household Appliances	Resolved
4/10/10			Aptos	Household items affected by SM installation		Open
4/11/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
4/12/10			Alamo	Customer Denies Access	Under Investigation	Open
4/12/10			Berkeley	Customer Denies Access	Under Investigation	Open
4/12/10			Berkeley	Customer Denies Access		Open
4/12/10			Berkeley	Meter/Module	Under Investigation	Open
4/12/10			El Cerrito	Other		Open
4/12/10			Guerneville	Customer Denies Access	Under Investigation	Open
4/12/10			Mountain View	Household items affected by SM installation	Under Investigation	Open
					· · · ·	Open
	4/8/10 4/8/10 4/8/10 4/8/10 4/8/10 4/8/10 4/8/10 4/8/10 4/8/10 4/8/10 4/8/10 4/8/10 4/8/10 4/8/10 4/9/10 4/12/10 4/12/10 4/12/10 4/12/10 4/12/10	4/8/10         4/8/10         4/8/10         4/8/10         4/8/10         4/8/10         4/8/10         4/8/10         4/8/10         4/8/10         4/8/10         4/8/10         4/8/10         4/8/10         4/8/10         4/8/10         4/8/10         4/8/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/10/10         4/12/10         4/12/10         4/12/10         4/12/10         4/12/10	4/8/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/9/10         4/10/10         4/12/10         4/12/10         4/12/10         4/12/10         4/12/10	4/8/10       Jkiah         4/8/10       Walnut Creek         4/8/10       El Dorado Hills         4/8/10       Fresno         4/8/10       San Jose         4/8/10       San Jose         4/8/10       San Jose         4/8/10       San Jose         4/8/10       Yuba City         4/8/10       Alameda         4/8/10       San Jose         4/9/10       San Francisco         4/9/10       San Jose         4/9/10       Santa Rosa         4/9/10       Santa Rosa         4/9/10       Santa Rosa         4/9/10       Santa Rosa         4/9/10       Santa Rosa <td>4/8/10       Jkiah       Other         4/8/10       Wahut Creek       Customer Denies Access         4/8/10       Wahut Creek       Household Items affected by SM installation         4/8/10       Wellington Installer       Fresno         4/8/10       Customer Denies Access       Customer Denies Access         4/8/10       San Jose       Customer Denies Access         4/8/10       San Jose       Meter/Module         3an Jose       Other       San Jose         4/8/10       Yuta       Tracy       Household Items affected by SM installation         4/8/10       Yuta       Customer Denies Access       Yuta         4/8/10       Yuta       Tracy       Household Items affected by SM installation         4/8/10       Yuta       Customer Denies Access       Yuta         4/8/10       Yuta       Other       Napa       Schmond         4/8/10       Yuta       Customer Denies Access       Yuta       Yuta         4/8/10       Yuta       Customer Denies Access       Yuta       Yuta         4/8/10       Schmond       Wellington Installer       Yuta         4/9/10       Sant Anselmo       Sad Meter / Module Equipment       Sant Anselmo       Sat Meter</td> <td>48/10     Julain     Other     Under investigation       48/10     AB/10     Aainut Creek     Customer Denies Access     Under Investigation       48/10     Aainut Creek     Household items affected by SM installation     Under Investigation       48/10     Customer Denies Access     Customer does not want a SmartMeter       48/10     Sa Banos     Customer Denies Access     Customer does not want a SmartMeter       48/10     Sa Jose     Meter/Module     Other       48/10     San Jose     Other     Other       48/10     San Jose     Other     Other       48/10     Aained     Other     Under Investigation       48/10     Aained     Other     Under Investigation       48/10     Aained     Other     Under Investigation       49/10     Aained     Other     Under Investigation       49/10     San Asse     Other     Under Investigation       49/10     San Assea     Other     Under Investigation</td>	4/8/10       Jkiah       Other         4/8/10       Wahut Creek       Customer Denies Access         4/8/10       Wahut Creek       Household Items affected by SM installation         4/8/10       Wellington Installer       Fresno         4/8/10       Customer Denies Access       Customer Denies Access         4/8/10       San Jose       Customer Denies Access         4/8/10       San Jose       Meter/Module         3an Jose       Other       San Jose         4/8/10       Yuta       Tracy       Household Items affected by SM installation         4/8/10       Yuta       Customer Denies Access       Yuta         4/8/10       Yuta       Tracy       Household Items affected by SM installation         4/8/10       Yuta       Customer Denies Access       Yuta         4/8/10       Yuta       Other       Napa       Schmond         4/8/10       Yuta       Customer Denies Access       Yuta       Yuta         4/8/10       Yuta       Customer Denies Access       Yuta       Yuta         4/8/10       Schmond       Wellington Installer       Yuta         4/9/10       Sant Anselmo       Sad Meter / Module Equipment       Sant Anselmo       Sat Meter	48/10     Julain     Other     Under investigation       48/10     AB/10     Aainut Creek     Customer Denies Access     Under Investigation       48/10     Aainut Creek     Household items affected by SM installation     Under Investigation       48/10     Customer Denies Access     Customer does not want a SmartMeter       48/10     Sa Banos     Customer Denies Access     Customer does not want a SmartMeter       48/10     Sa Jose     Meter/Module     Other       48/10     San Jose     Other     Other       48/10     San Jose     Other     Other       48/10     Aained     Other     Under Investigation       48/10     Aained     Other     Under Investigation       48/10     Aained     Other     Under Investigation       49/10     Aained     Other     Under Investigation       49/10     San Asse     Other     Under Investigation       49/10     San Assea     Other     Under Investigation

Page 21 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

100

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
862	4/12/10			San Jose	Customer Denies Access	Under Investigation	Open
863	4/12/10			San Jose	Household items affected by SM installation	Under Investigation	Open
864	4/12/10			San Jose	Household items affected by SM installation	Under Investigation	Open
865	4/12/10			San Jose	Meter/Module	Under Investigation	Open
866	4/12/10			San Pablo	Customer Denies Access	Under Investigation	Open
867	4/12/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
868	4/12/10			Santa Rosa	Wellington Installer	Under Investigation	Open
869	4/12/10			Fairfield	Customer Denies Access	Customer does not want a SmartMeter	Resolved
870	4/12/10			Marysville	Customer Denies Access	Customer Denies Wellington Access	Resolved
871	4/12/10			Redwood City	Customer Denies Access	Customer does not want a SmartMeter	Resolved
872	4/12/10			Richmond	Other	Other	Resolved
873	4/12/10			Richmond	Other	Other	Resolved
874	4/12/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
875	4/12/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
876	4/12/10			Sebastopol	Customer Denies Access	Customer does not want a SmartMeter	Resolved
877	4/12/10			√allejo	Household items affected by SM installation	Other	Resolved
878	4/12/10			Wheatland	Customer Denies Access	Customer Denies Wellington Access	Resolved
879	4/13/10			Berkeley	Customer Denies Access	Under Investigation	Open
880	4/13/10			Berkeley	Customer Denies Access	Under Investigation	Open
881	4/13/10			Berkeley	Customer Denies Access	Under Investigation	Open
882	4/13/10			Chowchilla	Bad Meter / Module Equipment	Under Investigation	Open
883	4/13/10			Forestville	Customer Denies Access	Under Investigation	Open
884	4/13/10			Hercules	Power Interruption	Under Investigation	Open
885	4/13/10			Hercules	Power Interruption	Under Investigation	Open
886	4/13/10			Hercules	Power Interruption	Under Investigation	Open
887	4/13/10			Merced	Power Interruption	Under Investigation	Open
888	4/13/10			Monterey	Customer Denies Access	Under Investigation	Open
889	4/13/10			OCCIDENTAL	Customer Denies Access	Under Investigation	Open
890	4/13/10			Placerville	Customer Denies Access	Under Investigation	Open
891	4/13/10			San Francisco	SmartMeter Customer Communication	Under Investigation	Open
892	4/13/10			San Jose	Customer Denies Access	Under Investigation	Open
893	4/13/10			San Jose	Household items affected by SM installation	Under Investigation	Open
894	4/13/10			San Jose	Meter/Module	Under Investigation	Open
895	4/13/10			San Jose	Power Interruption	Under Investigation	Open
896	4/13/10			San Jose	Power Interruption	Under Investigation	Open
897	4/13/10			San Ramon	Household items affected by SM installation	Under Investigation	Open
898	4/13/10			San Ramon	Other	Under Investigation	Open
899	4/13/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
900	4/13/10			Walnut Creek	Customer Denies Access	Under Investigation	Open
901	4/13/10			ANGWIN	Customer Denies Access	Customer does not want a SmartMeter	Resolved
902	4/13/10			El Cerrito	Power Interruption	Breaker keeps tripping	Resolved

Page 22 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

	Complaint						
No.	Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
903	4/13/10			Richmond	Household items affected by SM installation	Damaged Other Household Appliances	Resolved
904	4/13/10			Sebastopol	Customer Denies Access	Customer does not want a SmartMeter	Resolved
905	4/13/10			√allejo	Customer Denies Access	Customer does not want a SmartMeter	Resolved
906	4/13/10			Yuba City	Other	Other	Resolved
907	4/13/10			Yuba City	Other	Other	Resolved
908	4/14/10			BEAR VALLEY	Meter/Module	Under Investigation	Open
909	4/14/10			Berkeley	Customer Denies Access	Under Investigation	Open
910	4/14/10			Berkeley	Customer Denies Access	Under Investigation	Open
911	4/14/10			Berkeley	Customer Denies Access	Under Investigation	Open
912	4/14/10			El Cerrito	Customer Denies Access	Under Investigation	Open
913	4/14/10			KENWOOD	Customer Denies Access	Under Investigation	Open
914	4/14/10			Kingsburg	Power Interruption	Under Investigation	Open
915	4/14/10			Madera	Wellington Installer	Under Investigation	Open
916	4/14/10			Napa	Power Interruption	Under Investigation	Open
917	4/14/10			Orinda	Other	Under Investigation	Open
918	4/14/10			Petaluma	Household items affected by SM installation	Under Investigation	Open
919	4/14/10			Petaluma	Power Interruption	Under Investigation	Open
920	4/14/10			Richmond	Customer Denies Access	Under Investigation	Open
921	4/14/10			Richmond	Customer Denies Access	Under Investigation	Open
922	4/14/10			San Jose	Customer Denies Access	Under Investigation	Open
923	4/14/10			San Jose	Customer Denies Access	Under Investigation	Open
924	4/14/10			San Jose	Customer Denies Access	Under Investigation	Open
925	4/14/10			San Jose	Customer Denies Access	Under Investigation	Open
926	4/14/10			San Jose	Customer Denies Access	Under Investigation	Open
927	4/14/10			San Jose	Household items affected by SM installation	Under Investigation	Open
928	4/14/10			San Jose	Household items affected by SM installation	Under Investigation	Open
929	4/14/10			San Jose	Other	Under Investigation	Open
930	4/14/10			San Jose	SmartMeter Customer Communication	Under Investigation	Open
931	4/14/10			San Jose	Wellington Installer	Under Investigation	Open
932	4/14/10			San Mateo	Household items affected by SM installation	Under Investigation	Open
933	4/14/10			San Ramon	Customer Denies Access	Under Investigation	Open
934	4/14/10			San Ramon	Power Interruption	Under Investigation	Open
935	4/14/10			Sebastopol	Customer Denies Access	Under Investigation	Open
936	4/14/10			Tracy	Power Interruption	Under Investigation	Open
937	4/14/10			Walnut Creek	Customer Denies Access	Under Investigation	Open
938	4/14/10			Bakersfield	Meter/Module	Meter/Module clearance issues	Resolved
939	4/14/10			Bakersfield	Power Interruption	Partial Power Outage	Resolved
940	4/14/10			Fowler	Customer Denies Access	Other	Resolved
941	4/14/10			PLUMAS LAKE	Customer Denies Access	Customer does not want a SmartMeter	Resolved
942	4/14/10			Rohnert Park	Customer Denies Access	Customer does not want a SmartMeter	Resolved
943	4/14/10			San Anselmo	Customer Denies Access	Customer does not want a SmartMeter	Resolved

Page 23 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
944	4/14/10			San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
945	4/14/10			Tracy	Customer Denies Access	Customer does not want a SmartMeter	Resolved
946	4/14/10			√allejo	Household items affected by SM installation	Motion/Sensor Appliance Malfunctioning	Resolved
947	4/14/10			Yuba City	Customer Denies Access	Customer Denies Wellington Access	Resolved
948	4/15/10			Berkeley	Customer Denies Access	Under Investigation	Open
949	4/15/10			Berkeley	Customer Denies Access	Under Investigation	Open
950	4/15/10			Berkeley	Household items affected by SM installation	Under Investigation	Open
951	4/15/10			Berkeley	Household items affected by SM installation	Under Investigation	Open
952	4/15/10			Berkeley	Other	Under Investigation	Open
953	4/15/10			El Cerrito	Household items affected by SM installation	Under Investigation	Open
954	4/15/10			El Cerrito	Household items affected by SM installation	Under Investigation	Open
955	4/15/10			Forestville	Customer Denies Access	Under Investigation	Open
956	4/15/10			Fremont	Customer Denies Access	Under Investigation	Open
957	4/15/10			Hanford	Meter/Module	Under Investigation	Open
958	4/15/10			Madera	Other	Under Investigation	Open
959	4/15/10			Napa	Customer Denies Access	Under Investigation	Open
960	4/15/10			Pittsburg	Other	Under Investigation	Open
961	4/15/10			Richmond	Customer Denies Access	Under Investigation	Open
962	4/15/10			San Jose	Customer Denies Access	Under Investigation	Open
963	4/15/10			San Jose	Customer Denies Access	Under Investigation	Open
964	4/15/10			San Jose	Customer Denies Access	Under Investigation	Open
965	4/15/10			San Jose	Customer Denies Access	Under Investigation	Open
966	4/15/10			San Jose	Customer Denies Access	Under Investigation	Open
967	4/15/10			San Jose	Household items affected by SM installation	Under Investigation	Open
968	4/15/10			San Jose	Other	Under Investigation	Open
969	4/15/10			San Jose	Other	Under Investigation	Open
970	4/15/10			San Jose	SmartMeter Customer Communication	Under Investigation	Open
971	4/15/10			San Jose	Wellington Installer	Under Investigation	Open
972	4/15/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
973	4/15/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
974	4/15/10			Santa Rosa	Wellington Installer	Under Investigation	Open
975	4/15/10			Tracy	Meter/Module	Under Investigation	Open
976	4/15/10			Tracy	Power Interruption	Under Investigation	Open
977	4/15/10			√allejo	Customer Denies Access	Under Investigation	Open
978	4/15/10			ANGWIN	Customer Denies Access	Customer does not want a SmartMeter	Resolved
979	4/15/10			Antioch	Meter/Module	Other	Resolved
980	4/15/10			El Dorado Hills	Household items affected by SM installation	Internet/Cable Connection Problem	Resolved
981	4/15/10			El Dorado Hills	Household items affected by SM installation	Other	Resolved
982	4/15/10			Forestville	Customer Denies Access	Customer Denies Wellington Access	Resolved
983	4/15/10			Forestville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
984	4/15/10			Richmond	Power Interruption	Flickering Lights	Resolved

Page 24 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
985	4/15/10			San Francisco	Customer Denies Access	Customer does not want a SmartMeter	Resolved
986	4/15/10			San Francisco	Meter/Module	Meter/Module clearance issues	Resolved
987	4/15/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
988	4/15/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
989	4/15/10			Santa Rosa	Other	Other	Resolved
990	4/15/10			Soda Springs	Meter/Module	Other	Resolved
991	4/15/10			Tracy	Customer Denies Access	Customer does not want a SmartMeter	Resolved
992	4/15/10			Tracy	Household items affected by SM installation	Other	Resolved
993	4/15/10			Vallejo	Power Interruption	Partial Power Outage	Resolved
994	4/15/10			Yuba City	Customer Denies Access	Customer Denies Wellington Access	Resolved
995	4/15/10			Yuba City	Household items affected by SM installation	Damaged Other Household Appliances	Resolved
996	4/16/10			Berkeley	Power Interruption	Under Investigation	Open
997	4/16/10			Forestville	Customer Denies Access	Under Investigation	Open
998	4/16/10			Healdsburg	Wellington Installer	Under Investigation	Open
999	4/16/10			Live Oak	Household items affected by SM installation	Under Investigation	Open
1000	4/16/10			Madera	Meter/Module	Under Investigation	Open
1001	4/16/10			Madera	Power Interruption	Under Investigation	Open
1002	4/16/10			Milpitas	Customer Denies Access	Under Investigation	Open
1003	4/16/10			Novato	Meter/Module	Under Investigation	Open
1004	4/16/10			Petaluma	Customer Denies Access	Under Investigation	Open
1005	4/16/10			Pinole	Customer Denies Access	Under Investigation	Open
1006	4/16/10			San Jose	Customer Denies Access	Under Investigation	Open
1007	4/16/10			San Jose	Scheduling Problems	Under Investigation	Open
1008	4/16/10			Tracy	Household items affected by SM installation	Under Investigation	Open
1009	4/16/10			El Dorado	Household items affected by SM installation	Other	Resolved
1010	4/16/10			El Dorado Hills	Household items affected by SM installation	Damaged Computer	Resolved
1011	4/16/10			Rohnert Park	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1012	4/16/10			Santa Cruz	Customer Denies Access	Radio Frequency Concern	Resolved
1013	4/16/10			Vallejo	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1014	4/17/10			San Jose	Household items affected by SM installation	Under Investigation	Open
1015	4/17/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
1016	4/17/10			Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1017	4/19/10			Berkeley	Customer Denies Access	Under Investigation	Open
1018	4/19/10			Berkeley	Household items affected by SM installation	Under Investigation	Open
1019	4/19/10			Brentwood	Household items affected by SM installation	Under Investigation	Open
1020	4/19/10			Calistoga	Meter/Module	Under Investigation	Open
1021	4/19/10			Cupertino	Meter/Module	Under Investigation	Open
1022	4/19/10			Cupertino	Power Interruption	Under Investigation	Open
1023	4/19/10			Dos Palos	Customer Denies Access	Under Investigation	Open
1024	4/19/10			El Cerrito	Household items affected by SM installation	Under Investigation	Open
1025	4/19/10			El Sobrante	Customer Denies Access	Under Investigation	Open

Page 25 of 34

SB\_GT&S\_0783758

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

200 52/2

1202       4/19/10       Fairfax       Customer Denies Access       Under Investigation         1202       4/19/10       Customer Denies Access       Under Investigation         1203       4/19/10       Customer Denies Access       Under Investigation         1203       4/19/10       Customer Denies Access       Under Investigation         1203       4/19/10       Madra       Weilington Installer       Under Investigation         1203       4/19/10       Mipitas       Other Investigation       Mipitas         1203       4/19/10       Mipitas       Other Investigation       Mipitas         1203       4/19/10       Moletamme Hill       Power Interruption       Under Investigation         1203       4/19/10       Otakiand       Customer Denies Access       Under Investigation         1203       4/19/10       Dakiand       Customer Denies Access       Under Investigation         1203       4/19/10       Dakiand       Customer Denies Access       Under Investigation         1204       4/19/10       Dakiand       Customer Denies Access       Under Investigation         1204       4/19/10       Ban Access       Under Investigation       Dakiand         1204       4/19/10       Ban Access       Und	No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1027         4/19/10           1028         4/19/10           1029         4/19/10           1030         4/19/10           1031         4/19/10           1032         4/19/10           1033         4/19/10           1033         4/19/10           1033         4/19/10           1033         4/19/10           1033         4/19/10           1033         4/19/10           1034         4/19/10           1035         4/19/10           1034         4/19/10           1035         4/19/10           1035         4/19/10           1036         4/19/10           1037         4/19/10           1038         4/19/10           1038         4/19/10           1039         4/19/10           1034         4/19/10           1034         4/19/10           1034         4/19/10           1034         4/19/10           1034         4/19/10           1034         4/19/10           1042         4/19/10           1043         4/19/10           1044         4/19/10 <td></td> <td></td> <td>Customer hume</td> <td>Recount</td> <td></td> <td></td> <td></td> <td>Open</td>			Customer hume	Recount				Open
1028       4/19/10         1029       4/19/10         1030       4/19/10         1031       4/19/10         1032       4/19/10         1033       4/19/10         1034       4/19/10         1035       4/19/10         1036       4/19/10         1037       4/19/10         1038       4/19/10         1034       4/19/10         1035       4/19/10         1036       4/19/10         1037       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1039       4/19/10         1040       4/19/10         1041       4/19/10         1042       4/19/10         1043       4/19/10         1044       4/19/10         1045       4/19/10         1046       4/19/10         1047       4/19/10         1048       4/19/10 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Open</td>								Open
1022       4/19/10         1030       4/19/10         1031       4/19/10         1032       4/19/10         1033       4/19/10         1034       4/19/10         1035       4/19/10         1034       4/19/10         1035       4/19/10         1034       4/19/10         1035       4/19/10         1036       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1039       4/19/10         1041       4/19/10         1042       4/19/10         1042       4/19/10         1043       4/19/10         1044       4/19/10         1043       4/19/10         1044       4/19/10         1043       4/19/10         1044       4/19/10         1045       4/19/10         1046       4/19/10         1047       4/19/10         1048       4/19/10 <td>-</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>-</td> <td>Open</td>	-						-	Open
1030       4/19/10         1031       4/19/10         1032       4/19/10         1033       4/19/10         1034       4/19/10         1035       4/19/10         1034       4/19/10         1035       4/19/10         1036       4/19/10         1037       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1039       4/19/10         1041       4/19/10         1044       4/19/10         1044       4/19/10         1044       4/19/10         1044       4/19/10         1044       4/19/10         1044       4/19/10         1045       4/19/10         1044       4/19/10         1045       4/19/10         1044       4/19/10         1045       4/19/10         1046       4/19/10         1047       4/19/10         1048       4/19/10         1044       4/19/10         1045       4/19/10 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Open</td>								Open
1031       4/19/10         1032       4/19/10         1033       4/19/10         1034       4/19/10         1035       4/19/10         1036       4/19/10         1037       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1039       4/19/10         1040       4/19/10         1041       4/19/10         1042       4/19/10         1042       4/19/10         1043       4/19/10         1044       4/19/10         1045       4/19/10         1044       4/19/10         1045       4/19/10         1046       4/19/10         1047       4/19/10         1048       4/19/10         1044       4/19/10         1045       4/19/10         1046       4/19/10         1047       4/19/10 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td><b>v</b></td> <td>Open</td>							<b>v</b>	Open
1032         4/19/10           1033         4/19/10           1034         4/19/10           1035         4/19/10           1036         4/19/10           1037         4/19/10           1038         4/19/10           1036         4/19/10           1037         4/19/10           1038         4/19/10           1038         4/19/10           1038         4/19/10           1038         4/19/10           1038         4/19/10           1038         4/19/10           1041         4/19/10           1042         4/19/10           1043         4/19/10           1044         4/19/10           1044         4/19/10           1044         4/19/10           1044         4/19/10           1045         4/19/10           1046         4/19/10           1046         4/19/10           1047         4/19/10           1048         4/19/10           1044         4/19/10           1045         4/19/10           1046         4/19/10           1047         4/19/10 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Open</td>								Open
1033       4/19/10         1034       4/19/10         1035       4/19/10         1036       4/19/10         1036       4/19/10         1037       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1038       4/19/10         1039       4/19/10         1040       4/19/10         1041       4/19/10         1042       4/19/10         1043       4/19/10         1044       4/19/10         1045       4/19/10         1044       4/19/10         1045       4/19/10         1044       4/19/10         1045       4/19/10         1044       4/19/10         1045       4/19/10         1044       4/19/10         1045       4/19/10         1046       4/19/10         1047       4/19/10         1048       4/19/10         1044       4/19/10         1045       4/19/10         1046       4/19/10         1047       4/19/10         1048       4/19/10 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Open</td>								Open
10344/19/1010354/19/1010364/19/1010374/19/1010384/19/1010384/19/1010384/19/1010384/19/1010394/19/1010394/19/1010444/19/1010444/19/1010444/19/1010444/19/1010444/19/1010444/19/1010454/19/1010464/19/101047A/19/101048A/19/1010444/19/1010434/19/1010444/19/1010444/19/1010454/19/1010464/19/1010464/19/1010464/19/1010464/19/1010464/19/1010464/19/101047A/19/1010484/19/101049A/19/1010444/19/1010454/19/1010464/19/101047A/19/1010484/19/101049A/19/101049A/19/101049A/19/101049A/19/101049A/19/1010514/19/1010534/19/1010544/19/1010544/19/1010544/19/1010554/19/1010544/19/1010544/19/1010554/19/1010564/1								Open
10354/19/1010364/19/1010374/19/1010384/19/1010394/19/1010394/19/1010394/19/1010404/19/1010414/19/1010424/19/1010444/19/1010424/19/1010434/19/1010444/19/1010444/19/1010454/19/1010444/19/1010454/19/1010444/19/1010454/19/1010444/19/1010454/19/1010464/19/1010474/19/1010484/19/1010444/19/1010454/19/1010464/19/1010474/19/1010484/19/1010495an Ramon10444/19/1010444/19/1010454/19/1010464/19/1010474/19/1010484/19/1010495an Ramon10504/19/1010444/19/1010544/19/1010544/19/1010554/19/1010554/19/1010554/19/1010554/19/1010544/19/1010554/19/1010544/19/1010554/19/1010564/19/1010564/19/1010564/19/101056 <td< td=""><td></td><td></td><td></td><td></td><td>1 · · · · · · · · · · · · · · · · · · ·</td><td>•</td><td>· · · · ·</td><td>Open</td></td<>					1 · · · · · · · · · · · · · · · · · · ·	•	· · · · ·	Open
10364/19/1010374/19/1010384/19/1010384/19/1010394/19/1010394/19/1010404/19/1010414/19/1010414/19/1010424/19/1010434/19/1010444/19/1010434/19/1010444/19/1010454/19/1010464/19/1010474/19/1010484/19/1010494/19/1010494/19/1010444/19/1010454/19/1010464/19/1010474/19/1010484/19/1010494/19/1010494/19/1010494/19/1010494/19/1010494/19/1010494/19/1010494/19/1010494/19/1010494/19/1010514/19/1010514/19/1010524/19/1010534/19/1010544/19/1010544/19/1010554/19/1010544/19/1010544/19/1010544/19/1010544/19/1010544/19/1010544/19/1010544/19/1010544/19/1010544/19/1010544/19/1010544/19/1010544/19/1010544/1								Open
10374/19/1010384/19/1010394/19/1010394/19/1010414/19/1010414/19/1010424/19/1010434/19/1010444/19/1010424/19/1010434/19/1010444/19/1010444/19/1010454/19/1010464/19/1010474/19/1010484/19/1010494/19/1010444/19/1010444/19/1010454/19/1010464/19/1010474/19/1010484/19/1010494/19/1010444/19/1010444/19/1010454/19/1010464/19/1010474/19/1010484/19/10104910/19/1010494/19/1010504/19/1010504/19/1010524/19/1010544/19/1010554/19/1010554/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010584/19/1010584/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/					Oakland			Open
10384/19/1010394/19/1010404/19/1010414/19/1010424/19/1010434/19/1010444/19/1010434/19/1010444/19/1010444/19/1010454/19/1010464/19/1010474/19/1010484/19/1010484/19/1010494/19/1010444/19/1010454/19/1010464/19/1010474/19/1010484/19/1010494/19/1010494/19/1010444/19/1010494/19/1010494/19/1010494/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010554/19/1010564/19/1010564/19/1010564/19/1010574/19/1010564/19/1010564/19/1010574/19/1010584/19/1010594/19/1010594/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/1								Open
10394/19/1010404/19/1010414/19/1010414/19/1010414/19/1010424/19/1010434/19/1010444/19/1010434/19/1010444/19/1010444/19/1010444/19/1010444/19/1010454/19/1010464/19/1010474/19/1010484/19/1010494/19/1010444/19/1010454/19/1010464/19/1010474/19/1010484/19/1010494/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010584/19/1010594/19/1010584/19/1010584/19/1010584/19/1010594/19/1010584/19/1010594/19/1010544/19/1010544/19/1010554/19/1010564/19/1010574/1								Open
10404/19/1010414/19/1010424/19/1010424/19/1010434/19/1010434/19/1010444/19/1010444/19/1010454/19/1010464/19/1010474/19/1010484/19/101049104610494/19/1010454/19/1010464/19/1010474/19/1010484/19/101049104610494/19/101049104710494/19/1010491049/1010494/19/1010494/19/1010514/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010554/19/1010564/19/1010554/19/1010564/19/1010564/19/1010564/19/1010564/19/1010574/19/1010584/19/1010594/19/1010594/19/1010584/19/1010594/19/1010584/19/1010594/19/1010584/19/1010594/19/1010594/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/10								Open
10414/19/1010424/19/1010434/19/1010434/19/1010444/19/1010454/19/1010461/19/1010471/19/1010464/19/1010471/19/1010484/19/1010491/19/1010491/19/1010491/19/1010491/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010574/19/1010584/19/1010584/19/1010594/19/1010584/19/1010584/19/1010594/19/1010594/19/1010584/19/1010594/19/1010584/19/1010594/19/1010584/19/1010594/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/1								Open
10424/19/1010434/19/1010444/19/1010444/19/1010454/19/1010454/19/1010464/19/1010474/19/1010484/19/1010494/19/1010494/19/1010494/19/1010494/19/1010494/19/1010494/19/1010494/19/1010494/19/1010504/19/1010514/19/1010534/19/1010544/19/1010554/19/1010564/19/1010584/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010574/19/1010584/19/1010594/19/1010564/19/1010574/19/1010584/19/1010594/19/1010584/19/1010594/19/1010504/19/1010514/19/1010514/19/1010514/19/1010534/19/1010544/19/1010574/19/1010584/19/1010594/19/1010504/19/1010514/19/1010514/19/1010524/19/1010534/19/1010544/1								Open
10434/19/1010444/19/1010454/19/1010454/19/1010464/19/1010474/19/1010484/19/1010474/19/1010484/19/1010484/19/1010494/19/1010494/19/101041San Ramon10424/19/1010434/19/1010444/19/1010454/19/101046Linexityation10474/19/1010484/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010554/19/1010554/19/1010564/19/1010574/19/1010584/19/1010584/19/1010584/19/1010584/19/1010564/19/1010574/19/1010564/19/1010574/19/1010584/19/1010594/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010504/19/1010514/19/1010524/19/101053 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Open</td>								Open
10444/19/1010454/19/1010464/19/101047San Ramon10484/19/101047San Ramon10484/19/1010484/19/1010494/19/1010494/19/101051Santa Rosa10524/19/1010534/19/1010544/19/1010554/19/1010554/19/1010564/19/1010574/19/1010584/19/1010554/19/1010564/19/1010574/19/1010584/19/1010564/19/1010564/19/1010574/19/1010584/19/1010564/19/1010564/19/1010574/19/1010584/19/1010584/19/1010584/19/1010594/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010504/19/1010514/19/1010514/19/1010514/19/1010514/19/1010514/19/1010514/19/1010514/19/1010514/19/101051								Open
10454/19/1010464/19/1010474/19/1010484/19/1010484/19/1010484/19/1010484/19/1010494/19/1010494/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010594/19/1010564/19/1010574/19/1010584/19/1010594/19/1010594/19/1010594/19/1010504/19/1010504/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010594/19/1010604/19/1010614/19/1010624/19/1010634/1						-		Open
10464/19/1010474/19/1010484/19/1010484/19/1010494/19/1010504/19/1010514/19/1010524/19/1010524/19/1010534/19/1010544/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010564/19/1010554/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010564/19/1010574/19/1010584/19/1010594/19/1010584/19/1010584/19/1010594/19/1010584/19/1010594/19/1010584/19/1010594/19/1010594/19/1010594/19/1010594/19/1010594/19/1010594/19/1010594/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010594/19/1010514/19/1010524/1								Open
10474/19/1010484/19/1010484/19/1010494/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010554/19/1010564/19/1010574/19/1010584/19/1010584/19/1010594/19/1010594/19/1010504/19/1010514/19/1010534/19/1010544/19/1010554/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010594/19/1010604/19/1010614/19/1010624/19/1010624/19/1010634/19/1010644/20/1010644/20/1010644/20/10	1046	4/19/10			San Ramon			Open
10484/19/1010494/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010534/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010594/19/1010604/19/1010614/19/1010624/19/1010634/19/1010644/20/10	1047	4/19/10			Santa Rosa		· · · · · · · · · · · · · · · · · · ·	Open
10494/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010584/19/1010594/19/1010514/19/1010524/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010594/19/1010514/19/1010534/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010614/19/1010634/19/1010644/20/1010634/19/1010644/20/10								Open
10514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010594/19/1010594/19/1010594/19/1010584/19/1010584/19/1010584/19/1010584/19/1010594/19/1010594/19/1010504/19/1010534/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010604/19/1010614/19/1010624/19/1010624/19/1010634/19/1010644/20/1010644/20/10	1049	4/19/10			Santa Rosa	Meter/Module	Under Investigation	Open
10514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010504/19/1010514/19/1010524/19/1010564/19/1010574/19/1010584/19/1010594/19/1010594/19/1010594/19/1010594/19/1010504/19/1010504/19/1010534/19/1010604/19/1010614/19/1010624/19/1010634/19/1010644/20/10	1050	4/19/10			Stockton			Open
10524/19/1010534/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010594/19/1010594/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010604/19/1010614/19/1010624/19/1010634/19/1010634/19/1010644/20/10	1051	4/19/10			Sunnyvale		-	Open
10534/19/1010544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010594/19/1010594/19/1010504/19/1010514/19/1010524/19/1010534/19/1010544/19/1010554/19/1010584/19/1010594/19/1010604/19/1010614/19/1010614/19/1010624/19/1010634/19/1010644/20/10	1052	4/19/10				Wellington Installer		Open
10544/19/1010554/19/1010564/19/1010574/19/1010584/19/1010594/19/1010594/19/1010604/19/1010614/19/1010614/19/1010624/19/1010634/19/1010644/20/10	1053	4/19/10			Tracy	Customer Denies Access	Under Investigation	Open
10564/19/1010574/19/1010584/19/1010584/19/1010594/19/1010604/19/1010614/19/1010624/19/1010634/19/1010644/20/10	1054	4/19/10			Tracy	Customer Denies Access	Under Investigation	Open
10574/19/1010584/19/1010594/19/1010594/19/1010604/19/1010614/19/1010624/19/1010634/19/1010644/20/10	1055	4/19/10			Berkeley	Meter/Module	Other	Resolved
10574/19/1010584/19/1010594/19/1010594/19/1010604/19/1010614/19/1010624/19/1010634/19/1010644/20/10	1056	4/19/10			Forestville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
10584/19/1010594/19/1010604/19/1010614/19/1010614/19/1010624/19/1010634/19/1010644/20/10	1057	4/19/10			Pittsburg	Household items affected by SM installation		Resolved
10604/19/1010614/19/1010624/19/1010634/19/1010644/20/10	1058	4/19/10				Customer Denies Access	Customer does not want a SmartMeter	Resolved
10614/19/1010624/19/1010634/19/1010644/20/10	1059	4/19/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
10624/19/1010634/19/1010644/20/1020644/20/1020644/20/1020644/20/1020644/20/1020644/20/1020644/20/10	1060	4/19/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
10624/19/10Santa RosaCustomer Denies AccessCustomer does not want a SmartMeterF10634/19/10Santa RosaCustomer Denies AccessCustomer does not want a SmartMeterF10644/20/10AcampoOtherUnder InvestigationF	1061	4/19/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1064     4/20/10     Under Investigation	1062	4/19/10				Customer Denies Access	Customer does not want a SmartMeter	Resolved
1064     4/20/10     Under Investigation	1063	4/19/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
	1064	4/20/10			Acampo	Other		Open
	1065	4/20/10			Berkeley	Customer Denies Access	Under Investigation	Open
1066 4/20/10 Berkeley Household items affected by SM installation Under Investigation	1066	4/20/10			Berkeley	Household items affected by SM installation	Under Investigation	Open

Page 26 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

	Complaint						
No.	Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1067	4/20/10			Berkeley	Other	Under Investigation	Open
1068	4/20/10			Berkeley	Power Interruption	Under Investigation	Open
1069	4/20/10			Berkeley	Power Interruption	Under Investigation	Open
1070	4/20/10			Daly City	Meter/Module	Under Investigation	Open
1071	4/20/10			Glenn	Wellington Installer	Under Investigation	Open
1072	4/20/10			Hercules	Other	Under Investigation	Open
1073	4/20/10			Hopland	Network Equipment Installation	Under Investigation	Open
1074	4/20/10			Milpitas	Household items affected by SM installation	Under Investigation	Open
1075	4/20/10			Mountain View	Wellington Installer	Under Investigation	Open
1076	4/20/10			Oakland	Customer Denies Access	Under Investigation	Open
1077	4/20/10			Petaluma	Customer Denies Access	Under Investigation	Open
1078	4/20/10			Pleasanton	Customer Denies Access	Under Investigation	Open
1079	4/20/10			Richmond	Customer Denies Access	Under Investigation	Open
1080	4/20/10			San Francisco	Other	Under Investigation	Open
1081	4/20/10			San Jose	Customer Denies Access	Under Investigation	Open
1082	4/20/10			San Jose	Household items affected by SM installation	Under Investigation	Open
1083	4/20/10			San Jose	Meter/Module	Under Investigation	Open
1084	4/20/10			San Jose	Power Interruption	Under Investigation	Open
1085	4/20/10			San Pablo	Household items affected by SM installation	Under Investigation	Open
1086	4/20/10			San Ramon	Household items affected by SM installation	Under Investigation	Open
1087	4/20/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
1088	4/20/10			Tracy	Household items affected by SM installation	Under Investigation	Open
1089	4/20/10			Walnut Creek	Other	Under Investigation	Open
1090	4/20/10			Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1091	4/20/10			Santa Rosa	Household items affected by SM installation	Customer does not want a SmartMeter	Resolved
1092	4/21/10			Bakersfield	Wellington Installer	Under Investigation	Open
1093	4/21/10			Berkeley	Household items affected by SM installation	Under Investigation	Open
1094	4/21/10			Berkeley	Other	Under Investigation	Open
1095	4/21/10			Berkeley	Power Interruption	Under Investigation	Open
1096	4/21/10			Danville	Customer Denies Access	Under Investigation	Open
1097	4/21/10			El Dorado	Wellington Installer	Under Investigation	Open
1098	4/21/10			Fortuna	Household items affected by SM installation	Under Investigation	Open
1099	4/21/10			Livermore	Household items affected by SM installation	Under Investigation	Open
1100	4/21/10			Los Banos	Other	Under Investigation	Open
1101	4/21/10			Madera	Household items affected by SM installation	Under Investigation	Open
1102	4/21/10			Mariposa	Customer Denies Access	Under Investigation	Open
1103	4/21/10			Mountain View	Meter/Module	Under Investigation	Open
1104	4/21/10			Richmond	Meter/Module	Under Investigation	Open
1105	4/21/10			Sacramento	Meter/Module	Under Investigation	Open
1106	4/21/10			San Jose	Customer Denies Access	Under Investigation	Open
1107	4/21/10			San Jose	Customer Denies Access	Under Investigation	Open

Page 27 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

100

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1108	4/21/10			San Jose	Household items affected by SM installation	Under Investigation	Open
1109	4/21/10			San Jose	Household items affected by SM installation	Under Investigation	Open
1110	4/21/10			San Jose	Wellington Installer	Under Investigation	Open
1111	4/21/10			Santa Clara	Wellington Installer	Under Investigation	Open
1112	4/21/10			Santa Rosa	Power Interruption	Under Investigation	Open
1113	4/21/10			Sonoma	Customer Denies Access	Under Investigation	Open
1114	4/21/10			Sunnyvale	Wellington Installer	Under Investigation	Open
1115	4/21/10			Forestville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1116	4/21/10			Merced	Household items affected by SM installation	Customer does not want a SmartMeter	Resolved
1117	4/22/10			Alamo	Other	Under Investigation	Open
1118	4/22/10			Berkeley	Customer Denies Access	Under Investigation	Open
1119	4/22/10			Berkeley	Customer Denies Access	Under Investigation	Open
1120	4/22/10			Berkeley	Customer Denies Access	Under Investigation	Open
1121	4/22/10			Berkeley	Customer Denies Access	Under Investigation	Open
1122	4/22/10			Berkeley	Customer Denies Access	Under Investigation	Open
1123	4/22/10			Colfax	Power Interruption	Under Investigation	Open
1124	4/22/10			Copperopolis	Meter/Module	Under Investigation	Open
1125	4/22/10			Copperopolis	Meter/Module	Under Investigation	Open
1126	4/22/10			El Cerrito	Customer Denies Access	Under Investigation	Open
1127	4/22/10			El Sobrante	Power Interruption	Under Investigation	Open
1128	4/22/10			Forestville	Customer Denies Access	Under Investigation	Open
1129	4/22/10			Fresno	Meter/Module	Under Investigation	Open
1130	4/22/10			Glen Ellen	Power Interruption	Under Investigation	Open
1131	4/22/10			Los Banos	Customer Denies Access	Under Investigation	Open
1132	4/22/10			Madera	Customer Denies Access	Under Investigation	Open
1133	4/22/10			Madera	Household items affected by SM installation	Under Investigation	Open
1134	4/22/10			Mountain View	Meter/Module	Under Investigation	Open
1135	4/22/10			Pacifica	Power Interruption	Under Investigation	Open
1136	4/22/10			Pinole	Meter/Module	Under Investigation	Open
1137	4/22/10			San Jose	Customer Denies Access	Under Investigation	Open
1138	4/22/10			San Ramon	Household items affected by SM installation	Under Investigation	Open
1139	4/22/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
1140	4/22/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
1141	4/22/10			Sonoma	Customer Denies Access	Under Investigation	Open
1142	4/22/10			Tracy	Customer Denies Access	Under Investigation	Open
1143	4/22/10			Tracy	Customer Denies Access	Under Investigation	Open
1144	4/22/10			Tracy	Customer Denies Access	Under Investigation	Open
1145	4/22/10			√allejo	Customer Denies Access	Under Investigation	Open
1146	4/22/10			√allejo	Other	Under Investigation	Open
1147	4/22/10			Willits	Customer Denies Access	Under Investigation	Open
1148	4/22/10			Bolinas	Customer Denies Access	Customer does not want a SmartMeter	Resolved

Page 28 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

	Complaint						
No.	Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1149	4/22/10			El Sobrante	Household items affected by SM installation	Internet/Cable Connection Problem	Resolved
1150	4/22/10			Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1151	4/22/10			Sebastopol	Other	Other	Resolved
1152	4/23/10			Berkeley	Other	Under Investigation	Open
1153	4/23/10			Berkeley	Other	Under Investigation	Open
1154	4/23/10			Berkeley	Other	Under Investigation	Open
1155	4/23/10			Berkeley	Power Interruption	Under Investigation	Open
1156	4/23/10			Calistoga	Power Interruption	Under Investigation	Open
1157	4/23/10			Clovis	SmartMeter Customer Communication	Under Investigation	Open
1158	4/23/10			El Cerrito	Household items affected by SM installation	Under Investigation	Open
1159	4/23/10			El Dorado Hills	Customer Denies Access	Under Investigation	Open
1160	4/23/10			El Dorado Hills	Other	Under Investigation	Open
1161	4/23/10			El Sobrante	Power Interruption	Under Investigation	Open
1162	4/23/10			Escalon	Meter/Module	Under Investigation	Open
1163	4/23/10			Madera	Wellington Installer	Under Investigation	Open
1164	4/23/10			Milpitas	Household items affected by SM installation	Under Investigation	Open
1165	4/23/10			Oakland	Customer Denies Access	Under Investigation	Open
1166	4/23/10			Pleasanton	Customer Denies Access	Under Investigation	Open
1167	4/23/10			Richmond	Customer Denies Access	Under Investigation	Open
1168	4/23/10			Richmond	Customer Denies Access	Under Investigation	Open
1169	4/23/10			San Jose	Customer Denies Access	Under Investigation	Open
1170	4/23/10			San Jose	Customer Denies Access	Under Investigation	Open
1171	4/23/10			San Jose	Customer Denies Access	Under Investigation	Open
1172	4/23/10			San Jose	Meter/Module	Under Investigation	Open
1173	4/23/10			San Ramon	Customer Denies Access	Under Investigation	Open
1174	4/23/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
1175	4/23/10			Santa Rosa	SmartMeter Customer Communication	Under Investigation	Open
1176	4/23/10			Sebastopol	Customer Denies Access	Under Investigation	Open
1177	4/23/10			Selma	Wellington Installer	Under Investigation	Open
1178	4/23/10			Stockton	Customer Denies Access	Under Investigation	Open
1179	4/23/10			Tracy	Household items affected by SM installation	Under Investigation	Open
1180	4/23/10			Tracy	Household items affected by SM installation	Under Investigation	Open
1181	4/23/10			Ukiah	Meter/Module	Under Investigation	Open
1182	4/23/10			Camp Meeker	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1183	4/23/10		1	Camp Meeker	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1184	4/23/10		1	Camp Meeker	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1185	4/23/10		1	Camp Meeker	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1186	4/23/10		1	Camp Meeker	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1187	4/23/10		1	Forestville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1188	4/23/10		1	Gien Ellen	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1189	4/23/10		I	Mendota	Household items affected by SM installation	Internet/Cable Connection Problem	Resolved

Page 29 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

100

SS [202

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1190	4/23/10			Monterey	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1191	4/23/10			Tracy	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1192	4/25/10			Cloverdale	Customer Denies Access	Under Investigation	Open
1193	4/25/10			El Dorado Hills	Customer Denies Access	Under Investigation	Open
1194	4/25/10			Oakland	Customer Denies Access	Under Investigation	Open
1195	4/26/10			Alameda	Customer Denies Access	Under Investigation	Open
1196	4/26/10			Alameda	Customer Denies Access	Under Investigation	Open
1197	4/26/10			Alameda	Customer Denies Access	Under Investigation	Open
1198	4/26/10			Berkeley	Meter/Module	Under Investigation	Open
1199	4/26/10			Bolinas	Customer Denies Access	Under Investigation	Open
1200	4/26/10			Calistoga	Meter/Module	Under Investigation	Open
1201	4/26/10			Campbell	Wellington Installer	Under Investigation	Open
1202	4/26/10			Clayton	Customer Denies Access	Under Investigation	Open
1203	4/26/10			Clayton	Customer Denies Access	Under Investigation	Open
1204	4/26/10			El Cerrito	Customer Denies Access	Under Investigation	Open
1205	4/26/10			El Dorado Hills	Customer Denies Access	Under Investigation	Open
1206	4/26/10			Livermore	Meter/Module	Under Investigation	Open
1207	4/26/10			Los Gatos	Customer Denies Access	Under Investigation	Open
1208	4/26/10			Los Gatos	Customer Denies Access	Under Investigation	Open
1209	4/26/10			Madera	Household items affected by SM installati	orUnder Investigation	Open
1210	4/26/10			Madera	Scheduling Problems	Under Investigation	Open
1211	4/26/10			Madera	Wellington Installer	Under Investigation	Open
1212	4/26/10			Napa	Wellington Installer	Under Investigation	Open
1213	4/26/10			Oakhurst	Customer Denies Access	Under Investigation	Open
1214	4/26/10			Oakland	Customer Denies Access	Under Investigation	Open
1215	4/26/10			Oakland	Customer Denies Access	Under Investigation	Open
1216	4/26/10			Oakland	Customer Denies Access	Under Investigation	Open
1217	4/26/10			Oakland	Meter/Module	Under Investigation	Open
1218	4/26/10			Orinda	Meter/Module	Under Investigation	Open
1219	4/26/10			Petaluma	Customer Denies Access	Under Investigation	Open
1220	4/26/10			Richmond	Customer Denies Access	Under Investigation	Open
1221	4/26/10			Richmond	Customer Denies Access	Under Investigation	Open
1222	4/26/10			Richmond	Scheduling Problems	Under Investigation	Open
1223	4/26/10			Rodeo	SmartMeter Customer Communication	Under Investigation	Open
1224	4/26/10			San Carlos	Customer Denies Access	Under Investigation	Open
1225	4/26/10			San Jose	Customer Denies Access	Under Investigation	Open
1226	4/26/10			San Jose	Customer Denies Access	Under Investigation	Open
1227	4/26/10			San Jose	Power Interruption	Under Investigation	Open
1228	4/26/10			San Leandro	Other	Under Investigation	Open
1229	4/26/10			San Ramon	Customer Denies Access	Under Investigation	Open
1230	4/26/10			San Ramon	Wellington Installer	Under Investigation	Open

Page 30 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1231	4/26/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
1232	4/26/10			Seaside	Meter/Module	Under Investigation	Open
1233	4/26/10			Sebastopol	Customer Denies Access	Under Investigation	Open
1234	4/26/10			Sebastopol	Customer Denies Access	Under Investigation	Open
1235	4/26/10			Sonoma	Customer Denies Access	Under Investigation	Open
1236	4/26/10			Sonoma	Customer Denies Access	Under Investigation	Open
1237	4/26/10			Tracy	Household items affected by SM installation		Open
1238	4/26/10			Tracy	Household items affected by SM installation		Open
1239	4/26/10			Walnut Creek	Household items affected by SM installation		Open
1240	4/26/10			Cloverdale	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1241	4/26/10			Santa Rosa	Customer Denies Access	Customer Denies Wellington Access	Resolved
1242	4/26/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1243	4/26/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1244	4/27/10			Alameda	Customer Denies Access	Under Investigation	Open
1245	4/27/10			Alameda	Customer Denies Access	Under Investigation	Open
1246	4/27/10			Alameda	Customer Denies Access	Under Investigation	Open
1247	4/27/10			Alameda	Customer Denies Access	Under Investigation	Open
1248	4/27/10			Alameda	Customer Denies Access	Under Investigation	Open
1249	4/27/10			Alameda	Customer Denies Access	Under Investigation	Open
1250	4/27/10			Alameda	Customer Denies Access	Under Investigation	Open
1251	4/27/10			Alameda	Customer Denies Access	Under Investigation	Open
1252	4/27/10			Alameda	Customer Denies Access	Under Investigation	Open
1253	4/27/10			Alameda	Customer Denies Access	Under Investigation	Open
1254	4/27/10			Bakersfield	Power Interruption	Under Investigation	Open
1255	4/27/10			Belmont	SmartMeter Customer Communication	Under Investigation	Open
1256	4/27/10			Berkeley	Customer Denies Access	Under Investigation	Open
1257	4/27/10			Berkeley	Customer Denies Access	Under Investigation	Open
1258	4/27/10			Berkeley	Customer Denies Access	Under Investigation	Open
1259	4/27/10			Berkeley	Customer Denies Access	Under Investigation	Open
1260	4/27/10			Berkeley	Household items affected by SM installation		Open
1261	4/27/10			Clovis	Household items affected by SM installation		Open
1262	4/27/10			Coarsegold	Customer Denies Access	Under Investigation	Open
1263	4/27/10			Cupertino	Customer Denies Access	Under Investigation	Open
1264	4/27/10			El Cerrito	Meter/Module	Under Investigation	Open
1265	4/27/10			Fresno	Other	Under Investigation	Open
1266	4/27/10			Jenner	Other	Under Investigation	Open
1267	4/27/10			Kingsburg	Customer Denies Access	Under Investigation	Open
1268	4/27/10			Lemoore	Customer Denies Access	Under Investigation	Open
1269	4/27/10			Madera	Customer Denies Access	Under Investigation	Open
1270	4/27/10			Manteca	Household items affected by SM installation	V	Open
1270	4/27/10			Oakland	Customer Denies Access	Under Investigation	Open
1211	1121110	•	1				

Page 31 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

	Complaint						
No.	Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1272	4/27/10			Orinda		Under Investigation	Open
1273	4/27/10			Pittsburg	Other	Under Investigation	Open
1274	4/27/10			Pleasanton	Other	Under Investigation	Open
1275	4/27/10			Reedley	Customer Denies Access	Under Investigation	Open
1276	4/27/10			Reedley	Customer Denies Access	Under Investigation	Open
1277	4/27/10			Reedley	Customer Denies Access	Under Investigation	Open
1278	4/27/10			Reedley	Customer Denies Access	Under Investigation	Open
1279	4/27/10			Reedley	Customer Denies Access	Under Investigation	Open
1280	4/27/10			Richmond	Customer Denies Access	Under Investigation	Open
1281	4/27/10			Richmond	Customer Denies Access	Under Investigation	Open
1282	4/27/10			San Carlos	SmartMeter Customer Communication	Under Investigation	Open
1283	4/27/10			San Jose	Customer Denies Access	Under Investigation	Open
1284	4/27/10			San Jose	Power Interruption	Under Investigation	Open
1285	4/27/10			San Leandro	Other	Under Investigation	Open
1286	4/27/10			San Ramon	Customer Denies Access	Under Investigation	Open
1287	4/27/10			Saratoga	Customer Denies Access	Under Investigation	Open
1288	4/27/10			Saratoga	Customer Denies Access	Under Investigation	Open
1289	4/27/10			Saratoga	Customer Denies Access	Under Investigation	Open
1290	4/27/10			Walnut Creek	Customer Denies Access	Under Investigation	Open
1291	4/27/10			Belmont	SmartMeter Customer Communication	Other	Resolved
1292	4/27/10			Benicia	Other	Other	Resolved
1293	4/27/10			Berkeley	Other	Other	Resolved
1294	4/27/10			El Cerrito	Power Interruption	Breaker keeps tripping	Resolved
1295	4/27/10			Healdsburg	Other	Other	Resolved
1296	4/27/10			Red Bluff	Household items affected by SM installation	Internet/Cable Connection Problem	Resolved
1297	4/27/10			Richmond	Meter/Module	Damaged Television	Resolved
1298	4/27/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1299	4/27/10			Santa Rosa	Household items affected by SM installation		Resolved
1300	4/27/10			Santa Rosa	Other	Other	Resolved
1301	4/27/10			Santa Rosa	Wellington Installer	Customer does not want a SmartMeter	Resolved
1302	4/27/10			Sebastopol	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1303	4/28/10			Alameda	Customer Denies Access	Under Investigation	Open
1304	4/28/10			Alameda	Customer Denies Access	Under Investigation	Open
1305	4/28/10			Alameda	Customer Denies Access	Under Investigation	Open
1306	4/28/10			Alameda	Customer Denies Access	Under Investigation	Open
1307	4/28/10			Alameda	Customer Denies Access	Under Investigation	Open
1308	4/28/10			Alamo	Customer Denies Access	Under Investigation	Open
1309	4/28/10			Antioch	Meter/Module	Under Investigation	Open
1310	4/28/10			Atwater	Household items affected by SM installation	· ·	Open
1311	4/28/10			Bakersfield	Power Interruption	Under Investigation	Open
1312	4/28/10			Berkeley	Customer Denies Access	Under Investigation	Open
1012							

Page 32 of 34

SB GT&S 0783765

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1313	4/28/10			Berkeley	Household items affected by SM installation		Open
1314	4/28/10			Cupertino		Under Investigation	Open
1315	4/28/10			Hayward		Under Investigation	Open
1316	4/28/10			Hercules	Household items affected by SM installation		Open
1317	4/28/10			Lafayette		Under Investigation	Open
1318	4/28/10			Oakland		Under Investigation	Open
1319	4/28/10			Oakland		Under Investigation	Open
1320	4/28/10			Oakland		Under Investigation	Open
1321	4/28/10			Oakland		Under Investigation	Open
1322	4/28/10			Oakland		Under Investigation	Open
1323	4/28/10			Oakland		Under Investigation	Open
1324	4/28/10			Oakley		Under Investigation	Open
1325	4/28/10			Petaluma		Under Investigation	Open
1326	4/28/10			Pinole		Under Investigation	Open
1327	4/28/10			Richmond		Under Investigation	Open
1328	4/28/10			Richmond	Wellington Installer	Under Investigation	Open
1329	4/28/10			San Jose		Under Investigation	Open
1330	4/28/10			Tracy	Customer Denies Access	Under Investigation	Open
1331	4/28/10			Forestville	Household items affected by SM installation	Damaged Other Household Appliances	Resolved
1332	4/28/10			Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1333	4/28/10			Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1334	4/28/10			Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1335	4/28/10			Rohnert Park	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1336	4/28/10			San Anselmo	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1337	4/29/10			Alameda	Customer Denies Access	Under Investigation	Open
1338	4/29/10			Alameda	Customer Denies Access	Under Investigation	Open
1339	4/29/10			Alameda	Customer Denies Access	Under Investigation	Open
1340	4/29/10			American Canyon	Other	Under Investigation	Open
1341	4/29/10			Danville	Customer Denies Access	Under Investigation	Open
1342	4/29/10			Danville	Other	Under Investigation	Open
1343	4/29/10			Emeryville	Customer Denies Access	Under Investigation	Open
1344	4/29/10			Livermore	Other	Under Investigation	Open
1345	4/29/10			Los Gatos	Customer Denies Access	Under Investigation	Open
1346	4/29/10			Madera	Wellington Installer	Under Investigation	Open
1347	4/29/10			Marysville	Power Interruption	Under Investigation	Open
1348	4/29/10			Mountain House	Other	Under Investigation	Open
1349	4/29/10			Napa	Meter/Module	Under Investigation	Open
1350	4/29/10			Oakland	Customer Denies Access	Under Investigation	Open
1351	4/29/10			Oakland	Customer Denies Access	Under Investigation	Open
1352	4/29/10			Oakland	Customer Denies Access	Under Investigation	Open
1353	4/29/10			Oakland	Customer Denies Access	Under Investigation	Open

Page 33 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

NI -	Complaint	Questo		Com Branner		Chattar
No.	Date 4/29/10	Customer Name Accour	It Service City Dakland	Core Process Customer Denies Access	Nature of Complaint Under Investigation	Status Open
1354	4/29/10		Oakland	Customer Denies Access		
1355	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1356					Under Investigation	Open
1357	4/29/10 4/29/10		Oakland Oakland	Customer Denies Access	Under Investigation	Open
1358			Oakland Oakland	Customer Denies Access	Under Investigation	Open
1359	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1360	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1361	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1362	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1363	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1364	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1365	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1366	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1367	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1368	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1369	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1370	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1371	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1372	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1373	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1374	4/29/10		Oakland	Customer Denies Access	Under Investigation	Open
1375	4/29/10		Oakland	Wellington Installer	Under Investigation	Open
1376	4/29/10		Petaluma	Customer Denies Access	Under Investigation	Open
1377	4/29/10		Pinole	Household items affected by SM installation	Under Investigation	Open
1378	4/29/10		Redding	Meter/Module	Under Investigation	Open
1379	4/29/10		San Jose	Customer Denies Access	Under Investigation	Open
1380	4/29/10		San Jose	Household items affected by SM installation	Under Investigation	Open
1381	4/29/10		San Pablo	Customer Denies Access	Under Investigation	Open
1382	4/29/10		Santa Rosa	Power Interruption	Under Investigation	Open
1383	4/29/10		Stockton	Meter/Module	Under Investigation	Open
1384	4/29/10		Walnut Creek	Customer Denies Access	Under Investigation	Open
1385	4/29/10		Yuba City	Customer Denies Access	Under Investigation	Open
1386	4/29/10		Yuba City	Customer Denies Access	Under Investigation	Open
1387	4/29/10		Cameron Park	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1388	4/29/10		Camino	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1389	4/29/10		Camino	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1390	4/29/10		Forestville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1391	4/29/10		Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1392	4/29/10		Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1393	4/29/10		Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1394	4/29/10		Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1004		•				

Page 34 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

100

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1395	4/29/10	Oustomer Mame	Account	Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1396	4/29/10			Placerville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1397	4/29/10			Red Bluff	Household items affected by SM installation		Resolved
1398	4/29/10			Rohnert Park	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1399	4/29/10			Rohnert Park		Customer does not want a SmartMeter	Resolved
1400	4/29/10			Santa Rosa	Scheduling Problems	Other	Resolved
1401	4/29/10			Santa Rosa	Scheduling Problems	Other	Resolved
1402	4/29/10			Woodside	Meter/Module	Meter/Module clearance issues	Resolved
1403	4/30/10			Alameda	Customer Denies Access	Under Investigation	Open
1404	4/30/10			Berkeley		Under Investigation	Open
1405	4/30/10			Berkeley	Customer Denies Access	Under Investigation	Open
1406	4/30/10			Berkeley		Under Investigation	Open
1407	4/30/10			Berkeley		Under Investigation	Open
1408	4/30/10			Concord	Other	Under Investigation	Open
1409	4/30/10			El Cerrito	Household items affected by SM installation	<u>v</u>	Open
1410	4/30/10			Forestville	Other	Under Investigation	Open
1411	4/30/10			Forestville		Under Investigation	Open
1412	4/30/10			Fresno		Under Investigation	Open
1413	4/30/10			Fresno	Power Interruption	Under Investigation	Open
1414	4/30/10			Livermore	Customer Denies Access	Under Investigation	Open
1415	4/30/10			Los Gatos	Customer Denies Access	Under Investigation	Open
1416	4/30/10			Los Gatos	Customer Denies Access	Under Investigation	Open
1417	4/30/10			Los Gatos		Under Investigation	Open
1418	4/30/10			Madera		Under Investigation	Open
1419	4/30/10			Madera		Under Investigation	Open
1420	4/30/10			Marysville	Customer Denies Access	Under Investigation	Open
1421	4/30/10			Oakland	Customer Denies Access	Under Investigation	Open
1422	4/30/10			Oakland	Customer Denies Access	Under Investigation	Open
1423	4/30/10			Oakland	Customer Denies Access	Under Investigation	Open
1424	4/30/10			Oakland		Under Investigation	Open
1425	4/30/10			Oakland	Customer Denies Access	Under Investigation	Open
1426	4/30/10			Oakland		Under Investigation	Open
1427	4/30/10			Oakland	Customer Denies Access	Under Investigation	Open
1428	4/30/10			Oakland		Under Investigation	Open
1429	4/30/10			Oakland		Under Investigation	Open
1430	4/30/10		1	Oakland	Customer Denies Access	Under Investigation	Open
1431	4/30/10			Oakland	Customer Denies Access	Under Investigation	Open
1432	4/30/10			Oakland		Under Investigation	Open
1433	4/30/10		1	Oakland		Under Investigation	Open
1434	4/30/10			Oakland		Under Investigation	Open
1435	4/30/10		1	Petaluma		Under Investigation	Open

Page 35 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

## SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1436	4/30/10	Customer Mame	Account	Petaluma	Customer Denies Access	Under Investigation	Open
1437	4/30/10			Richmond	Customer Denies Access	Under Investigation	Open
1438	4/30/10			Richmond	Other	Under Investigation	Open
1439	4/30/10			Richmond	Power Interruption	Under Investigation	Open
1440	4/30/10			Richmond	SmartMeter Customer Communication	Under Investigation	Open
1441	4/30/10			Richmond	Wellington Installer	Under Investigation	Open
1442	4/30/10			San Jose	Customer Denies Access	Under Investigation	Open
1443	4/30/10			San Jose	Customer Denies Access	Under Investigation	Open
444	4/30/10			San Jose	Customer Denies Access	Under Investigation	Open
1445	4/30/10			San Jose	Household items affected by SM installation		Open
1446	4/30/10			San Jose	Other	Under Investigation	Open
1447	4/30/10			San Pablo	Customer Denies Access	Under Investigation	Open
1448	4/30/10			Santa Cruz	Meter/Module	Under Investigation	Open
1449	4/30/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
1450	4/30/10			Saratoga	Customer Denies Access	Under Investigation	Open
1451	4/30/10			Saratoga	Customer Denies Access	Under Investigation	Open
1452	4/30/10			Tracy	Household items affected by SM installation		Open
1453	4/30/10			Tracy	Household items affected by SM installation		Open
1454	4/30/10			Valley Springs	Power Interruption	Under Investigation	Open
1455	4/30/10			Yuba City		Under Investigation	Open
1456	4/30/10			Benicia	Household items affected by SM installation		Resolved
1457	4/30/10			Camino	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1458	4/30/10			Forestville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1459	4/30/10			Napa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1460	4/30/10			Oakland	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1461	4/30/10			Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1462	4/30/10			Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
463	4/30/10			Petaluma	Household items affected by SM installation		Resolved
464	4/30/10			Placerville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
465	4/30/10			S. San Francisco	Meter/Module	Other	Resolved
466	4/30/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
467	4/30/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
468	5/1/10			Chowchilla		Under Investigation	Open
469	5/1/10			El Cerrito	installation	Under Investigation	Open
470	5/1/10			Los Gatos	Customer Denies Access	Under Investigation	Open
471	5/1/10			Marysville		Under Investigation	Open
472	5/1/10			Petaluma		Under Investigation	Open
473	5/1/10			San Jose	installation	Under Investigation	Open
474	5/1/10			San Jose	installation	Under Investigation	Open
1475	5/1/10			San Jose	installation	Under Investigation	Open
1476	5/1/10			San Jose	Other	Under Investigation	Open

Page 36 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

100

# SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1477	5/1/10			San Jose	Other	Under Investigation	Open
1478	5/1/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
1479	5/1/10			Alameda	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1480	5/1/10			Camino	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1481	5/1/10			Forestville	Other	Other	Resolved
1482	5/1/10			Forestville	Other	Other	Resolved
1483	5/1/10			Hercules	installation	Damaged Other Household Appliances	Resolved
1484	5/1/10			Kyburz	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1485	5/1/10			Óakland	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1486	5/1/10			Oakland	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1487	5/1/10			Oakland	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1488	5/1/10			Oakland	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1489	5/1/10			Oakland	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1490	5/1/10			Oakland	Other	Other	Resolved
1491	5/1/10			Union City	Other	Other	Resolved
1492	5/3/10			Bodega Bay	Customer Denies Access	Under Investigation	Open
1493	5/3/10			Cupertino	Meter/Module	Under Investigation	Open
494	5/3/10			El Dorado Hills	Customer Denies Access	Under Investigation	Open
1495	5/3/10			Forestville	Customer Denies Access	Under Investigation	Open
1496	5/3/10			Los Gatos	Customer Denies Access	Under Investigation	Open
497	5/3/10			Los Gatos	Customer Denies Access	Under Investigation	Open
1498	5/3/10			Madera	installation	Under Investigation	Open
1499	5/3/10			Napa	Other	Under Investigation	Open
1500	5/3/10			Napa	SmartMeter Customer Communication	Under Investigation	Open
1501	5/3/10			Oakland	Customer Denies Access	Under Investigation	Open
1502	5/3/10			Oakland	Customer Denies Access	Under Investigation	Open
503	5/3/10			Oakland	Customer Denies Access	Under Investigation	Open
504	5/3/10			Oakland	Customer Denies Access	Under Investigation	Open
505	5/3/10			Richmond	installation	Under Investigation	Open
506	5/3/10			San Francisco	Customer Denies Access	Under Investigation	Open
507	5/3/10			San Jose	Customer Denies Access	Under Investigation	Open
1508	5/3/10			San Jose	Customer Denies Access	Under Investigation	Open
509	5/3/10			San Jose	Customer Denies Access	Under Investigation	Open
1510	5/3/10			San Jose	Customer Denies Access	Under Investigation	Open
1511	5/3/10			San Jose	Customer Denies Access	Under Investigation	Open
512	5/3/10			San Jose	Customer Denies Access	Under Investigation	Open
1513	5/3/10			San Jose	Customer Denies Access	Under Investigation	Open
1514	5/3/10			Tracy	Customer Denies Access	Under Investigation	Open
515	5/3/10			Tracy	Customer Denies Access	Under Investigation	Open
1516	5/3/10			Yuba City	Customer Denies Access	Under Investigation	Open
1517	5/3/10			Yuba City	Customer Denies Access	Under Investigation	Open

Page 37 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

# SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

	Complaint						
No.	Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1518	5/3/10			Yuba City	Customer Denies Access	Under Investigation	Open
1519	5/3/10			Alameda	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1520	5/3/10			Ceres	Meter/Module	Other	Resolved
1521	5/3/10			Concord	Other	Other	Resolved
1522	5/3/10			Dublin	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1523	5/3/10			Dublin	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1524	5/3/10			El Sobrante	SmartMeter Customer Communication	General inquiry on communication	Resolved
1525	5/3/10			Los Banos	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1526	5/3/10			Oakland	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1527	5/3/10			Oakland	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1528	5/3/10			Oakland	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1529	5/3/10			Oakland	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1530	5/3/10			Oakland	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1531	5/3/10			Oakland	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1532	5/3/10			Oakland	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1533	5/3/10			Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1534	5/3/10			Pinole	installation	Damaged Television	Resolved
1535	5/3/10			Richmond	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1536	5/3/10			Saint Helena	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1537	5/3/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1538	5/3/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1539	5/3/10			Walnut Grove	Meter/Module	Other	Resolved
1540	5/4/10			Alameda	Customer Denies Access	Under Investigation	Open
1541	5/4/10			Alameda	Customer Denies Access	Under Investigation	Open
1542	5/4/10			Alameda	Customer Denies Access	Under Investigation	Open
1543	5/4/10			Concord	Customer Denies Access	Under Investigation	Open
1544	5/4/10			Concord	Meter/Module	Under Investigation	Open
1545	5/4/10			El Cerrito	Power Interruption	Under Investigation	Open
1546	5/4/10			Folsom	Customer Denies Access	Under Investigation	Open
1547	5/4/10			Half Moon Bay	Customer Denies Access	Under Investigation	Open
1548	5/4/10			Hercules	Meter/Module	Under Investigation	Open
1549	5/4/10			Los Gatos	Customer Denies Access	Under Investigation	Open
1550	5/4/10			Monterey	Customer Denies Access	Under Investigation	Open
1551	5/4/10			Oakland	Customer Denies Access	Under Investigation	Open
1552	5/4/10			Oakland	Customer Denies Access	Under Investigation	Open
1553	5/4/10			Oakland	Customer Denies Access	Under Investigation	Open
1554	5/4/10			Oakland	Customer Denies Access	Under Investigation	Open
1555	5/4/10			Oakland	Customer Denies Access	Under Investigation	Open
1556	5/4/10			Oakland	Customer Denies Access	Under Investigation	Open
1557	5/4/10			Oakland	Customer Denies Access	Under Investigation	Open
1558	5/4/10			Oakland	Customer Denies Access	Under Investigation	Open

Page 38 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

# SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

	Complaint						
No.	Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1559	5/4/10			Oakland	Customer Denies Access	Under Investigation	Open
1560	5/4/10			Oakland	installation	Under Investigation	Open
1561	5/4/10			Oakland	Other	Under Investigation	Open
1562	5/4/10			Oakland	Other	Under Investigation	Open
1563	5/4/10			Oakley	Other	Under Investigation	Open
1564	5/4/10			Pacifica	installation	Under Investigation	Open
1565	5/4/10			Petaluma	Customer Denies Access	Under Investigation	Open
1566	5/4/10			Pinole	Customer Denies Access	Under Investigation	Open
1567	5/4/10			Pleasanton	Customer Denies Access	Under Investigation	Open
1568	5/4/10			S. San Francisco	Wellington Installer	Under Investigation	Open
1569	5/4/10			San Francisco	Customer Denies Access	Under Investigation	Open
1570	5/4/10			San Jose	Customer Denies Access	Under Investigation	Open
1571	5/4/10			San Jose	Customer Denies Access	Under Investigation	Open
1572	5/4/10			San Jose	installation	Under Investigation	Open
1573	5/4/10			San Ramon	Other	Under Investigation	Open
1574	5/4/10			Saratoga	Customer Denies Access	Under Investigation	Open
1575	5/4/10			Saratoga	Customer Denies Access	Under Investigation	Open
1576	5/4/10			Tracy	Power Interruption	Under Investigation	Open
1577	5/4/10			Camp Meeker	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1578	5/4/10			Hayward	Meter/Module	Meter/Module clearance issues	Resolved
1579	5/4/10			Live Oak	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1580	5/4/10			Merced	SmartMeter Customer Communication	Other	Resolved
1581	5/4/10			Novato	Other	Other	Resolved
1582	5/4/10			Oakland	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1583	5/4/10			Petaluma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1584	5/4/10			Pleasant Hill	SmartMeter Customer Communication	Other	Resolved
1585	5/4/10			Richmond	SmartMeter Customer Communication	Other	Resolved
1586	5/4/10			San Francisco	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1587	5/4/10			San Mateo	Meter/Module	Meter/Module clearance issues	Resolved
1588	5/4/10			Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1589	5/4/10			Tracy	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1590	5/5/10			Alameda	Customer Denies Access	Under Investigation	Open
1591	5/5/10			Alameda	Customer Denies Access	Under Investigation	Open
1592	5/5/10			Alameda	Customer Denies Access	Under Investigation	Open
1593	5/5/10			Alameda	Customer Denies Access	Under Investigation	Open
1594	5/5/10			Berkeley	Customer Denies Access	Under Investigation	Open
1595	5/5/10			Berkeley	Customer Denies Access	Under Investigation	Open
1596	5/5/10			Berkeley	installation	Under Investigation	Open
1597	5/5/10			Calistoga	Customer Denies Access	Under Investigation	Open
1598	5/5/10			Corcoran	Customer Denies Access	Under Investigation	Open
1599	5/5/10			El Cerrito	Customer Denies Access	Under Investigation	Open
1000			-				

Page 39 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

100

SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1600	5/5/10	Customer Maine	Account	Livermore	installation	Under Investigation	Open
1600	5/5/10			Los Banos	installation	Under Investigation	Open
1601	5/5/10			Madera	installation	Under Investigation	Open
1602	5/5/10			Manteca	SmartMeter Customer Communication	Under Investigation	Open
1603	5/5/10			Napa	Power Interruption	Under Investigation	Open
1605	5/5/10			Oakland	Customer Denies Access	Under Investigation	Open
1605	5/5/10			Oakland	Customer Denies Access	Under Investigation	Open
1607	5/5/10			Oakland	Customer Denies Access	Under Investigation	Open
1607	5/5/10			Oakland	Customer Denies Access	Under Investigation	Open
1609	5/5/10			Oakland	Customer Denies Access	Under Investigation	Open
1610	5/5/10			Oakland	Customer Denies Access	Under Investigation	Open
1610	5/5/10			Oakland	Customer Denies Access	Under Investigation	Open
1612	5/5/10			Oakland	Wellington Installer	Under Investigation	Open
1612	5/5/10			Petaluma	installation	Under Investigation	Open
1613	5/5/10			Placerville	Customer Denies Access	Under Investigation	Open
1615	5/5/10			Placerville	Customer Denies Access	Under Investigation	Open
1615	5/5/10			Richmond	Other	Under Investigation	Open
1617	5/5/10			Rodeo	Meter/Module	Under Investigation	Open
1618	5/5/10			San Jose	Customer Denies Access	Under Investigation	Open
1618	5/5/10			San Jose	Customer Denies Access	Under Investigation	Open
1619	5/5/10			San Jose	Meter/Module	Under Investigation	Open
1620	5/5/10			San Jose	Other	Under Investigation	Open
1621	5/5/10			San Jose	Wellington Installer	Under Investigation	Open
1622	5/5/10			San Leandro	Meter/Module	Under Investigation	Open
1623	5/5/10			San Leandro	SmartMeter Customer Communication	Under Investigation	Open
1624	5/5/10			Santa Nella	installation	Under Investigation	Open
1625	5/5/10			Santa Nella	Other	Under Investigation	Open
1620	5/5/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
1627	5/5/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
1628	5/5/10			Santa Rosa	installation	Under Investigation	Open
1629	5/5/10			Saratoga	Customer Denies Access	Under Investigation	Open
1630	5/5/10			Vallejo	Other	Under Investigation	Open
1631	5/5/10			Watsonville	Meter/Module	Under Investigation	Open
1633	5/5/10			Berkeley	installation	Internet/Cable Connection Problem	Resolved
1633	5/5/10			Danville	installation	Gas Appliance Not Working	Resolved
1634	5/5/10			Lemoore	Meter/Module	Meter/Module clearance issues	Resolved
1635	5/5/10			Livermore	installation	Other	Resolved
1636	5/5/10			Loomis	Meter/Module	Meter/Module clearance issues	Resolved
1637	5/5/10			Los Gatos	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1638	5/5/10			San Jose	Customer Denies Access	Customer does not want a Smartiveter	Resolved
	5/5/10			San Jose San Jose	installation		Resolved
1640	5/5/10			pan Jose	เกรเลแลแงก	Damaged Computer	Resolved

SI 53 83

Page 40 of 34

Pacific Gas and Electric Company

· · · · ·

SmartMeterTM Complaint Report

100

SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1641	5/5/10			San Jose	Other	Other	Resolved
1642	5/5/10			San Ramon	Meter/Module	Other	Resolved
1643	5/5/10			Tracy	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1644	5/6/10			Alameda	Customer Denies Access	Under Investigation	Open
1645	5/6/10			Camino	Customer Denies Access	Under Investigation	Open
1646	5/6/10			Concord	Customer Denies Access	Under Investigation	Open
1647	5/6/10			Forestville	Customer Denies Access	Under Investigation	Open
1648	5/6/10			Fremont	Customer Denies Access	Under Investigation	Open
1649	5/6/10			Galt	Meter/Module	Under Investigation	Open
1650	5/6/10			Los Banos	Power Interruption	Under Investigation	Open
1651	5/6/10			Madera	Customer Denies Access	Under Investigation	Open
1652	5/6/10			Madera	installation	Under Investigation	Open
1653	5/6/10			Marysville	Wellington Installer	Under Investigation	Open
1654	5/6/10			Newark	Customer Denies Access	Under Investigation	Open
1655	5/6/10			Oakland	Customer Denies Access	Under Investigation	Open
1656	5/6/10			Oakland	Customer Denies Access	Under Investigation	Open
1657	5/6/10			Oakland	Customer Denies Access	Under Investigation	Open
1658	5/6/10			Oakland	Customer Denies Access	Under Investigation	Open
1659	5/6/10			Oakland	Customer Denies Access	Under Investigation	Open
1660	5/6/10			Oakland	Customer Denies Access	Under Investigation	Open
1661	5/6/10			Oakland	Customer Denies Access	Under Investigation	Open
1662	5/6/10			Petaluma	Meter/Module	Under Investigation	Open
1663	5/6/10			Pinole	Customer Denies Access	Under Investigation	Open
1664	5/6/10			Pinole	Customer Denies Access	Under Investigation	Open
1665	5/6/10			Richmond	Customer Denies Access	Under Investigation	Open
1666	5/6/10			San Francisco	Customer Denies Access	Under Investigation	Open
1667	5/6/10			San Jose	Customer Denies Access	Under Investigation	Open
1668	5/6/10			San Jose	Wellington Installer	Under Investigation	Open
1669	5/6/10			San Mateo	Other	Under Investigation	Open
1670	5/6/10			Sebastopol	Other	Under Investigation	Open
1671	5/6/10			Sonoma	Customer Denies Access	Under Investigation	Open
1672	5/6/10			Vacaville	Meter/Module	Under Investigation	Open
1673	5/6/10			Yuba City	Customer Denies Access	Under Investigation	Open
1674	5/6/10			Milpitas	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1675	5/6/10			Sacramento	Wellington Installer	Installer jumped fence, broke lock	Resolved
1676	5/6/10			San Jose	Customer Denies Access	Customer Denies Wellington Access	Resolved
1677	5/6/10		1	San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1678	5/6/10			Sonora	installation	Damaged Fans	Resolved
1679	5/6/10		1	Sunnyvale	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1680	5/7/10			Alameda	Customer Denies Access	Under Investigation	Open
1681	5/7/10		1	Berkeley	Wellington Installer	Under Investigation	Open

Page 41 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

100

# SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

1

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1682	5/7/10			Brentwood	Customer Denies Access	Under Investigation	Open
1683	5/7/10			Clayton	Other	Under Investigation	Open
1684	5/7/10			Concord	Bad Meter / Module Equipment	Under Investigation	Open
1685	5/7/10			Concord	Wellington Installer	Under Investigation	Open
1686	5/7/10			Cupertino	Meter/Module	Under Investigation	Open
1687	5/7/10			Daly City	Wellington Installer	Under Investigation	Open
1688	5/7/10			El Sobrante	Other	Under Investigation	Open
1689	5/7/10			Fairfield	Meter/Module	Under Investigation	Open
1690	5/7/10			Firebaugh	Power Interruption	Under Investigation	Open
1691	5/7/10			Fremont	Meter/Module	Under Investigation	Open
1692	5/7/10			Healdsburg	Scheduling Problems	Under Investigation	Open
1693	5/7/10			Kingsburg	installation	Under Investigation	Open
1694	5/7/10			Livermore	Wellington Installer	Under Investigation	Open
1695	5/7/10			Napa	installation	Under Investigation	Open
1696	5/7/10			Oakland	Customer Denies Access	Under Investigation	Open
1697	5/7/10			Oakland	Customer Denies Access	Under Investigation	Open
1698	5/7/10			Oakland	Customer Denies Access	Under Investigation	Open
1699	5/7/10			Oakland	Customer Denies Access	Under Investigation	Open
1700	5/7/10			Oakland	Customer Denies Access	Under Investigation	Open
1701	5/7/10			Oakland	Customer Denies Access	Under Investigation	Open
1702	5/7/10			Oakland	Customer Denies Access	Under Investigation	Open
1703	5/7/10			Oakland	Customer Denies Access	Under Investigation	Open
1704	5/7/10			Oakland	Customer Denies Access	Under Investigation	Open
1705	5/7/10			Oakland	Customer Denies Access	Under Investigation	Open
1706	5/7/10			Oakland	Customer Denies Access	Under Investigation	Open
1707	5/7/10			Oakland	Other	Under Investigation	Open
1708	5/7/10			Oakland	Scheduling Problems	Under Investigation	Open
1709	5/7/10			Petaluma	Customer Denies Access	Under Investigation	Open
1710	5/7/10			Pinole	Customer Denies Access	Under Investigation	Open
1711	5/7/10			Pleasanton	Customer Denies Access	Under Investigation	Open
1712	5/7/10			Pleasanton	installation	Under Investigation	Open
1713	5/7/10			Redwood City	installation	Under Investigation	Open
1714	5/7/10			Richmond	Other	Under Investigation	Open
1715	5/7/10			San Jose	Customer Denies Access	Under Investigation	Open
1716	5/7/10			San Jose	Customer Denies Access	Under Investigation	Open
1717	5/7/10			San Jose	Customer Denies Access	Under Investigation	Open
1718	5/7/10			San Jose	installation	Under Investigation	Open
1719	5/7/10			San Jose	installation	Under Investigation	Open
1720	5/7/10			San Jose	installation	Under Investigation	Open
1721	5/7/10			San Jose	installation	Under Investigation	Open
1722	5/7/10			San Jose	Meter/Module	Under Investigation	Open

Page 42 of 34

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

# SmartMeterTM Installation Complaint Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	1000

No.	Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
1723	5/7/10	Gustomet Name	Account	San Mateo	Customer Denies Access	Under Investigation	Open
1724	5/7/10			San Rafael	Customer Denies Access	Under Investigation	Open
1725	5/7/10			San Ramon	installation	Under Investigation	Open
1726	5/7/10			San Ramon	Wellington Installer	Under Investigation	Open
1727	5/7/10			Santa Rosa	Customer Denies Access	Under Investigation	Open
1728	5/7/10			Santa Rosa	installation	Under Investigation	Open
1729	5/7/10			Santa Rosa	installation	Under Investigation	Open
1730	5/7/10			Sebastopol	Customer Denies Access	Under Investigation	Open
1731	5/7/10			Shingle Springs	Customer Denies Access	Under Investigation	Open
1732	5/7/10			Squaw Valley	Customer Denies Access	Under Investigation	Open
1733	5/7/10			Stockton	Meter/Module	Under Investigation	Open
1734	5/7/10			Stockton	SmartMeter Customer Communication	Under Investigation	Open
1735	5/7/10			Taft	Meter/Module	Under Investigation	Open
1736	5/7/10			Tiburon	installation	Under Investigation	Open
1737	5/7/10			Tracy	Customer Denies Access	Under Investigation	Open
1738	5/7/10			Tracy	Customer Denies Access	Under Investigation	Open
1739	5/7/10			Tracy	installation	Under Investigation	Open
1740	5/7/10			Walnut Creek	Customer Denies Access	Under Investigation	Open
1741	5/7/10			Walnut Creek	installation	Under Investigation	Open
1742	5/7/10			Wheatland	installation	Under Investigation	Open
1743	5/7/10			Placerville	installation	Other	Resolved
1744	5/7/10			San Jose	Other	Other	Resolved
1745	5/7/10			Sebastopol	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1746	5/7/10			Sonoma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1747	5/7/10			Sonoma	Customer Denies Access	Customer does not want a SmartMeter	Resolved
1748	5/7/10			Vallejo	installation	Other	Resolved

1,467 Open Complaints on Last Report

250 Open Complaints Resolved Since the Last Report

281 New Complaints Since the Last Report

70 New Complaints Resolved Since the Last Report

211 New Complaints Open

Page 43 of 34

Page 44 of 34

Page 45 of 34

Page 46 of 34

Page 47 of 34

Page 48 of 34

Page 49 of 34

Page 50 of 34

Page 51 of 34

Page 52 of 34

Page 53 of 34

Page 54 of 34

Page 55 of 34

Page 56 of 34

Page 57 of 34

Page 58 of 34

Page 59 of 34

Page 60 of 34

Page 61 of 34

Page 62 of 34

Page 63 of 34

Page 64 of 34

Page 65 of 34

Page 66 of 34

Page 67 of 34

Page 68 of 34

Page 69 of 34

Page 70 of 34

Page 71 of 34

Page 72 of 34

Page 73 of 34

Page 74 of 34

Page 75 of 34

Page 76 of 34

Page 77 of 34

Page 78 of 34

Page 79 of 34

Page 80 of 34

Page 81 of 34

Page 82 of 34

Page 83 of 34

Page 84 of 34

Page 85 of 34

Page 86 of 34

This report contains confidential customer information and is being submitted under CPUC Code Section 583.

Pacific Gas and Electric Company

SmartMeterTM Complaint Report

## SmartMeterTM Installation Complaint Report

May 13, 2010 - For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

	Complaint										
No.	Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status				
1	5/7/09	{Redacted}	{Redacted}	Brentwood	Household items affected by SM installation	Under Investigation	Open				
2	6/9/09	-		Citrus Heights	Meter/Module	Under Investigation	Open				
3	6/25/09	4		PARADISE	Meter/Module	Under Investigation	Open				
4	7/1/09	4		Capay	Other	Under Investigation	Open				
5	7/2/09	4		Soda Springs	Scheduling Problems	Under Investigation	Open				
6	9/18/09			Moraga	SmartMeter Customer Communication	Under Investigation	Open				
7	9/29/09				Ahwahnee	Meter/Module	Under Investigation	Open			
8	10/15/09			Stockton	Household items affected by SM installation	Under Investigation	Open				
9	10/26/09			Fremont	Other	Under Investigation	Open				
10	10/28/09			Vacaville	Wellington Installer	Under Investigation	Open				
11	11/10/09			Hillsborough	Customer Denies Access	Under Investigation	Open				
12	11/10/09			Vacaville	Customer Denies Access	Customer does not want a SmartMeter	Resolved				
13	11/12/09			Newark	Meter/Module	Under Investigation	Open				
14	11/16/09			√acaville	Household items affected by SM installation	Under Investigation	Open				
15	11/20/09			Fremont	Meter/Module	Under Investigation	Open				
16	11/23/09			WOODLAND	Meter/Module	Under Investigation	Open				
17	11/24/09			Kingsburg	Meter/Module	Under Investigation	Open				
18	11/25/09	1		Richmond	Network Equipment Installation	Under Investigation	Open				
19	11/30/09	1		Fresno	Household items affected by SM installation	Under Investigation	Open				
20	11/30/09	1		MIRAMONTE	Household items affected by SM installation	Under Investigation	Open				
21	12/2/09	1		Fremont	Power Interruption	Under Investigation	Open				
22	12/2/09							Redwood City	Household items affected by SM installation	Under Investigation	Open
23	12/3/09									Manteca Household items affected	Household items affected by SM installation
24	12/3/09					Manteca	Household items affected by SM installation	Under Investigation	Open		
25	12/3/09				Stockton	Household items affected by SM installation	Under Investigation	Open			
26	12/4/09					Hanford	Household items affected by SM installation	Under Investigation	Open		
27	12/4/09						Napa	Household items affected by SM installation	Under Investigation	Open	
28	12/7/09				Napa	Wellington Installer	Under Investigation	Open			
29	12/8/09			PIONEER	Household items affected by SM installation	Under Investigation	Open				
30	12/9/09			Los Altos	Household items affected by SM installation	Under Investigation	Open				
31	12/9/09					Stockton	Power Interruption	Under Investigation	Open		
32	12/11/09			MILLBRAE	Power Interruption	Under Investigation	Open				
33	12/11/09			Plymouth	Meter/Module	Under Investigation	Open				
34	12/11/09			Stockton	Household items affected by SM installation	Under Investigation	Open				
35	12/16/09	1	1	Mountain View	Scheduling Problems	Under Investigation	Open				
36	12/18/09	1	1		Meter/Module	Under Investigation	Open				
37	12/17/09	1		Sunnyvale Vacaville	Meter/Module	-	Open				
38	12/17/09	1	1			Under Investigation Other	Resolved				
		1			Other						
39	12/22/09	1	1		Household items affected by SM installation	Under Investigation	Open				
40	12/22/09	1	1		Wellington Installer	Under Investigation	Open				
41	12/23/09	J	1	Dublin	Meter/Module	Under Investigation	Open				

Page 1 of 34

42	12/23/09	
43	12/23/09	
44	12/23/09	
45	12/29/09	
46	12/29/09	
47	12/29/09	
48	12/30/09	
49	12/31/09	
50	12/31/09	
51	1/4/10	
52	1/4/10	
53	1/5/10	
54	1/5/10	
55	1/7/10	
56	1/8/10	
57	1/11/10	
58	1/11/10	
59	1/11/10	
60	1/11/10	
61	1/12/10	
62	1/12/10	
63		
	1/12/10	
64	1/12/10	
65	1/13/10	
66	1/14/10	
67	1/14/10	
68	1/14/10	
69	1/15/10	
70	1/15/10	
71	1/15/10	
72	1/15/10	
73	1/16/10	
74	1/19/10	
75	1/19/10	
76	1/19/10	
77	1/20/10	
78	1/20/10	
79	1/22/10	
80	1/22/10	
81	1/23/10	
82	1/25/10	
83	1/26/10	
84	1/26/10	
85	1/26/10	
86	1/26/10	
87	1/26/10	
88	1/26/10	
89	1/26/10	
90	1/26/10	
91	1/26/10	
92	1/26/10	

Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Valnut Creek	SmartMeter Customer Communication	Under Investigation	Open
El Granada	Power Interruption	Under Investigation	Open
.ivermore	Meter/Module	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
os Banos	Network Equipment Installation	Under Investigation	Open
_ivermore	Household items affected by SM installation	Under Investigation	Open
Mountain View	Household items affected by SM installation	Under Investigation	Open
vienio Park	Customer Denies Access	Under Investigation	Open
/lerced	Customer Denies Access	Under Investigation	Open
UBURN	Power Interruption	Under Investigation	Open
Sebastopol	Other	Customer does not want a SmartMeter	Resolved
os Altos	Other	Other	Resolved
ivermore	Household items affected by SM installation	Under Investigation	Open
Burlingame	Household items affected by SM installation	Under Investigation	Open
airfield	Meter/Module	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
/acaville	Meter/Module	Under Investigation	Open
ivermore	Power Interruption	Under Investigation	Open
/loraga	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Berkeley	Customer Denies Access	Customer does not want a SmartMeter	Resolved
.ODI	Meter/Module	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Supertino	Household items affected by SM installation	Under Investigation	Open
Jublin	Household items affected by SM installation	Under Investigation	Open
Corcoran	Wellington Installer	Under Investigation	Open
Dublin	Household items affected by SM installation	Under Investigation	
	Scheduling Problems	Under Investigation	Open Open
Napa San Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
San Jose	Household items affected by SM installation	Under Investigation	
	Other		Open Open
Aartinez	Other	Under Investigation Other	Resolved
Aptos			
San Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Cupertino	Household items affected by SM installation	Under Investigation	Open
Cupertino	Power Interruption	Under Investigation	Open
Fremont	Household items affected by SM installation	Under Investigation	Open
Sebastopol	Customer Denies Access	Under Investigation	Open
Kensington Pinole	Household items affected by SM installation SmartMeter Customer Communication	Under Investigation	Open Resolved
		General inquiry on communication	-
American Canyon	Customer Denies Access	Under Investigation	Open
ivermore	Customer Denies Access	Under Investigation	Open
Aadera	Wellington Installer	Under Investigation	Open
	Meter/Module	Under Investigation	Open
Pleasanton	Wellington Installer	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Meter/Module	Under Investigation	Open
Stockton	Wellington Installer	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open

Page 2 of 34

93         1/26/10           94         1/26/10           95         1/26/10           96         1/27/10           97         1/27/10           98         1/27/10           99         1/28/10           100         1/28/10           101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         <		
95         1/26/10           96         1/27/10           97         1/27/10           98         1/27/10           99         1/28/10           100         1/28/10           101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/110           130         2/2/10           131         <	93	1/26/10
96         1/27/10           97         1/27/10           98         1/27/10           99         1/28/10           100         1/28/10           101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/10           131         2/3/10           132 <td< td=""><td>94</td><td>1/26/10</td></td<>	94	1/26/10
97         1/27/10           98         1/27/10           99         1/28/10           100         1/28/10           101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           130         2/2/10           131         2/3/10           132	95	1/26/10
98         1/27/10           99         1/28/10           100         1/28/10           101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/10           130         2/2/10           131         2/3/10           132         2/3/10           133 <td< td=""><td>96</td><td>1/27/10</td></td<>	96	1/27/10
99         1/28/10           100         1/28/10           101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/10           130         2/2/10           131         2/3/10           132         <	97	1/27/10
100         1/28/10           101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/10           130         2/2/10           131         2/3/10           132         2/3/10           133         <	98	1/27/10
101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135 <td< td=""><td>99</td><td></td></td<>	99	
102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136	100	1/28/10
103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2	101	1/28/10
103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2	102	
104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           133         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2	103	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$		
106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           133         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           142         2/		
107         1/29/10           108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           133         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           141         2/5/10           142         2/5/10		
109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           141         2/5/10           142         2/5/10		
110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           141         2/5/10           142         2/5/10		
111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           137         2/4/10           138         2/4/10           140         2/5/10           141         2/5/10		
112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           119         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           138         2/4/10           140         2/5/10           141         2/5/10		
114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           119         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           119         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
116         1/29/10           117         1/29/10           118         1/31/10           119         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
117         1/29/10           118         1/31/10           119         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
118         1/31/10           119         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           122         1/31/10           122         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
119         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           137         2/4/10           138         2/4/10           140         2/5/10           141         2/5/10		
120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           137         2/4/10           138         2/4/10           140         2/5/10           141         2/5/10		
121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           141         2/5/10           142         2/5/10		
125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           141         2/5/10           142         2/5/10		
126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           137         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
135         2/3/10           136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		2/3/10
137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
140         2/5/10           141         2/5/10           142         2/5/10		2/4/10
141         2/5/10           142         2/5/10	139	2/4/10
142 2/5/10	140	2/5/10
	141	
143 2/8/10	142	2/5/10
	143	2/8/10

ivermore	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Merced	Customer Denies Access	Customer does not want a SmartMeter	Resolved
/allejo	Wellington Installer	Other	Resolved
lillsborough	Customer Denies Access	Under Investigation	Open
Pleasanton	Wellington Installer	Under Investigation	Open
Redwood City	Meter/Module	Under Investigation	Open
merican Canyon	Wellington Installer	Under Investigation	Open
I Sobrante	Wellington Installer	Under Investigation	Open
loraga	Wellington Installer	Under Investigation	Open
leasanton	Household items affected by SM installation	Under Investigation	Open
an Francisco	Power Interruption	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	Open
an Jose	Wellington Installer	Under Investigation	Open
unnyvale	Power Interruption	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
/ladera	Wellington Installer	Under Investigation	Open
Pinole	Wellington Installer	Under Investigation	Open
Richmond	Wellington Installer	Under Investigation	Open
tio Vista	Household items affected by SM installation	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	Open
an Jose	Meter/Module	Under Investigation	Open
stockton	Wellington Installer	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
iunnyvale	Wellington Installer	Under Investigation	Open
lensington	Meter/Module	Meter/Module clearance issues	Resolved
an Jose	Household items affected by SM installation	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	Open
Jakersfield	Household items affected by SM installation	Other	Resolved
Danville	Meter/Module	Meter/Module clearance issues	Resolved
I Sobrante	Wellington Installer	Under Investigation	Open
A HONDA	Customer Denies Access	Under Investigation	•
ivermore		onder investigation	
	Household items affected by SM installation	Under Investigation	Open Open
	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open Open
Pleasanton San Jose	Meter/Module Power Interruption	Under Investigation Under Investigation	Open Open Open
Pleasanton San Jose San Jose	Meter/Module Power Interruption Power Interruption	Under Investigation Under Investigation Under Investigation	Open Open Open Open
leasanton an Jose an Jose acaville	Meter/Module Power Interruption Power Interruption Meter/Module	Under Investigation Under Investigation Under Investigation Under Investigation	Open Open Open Open Open
Pleasanton San Jose San Jose Yacaville San Jose	Meter/Module Power Interruption Power Interruption Meter/Module Household items affected by SM installation	Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation	Open Open Open Open Open Open
Pleasanton San Jose San Jose Vacaville San Jose CORDELIA	Meter/Module Power Interruption Power Interruption Meter/Module Household items affected by SM installation Wellington Installer	Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation	Open Open Open Open Open Open Open
Pleasanton San Jose Vacaville San Jose CORDELIA SRATON	Meter/Module Power Interruption Power Interruption Meter/Module Household items affected by SM installation Wellington Installer Other	Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation	Open Open Open Open Open Open Open
Pleasanton San Jose Gan Jose Gacaville San Jose CORDELIA SRATON ivermore	Meter/Module Power Interruption Power Interruption Meter/Module Household items affected by SM installation Wellington Installer Other Household items affected by SM installation	Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation	Open Open Open Open Open Open Open Open
Pleasanton San Jose Gan Jose Gacaville San Jose CORDELIA SRATON ivermore Mountain View	Meter/Module         Power Interruption         Power Interruption         Meter/Module         Household items affected by SM installation         Wellington Installer         Other         Household items affected by SM installation         Power Interruption	Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation	Open Open Open Open Open Open Open Open
Pleasanton San Jose Gan Jose Gacaville San Jose CORDELIA SRATON ivermore Mountain View Pleasanton	Meter/Module         Power Interruption         Power Interruption         Meter/Module         Household items affected by SM installation         Wellington Installer         Other         Household items affected by SM installation         Power Interruption         Power Interruption	Under Investigation Under Investigation	Open Open Open Open Open Open Open Open
Pleasanton ian Jose ian Jose ian Jose ian Jose ian Jose icoRDELIA icoRDELIA ivermore flountain View Pleasanton icay MOND	Meter/Module         Power Interruption         Power Interruption         Meter/Module         Household items affected by SM installation         Wellington Installer         Other         Household items affected by SM installation         Power Interruption         Meter/Module         Wellington Installer         Wellington Installer	Under Investigation Under Investigation	Open Open Open Open Open Open Open Open
Pleasanton San Jose San Jose /acaville San Jose CORDELIA SRATON .ivermore Mountain View Pleasanton RAYMOND Fresno	Meter/Module         Power Interruption         Power Interruption         Meter/Module         Household items affected by SM installation         Wellington Installer         Other         Household items affected by SM installation         Power Interruption         Meter/Module         Wellington Installer         Wellington Installer         Household items affected by SM installation	Under Investigation Under Investigation	Open Open Open Open Open Open Open Open
Pleasanton San Jose San Jose /acaville San Jose CORDELIA SRATON .ivermore Mountain View Pleasanton RAYMOND Fresno San Ramon	Meter/Module         Power Interruption         Power Interruption         Meter/Module         Household items affected by SM installation         Wellington Installer         Other         Household items affected by SM installation         Power Interruption         Meter/Module         Wellington Installer         Household items affected by SM installation         Power Interruption         Meter/Module         Wellington Installer         Household items affected by SM installation         Power Interruption	Under Investigation Under Investigation	Open Open Open Open Open Open Open Open
Pleasanton San Jose San Jose /acaville San Jose CORDELIA SRATON Livermore Mountain View Pleasanton RAYMOND Fresno San Ramon Suisun City	Meter/Module         Power Interruption         Power Interruption         Meter/Module         Household items affected by SM installation         Wellington Installer         Other         Household items affected by SM installation         Power Interruption         Meter/Module         Wellington Installer         Household items affected by SM installation         Power Interruption         Meter/Module         Power Interruption         Power Interruption         Meter/Module	Under InvestigationUnder Investigation	Open Open Open Open Open Open Open Open
Pleasanton San Jose San Jose Zacaville San Jose CORDELIA BRATON Livermore Mountain View Pleasanton RAYMOND Fresno San Ramon Suisun City Mountain View	Meter/Module         Power Interruption         Power Interruption         Meter/Module         Household items affected by SM installation         Wellington Installer         Other         Household items affected by SM installation         Power Interruption         Meter/Module         Wellington Installer         Household items affected by SM installation         Power Interruption         Meter/Module         Vellington Installer         Household items affected by SM installation         Power Interruption         Meter/Module         Other	Under InvestigationUnder Investigation	Open Open Open Open Open Open Open Open
Pleasanton San Jose San Jose /acaville San Jose CORDELIA SRATON Livermore Mountain View Pleasanton RAYMOND Fresno San Ramon Suisun City Mountain View Pleasanton San Ramon	Meter/Module         Power Interruption         Power Interruption         Meter/Module         Household items affected by SM installation         Wellington Installer         Other         Household items affected by SM installation         Power Interruption         Meter/Module         Wellington Installer         Household items affected by SM installation         Power Interruption         Meter/Module         Power Interruption         Power Interruption         Meter/Module	Under InvestigationUnder Investigation	Open Open Open Open Open Open Open Open

Page 3 of 34

144         2/9/10           145         2/9/10           146         2/10/10           147         2/10/10           148         2/10/10           149         2/10/10           150         2/10/10           151         2/10/10           152         2/10/10           153         2/10/10	
146         2/10/10           147         2/10/10           148         2/10/10           149         2/10/10           150         2/10/10           151         2/10/10           152         2/10/10           153         2/10/10	
147         2/10/10           148         2/10/10           149         2/10/10           150         2/10/10           151         2/10/10           152         2/10/10           153         2/10/10	
147         2/10/10           148         2/10/10           149         2/10/10           150         2/10/10           151         2/10/10           152         2/10/10           153         2/10/10	L
149         2/10/10           150         2/10/10           151         2/10/10           152         2/10/10           153         2/10/10	I
150         2/10/10           151         2/10/10           152         2/10/10           153         2/10/10	1
150         2/10/10           151         2/10/10           152         2/10/10           153         2/10/10	l
151         2/10/10           152         2/10/10           153         2/10/10	l
152         2/10/10           153         2/10/10	l
153 2/10/10	l
	l
154 2/10/10	l
155 2/10/10	l
156 2/10/10	l
157 2/11/10	l
	l
158 2/11/10 159 2/11/10	
	I
	I
161 2/11/10 162 2/12/10	I
162 2/12/10	I
163 2/12/10	
164 2/12/10	
165 2/12/10	I
166 2/12/10	
167 2/13/10	
168 2/14/10	
169 2/14/10	
170 2/16/10	
171 2/16/10	
172 2/16/10	
173 2/16/10	
174 2/16/10	
175 2/16/10	
176 2/17/10	l
177 2/17/10	I
178 2/17/10	I
179 2/17/10	I
180 2/17/10	I
181 2/17/10	I
182 2/17/10	I
183 2/17/10	1
184 2/17/10	I
185 2/17/10	I
186 2/17/10	I
187 2/17/10	I
187 2/17/10	I
	I
189 2/17/10	I
190 2/18/10	I
191 2/18/10	I
	I
192 2/18/10	I
192         2/18/10           193         2/18/10           194         2/18/10	J

Cupertino	Wellington Installer	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Berkeley	Customer Denies Access	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
Carmel	Network Equipment Installation	Under Investigation	Open
Cupertino	Meter/Module	Under Investigation	Open
Cupertino	Power Interruption	Under Investigation	Open
Cupertino	Scheduling Problems	Under Investigation	Open
NORTH FOLK	Wellington Installer	Under Investigation	Open
Rancho Cordova	Meter/Module	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
San Ramon	Wellington Installer	Under Investigation	Open
/acaville	Household items affected by SM installation	Under Investigation	Open
lealdsburg	Customer Denies Access	Under Investigation	Open
.ivermore	Household items affected by SM installation	Under Investigation	Open
lapa	Meter/Module	Under Investigation	Open
Sunnyvale	Power Interruption	Under Investigation	Open
/allejo	Wellington Installer	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
San Ramon	Household items affected by SM installation	Under Investigation	Open
San Ramon	Household items affected by SM installation	Under Investigation	Open
San Ramon	Wellington Installer	Under Investigation	Open
Berkeley	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Meter/Module	Under Investigation	Open
Valnut Creek	Household items affected by SM installation	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
Cupertino	Wellington Installer	Under Investigation	Open
	Meter/Module	Under Investigation	Open
Santa Clara	Meter/Module	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Forestville	Customer Denies Access	Under Investigation	Open
Aadera	Wellington Installer	Under Investigation	Open
Vewark	Household items affected by SM installation	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
Sunnyvale	Meter/Module	Under Investigation	Open
/allejo	Household items affected by SM installation	Under Investigation	Open
/allejo	Wellington Installer	Under Investigation	Open
/allejo	Wellington Installer	Under Investigation	Open
Valnut Creek	Customer Denies Access	Under Investigation	Open
Berkeley	Meter/Module	Meter/Module clearance issues	Resolved
San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Sunnyvale	Household items affected by SM installation	Damaged Other Household Appliances	Resolved
/adera	Wellington Installer	Under Investigation	Open
	Wellington Installer	Under Investigation	Open
vianuosa			
Mariposa Sanger	Scheduling Problems	Under Investigation	Onen
Sanger Santa Rosa	Scheduling Problems Customer Denies Access	Under Investigation Under Investigation	Open Open

Page 4 of 34

195	2/18/10
196	2/19/10
197	2/19/10
198	2/19/10
199	2/19/10

Los Banos	Other	Other	Resolved
American Canyon	Wellington Installer	Under Investigation	Open
Mountain View	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open

SB\_GT&S\_0783824

is report contains confidential customer information and is being submitted under CPUC Code Section 583.

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

Complaint Date	Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
5/7/09	{Redacted}	{Redacted}	Brentwood	Household items affected by SM installation	Under Investigation	Open
6/9/09	1 í	(	Citrus Heights	Meter/Module	Under Investigation	Open
6/25/09	1		PARADISE	Meter/Module	Under Investigation	Open
7/1/09	1		Capay	Other	Under Investigation	Open
7/2/09	1		Soda Springs	Scheduling Problems	Under Investigation	Open
9/18/09	1		Moraga	SmartMeter Customer Communication	Under Investigation	Open
9/29/09	1	Ahwahnee Meter/Module	Under Investigation	Open		
10/15/09			Stockton	Household items affected by SM installation	Under Investigation	Open
10/26/09			Fremont	Other	Under Investigation	Open
10/28/09	-		√acaville	Wellington Installer	Under Investigation	Open
11/10/09			Hillsborough	Customer Denies Access	Under Investigation	Open
11/10/09			/acaville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
11/12/09			Newark	Meter/Module	Under Investigation	Open
11/16/09			√acaville	Household items affected by SM installation	Under Investigation	Open
11/20/09			Fremont	Meter/Module	Under Investigation	Open
11/23/09	-		WOODLAND	Meter/Module	Under Investigation	Open
11/24/09	-		Kingsburg	Meter/Module	Under Investigation	Open
11/25/09	-		Richmond	Network Equipment Installation	Under Investigation	Open
11/30/09			Fresno	Household items affected by SM installation	Under Investigation	Open
11/30/09			MIRAMONTE	Household items affected by SM installation	Under Investigation	Open
12/2/09			Fremont	Power Interruption	Under Investigation	Open
12/2/09	-		Redwood City	Household items affected by SM installation	Under Investigation	Open
12/3/09			Manteca	Household items affected by SM installation	Under Investigation	Open
12/3/09	-		Vanteca	Household items affected by SM installation	Under Investigation	Open
12/3/09	-		Stockton	Household items affected by SM installation	Under Investigation	Open
12/4/09	-		Hanford	Household items affected by SM installation	Under Investigation	Open
12/4/09	1		Napa	Household items affected by SM installation	Under Investigation	Open
12/7/09	-		Napa Napa	Wellington Installer	Under Investigation	Open
12/8/09	-		PIONEER	Household items affected by SM installation	Under Investigation	Open
12/9/09	Los Altos Household items affected by SM installa	-	Under Investigation	Open		
12/9/09			· · · · · · · · · · · · · · · · · · ·	· · · · ·		
12/11/09	1		Under Investigation	Open Open		
12/11/09	1			Power Interruption		Open
12/11/09 12/11/09	1	Plymouth Meter/Module Under Investigatio Stockton Household items affected by SM installation Under Investigatio		Open		
	-			Household items affected by SM installation	Under Investigation	
12/16/09	1		Mountain View	Scheduling Problems	Under Investigation	Open
12/17/09	1		Sunnyvale	Meter/Module	Under Investigation	Open
<u>12/17/09</u>	1		√acaville _ATHROP	Meter/Module	Under Investigation Other	Open Resolved
12/18/09	1			Other		
12/22/09	1			Household items affected by SM installation	Under Investigation	Open
12/22/09	1			Wellington Installer	Under Investigation	Open
12/23/09	J		Dublin	Meter/Module	Under Investigation	Open

Page 6 of 34

42	12/23/09
43	12/23/09
44	12/23/09
45	12/29/09
46	12/29/09
47	12/29/09
48	12/30/09
49	12/31/09
50	12/31/09
51	1/4/10
52	1/4/10
53	1/5/10
54	1/5/10
55	1/7/10
56	1/8/10
57	1/11/10
58	1/11/10
59	1/11/10
60	1/11/10
61	1/12/10
62	1/12/10
63	
	1/12/10
64	1/12/10
65	1/13/10
66	1/14/10
67	1/14/10
68	1/14/10
69	1/15/10
70	1/15/10
71	1/15/10
72	1/15/10
73	1/16/10
74	1/19/10
75	1/19/10
76	1/19/10
77	1/20/10
78	1/20/10
79	1/22/10
80	1/22/10
81	1/23/10
82	1/25/10
83	1/26/10
84	1/26/10
85	1/26/10
86	1/26/10
87	1/26/10
88	1/26/10
89	1/26/10
90	1/26/10
91	1/26/10
92	1/26/10

Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Valnut Creek	SmartMeter Customer Communication	Under Investigation	Open
El Granada	Power Interruption	Under Investigation	Open
ivermore	Meter/Module	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
os Banos	Network Equipment Installation	Under Investigation	Open
.ivermore	Household items affected by SM installation	Under Investigation	Open
/lountain View	Household items affected by SM installation	Under Investigation	Open
/lenlo Park	Customer Denies Access	Under Investigation	Open
lerced	Customer Denies Access	Under Investigation	Open
UBURN	Power Interruption	Under Investigation	Open
Sebastopol	Other	Customer does not want a SmartMeter	Resolved
.os Altos	Other	Other	Resolved
ivermore	Household items affected by SM installation	Under Investigation	Open
urlingame	Household items affected by SM installation	Under Investigation	Open
airfield	Meter/Module	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
acaville	Meter/Module	Under Investigation	Open
ivermore	Power Interruption	Under Investigation	Open
loraga	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Jerkeley	Customer Denies Access	Customer does not want a SmartMeter	Resolved
ODI	Meter/Module	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Jublin	Household items affected by SM installation	Under Investigation	Open
Corcoran	Wellington Installer	Under Investigation	Open
Jublin	Household items affected by SM installation	Under Investigation	Open
	Scheduling Problems	Under Investigation	Open
lapa San Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
San Jose	Household items affected by SM installation		
	Other	Under Investigation	Open
Nartinez		Under Investigation Other	Open Recolved
ptos	Other		Resolved
San Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Supertino	Household items affected by SM installation	Under Investigation	Open
Cupertino	Power Interruption		Open
remont	Household items affected by SM installation	Under Investigation	Open
Sebastopol	Customer Denies Access	Under Investigation	Open
Kensington Pinole	Household items affected by SM installation SmartMeter Customer Communication	Under Investigation	Open Resolved
		General inquiry on communication	-
merican Canyon	Customer Denies Access	Under Investigation	Open
ivermore	Customer Denies Access	Under Investigation	Open
Aadera	Wellington Installer	Under Investigation	Open
IONTARA	Meter/Module	Under Investigation	Open
leasanton	Wellington Installer	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Meter/Module	Under Investigation	Open
Stockton	Wellington Installer Household items affected by SM installation	Under Investigation	Open
Sunnyvale		Under Investigation	Open

Page 7 of 34

93	1/26/10
94	1/26/10
95	1/26/10
96	1/27/10
97	1/27/10
98	1/27/10
99	1/28/10
100	1/28/10
101	1/28/10
102	1/28/10
103	1/28/10
104	1/28/10
105	1/28/10
106	1/28/10
100	1/29/10
107	1/29/10
	1/29/10
109	
110	1/29/10
111	1/29/10
112	1/29/10
113	1/29/10
114	1/29/10
115	1/29/10
116	1/29/10
117	1/29/10
118	1/31/10
119	1/31/10
120	1/31/10
121	1/31/10
122	1/31/10
123	2/1/10
124	2/1/10
125	2/1/10
126	2/1/10
127	2/1/10
128	2/1/10
129	2/1/10
130	2/2/10
131	2/3/10
132	2/3/10
133	2/3/10
134	2/3/10
135	2/3/10
136	2/3/10
137	2/4/10
138	2/4/10
139	2/4/10
140	2/5/10
140	2/5/10
141	2/5/10
	2/8/10
143	2/0/10

_ivermore	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Vierced	Customer Denies Access	Customer does not want a SmartMeter	Resolved
/allejo	Wellington Installer	Other	Resolved
Hillsborough	Customer Denies Access	Under Investigation	Open
Pleasanton	Wellington Installer	Under Investigation	Open
Redwood City	Meter/Module	Under Investigation	Open
American Canyon	Wellington Installer	Under Investigation	Open
El Sobrante	Wellington Installer	Under Investigation	Open
/loraga	Wellington Installer	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
San Francisco	Power Interruption	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
unnyvale	Power Interruption	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
/ladera	Wellington Installer	Under Investigation	Open
Pinole	Wellington Installer	Under Investigation	Open
Richmond	Wellington Installer	Under Investigation	Open
Rio Vista	Household items affected by SM installation	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	Open
an Jose	Meter/Module	Under Investigation	Open
Stockton	Wellington Installer	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Wellington Installer	Under Investigation	Open
Censington	Meter/Module	Meter/Module clearance issues	Resolved
San Jose	Household items affected by SM installation	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	Open
Bakersfield	Household items affected by SM installation	Other	Resolved
Danville	Meter/Module	Meter/Module clearance issues	Resolved
El Sobrante	Wellington Installer	Under Investigation	Open
A HONDA	Customer Denies Access	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
leasanton	Meter/Module	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
/acaville	Meter/Module	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
ORDELIA	Wellington Installer	Under Investigation	Open
RATON	Other	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
Iountain View	Power Interruption	Under Investigation	Open
leasanton	Meter/Module	Under Investigation	Open
AYMOND	Wellington Installer	Under Investigation	Open
resno	Household items affected by SM installation	Under Investigation	Open
an Ramon	Power Interruption	Under Investigation	Open
uisun City	Meter/Module	Under Investigation	Open
lountain View	Other	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open
San Ramon	Meter/Module	Under Investigation	
	Customer Denies Access	Under Investigation	Open Open

144	2/9/10
145	2/9/10
146	2/10/10
147	2/10/10
148	2/10/10
149	2/10/10
150	2/10/10
151	2/10/10
152	2/10/10
153	2/10/10
154	2/10/10
155	2/10/10
156	2/10/10
157	2/11/10
158	2/11/10
158	2/11/10
160	2/11/10
160	2/11/10
162 163	2/12/10 2/12/10
164	2/12/10
165	2/12/10
166	2/12/10
167	2/13/10
168	2/14/10
169	2/14/10
170	2/16/10
171	2/16/10
172	2/16/10
173	2/16/10
174	2/16/10
175	2/16/10
176	2/17/10
177	2/17/10
178	2/17/10
179	2/17/10
180	2/17/10
181	2/17/10
182	2/17/10
183	2/17/10
184	2/17/10
185	2/17/10
186	2/17/10
187	2/17/10
188	2/17/10
189	2/17/10
190	2/18/10
191	2/18/10
192	2/18/10
193	2/18/10
194	2/18/10

Crum a utiliza a	Mallington Installar	Linder Investigation	<b>A</b>
Cupertino	Wellington Installer	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Berkeley	Customer Denies Access	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
Carmel	Network Equipment Installation	Under Investigation	Open
Cupertino	Meter/Module	Under Investigation	Open
Cupertino	Power Interruption	Under Investigation	Open
Cupertino	Scheduling Problems	Under Investigation	Open
NORTH FOLK	Wellington Installer	Under Investigation	Open
Rancho Cordova	Meter/Module	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
San Ramon	Wellington Installer	Under Investigation	Open
/acaville	Household items affected by SM installation	Under Investigation	Open
lealdsburg	Customer Denies Access	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
lapa	Meter/Module	Under Investigation	Open
Sunnyvale	Power Interruption	Under Investigation	Open
/allejo	Wellington Installer	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
San Ramon	Household items affected by SM installation	Under Investigation	Open
San Ramon	Household items affected by SM installation	Under Investigation	Open
an Ramon	Wellington Installer	Under Investigation	Open
Berkeley	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Meter/Module	Under Investigation	Open
Valnut Creek	Household items affected by SM installation	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
Cupertino	Wellington Installer	Under Investigation	Open
RIPON	Meter/Module	Under Investigation	Open
Santa Clara	Meter/Module	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
orestville	Customer Denies Access	Under Investigation	Open
/ladera	Wellington Installer	Under Investigation	Open
vewark	Household items affected by SM installation	Under Investigation	· ·
San Jose		×	Open
	Wellington Installer	Under Investigation	Open
Sunnyvale	Meter/Module	Under Investigation	Open
/allejo /alleio	Household items affected by SM installation	Under Investigation	Open
/allejo	Wellington Installer		Open
/allejo	Wellington Installer	Under Investigation	Open
Valnut Creek	Customer Denies Access	Under Investigation	Open
Berkeley	Meter/Module	Meter/Module clearance issues	Resolved
San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
anta Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Sunnyvale	Household items affected by SM installation	Damaged Other Household Appliances	Resolved
/ladera	Wellington Installer	Under Investigation	Open
Mariposa	Wellington Installer	Under Investigation	Open
Sanger	Scheduling Problems	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
	Wellington Installer	Under Investigation	

Page 9 of 34

195	2/18/10
196	2/19/10
197	2/19/10
198	2/19/10
199	2/19/10

Los Banos	Other	Other	Resolved
American Canyon	Wellington Installer	Under Investigation	Open
Mountain View	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open

Page 10 of 34

ontains confidential customer information and is being submitted under CPUC Code Section 583.

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

Customer Name	Account	Service City	Core Process	Nature of Complaint	Status
{Redacted}	{Redacted}	Brentwood	Household items affected by SM installation	Under Investigation	Open
		Citrus Heights	Meter/Module	Under Investigation	Open
		PARADISE	Meter/Module	Under Investigation	Open
		Capay	Other	Under Investigation	Open
		Soda Springs	Scheduling Problems	Under Investigation	Open
		Moraga	SmartMeter Customer Communication	Under Investigation	Open
		Ahwahnee	Meter/Module	Under Investigation	Open
		Stockton	Household items affected by SM installation	Under Investigation	Open
		Fremont	Other	Under Investigation	Open
		Vacaville	Wellington Installer	Under Investigation	Open
		Hillsborough	Customer Denies Access	Under Investigation	Open
		Vacaville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
		Newark	Meter/Module	Under Investigation	Open
		Vacaville	Household items affected by SM installation	Under Investigation	Open
		Fremont	Meter/Module	Under Investigation	Open
		WOODLAND	Meter/Module	Under Investigation	Open
		Kingsburg	Meter/Module	Under Investigation	Open
		Richmond	Network Equipment Installation	Under Investigation	Open
		Fresno	Household items affected by SM installation	Under Investigation	Open
		MIRAMONTE	Household items affected by SM installation	Under Investigation	Open
		Fremont	Power Interruption	Under Investigation	Open
		Redwood City	Household items affected by SM installation	Under Investigation	Open
		Manteca	Household items affected by SM installation	Under Investigation	Open
		Manteca	Household items affected by SM installation	Under Investigation	Open
		Stockton	Household items affected by SM installation	Under Investigation	Open
		Hanford	Household items affected by SM installation	Under Investigation	Open
		Napa	Household items affected by SM installation	Under Investigation	Open
		Napa	Wellington Installer	Under Investigation	Open
		PIONEER	Household items affected by SM installation	Under Investigation	Open
		Los Altos	Household items affected by SM installation	Under Investigation	Open
		Stockton	Power Interruption	Under Investigation	Open
		MILLBRAE	Power Interruption	Under Investigation	Open
		Plymouth	Meter/Module	Under Investigation	Open
		Stockton	Household items affected by SM installation	Under Investigation	Open
		Mountain View	Scheduling Problems	Under Investigation	Open
		Sunnyvale	Meter/Module	Under Investigation	Open
		Vacaville	Meter/Module	Under Investigation	Open
		ATHROP	Other	Other	Resolved
		Fremont	Household items affected by SM installation	Under Investigation	Open
		PINE GROVE	Wellington Installer	Under Investigation	Open
		Dublin	Meter/Module	Under Investigation	Open

Page 11 of 34

42	12/23/09
43	12/23/09
44	12/23/09
45	12/29/09
46	12/29/09
47	12/29/09
48	12/30/09
49	12/31/09
50	12/31/09
51	1/4/10
52	1/4/10
53	1/5/10
54	1/5/10
55	1/7/10
56	1/8/10
57	1/11/10
58	1/11/10
59	1/11/10
60	1/11/10
61	1/12/10
62	1/12/10
63	1/12/10
64	1/12/10
65	1/12/10
66	1/13/10
67	1/14/10
68	1/14/10
69	1/15/10
70	1/15/10
70	1/15/10
72	1/15/10
72	1/16/10
73	1/10/10
74	
75	1/19/10
78	1/19/10 1/20/10
78	1/20/10
78	1/20/10
80	1/22/10
81	1/22/10
82	1/25/10
83	1/26/10
83	1/26/10
85	1/26/10
86	1/26/10
87	1/26/10
88	1/26/10
89	1/26/10
90	1/26/10
91	1/26/10
92	1/26/10

			0
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Nalnut Creek	SmartMeter Customer Communication	Under Investigation	Open
El Granada	Power Interruption	Under Investigation	Open
	Meter/Module	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
_os Banos	Network Equipment Installation	Under Investigation	Open
_ivermore	Household items affected by SM installation	Under Investigation	Open
Mountain View	Household items affected by SM installation	Under Investigation	Open
Venlo Park	Customer Denies Access	Under Investigation	Open
Merced	Customer Denies Access	Under Investigation	Open
AUBURN	Power Interruption	Under Investigation	Open
Sebastopol	Other	Customer does not want a SmartMeter	Resolved
_os Altos	Other	Other	Resolved
_ivermore	Household items affected by SM installation	Under Investigation	Open
Burlingame	Household items affected by SM installation	Under Investigation	Open
airfield	Meter/Module	Under Investigation	Open
_ivermore	Household items affected by SM installation	Under Investigation	Open
/acaville	Meter/Module	Under Investigation	Open
_ivermore	Power Interruption	Under Investigation	Open
Moraga	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Berkeley	Customer Denies Access	Customer does not want a SmartMeter	Resolved
	Meter/Module	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Dublin	Household items affected by SM installation	Under Investigation	Open
Corcoran	Wellington Installer	Under Investigation	Open
Dublin	Household items affected by SM installation	Under Investigation	Open
Napa	Scheduling Problems	Under Investigation	Open
San Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
San Jose	Household items affected by SM installation	Under Investigation	Open
Vartinez	Other	Under Investigation	Open
Aptos	Other	Other	Resolved
San Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Cupertino	Household items affected by SM installation	Under Investigation	Open
Cupertino	Power Interruption	Under Investigation	Open
Fremont	Household items affected by SM installation	Under Investigation	Open
Sebastopol	Customer Denies Access	Under Investigation	Open
•	Household items affected by SM installation		Open
Kensington Pinole	SmartMeter Customer Communication	Under Investigation	Resolved
American Canyon		General inquiry on communication Under Investigation	
Livermore	Customer Denies Access Customer Denies Access	Under Investigation	Open Open
	Wellington Installer	Under Investigation	Open
	Meter/Module	Under Investigation	Open
Pleasanton	Wellington Installer	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Meter/Module	Under Investigation	Open
Stockton	Wellington Installer	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open

Page 12 of 34

93         1/26/10           94         1/26/10           95         1/26/10	
95 1/26/10	
96 1/27/10	
97 1/27/10	
98 1/27/10	
99 1/28/10	
100 1/28/10	
101 1/28/10	
102 1/28/10	
103 1/28/10	
104 1/28/10	
105 1/28/10	
106 1/28/10	
107 1/29/10	
108 1/29/10	
109 1/29/10	
110 1/29/10	
111 1/29/10	
112 1/29/10	
113 1/29/10	_
114 1/29/10	
115 1/29/10	_
116 1/29/10	
117 1/29/10	
118 1/31/10	_
119 1/31/10	_
120 1/31/10	
	_
121 1/31/10	_
122 1/31/10	_
123 2/1/10	_
124 2/1/10	_
125 2/1/10	_
126 2/1/10	_
127 2/1/10	_
128 2/1/10	_
129 2/1/10	_
130 2/2/10	_
131 2/3/10	_
132 2/3/10	_
133 2/3/10	_
134 2/3/10	_
135 2/3/10	-
136 2/3/10	-
137 2/4/10	
138 2/4/10	
138         2/4/10           139         2/4/10           140         2/5/10	
138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10	
138         2/4/10           139         2/4/10           140         2/5/10	

Livermore	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Merced	Customer Denies Access	Customer does not want a SmartMeter	Resolved
√allejo	Wellington Installer	Other	Resolved
Hillsborough	Customer Denies Access	Under Investigation	Open
Pleasanton	Wellington Installer	Under Investigation	Open
Redwood City	Meter/Module	Under Investigation	Open
American Canyon	Wellington Installer	Under Investigation	Open
El Sobrante	Wellington Installer	Under Investigation	Open
Voraga	Wellington Installer	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
San Francisco	Power Interruption	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
Sunnyvale	Power Interruption	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Vadera	Wellington Installer	Under Investigation	Open
Pinole	Wellington Installer	Under Investigation	Open
Richmond	Wellington Installer	Under Investigation	Open
Rio Vista	Household items affected by SM installation	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Meter/Module	Under Investigation	Open
Stockton	Wellington Installer	Under Investigation	Open
	Household items affected by SM installation	Under Investigation	Open
Sunnyvale			•
Sunnyvale	Wellington Installer	Under Investigation	Open Received
Kensington	Meter/Module	Meter/Module clearance issues	Resolved
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
Bakersfield	Household items affected by SM installation	Other	Resolved
Danville	Meter/Module	Meter/Module clearance issues	Resolved
El Sobrante	Wellington Installer	Under Investigation	Open
	Customer Denies Access	Under Investigation	Open
_ivermore	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
/acaville	Meter/Module	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
CORDELIA	Wellington Installer	Under Investigation	Open
GRATON	Other	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
Mountain View	Power Interruption	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open
RAYMOND	Wellington Installer	Under Investigation	Open
resno	Household items affected by SM installation	Under Investigation	Open
San Ramon	Power Interruption	Under Investigation	Open
Suisun City	Meter/Module	Under Investigation	Open
Nountain View	Other	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open
San Ramon	Meter/Module	Under Investigation	Open
Sonoma	Customer Denies Access	Under Investigation	Open

Page 13 of 34

144         2/9/10           145         2/9/10           146         2/10/10           147         2/10/10           148         2/10/10           149         2/10/10           150         2/10/10           151         2/10/10           152         2/10/10           153         2/10/10           154         2/10/10           155         2/10/10           156         2/10/10           157         2/11/10           158         2/11/10           160         2/11/10           161         2/11/10           162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178
146         2/10/10           147         2/10/10           148         2/10/10           150         2/10/10           151         2/10/10           152         2/10/10           153         2/10/10           154         2/10/10           155         2/10/10           155         2/10/10           155         2/10/10           156         2/10/10           157         2/11/10           158         2/11/10           160         2/11/10           161         2/11/10           162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           178         2/17/10           179
147         2/10/10           148         2/10/10           149         2/10/10           150         2/10/10           151         2/10/10           152         2/10/10           153         2/10/10           154         2/10/10           155         2/10/10           155         2/10/10           155         2/10/10           156         2/10/10           157         2/11/10           168         2/11/10           161         2/11/10           162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           178         2/17/10           179
148         2/10/10           149         2/10/10           150         2/10/10           151         2/10/10           152         2/10/10           153         2/10/10           154         2/10/10           155         2/10/10           155         2/10/10           155         2/10/10           155         2/10/10           156         2/10/10           157         2/11/10           168         2/11/10           161         2/11/10           162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           178         2/17/10           179         2/17/10           180
149         2/10/10           150         2/10/10           151         2/10/10           152         2/10/10           153         2/10/10           154         2/10/10           155         2/10/10           155         2/10/10           155         2/10/10           155         2/10/10           155         2/10/10           156         2/10/10           157         2/11/10           168         2/11/10           161         2/11/10           162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           178         2/17/10           179         2/17/10           180
149         2/10/10           150         2/10/10           151         2/10/10           152         2/10/10           153         2/10/10           154         2/10/10           155         2/10/10           155         2/10/10           155         2/10/10           155         2/10/10           155         2/10/10           156         2/11/10           157         2/11/10           160         2/11/10           161         2/11/10           162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           178         2/17/10           179         2/17/10           180
150         2/10/10           151         2/10/10           152         2/10/10           153         2/10/10           154         2/10/10           155         2/10/10           155         2/10/10           155         2/10/10           155         2/10/10           155         2/10/10           156         2/10/10           157         2/11/10           160         2/11/10           161         2/11/10           162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           178         2/17/10           179         2/17/10           180
151         2/10/10           152         2/10/10           153         2/10/10           154         2/10/10           155         2/10/10           156         2/10/10           157         2/11/10           158         2/11/10           159         2/11/10           161         2/11/10           162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
1522/10/101532/10/101542/10/101552/10/101562/10/101572/11/101582/11/101592/11/101602/11/101612/11/101622/12/101632/12/101642/12/101652/12/101662/12/101672/13/101682/14/101702/16/101712/16/101722/16/101732/16/101742/16/101752/16/101762/17/101782/17/101792/17/101802/17/10
153         2/10/10           154         2/10/10           155         2/10/10           155         2/10/10           156         2/10/10           157         2/11/10           158         2/11/10           159         2/11/10           160         2/11/10           161         2/11/10           162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
154         2/10/10           155         2/10/10           156         2/10/10           157         2/11/10           158         2/11/10           159         2/11/10           160         2/11/10           161         2/11/10           162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
155         2/10/10           156         2/10/10           157         2/11/10           157         2/11/10           158         2/11/10           159         2/11/10           160         2/11/10           161         2/11/10           162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
1562/10/101572/11/101582/11/101592/11/101602/11/101612/11/101622/12/101632/12/101642/12/101652/12/101662/12/101672/13/101682/14/101702/16/101712/16/101722/16/101752/16/101762/17/101772/17/101782/17/101792/17/101802/17/10
1572/11/101582/11/101592/11/101602/11/101612/11/101622/12/101632/12/101642/12/101652/12/101662/12/101672/13/101682/14/101692/14/101702/16/101712/16/101732/16/101742/16/101752/16/101762/17/101772/17/101782/17/101792/17/101802/17/10
1582/11/101592/11/101602/11/101612/11/101622/12/101632/12/101642/12/101652/12/101662/12/101672/13/101682/14/101692/14/101702/16/101712/16/101732/16/101742/16/101752/16/101762/17/101772/17/101782/17/101792/17/101802/17/10
159         2/11/10           160         2/11/10           161         2/11/10           162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
160         2/11/10           161         2/11/10           162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
161         2/11/10           162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
162         2/12/10           163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           169         2/14/10           170         2/16/10           171         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
163         2/12/10           164         2/12/10           165         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           169         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
164         2/12/10           165         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           169         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
165         2/12/10           166         2/12/10           167         2/13/10           168         2/14/10           169         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
166         2/12/10           167         2/13/10           168         2/14/10           169         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
167         2/13/10           168         2/14/10           169         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
168         2/14/10           169         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
169         2/14/10           170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
170         2/16/10           171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
171         2/16/10           172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
172         2/16/10           173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
173         2/16/10           174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
174         2/16/10           175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
175         2/16/10           176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
176         2/17/10           177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
177         2/17/10           178         2/17/10           179         2/17/10           180         2/17/10
178         2/17/10           179         2/17/10           180         2/17/10
1792/17/101802/17/10
180 2/17/10
181 2/17/10 182 2/17/10
182 2/17/10 182 2/17/10
183 2/17/10
184 2/17/10
185 2/17/10
186 2/17/10
187 2/17/10
188 2/17/10
189 2/17/10
190 2/18/10
191 2/18/10
192 2/18/10
193 2/18/10

Cupertino	Wellington Installer	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Berkeley	Customer Denies Access	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
Carmel	Network Equipment Installation	Under Investigation	Open
Cupertino	Meter/Module	Under Investigation	Open
Cupertino	Power Interruption	Under Investigation	Open
Cupertino	Scheduling Problems	Under Investigation	Open
NORTH FOLK	Wellington Installer	Under Investigation	Open
Rancho Cordova	Meter/Module	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
San Ramon	Wellington Installer	Under Investigation	Open
Vacaville	Household items affected by SM installation	Under Investigation	Open
Healdsburg	Customer Denies Access	- · · · · · · · · · · · · · · · · · · ·	•
	Household items affected by SM installation	Under Investigation	Open
Livermore		Under Investigation	Open
Napa Duppusala	Meter/Module	Under Investigation	Open
Sunnyvale	Power Interruption		Open
Vallejo Daulastas	Wellington Installer	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
San Ramon	Household items affected by SM installation	Under Investigation	Open
San Ramon	Household items affected by SM installation	Under Investigation	Open
San Ramon	Wellington Installer	Under Investigation	Open
Berkeley	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Meter/Module	Under Investigation	Open
Walnut Creek	Household items affected by SM installation	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
Cupertino	Wellington Installer	Under Investigation	Open
RIPON	Meter/Module	Under Investigation	Open
Santa Clara	Meter/Module	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Forestville	Customer Denies Access	Under Investigation	Open
Madera	Wellington Installer	Under Investigation	Open
Newark	Household items affected by SM installation	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
Sunnyvale	Meter/Module	Under Investigation	Open
√allejo	Household items affected by SM installation	Under Investigation	Open
√allejo	Wellington Installer	Under Investigation	Open
√allejo	Wellington Installer	Under Investigation	Open
Walnut Creek	Customer Denies Access	Under Investigation	Open
Berkeley	Meter/Module	Meter/Module clearance issues	Resolved
San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Sunnyvale	Household items affected by SM installation	Damaged Other Household Appliances	Resolved
Madera	Wellington Installer	Under Investigation	Open
Mariposa	Wellington Installer	Under Investigation	Open
Sanger	Scheduling Problems	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Somerset	Wellington Installer	Under Investigation	Open

Page 14 of 34

2/18/10
2/19/10
2/19/10
2/19/10
2/19/10

Los Banos	Other	Other	Resolved
American Canyon	Wellington Installer	Under Investigation	Open
Mountain View	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open

Page 15 of 34

omer information and is being submitted under CPUC Code Section 583.

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

ount	Service City	Core Process	Nature of Complaint	Status
acted}	Brentwood	Household items affected by SM installation	Under Investigation	Open
	Citrus Heights	Meter/Module	Under Investigation	Open
	PARADISE	Meter/Module	Under Investigation	Open
	Сарау	Other	Under Investigation	Open
	Soda Springs	Scheduling Problems	Under Investigation	Open
	Moraga	SmartMeter Customer Communication	Under Investigation	Open
	Ahwahnee	Meter/Module	Under Investigation	Open
	Stockton	Household items affected by SM installation	Under Investigation	Open
	Fremont	Other	Under Investigation	Open
	√acaville	Wellington Installer	Under Investigation	Open
	Hillsborough	Customer Denies Access	Under Investigation	Open
	Vacaville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
	Newark	Meter/Module	Under Investigation	Open
	√acaville	Household items affected by SM installation	Under Investigation	Open
	Fremont	Meter/Module	Under Investigation	Open
	WOODLAND	Meter/Module	Under Investigation	Open
	Kingsburg	Meter/Module	Under Investigation	Open
	Richmond	Network Equipment Installation	Under Investigation	Open
	Fresno	Household items affected by SM installation	Under Investigation	Open
	MIRAMONTE	Household items affected by SM installation	Under Investigation	Open
	Fremont	Power Interruption	Under Investigation	Open
	Redwood City	Household items affected by SM installation	Under Investigation	Open
	Manteca	Household items affected by SM installation	Under Investigation	Open
	Manteca	Household items affected by SM installation	Under Investigation	Open
	Stockton	Household items affected by SM installation	Under Investigation	Open
	Hanford	Household items affected by SM installation	Under Investigation	Open
	Napa	Household items affected by SM installation	Under Investigation	Open
	Napa	Wellington Installer	Under Investigation	Open
	PIONEER	Household items affected by SM installation	Under Investigation	Open
	Los Altos	Household items affected by SM installation	Under Investigation	Open
	Stockton	Power Interruption	Under Investigation	Open
	MILLBRAE	Power Interruption	Under Investigation	Open
	Plymouth	Meter/Module	Under Investigation	Open
	Stockton	Household items affected by SM installation	Under Investigation	Open
	Mountain View	Scheduling Problems	Under Investigation	Open
	Sunnyvale	Meter/Module	Under Investigation	Open
	Vacaville	Meter/Module	Under Investigation	Open
	LATHROP	Other	Other	Resolved
	Fremont	Household items affected by SM installation	Under Investigation	Open
	PINE GROVE	Wellington Installer	Under Investigation	Open
	Dublin	Meter/Module	Under Investigation	Open

Page 16 of 34

42	12/23/09
43	12/23/09
44	12/23/09
45	12/29/09
46	12/29/09
47	12/29/09
48	12/30/09
49	12/31/09
50	12/31/09
51	1/4/10
52	1/4/10
53	1/5/10
54	1/5/10
55	1/7/10
56 57	1/8/10
57	1/11/10
58	1/11/10
59	1/11/10
60	1/11/10
61	1/12/10
62	1/12/10
63	1/12/10
64	1/12/10
65	1/13/10
66	1/14/10
67	1/14/10
68	1/14/10
69	1/15/10
70	1/15/10
71	1/15/10
72	1/15/10
73	1/16/10
74	1/19/10
75	1/19/10
76	1/19/10
77	1/20/10
78	1/20/10
79	1/22/10
80	1/22/10
81	1/23/10
82	1/25/10
83	1/26/10
84	1/26/10
85	1/26/10
86	1/26/10
87	1/26/10
88	1/26/10
89	1/26/10
90	1/26/10
91	1/26/10
92	1/26/10

Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Nalnut Creek	SmartMeter Customer Communication	Under Investigation	Open
El Granada	Power Interruption	Under Investigation	Open
_ivermore	Meter/Module	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
Los Banos	Network Equipment Installation	Under Investigation	Open
_ivermore	Household items affected by SM installation	Under Investigation	Open
Mountain View	Household items affected by SM installation	Under Investigation	Open
vlenio Park	Customer Denies Access	Under Investigation	Open
Vierced	Customer Denies Access	Under Investigation	Open
AUBURN	Power Interruption	Under Investigation	Open
Sebastopol	Other	Customer does not want a SmartMeter	Resolved
_os Altos	Other	Other	Resolved
_ivermore	Household items affected by SM installation	Under Investigation	Open
Burlingame	Household items affected by SM installation	Under Investigation	Open
Fairfield	Meter/Module	Under Investigation	Open
livermore	Household items affected by SM installation	Under Investigation	Open
/acaville	Meter/Module	Under Investigation	Open
_ivermore	Power Interruption	Under Investigation	Open
Moraga	Household items affected by SM installation	Under Investigation	Open
	-	Under Investigation	Open
Sunnyvale	Household items affected by SM installation Customer Denies Access	Customer does not want a SmartMeter	Resolved
Berkeley			
<u>_ODI</u>	Meter/Module	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Dublin	Household items affected by SM installation		Open
Corcoran	Wellington Installer	Under Investigation	Open
Dublin	Household items affected by SM installation	Under Investigation	Open
Napa	Scheduling Problems	Under Investigation	Open
San Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
San Jose	Household items affected by SM installation	Under Investigation	Open
Martinez	Other	Under Investigation	Open
Aptos	Other	Other	Resolved
San Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Cupertino	Household items affected by SM installation	Under Investigation	Open
Cupertino	Power Interruption	Under Investigation	Open
remont	Household items affected by SM installation	Under Investigation	Open
Sebastopol	Customer Denies Access	Under Investigation	Open
Kensington	Household items affected by SM installation	Under Investigation	Open
Pinole	SmartMeter Customer Communication	General inquiry on communication	Resolved
American Canyon	Customer Denies Access	Under Investigation	Open
ivermore	Customer Denies Access	Under Investigation	Open
Madera	Wellington Installer	Under Investigation	Open
MONTARA	Meter/Module	Under Investigation	Open
Pleasanton	Wellington Installer	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Meter/Module	Under Investigation	Open
Stockton	Wellington Installer	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open

Page 17 of 34

93         1/26/10           94         1/26/10           95         1/26/10	
95 1/26/10	
96 1/27/10	
97 1/27/10	
98 1/27/10	
99 1/28/10	
100 1/28/10	
101 1/28/10	
102 1/28/10	
103 1/28/10	
104 1/28/10	
105 1/28/10	
106 1/28/10	
107 1/29/10	
108 1/29/10	
109 1/29/10	
110 1/29/10	
111 1/29/10	
112 1/29/10	
113 1/29/10	_
114 1/29/10	
115 1/29/10	_
116 1/29/10	
117 1/29/10	
118 1/31/10	_
119 1/31/10	_
120 1/31/10	
	_
121 1/31/10	_
122 1/31/10	_
123 2/1/10	_
124 2/1/10	_
125 2/1/10	_
126 2/1/10	_
127 2/1/10	_
128 2/1/10	_
129 2/1/10	_
130 2/2/10	_
131 2/3/10	_
132 2/3/10	_
133 2/3/10	_
134 2/3/10	_
135 2/3/10	-
136 2/3/10	-
137 2/4/10	
138 2/4/10	
138         2/4/10           139         2/4/10           140         2/5/10	
138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10	
138         2/4/10           139         2/4/10           140         2/5/10	

Livermore	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Verced	Customer Denies Access	Customer does not want a SmartMeter	Resolved
/allejo	Wellington Installer	Other	Resolved
Hillsborough	Customer Denies Access	Under Investigation	Open
Pleasanton	Wellington Installer	Under Investigation	Open
Redwood City	Meter/Module	Under Investigation	Open
American Canyon	Wellington Installer	Under Investigation	Open
El Sobrante	Wellington Installer	Under Investigation	Open
Vloraga	Wellington Installer	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
San Francisco	Power Interruption	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
Sunnyvale	Power Interruption	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Vadera	Wellington Installer	Under Investigation	Open
Pinole	Wellington Installer	Under Investigation	Open
Richmond	Wellington Installer	Under Investigation	Open
Rio Vista	Household items affected by SM installation	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Meter/Module	Under Investigation	Open
Stockton	Wellington Installer	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Wellington Installer	Under Investigation	Open
Kensington	Meter/Module	Meter/Module clearance issues	Resolved
San Jose		Under Investigation	
San Jose	Household items affected by SM installation Household items affected by SM installation		Open
	-	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation Other	Open Resolved
Bakersfield	Household items affected by SM installation	Meter/Module clearance issues	Resolved
Danville	Meter/Module		
El Sobrante	Wellington Installer	Under Investigation	Open
	Customer Denies Access	Under Investigation	Open
	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
/acaville	Meter/Module	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
	Wellington Installer	Under Investigation	Open
GRATON	Other	Under Investigation	Open
_ivermore	Household items affected by SM installation	Under Investigation	Open
Mountain View	Power Interruption	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open
RAYMOND	Wellington Installer	Under Investigation	Open
Fresno	Household items affected by SM installation	Under Investigation	Open
San Ramon	Power Interruption	Under Investigation	Open
Suisun City	Meter/Module	Under Investigation	Open
Nountain View	Other	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open
San Ramon	Meter/Module	Under Investigation	Open
Sonoma	Customer Denies Access	Under Investigation	Open

Page 18 of 34

144	2/9/10
145	2/9/10
146	2/10/10
147	2/10/10
148	2/10/10
149	2/10/10
150	2/10/10
151	2/10/10
152	2/10/10
153	2/10/10
154	2/10/10
155	2/10/10
156	2/10/10
157	2/11/10
158	2/11/10
159	2/11/10
160	2/11/10
	2/11/10
161	
162	2/12/10
163	2/12/10
164	2/12/10
165	2/12/10
166	2/12/10
167	2/13/10
168	2/14/10
169	2/14/10
170	2/16/10
171	2/16/10
172	2/16/10
173	2/16/10
174	2/16/10
175	2/16/10
176	2/17/10
177	2/17/10
178	2/17/10
179	2/17/10
180	2/17/10
181	2/17/10
182	2/17/10
183	2/17/10
184	2/17/10
185	2/17/10
186	2/17/10
180	2/17/10
187	
189	2/17/10
	2/17/10
190	2/18/10
191	2/18/10
192	2/18/10
193	2/18/10
194	2/18/10

Cupertino	Wellington Installer	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Berkeley	Customer Denies Access	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
Carmel	Network Equipment Installation	Under Investigation	Open
Cupertino	Meter/Module	Under Investigation	Open
Cupertino	Power Interruption	Under Investigation	Open
Cupertino	Scheduling Problems	Under Investigation	Open
NORTH FOLK	Wellington Installer	Under Investigation	Open
Rancho Cordova	Meter/Module	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
San Ramon	Wellington Installer	Under Investigation	Open
√acaville	Household items affected by SM installation	Under Investigation	Open
Healdsburg	Customer Denies Access	- · · · · · · · · · · · · · · · · · · ·	•
	Household items affected by SM installation	Under Investigation	Open
		Under Investigation	Open
Napa	Meter/Module	Under Investigation	Open
Sunnyvale	Power Interruption	Under Investigation	Open
√allejo Zarkolov	Wellington Installer	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
San Ramon	Household items affected by SM installation		Open
San Ramon	Household items affected by SM installation	Under Investigation	Open
San Ramon	Wellington Installer	Under Investigation	Open
Berkeley	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Meter/Module	Under Investigation	Open
Walnut Creek	Household items affected by SM installation	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
Cupertino	Wellington Installer	Under Investigation	Open
RIPON	Meter/Module	Under Investigation	Open
Santa Clara	Meter/Module	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Forestville	Customer Denies Access	Under Investigation	Open
Madera	Wellington Installer	Under Investigation	Open
Newark	Household items affected by SM installation	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
Sunnyvale	Meter/Module	Under Investigation	Open
√allejo	Household items affected by SM installation	Under Investigation	Open
√allejo	Wellington Installer	Under Investigation	Open
√allejo	Wellington Installer	Under Investigation	Open
Walnut Creek	Customer Denies Access	Under Investigation	Open
Berkeley	Meter/Module	Meter/Module clearance issues	Resolved
San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Sunnyvale	Household items affected by SM installation	Damaged Other Household Appliances	Resolved
Madera	Wellington Installer	Under Investigation	Open
Mariposa	Wellington Installer	Under Investigation	Open
Sanger	Scheduling Problems	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Somerset	Wellington Installer	Under Investigation	Open

Page 19 of 34

2/18/10
2/19/10
2/19/10
2/19/10
2/19/10

Los Banos	Other	Other	Resolved
American Canyon	Wellington Installer	Under Investigation	Open
Mountain View	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open

Page 20 of 34

## nation and is being submitted under CPUC Code Section 583.

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

Service City	Core Process	Nature of Complaint	Status
Brentwood	Household items affected by SM installation	Under Investigation	Open
Citrus Heights	Meter/Module	Under Investigation	Open
PARADISE	Meter/Module	Under Investigation	Open
Capay	Other	Under Investigation	Open
Soda Springs	Scheduling Problems	Under Investigation	Open
Moraga	SmartMeter Customer Communication	Under Investigation	Open
Ahwahnee	Meter/Module	Under Investigation	Open
Stockton	Household items affected by SM installation	Under Investigation	Open
Fremont	Other	Under Investigation	Open
Vacaville	Wellington Installer	Under Investigation	Open
Hillsborough	Customer Denies Access	Under Investigation	Open
Vacaville	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Newark	Meter/Module	Under Investigation	Open
Vacaville	Household items affected by SM installation	Under Investigation	Open
Fremont	Meter/Module	Under Investigation	Open
WOODLAND	Meter/Module	Under Investigation	Open
Kingsburg	Meter/Module	Under Investigation	Open
Richmond	Network Equipment Installation	Under Investigation	Open
Fresno	Household items affected by SM installation	Under Investigation	Open
MIRAMONTE	Household items affected by SM installation	Under Investigation	Open
Fremont	Power Interruption	Under Investigation	Open
Redwood City	Household items affected by SM installation	Under Investigation	Open
Manteca	Household items affected by SM installation	Under Investigation	Open
Manteca	Household items affected by SM installation	Under Investigation	Open
Stockton	Household items affected by SM installation	Under Investigation	Open
Hanford	Household items affected by SM installation	Under Investigation	Open
Napa	Household items affected by SM installation	Under Investigation	Open
Napa	Wellington Installer	Under Investigation	Open
PIONEER	Household items affected by SM installation	Under Investigation	Open
Los Altos	Household items affected by SM installation	Under Investigation	Open
Stockton	Power Interruption	Under Investigation	Open
MILLBRAE	Power Interruption	Under Investigation	Open
Plymouth	Meter/Module	Under Investigation	Open
Stockton	Household items affected by SM installation	Under Investigation	Open
Mountain View	Scheduling Problems	Under Investigation	Open
Sunnyvale	Meter/Module	Under Investigation	Open
Vacaville	Meter/Module	Under Investigation	Open
LATHROP	Other	Other	Resolved
Fremont	Household items affected by SM installation	Under Investigation	Open
PINE GROVE	Wellington Installer	Under Investigation	Open
Dublin	Meter/Module	Under Investigation	Open

Page 21 of 34

42	12/23/09
43	12/23/09
44	12/23/09
45	12/29/09
46	12/29/09
47	12/29/09
48	12/30/09
49	12/31/09
50	12/31/09
51	1/4/10
52	1/4/10
53	1/5/10
54	1/5/10
55	1/7/10
56	1/8/10
57	1/11/10
58	1/11/10
59	1/11/10
60	1/11/10
61	1/12/10
62	1/12/10
63	1/12/10
64	1/12/10
65	1/12/10
66	1/13/10
67	1/14/10
68	1/14/10
69	1/14/10
70	
	1/15/10 1/15/10
71	
72	1/15/10
73	1/16/10
74	1/19/10
75	1/19/10
76	1/19/10
77	1/20/10
78	1/20/10
79	1/22/10
80	1/22/10
81	1/23/10 1/25/10
82	
83	1/26/10
84	1/26/10
85	1/26/10
86	1/26/10
87	1/26/10
88	1/26/10
89	1/26/10
90	1/26/10
91	1/26/10
92	1/26/10

Sunnyvale	Household items affected by SM installation	Inder Investigation	Open
	· · · · · · · · · · · · · · · · · · ·	Under Investigation	•
Sunnyvale Nalnut Creek	Household items affected by SM installation SmartMeter Customer Communication	Under Investigation	Open
El Granada	Power Interruption	Under Investigation Under Investigation	Open Open
ivermore	Meter/Module	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
los Banos	Network Equipment Installation	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
Nountain View	Household items affected by SM installation	Under Investigation	Open
Ienlo Park	Customer Denies Access	Under Investigation	Open
lerced	Customer Denies Access	Under Investigation	Open
UBURN	Power Interruption	Under Investigation	Open
ebastopol	Other	Customer does not want a SmartMeter	Resolved
os Altos	Other	Other	Resolved
ivermore	Household items affected by SM installation	Under Investigation	Open
	Household items affected by SM installation	-	-
urlingame airfield	Meter/Module	Under Investigation Under Investigation	Open Open
ivermore	Household items affected by SM installation	Under Investigation	Open
acaville	Meter/Module	Under Investigation	Open
ivermore	Power Interruption	Under Investigation	Open
loraga	Household items affected by SM installation	Under Investigation	Open
	Household items affected by SM installation	Under Investigation	Open
iunnyvale erkeley	Customer Denies Access	Customer does not want a SmartMeter	Resolved
ODI	Meter/Module	Under Investigation	
			Open Open
	Household items affected by SM installation Household items affected by SM installation	Under Investigation	•
upertino Jublin		Under Investigation	Open
	Household items affected by SM installation	Under Investigation	Open
orcoran	Wellington Installer	Under Investigation	Open
Jublin	Household items affected by SM installation	Under Investigation	Open
lapa an Baman	Scheduling Problems	Under Investigation Customer does not want a SmartMeter	Open Resolved
an Ramon	Customer Denies Access		
an Jose Iartinez	Household items affected by SM installation	Under Investigation	Open
	Other	Under Investigation Other	Open Resolved
ptos	Other		
an Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Cupertino	Household items affected by SM installation	Under Investigation	Open
Cupertino	Power Interruption	Under Investigation	Open
remont	Household items affected by SM installation	Under Investigation	Open
Sebastopol	Customer Denies Access	Under Investigation	Open
Censington Pinole	Household items affected by SM installation SmartMeter Customer Communication	Under Investigation	Open Resolved
		General inquiry on communication	-
mariaan Canvan	Customer Denies Access	Under Investigation	Open
	Customer Denice Assess		
ivermore	Customer Denies Access	Under Investigation	Open
ivermore ladera	Wellington Installer	Under Investigation	Open
ivermore /ladera /IONTARA	Wellington Installer Meter/Module	Under Investigation Under Investigation	Open Open
ivermore /ladera /IONTARA Pleasanton	Wellington Installer Meter/Module Wellington Installer	Under Investigation Under Investigation Under Investigation	Open Open Open
ivermore Madera MONTARA Pleasanton San Jose	Wellington Installer Meter/Module Wellington Installer Household items affected by SM installation	Under Investigation Under Investigation Under Investigation Under Investigation	Open Open Open Open
ivermore Aadera MONTARA Pleasanton San Jose San Jose	Wellington Installer Meter/Module Wellington Installer Household items affected by SM installation Meter/Module	Under Investigation Under Investigation Under Investigation Under Investigation Under Investigation	Open Open Open Open Open
American Canyon Livermore Madera MONTARA Pleasanton San Jose San Jose Stockton Sunnyvale	Wellington Installer Meter/Module Wellington Installer Household items affected by SM installation	Under Investigation Under Investigation Under Investigation Under Investigation	Open Open Open Open

Page 22 of 34

Sunn Sunn Walni El Gra Liverr

Pleas Los B Liverr Moun Menio Merce

AUBL

Seba Los A Liverr Burlin

Fairfie Liverr Vacav Liverr Morag Sunny Berke LODI Cupe Cupe Dublin

Corc Dublii

Napa San F San J Martir Aptos San F Cupel Fremo Sebas Kensi P Amer Liverr Made MON

Pleas San J San J

Stock Sunn Sunn

93	1/26/10
94	1/26/10
95	1/26/10
96	1/27/10
97	1/27/10
98	1/27/10
99	1/28/10
100	1/28/10
101	1/28/10
102	1/28/10
103	1/28/10
104	1/28/10
105	1/28/10
106	1/28/10
107	1/29/10
108	1/29/10
109	1/29/10
110	1/29/10
111	1/29/10
112	1/29/10
112	1/29/10
113	
	1/29/10
115	1/29/10
116	1/29/10
117	1/29/10
118	1/31/10
119	1/31/10
120	1/31/10
121	1/31/10
122	1/31/10
123	2/1/10
124	2/1/10
125	2/1/10
126	2/1/10
127	2/1/10
128	2/1/10
129	2/1/10
130	2/2/10
131	2/3/10
132	2/3/10
133	2/3/10
134	2/3/10
135	2/3/10
136	2/3/10
137	2/4/10
138	2/4/10
139	2/4/10
140	2/5/10
141	2/5/10
142	2/5/10
143	2/8/10

_ivermore	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Merced	Customer Denies Access	Customer does not want a SmartMeter	Resolved
√allejo	Wellington Installer	Other	Resolved
Hillsborough	Customer Denies Access	Under Investigation	Open
Pleasanton	Wellington Installer	Under Investigation	Open
Redwood City	Meter/Module	Under Investigation	Open
American Canyon	Wellington Installer	Under Investigation	Open
El Sobrante	Wellington Installer	Under Investigation	Open
Noraga	Wellington Installer	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
San Francisco	Power Interruption	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
Sunnyvale	Power Interruption	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Madera	Wellington Installer	Under Investigation	Open
Pinole	Wellington Installer	Under Investigation	Open
Richmond	Wellington Installer	Under Investigation	Open
Rio Vista	Household items affected by SM installation	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Meter/Module	Under Investigation	Open
Stockton	Wellington Installer	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Wellington Installer	Under Investigation	Open
Kensington	Meter/Module	Meter/Module clearance issues	Resolved
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
Bakersfield	Household items affected by SM installation	Other	Resolved
Danville	Meter/Module	Meter/Module clearance issues	Resolved
El Sobrante	Wellington Installer	Under Investigation	Open
A HONDA	Customer Denies Access	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
/acaville	Meter/Module	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
	Wellington Installer	Under Investigation	Open
GRATON	Other	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
Aountain View	Power Interruption	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open
RAYMOND	Wellington Installer	Under Investigation	Open
Fresno	Household items affected by SM installation	Under Investigation	Open
San Ramon	Power Interruption	Under Investigation	Open
Suisun City	Meter/Module	Under Investigation	Open
Mountain View	Other	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open
San Ramon	Meter/Module	Under Investigation	Open
Sonoma	Customer Denies Access	Under Investigation	Open

Page 23 of 34

Liverr Merce Vallej Hillsb Pleas Redw Amer E Morag Pleas San F

San J San J Sunn;

Cupe Made P

r Richn Rio V San J

San J Stock Sunn Sunn Kensi

San J San J San J

Baker Danvi E LA H Liverr Pleas San J San J Vaca San J CORI GRA<sup>-</sup> Liverr Moun Pleas RAYN Fresn San F

Suisu Moun Pleas San F Sonol

144	2/9/10
145	2/9/10
146	2/10/10
147	2/10/10
148	2/10/10
149	2/10/10
150	2/10/10
151	2/10/10
152	2/10/10
153	2/10/10
154	2/10/10
155	2/10/10
156	2/10/10
150	2/10/10
158	2/11/10
159	2/11/10
160	2/11/10
161	2/11/10
162	2/12/10
163	2/12/10
164	2/12/10
165	2/12/10
166	2/12/10
167	2/13/10
168	2/14/10
169	2/14/10
170	2/16/10
171	2/16/10
172	2/16/10
173	2/16/10
174	2/16/10
175	2/16/10
176	2/17/10
177	2/17/10
178	2/17/10
179	2/17/10
180	2/17/10
181	2/17/10
182	2/17/10
183	2/17/10
183	2/17/10
185	2/17/10
186	2/17/10
187	2/17/10
188	2/17/10
189	2/17/10
190	2/18/10
191	2/18/10
192	2/18/10
193	2/18/10
194	2/18/10

Cupertino	Wellington Installer	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Berkeley	Customer Denies Access	Under Investigation	Open
	Wellington Installer		•
Berkeley		Under Investigation	Open
Carmel	Network Equipment Installation	Under Investigation	Open
	Meter/Module	Under Investigation	Open
Cupertino	Power Interruption	Under Investigation	Open
	Scheduling Problems	Under Investigation	Open
	Wellington Installer	Under Investigation	Open
Rancho Cordova	Meter/Module	Under Investigation	Open
an Jose	Wellington Installer	Under Investigation	Open
an Ramon	Wellington Installer	Under Investigation	Open
/acaville	Household items affected by SM installation	Under Investigation	Open
lealdsburg	Customer Denies Access	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
lapa	Meter/Module	Under Investigation	Open
Sunnyvale	Power Interruption	Under Investigation	Open
/allejo	Wellington Installer	Under Investigation	Open
lerkeley	Wellington Installer	Under Investigation	Open
an Jose	Power Interruption	Under Investigation	Open
an Ramon	Household items affected by SM installation	Under Investigation	Open
an Ramon	Household items affected by SM installation	Under Investigation	Open
an Ramon	Wellington Installer	Under Investigation	Open
lerkeley	Household items affected by SM installation	Under Investigation	Open
unnyvale	Meter/Module	Under Investigation	Open
Valnut Creek	Household items affected by SM installation	Under Investigation	Open
erkeley	Wellington Installer	Under Investigation	Open
upertino	Wellington Installer	Under Investigation	Open
	Meter/Module	Under Investigation	Open
anta Clara	Meter/Module	Under Investigation	Open
anta Rosa	Customer Denies Access	Under Investigation	Open
unnyvale	Household items affected by SM installation	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
orestville	Customer Denies Access	Under Investigation	Open
/adera	Wellington Installer	Under Investigation	Open
lewark	Household items affected by SM installation	Under Investigation	Open
an Jose	Wellington Installer	Under Investigation	Open
Sunnyvale	Meter/Module	Under Investigation	Open
allejo	Household items affected by SM installation	Under Investigation	Open
allejo	Wellington Installer	Under Investigation	Open
	Wellington Installer	· · · · · · · · · · · · · · · · · · ·	-
/allejo Valnut Creek	Customer Denies Access	Under Investigation	Open
		Under Investigation Meter/Module clearance issues	Open Resolved
erkeley	Meter/Module		Resolved
an Jose	Customer Denies Access	Customer does not want a SmartMeter Customer does not want a SmartMeter	Resolved
anta Rosa	Customer Denies Access		
Sunnyvale	Household items affected by SM installation	Damaged Other Household Appliances	Resolved
/ladera	Wellington Installer	Under Investigation	Open
Mariposa	Wellington Installer	Under Investigation	Open
Sanger	Scheduling Problems	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
omerset	Wellington Installer	Under Investigation	Open

Page 24 of 34

Cupe Santa Berke Berke Carm Cupe

Cupe Cupe NOR

Ranc San J San F Vaca Heald Liverr Napa Sunn Vallej Berke San J San F San F San F Berke Sunn Waln Berke Cupe RIPO Santa Santa Sunn Cupe F Made Newa San J Sunn Vallej Vallej

Vallej Walni Berke

San J Santa Sunn Made

Sang Santa Some

195	2/18/10
196	2/19/10
197	2/19/10
198	2/19/10
199	2/19/10

Los Banos	Other	Other	Resolved
American Canyon	Wellington Installer	Under Investigation	Open
Mountain View	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open

Page 25 of 34

Moun Pleas Pleas

Los B Amer

## eing submitted under CPUC Code Section 583.

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

Core Process	Nature of Complaint	Status
Household items affected by SM installation	Under Investigation	Open
Meter/Module	Under Investigation	Open
Meter/Module	Under Investigation	Open
Other	Under Investigation	Open
Scheduling Problems	Under Investigation	Open
SmartMeter Customer Communication	Under Investigation	Open
Meter/Module	Under Investigation	Open
Household items affected by SM installation	Under Investigation	Open
Other	Under Investigation	Open
Wellington Installer	Under Investigation	Open
Customer Denies Access	Under Investigation	Open
Customer Denies Access	Customer does not want a SmartMeter	Resolved
Meter/Module	Under Investigation	Open
Household items affected by SM installation	Under Investigation	Open
Meter/Module	Under Investigation	Open
Meter/Module	Under Investigation	Open
Meter/Module	Under Investigation	Open
Network Equipment Installation	Under Investigation	Open
Household items affected by SM installation	Under Investigation	Open
Household items affected by SM installation	Under Investigation	Open
Power Interruption	Under Investigation	Open
Household items affected by SM installation	Under Investigation	Open
Household items affected by SM installation	Under Investigation	Open
Household items affected by SM installation	Under Investigation	Open
Household items affected by SM installation	Under Investigation	Open
Household items affected by SM installation	Under Investigation	Open
Household items affected by SM installation	Under Investigation	Open
Wellington Installer	Under Investigation	Open
Household items affected by SM installation	Under Investigation	Open
Household items affected by SM installation	Under Investigation	Open
Power Interruption	Under Investigation	Open
Power Interruption	Under Investigation	Open
Meter/Module	Under Investigation	Open
Household items affected by SM installation	Under Investigation	Open
Scheduling Problems	Under Investigation	Open
Meter/Module	Under Investigation	Open
Meter/Module	Under Investigation	Open
Other	Other	Resolved
Household items affected by SM installation	Under Investigation	Open
Wellington Installer	Under Investigation	Open
Meter/Module	Under Investigation	Open

Page 26 of 34

42	12/23/09
43	12/23/09
44	12/23/09
45	12/29/09
46	12/29/09
47	12/29/09
48	12/30/09
49	12/31/09
50	12/31/09
51	1/4/10
52	1/4/10
53	1/5/10
54	1/5/10
55	1/7/10
56	1/8/10
57	1/11/10
58	1/11/10
59	1/11/10
60	1/11/10
61	1/12/10
62	1/12/10
63	1/12/10
64	1/12/10
65	1/12/10
66	1/14/10
67	1/14/10
68	1/14/10
69	1/15/10
70	1/15/10
71	1/15/10
72	1/15/10
73	1/16/10
74	1/19/10
75	1/19/10
76	1/19/10
77	1/10/10
78	1/20/10
79	1/22/10
80	1/22/10
81	1/23/10
82	1/25/10
83	1/26/10
84	1/26/10
85	1/26/10
86	1/26/10
87	1/26/10
88	1/26/10
89	1/26/10
90	1/26/10
91	1/26/10
91	1/26/10
32	1/20/10

Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Valnut Creek	SmartMeter Customer Communication	Under Investigation	Open
El Granada	Power Interruption	Under Investigation	Open
ivermore	Meter/Module	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
os Banos	Network Equipment Installation	Under Investigation	Open
.ivermore	Household items affected by SM installation	Under Investigation	Open
/lountain View	Household items affected by SM installation	Under Investigation	Open
/lenlo Park	Customer Denies Access	Under Investigation	Open
/erced	Customer Denies Access	Under Investigation	Open
UBURN	Power Interruption	Under Investigation	Open
ebastopol	Other	Customer does not want a SmartMeter	Resolved
os Altos	Other	Other	Resolved
ivermore	Household items affected by SM installation	Under Investigation	Open
Jurlingame	Household items affected by SM installation	Under Investigation	Open
airfield	Meter/Module	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
acaville	Meter/Module	Under Investigation	Open
ivermore	Power Interruption	Under Investigation	Open
loraga	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	· ·	Under Investigation	Open
	Household items affected by SM installation Customer Denies Access	Customer does not want a SmartMeter	Resolved
erkeley			20000000000000000000000000000000000000
ODI	Meter/Module	Under Investigation	Open
Supertino	Household items affected by SM installation	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Dublin	Household items affected by SM installation	Under Investigation	Open
Corcoran	Wellington Installer	Under Investigation	Open
Jublin	Household items affected by SM installation	Under Investigation	Open
lapa	Scheduling Problems	Under Investigation	Open
an Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
an Jose	Household items affected by SM installation	Under Investigation	Open
lartinez	Other	Under Investigation	Open
ptos	Other	Other	Resolved
San Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Cupertino	Household items affected by SM installation	Under Investigation	Open
Cupertino	Power Interruption	Under Investigation	Open
remont	Household items affected by SM installation	Under Investigation	Open
Sebastopol	Customer Denies Access	Under Investigation	Open
Kensington	Household items affected by SM installation	Under Investigation	Open
Pinole	SmartMeter Customer Communication	General inquiry on communication	Resolved
merican Canyon	Customer Denies Access	Under Investigation	Open
ivermore	Customer Denies Access	Under Investigation	Open
ladera	Wellington Installer	Under Investigation	Open
IONTARA	Meter/Module	Under Investigation	Open
Pleasanton	Wellington Installer	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Meter/Module	Under Investigation	Open
Stockton	Wellington Installer	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open

Page 27 of 34

Hous Hous Smar Powe Meter Hous Netwo Hous Hous Custo Custo Powe Other Other Hous Hous Meter Hous Meter Powe Hous Hous Custo Meter Hous Hous Hous Wellir Hous Schee Custo Hous Other Other Custo Hous Powe Hous Custo Hous Smar Custo Custo Wellir Meter Wellir Hous Meter Wellir Hous Hous

93	1/26/10
94	1/26/10
95	1/26/10
96	1/27/10
97	1/27/10
98	1/27/10
99	1/28/10
100	1/28/10
101	1/28/10
102	1/28/10
103	1/28/10
104	1/28/10
105	1/28/10
106	1/28/10
107	1/29/10
108	1/29/10
109	1/29/10
110	1/29/10
111	1/29/10
112	1/29/10
112	1/29/10
113	
	1/29/10
115	1/29/10
116	1/29/10
117	1/29/10
118	1/31/10
119	1/31/10
120	1/31/10
121	1/31/10
122	1/31/10
123	2/1/10
124	2/1/10
125	2/1/10
126	2/1/10
127	2/1/10
128	2/1/10
129	2/1/10
130	2/2/10
131	2/3/10
132	2/3/10
133	2/3/10
134	2/3/10
135	2/3/10
136	2/3/10
137	2/4/10
138	2/4/10
139	2/4/10
140	2/5/10
141	2/5/10
142	2/5/10
143	2/8/10

_ivermore	Customer Denies Access	Customer does not want a SmartMeter	Resolved
/lerced	Customer Denies Access	Customer does not want a SmartMeter	Resolved
/allejo	Wellington Installer	Other	Resolved
Hillsborough	Customer Denies Access	Under Investigation	Open
Pleasanton	Wellington Installer	Under Investigation	Open
Redwood City	Meter/Module	Under Investigation	Open
American Canyon	Wellington Installer	Under Investigation	Open
El Sobrante	Wellington Installer	Under Investigation	Open
/loraga	Wellington Installer	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
San Francisco	Power Interruption	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
Sunnyvale	Power Interruption	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
/ladera	Wellington Installer	Under Investigation	Open
Pinole	Wellington Installer	Under Investigation	Open
Richmond	Wellington Installer	Under Investigation	Open
Rio Vista	Household items affected by SM installation	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Meter/Module	Under Investigation	Open
Stockton	Wellington Installer	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Wellington Installer	Under Investigation	Open
(ensington	Meter/Module	Meter/Module clearance issues	Resolved
San Jose	Household items affected by SM installation	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	Open
akersfield	Household items affected by SM installation	Other	Resolved
Danville	Meter/Module	Meter/Module clearance issues	Resolved
El Sobrante	Wellington Installer	Under Investigation	Open
A HONDA			•
	Customer Denies Access	Under Investigation	Open
	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
acaville	Meter/Module	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	Open
	Wellington Installer	Under Investigation	Open
	Other	Under Investigation	Open
	Household items affected by SM installation	Under Investigation	Open
Nountain View	Power Interruption	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open
	Wellington Installer	Under Investigation	Open
resno	Household items affected by SM installation	Under Investigation	Open
San Ramon	Power Interruption	Under Investigation	Open
Suisun City	Meter/Module	Under Investigation	Open
Nountain View	Other	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open
San Ramon	Meter/Module	Under Investigation	Open
Sonoma	Customer Denies Access	Under Investigation	Open

Page 28 of 34

Custo Custo Wellir Custo Wellir Meter Wellir Wellir Wellir Hous Powe Hous Wellir Powe Hous Wellir Wellir Wellir Hous Hous Meter Wellir Hous Wellir Meter Hous Hous Hous Hous Meter Wellir Custo Hous Meter Powe Powe Meter Hous Wellir Other Hous Powe Meter Wellir Hous Powe Meter Other Meter Meter Custo

144	2/9/10
145	2/9/10
146	2/10/10
147	2/10/10
148	2/10/10
149	2/10/10
150	2/10/10
151	2/10/10
152	2/10/10
153	2/10/10
154	2/10/10
155	2/10/10
156	2/10/10
150	2/10/10
158	2/11/10
159	2/11/10
160	2/11/10
161	2/11/10
162	2/12/10
163	2/12/10
164	2/12/10
165	2/12/10
166	2/12/10
167	2/13/10
168	2/14/10
169	2/14/10
170	2/16/10
171	2/16/10
172	2/16/10
173	2/16/10
174	2/16/10
175	2/16/10
176	2/17/10
177	2/17/10
178	2/17/10
179	2/17/10
180	2/17/10
181	2/17/10
182	2/17/10
183	2/17/10
183	2/17/10
185	2/17/10
186	2/17/10
187	2/17/10
188	2/17/10
189	2/17/10
190	2/18/10
191	2/18/10
192	2/18/10
193	2/18/10
194	2/18/10

Cupertino	Wellington Installer	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Berkeley	Customer Denies Access	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
Carmel	Network Equipment Installation	Under Investigation	Open
Cupertino	Meter/Module	Under Investigation	Open
Cupertino	Power Interruption	Under Investigation	Open
Cupertino	Scheduling Problems	Under Investigation	Open
NORTH FOLK	Wellington Installer	Under Investigation	Open
Rancho Cordova	Meter/Module	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
San Ramon	Wellington Installer	Under Investigation	Open
acaville	Household items affected by SM installation	Under Investigation	Open
lealdsburg	Customer Denies Access	Under Investigation	Open
	Household items affected by SM installation		Open
livermore		Under Investigation	•
lapa Suppyyale	Meter/Module Power Interruption	Under Investigation	Open
Sunnyvale Valleio	Power Interruption	Under Investigation Under Investigation	Open Open
/allejo Berkelev	Wellington Installer		Open
ian Jose	Wellington Installer Power Interruption	Under Investigation	Open
	•	Under Investigation	•
San Ramon San Ramon	Household items affected by SM installation	Under Investigation	Open
	Household items affected by SM installation Wellington Installer	Under Investigation	Open
an Ramon		Under Investigation	Open
Berkeley	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Meter/Module	Under Investigation	Open
Valnut Creek	Household items affected by SM installation	Under Investigation	Open
lerkeley	Wellington Installer	Under Investigation	Open
	Wellington Installer		Open
	Meter/Module	Under Investigation	Open
Santa Clara	Meter/Module	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
orestville	Customer Denies Access	Under Investigation	Open
/ladera	Wellington Installer	Under Investigation	Open
lewark	Household items affected by SM installation	Under Investigation	Open
San Jose	Wellington Installer		Open
Sunnyvale	Meter/Module	Under Investigation	Open
/allejo /alleio	Household items affected by SM installation	Under Investigation	Open
/allejo	Wellington Installer	Under Investigation	Open
/allejo	Wellington Installer	Under Investigation	Open
Valnut Creek	Customer Denies Access	Under Investigation	Open
Berkeley	Meter/Module	Meter/Module clearance issues	Resolved
San Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Santa Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Sunnyvale	Household items affected by SM installation	Damaged Other Household Appliances	Resolved
/ladera	Wellington Installer	Under Investigation	Open
Variposa	Wellington Installer	Under Investigation	Open
Sanger	Scheduling Problems	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Somerset	Wellington Installer	Under Investigation	Open

Page 29 of 34

Wellir Custo Custo Wellir Netwo Meter

Powe Sched Wellin Meter

Wellir Wellir Hous Custo Hous Meter Powe Wellir Wellir Powe House Hous Wellir Hous Meter Hous Wellir Wellir Meter Meter Custo Hous Hous Custo Wellir Hous Wellir Meter Hous Wellir Wellir Custo Meter Custo Custo Hous Wellir Wellir Schee Custo Wellir

195	2/18/10
196	2/19/10
197	2/19/10
198	2/19/10
199	2/19/10

Los Banos	Other	Other	Resolved
American Canyon	Wellington Installer	Under Investigation	Open
Mountain View	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open

Page 30 of 34

Other Wellin Hous Hous Meter

# Section 583.

Color Key	
Resolved Since the Last Report	
New Since the Last Report	

Nature of Complaint	Status
Under Investigation	Open
Customer does not want a SmartMeter	Resolved
Under Investigation	Open
Other	Resolved
Under Investigation	Open
Under Investigation	Open
Under Investigation	Open

Page 31 of 34

42	12/23/09
43	12/23/09
44	12/23/09
45	12/29/09
46	12/29/09
47	12/29/09
48	12/30/09
49	12/31/09
50	12/31/09
51	1/4/10
52	1/4/10
53	1/5/10
54	1/5/10
55	1/7/10
56	1/8/10
57	1/11/10
58	1/11/10
59	1/11/10
60	1/11/10
61	1/12/10
62	1/12/10
63	1/12/10
64	1/12/10
65	1/12/10
66	1/13/10
67	1/14/10
68	1/14/10
69	1/15/10
70	1/15/10
70	1/15/10
72	1/15/10
72	1/16/10
73	1/10/10
74	
75	1/19/10
78	1/19/10 1/20/10
78	1/20/10
78	1/20/10
80	1/22/10
81	1/22/10
82	1/25/10
83	1/26/10
83	1/26/10
85	1/26/10
86	1/26/10
87	1/26/10
88	1/26/10
89	1/26/10
90	1/26/10
91	1/26/10
92	1/26/10

Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Valnut Creek	SmartMeter Customer Communication	Under Investigation	Open
I Granada	Power Interruption	Under Investigation	Open
ivermore	Meter/Module	Under Investigation	Open
leasanton	Household items affected by SM installation	Under Investigation	Open
.os Banos	Network Equipment Installation	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
/lountain View	Household items affected by SM installation	Under Investigation	Open
Ienlo Park	Customer Denies Access	Under Investigation	Open
lerced	Customer Denies Access	Under Investigation	Open
UBURN	Power Interruption	Under Investigation	Open
ebastopol	Other	Customer does not want a SmartMeter	Resolved
os Altos	Other	Other	Resolved
ivermore	Household items affected by SM installation	Under Investigation	Open
Jurlingame	Household items affected by SM installation	Under Investigation	Open
airfield	Meter/Module	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
acaville	Meter/Module	Under Investigation	Open
ivermore	Power Interruption	Under Investigation	Open
loraga	Household items affected by SM installation	Under Investigation	Open
unnyvale	Household items affected by SM installation	Under Investigation	Open
erkeley	Customer Denies Access	Customer does not want a SmartMeter	Resolved
ODI	Meter/Module	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Jublin	Household items affected by SM installation	Under Investigation	Open
orcoran	Wellington Installer	Under Investigation	Open
Jublin	Household items affected by SM installation	Under Investigation	Open
lapa	Scheduling Problems	Under Investigation	Open
an Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
an Jose	Household items affected by SM installation	Under Investigation	Open
lartinez	Other	Under Investigation	Open
ptos	Other	Other	Resolved
an Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Cupertino	Household items affected by SM installation	Under Investigation	Open
Supertino	Power Interruption	Under Investigation	Open
remont	Household items affected by SM installation	Under Investigation	Open
ebastopol	Customer Denies Access	Under Investigation	Open
Censington	Household items affected by SM installation	Under Investigation	Open
Pinole	SmartMeter Customer Communication	General inquiry on communication	Resolved
merican Canyon	Customer Denies Access	Under Investigation	Open
ivermore	Customer Denies Access	Under Investigation	Open
ladera	Wellington Installer	Under Investigation	Open
IONTARA	Meter/Module	Under Investigation	Open
leasanton	Wellington Installer	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	
San Jose	Meter/Module	Under Investigation	Open
		- · · · · · · · · · · · · · · · · · · ·	Open
Stockton	Wellington Installer Household items affected by SM installation	Under Investigation	Open
Sunnyvale Sunnyvale	Household items affected by SM installation	Under Investigation Under Investigation	Open

Page 32 of 34

Under Under Under Under Under Under Under Under

Unde Unde C O

Unde Unde Unde

Unde Unde Unde

Unde

Unde C Unde Unde

Unde Unde Unde Unde C Unde Unde

O C Under Under Under Under Under Under

Unde Unde Unde

Unde Unde Unde Unde Unde

93         1/26/10           94         1/26/10           95         1/26/10           96         1/27/10           97         1/27/10           98         1/27/10           99         1/28/10           100         1/28/10           101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         <		
95         1/26/10           96         1/27/10           97         1/27/10           98         1/27/10           99         1/28/10           100         1/28/10           101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           130         2/2/10           131         <	93	1/26/10
96         1/27/10           97         1/27/10           98         1/27/10           99         1/28/10           100         1/28/10           101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           130         2/2/10           131         2/3/10           132         <	94	1/26/10
97         1/27/10           98         1/27/10           99         1/28/10           100         1/28/10           101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           130         2/2/10           131         2/3/10           132	95	1/26/10
98         1/27/10           99         1/28/10           100         1/28/10           101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           130         2/2/10           131         2/3/10           132	96	1/27/10
99         1/28/10           100         1/28/10           101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133	97	
100         1/28/10           101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134	98	1/27/10
101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         <	99	1/28/10
101         1/28/10           102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         <	100	1/28/10
102         1/28/10           103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136	101	
103         1/28/10           104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2		
104         1/28/10           105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           139         2/		
105         1/28/10           106         1/28/10           107         1/29/10           108         1/29/10           110         1/29/10           111         1/29/10           111         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           138         2/		
106         1/28/10           107         1/29/10           108         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
107         1/29/10           108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
108         1/29/10           109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
109         1/29/10           110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
110         1/29/10           111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           141         2/5/10           142         2/5/10		
111         1/29/10           112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           141         2/5/10		
112         1/29/10           113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
113         1/29/10           114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           119         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
114         1/29/10           115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           119         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
115         1/29/10           116         1/29/10           117         1/29/10           118         1/31/10           119         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
116         1/29/10           117         1/29/10           118         1/31/10           119         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
117         1/29/10           118         1/31/10           119         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           122         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           137         2/4/10           138         2/4/10           140         2/5/10           141         2/5/10		
118         1/31/10           119         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           122         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
119         1/31/10           120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
120         1/31/10           121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10	118	1/31/10
121         1/31/10           122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10	119	1/31/10
122         1/31/10           123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10	120	1/31/10
123         2/1/10           124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           141         2/5/10           142         2/5/10	121	1/31/10
124         2/1/10           125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           141         2/5/10           142         2/5/10	122	1/31/10
125         2/1/10           126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10	123	2/1/10
126         2/1/10           127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10	124	2/1/10
127         2/1/10           128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10	125	2/1/10
128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           141         2/5/10           142         2/5/10	126	2/1/10
128         2/1/10           129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           141         2/5/10           142         2/5/10	127	2/1/10
129         2/1/10           130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           141         2/5/10           142         2/5/10		
130         2/2/10           131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10		
131         2/3/10           132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
132         2/3/10           133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
133         2/3/10           134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
134         2/3/10           135         2/3/10           136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
135         2/3/10           136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
136         2/3/10           137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
137         2/4/10           138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
138         2/4/10           139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
139         2/4/10           140         2/5/10           141         2/5/10           142         2/5/10		
140         2/5/10           141         2/5/10           142         2/5/10		
141         2/5/10           142         2/5/10		
142 2/5/10		
143 2/8/10		
	143	2/8/10

VallejoWellington InstallerOtherIHillsboroughCustomer Denies AccessUnder InvestigationIPleasantonWellington InstallerUnder InvestigationIRedwood CityMeter/ModuleUnder InvestigationIAmerican CanyonWellington InstallerUnder InvestigationIEl SobranteWellington InstallerUnder InvestigationIMoragaWellington InstallerUnder InvestigationIPleasantonHousehold items affected by SM installationUnder InvestigationISan FranciscoPower InterruptionUnder InvestigationISan JoseHousehold items affected by SM installationUnder InvestigationISunnyvalePower InterruptionUnder InvestigationICupertinoHousehold items affected by SM installationUnder InvestigationISunnyvalePower InterruptionUnder InvestigationICupertinoHousehold items affected by SM installationUnder InvestigationIPinoleWellington InstallerUnder InvestigationIRichmondWellington InstallerUnder InvestigationISan JoseHousehold items affected by SM installationUnder InvestigationI <th>ivermore</th> <th>Customer Denies Access</th> <th>Customer does not want a SmartMeter</th> <th>Resolved</th>	ivermore	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Hillsborough       Customer Denies Access       Under Investigation         Pleasanton       Wellington Installer       Under Investigation         Edwood City       Meter/Module       Under Investigation         Samerican Canyon       Wellington Installer       Under Investigation         El Sobrante       Wellington Installer       Under Investigation         San Francisco       Power Interruption       Under Investigation         San Francisco       Power Interruption       Under Investigation         San Jose       Household items affected by SM installation       Under Investigation         San Jose       Household items affected by SM installation       Under Investigation         Sunnyvale       Power Interruption       Under Investigation         Cupertino       Household items affected by SM installation       Under Investigation         Valera       Wellington Installer       Under Investigation         Sichmond       Wellington Installer       Under Investigation         Sicka       Household items affected by SM installation       Under Investigation         Sicka       Household items affected by SM installation       Under Investigation         Sicka       Household items affected by SM installation       Under Investigation         Sicka       Household items affecte	lerced	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Pleasanton         Wellington Installer         Under Investigation           Redwood City         Meter/Module         Under Investigation           Immerican Canyon         Wellington Installer         Under Investigation           El Sobrante         Wellington Installer         Under Investigation           Isobrante         Wellington Installer         Under Investigation           Jan Francisco         Power Interruption         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           Cupertino         Household items affected by SM installation         Under Investigation           Cupertino         Household items affected by SM installation         Under Investigation           Sichmond         Wellington Installer         Under Investigation           Sichmond         Wellington Installer         Under Investigation           Six Vista         Household items affected by SM installation         Under Investigation           Six Vista         Household items affected by SM installation         Under Investigation           Six Vista         Household items affected by SM installation         Under Investigation           Six Vista         Household items a	/allejo	Wellington Installer	Other	Resolved
Redwood City         Meter/Module         Under Investigation           Immerican Canyon         Wellington Installer         Under Investigation         Immerican Canyon           I Sobrante         Wellington Installer         Under Investigation         Immerican Canyon           I Sobrante         Wellington Installer         Under Investigation         Immerican Canyon           I Sobrante         Household items affected by SM installation         Under Investigation         Immerican Canyon           San Jose         Household items affected by SM installation         Under Investigation         Immerican Canyon           San Jose         Household items affected by SM installation         Under Investigation         Immerican Canyon           Under Investigation         Household items affected by SM installation         Under Investigation         Immerican Canyon           Stan Jose         Household items affected by SM installation         Under Investigation         Immerican Canyon           Stan Jose         Household items affected by SM installation         Under Investigation         Immerican Canyon           Stan Jose         Household items affected by SM installation         Under Investigation         Immerican Canyon           Stan Jose         Household items affected by SM installation         Under Investigation         Immerican Canyon	lillsborough	Customer Denies Access	Under Investigation	Open
umerican Canyon         Wellington Installer         Under Investigation           I Sobrante         Wellington Installer         Under Investigation           Pleasanton         Household items affected by SM installation         Under Investigation           Pleasanton         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Wellington Installer         Under Investigation           Jupertino         Household items affected by SM installation         Under Investigation           Vupertino         Household items affected by SM installation         Under Investigation           Stehmond         Wellington Installer         Under Investigation           Stehmond         Wellington Installer         Under Investigation           Stehmond         Wellington Installer         Under Investigation           Stan Jose         Household items affected by SM installation         Under Investigation           Stan Jose         Meter/Module         Under Investigation           Stan Jose         Household items affected by SM installation         Under Investigation           Stan Jose         Household items affected by SM installation         Under Investigation           Stan Jose         H	leasanton	Wellington Installer	Under Investigation	Open
El Sobrante       Wellington Installer       Under Investigation         Aoraga       Wellington Installer       Under Investigation         Beasanton       Household Items affected by SM installation       Under Investigation         San Jose       Household Items affected by SM installation       Under Investigation         San Jose       Household Items affected by SM installation       Under Investigation         Sunyvale       Power Interruption       Under Investigation         Outer Investigation       Inder Investigation       Inder Investigation         Adera       Wellington Installer       Under Investigation       Inder Investigation         Stohmond       Wellington Installer       Under Investigation       Inder Investigation         Stohtond       Wellington Installer       Under Investigation       Inder Investigation         Stokton       Wellington Installer       Under Investigation       Inder In	Redwood City	Meter/Module	Under Investigation	Open
Abraga         Wellington Installer         Under Investigation           Pleasanton         Household items affected by SM installation         Under Investigation           San Francisco         Power Interruption         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Wellington Installer         Under Investigation           Quertino         Household items affected by SM installation         Under Investigation           Zupertino         Household items affected by SM installation         Under Investigation           Stohmod         Wellington Installer         Under Investigation           Stohmod         Wellington Installer         Under Investigation           Stohmod         Wellington Installer         Under Investigation           Stohtsta         Household items affected by SM installation         Under Investigation           Stokton         Wellington Installer         Under Investigation           Stokton         Wellington Installer         Under Investigation           Stokton         Wellington Installer         Under Investigation           Stonyale         Household items affected by SM installation         Under Investigation           Stan Jose         Household items affected by SM installation <td< td=""><td>merican Canyon</td><td>Wellington Installer</td><td>Under Investigation</td><td>Open</td></td<>	merican Canyon	Wellington Installer	Under Investigation	Open
Pleasanton         Household items affected by SM installation         Under Investigation           ian Francisco         Power Interruption         Under Investigation         Inder Investigation           ian Jose         Wellington Installer         Under Investigation         Inder Investigation           jumnyale         Power Interruption         Under Investigation         Inder Investigation           Zupertino         Household items affected by SM installation         Under Investigation         Inder Investigation           items         Mellington Installer         Under Investigation         Inder Investigation           items         Household items affected by SM installation         Under Investigation         Inder Investigation           items         Household items affected by SM installation         Under Investigation         Inder Investigation           isan Jose         Household items affected by SM installation         Under Investigation         Inder Investigation           isan Jose         Household items affected by SM installation         Under Investigation         Inder Investigation           isan Jose         Household items affected by SM installation         Under Investigation         Inder Investigation           isan Jose         Household items affected by SM installation         Under Investigation         Inder Investigation	I Sobrante	Wellington Installer	Under Investigation	Open
San Francisco         Power Interruption         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Wellington Installer         Under Investigation           Sunnyvale         Power Interruption         Under Investigation           Zupertino         Household items affected by SM installation         Under Investigation           Adera         Wellington Installer         Under Investigation           Nich         Wellington Installer         Under Investigation           Notal         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           Sunnyvale         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation <td< td=""><td>/loraga</td><td>Wellington Installer</td><td>Under Investigation</td><td>Open</td></td<>	/loraga	Wellington Installer	Under Investigation	Open
an Jose       Household items affected by SM installation       Under Investigation         ian Jose       Wellington Installer       Under Investigation         uppertino       Household items affected by SM installation       Under Investigation         Adera       Wellington Installer       Under Investigation         inole       Wellington Installer       Under Investigation         itchmond       Wellington Installer       Under Investigation         itcockton       Meter/Module       Meter/Module Clearance issues         itan Jose       Household items affected by SM installation       Under Investigation         itan Jose       Household items affected by SM installation       Under Investigation	leasanton	Household items affected by SM installation	Under Investigation	Open
ian Jose         Wellington Installer         Under Investigation           junnyvale         Power Interruption         Under Investigation         Investigation           dadera         Wellington Installer         Under Investigation         Investigation           incle         Wellington Installer         Under Investigation         Investigation           ikomond         Wellington Installer         Under Investigation         Investigation           iko Vista         Household items affected by SM installation         Under Investigation         Investigation           iko Vista         Household items affected by SM installation         Under Investigation         Investigation           iko Vista         Household items affected by SM installation         Under Investigation         Investigation           iko kon         Wellington Installer         Under Investigation         Investigation           ikonsport         Meter/Module         Meter/Module clearance issues         Investigation           ikonsport         Household items affected by SM installation         Under Investigation         Inder Investigation           ikarsfield         Household items affected by SM installation         Under Investigation         Inder Investigation           ikarsfield         Household items affected by SM installation         Under Investigation	San Francisco	Power Interruption	Under Investigation	Open
ian Jose         Wellington Installer         Under Investigation           iumnyvale         Power Interruption         Under Investigation         Investigation           iumnyvale         Wellington Installer         Under Investigation         Investigation           incle         Wellington Installer         Under Investigation         Investigation           ikhmond         Wellington Installer         Under Investigation         Investigation           iko Vista         Household items affected by SM installation         Under Investigation         Investigation           ian Jose         Meter/Module         Under Investigation         Investigation           iotoxton         Wellington Installer         Under Investigation         Investigation           iumnyvale         Household items affected by SM installation         Under Investigation         Investigation           ian Jose         Household items affected by SM installation         Under Investigation         Investigation           ian Jose         Household items affected by SM installation         Under Investigation         Investigation           ian Jose         Household items affected by SM installation         Under Investigation         Investigation           ian Jose         Household items affected by SM installation         Under Investigation         Investigation	an Jose	Household items affected by SM installation	Under Investigation	Open
Buyertino         Household items affected by SM installation         Under Investigation           Incle         Wellington Installer         Under Investigation           Vinole         Wellington Installer         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation<	an Jose	Wellington Installer		Open
Buyertino         Household items affected by SM installation         Under Investigation           Incle         Wellington Installer         Under Investigation           Vinole         Wellington Installer         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation           Vista         Household items affected by SM installation         Under Investigation<	unnyvale	Power Interruption	Under Investigation	Open
Adadera       Wellington Installer       Under Investigation         Vinole       Wellington Installer       Under Investigation         Bito Vista       Household items affected by SM installation       Under Investigation         Stan Jose       Household items affected by SM installation       Under Investigation         Stan Jose       Meter/Module       Under Investigation         Unnyvale       Wellington Installer       Under Investigation         Stanton       Meter/Module       Under Investigation         Stanton       Meter/Module       Under Investigation         Stanton       Meter/Module       Meter/Investigation         Stanton       Meter/Module       Meter/Investigation         Stanton       Meter/Module       Meter/Investigation         Stanton       Meter/Module       Inder Investigation         Stanton       Meter/Module clearance issues       Inder Investigation         Stanton       Meter/Module       Inder Investigation       Inder Investigation         Stanton       Meter/Module       Meter/Module clearance issues       Inder Investigation         Stanton       Meter/Module       Meter/Module clearance issues       Inder Investigation         Stanton       Meter/Module       Under Investigation       Inder Investig				Open
Prinole         Wellington Installer         Under Investigation           Richmond         Wellington Installer         Under Investigation           Ric Vista         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Meter/Module         Under Investigation           Stockton         Wellington Installer         Under Investigation           Sunnyvale         Household items affected by SM installation         Under Investigation           Sunnyvale         Wellington Installer         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation           San Jose         Household items affected by SM installation         Under Investigation <td< td=""><td>•</td><td></td><td></td><td>Open</td></td<>	•			Open
Richmond       Wellington Installer       Under Investigation         Rio Vista       Household items affected by SM installation       Under Investigation         ain Jose       Household items affected by SM installation       Under Investigation         ain Jose       Meter/Module       Under Investigation         bittokton       Wellington Installer       Under Investigation         bittokton       Wellington Installer       Under Investigation         bittokton       Meter/Module       Meter/Module clearance issues         bittokton       Meter/Module       Under Investigation         bittokton <td></td> <td></td> <td>-</td> <td>Open</td>			-	Open
No Vista       Household items affected by SM installation       Under Investigation         San Jose       Household items affected by SM installation       Under Investigation         Stockton       Wellington Installer       Under Investigation         Stockton       Wellington Installer       Under Investigation         Stockton       Wellington Installer       Under Investigation         Stockton       Meter/Module       Meter/Module clearance issues         Stockton       Meter/Module       Meter/Module clearance issues         San Jose       Household items affected by SM installation       Under Investigation         San Jose       Household items affected by SM installation       Under Investigation         San Jose       Household items affected by SM installation       Under Investigation         San Jose       Household items affected by SM installation       Under Investigation         San Jose       Household items affected by SM installation       Under Investigation         Satersfield       Household items affected by SM installation       Under Investigation         Satersfield       Household items affected by SM installation       Under Investigation         Vermore       Household items affected by SM installation       Under Investigation         Vermore       Household items affected by SM installation				Open
an Jose       Household items affected by SM installation       Under Investigation         an Jose       Meter/Module       Under Investigation         tockton       Wellington Installer       Under Investigation         unnyvale       Household items affected by SM installation       Under Investigation         unnyvale       Wellington Installer       Under Investigation         unnyvale       Wellington Installer       Under Investigation         ian Jose       Household items affected by SM installation       Under Investigation         ian Jose       Household items affected by SM installation       Under Investigation         ian Jose       Household items affected by SM installation       Under Investigation         ian Jose       Household items affected by SM installation       Under Investigation         ian Jose       Household items affected by SM installation       Under Investigation         iakersfield       Household items affected by SM installation       Under Investigation         iasanton       Meter/Module       Meter/Module clearance issues       Investigation         ian Jose       Household items affected by SM installation       Under Investigation       Inder Investigation         ian Jose       Power Interruption       Under Investigation       Inder Investigation       Inder Investigation				Open
Ban JoseMeter/ModuleUnder InvestigationBitocktonWellington InstallerUnder InvestigationBunnyvaleHousehold items affected by SM installationUnder InvestigationBunnyvaleWellington InstallerUnder InvestigationBunnyvaleWellington InstallerUnder InvestigationBunnyvaleMeter/ModuleMeter/Module clearance issuesBan JoseHousehold items affected by SM installationUnder InvestigationBan JoseHousehold items affected by SM installationUnder InvestigationBakersfieldHousehold items affected by SM installationUnder InvestigationBakersfieldHousehold items affected by SM installationOtherDanvilleMeter/ModuleMeter/Module clearance issuesBakersfieldHousehold items affected by SM installationUnder InvestigationBakersfieldHousehold items affected by SM installationUnder InvestigationBakersfieldWellington InstallerUnder InvestigationBan JoseHousehold items affected by SM installationUnder InvestigationBan JosePower InterruptionUnder InvestigationBan JosePower InterruptionUnder InvestigationBan JoseHousehold items affected by SM installationUnder InvestigationBan JosePower InterruptionUnder InvestigationBan JoseHousehold items affected by SM installationUnder InvestigationBan JoseHousehold items affected by SM installationUnder InvestigationBan JoseHousehold items affec		-	-	Open
Bit Stockton         Wellington Installer         Under Investigation           Bunnyvale         Household items affected by SM installation         Under Investigation           Bunnyvale         Wellington Installer         Under Investigation           Bunnyvale         Wellington Installer         Under Investigation           Busehold items affected by SM installation         Under Investigation         Investigation           Ban Jose         Household items affected by SM installation         Under Investigation         Investigation           Ban Jose         Household items affected by SM installation         Under Investigation         Investigation           Ban Jose         Household items affected by SM installation         Under Investigation         Investigation           Bakersfield         Household items affected by SM installation         Under Investigation         Investigation           Banville         Meter/Module         Meter/Module clearance issues         Investigation           Banscher         Wellington Installer         Under Investigation         Investigation           Ban Jose         Power Interruption         Under Investigation         Investigation           Ban Jose         Power Interruption         Under Investigation         Investigation           Ban Jose         Power Interruption         Und		· ·		Open
Bunnyvale         Household items affected by SM installation         Under Investigation           Sunnyvale         Wellington Installer         Under Investigation         I           Gensington         Meter/Module         Meter/Module clearance issues         I           San Jose         Household items affected by SM installation         Under Investigation         I           San Jose         Household items affected by SM installation         Under Investigation         I           San Jose         Household items affected by SM installation         Under Investigation         I           San Jose         Household items affected by SM installation         Under Investigation         I           Bakersfield         Household items affected by SM installation         Under Investigation         I           Danville         Meter/Module         Meter/Module clearance issues         I           Sobrante         Wellington Installer         Under Investigation         I           A HONDA         Customer Denies Affected by SM installation         Under Investigation         I           Vieenando         Under Investigation         I         I           Beasanton         Meter/Module         Under Investigation         I           San Jose         Power Interruption         Under Investigation				Open
Bunnyvale         Wellington Installer         Under Investigation           Kensington         Meter/Module         Meter/Module clearance issues         I           San Jose         Household items affected by SM installation         Under Investigation         I           San Jose         Household items affected by SM installation         Under Investigation         I           San Jose         Household items affected by SM installation         Under Investigation         I           Sakersfield         Household items affected by SM installation         Under Investigation         I           Janville         Meter/Module         Meter/Module clearance issues         I           Sobrante         Wellington Installer         Under Investigation         I           A HONDA         Customer Denies Access         Under Investigation         I           Vermore         Household items affected by SM installation         Under Investigation         I           Saa Jose         Power Interruption         Under Investigation         I           Saa Jose         Power Interruption         Under Investigation         I           Saa Jose         Power Interruption         Under Investigation         I           Saa Jose         Household items affected by SM installation         Under Investigation		_		Open
KensingtonMeter/ModuleMeter/Module clearance issuesStan JoseHousehold items affected by SM installationUnder InvestigationStan JoseHousehold items affected by SM installationUnder InvestigationStan JoseHousehold items affected by SM installationUnder InvestigationStan JoseHousehold items affected by SM installationUnder InvestigationStakersfieldHousehold items affected by SM installationOtherDarvilleMeter/ModuleMeter/Module clearance issuesIA HONDACustomer Denies AccessUnder InvestigationIViermoreHousehold items affected by SM installationUnder InvestigationIVieravilleMeter/ModuleUnder InvestigationIStan JosePower InterruptionUnder InvestigationIVieravilleMeter/ModuleUnder InvestigationIStan JoseHousehold items affected by SM installationUnder InvestigationIStan JoseHousehold items affected by SM installationUnder InvestigationIStan JoseHousehold items affected by SM installationUnder InvestigationICORDELIAWellington InstallerUnder InvestigationIViermoreHousehold items affected by SM installa	•	-		Open
San JoseHousehold items affected by SM installationUnder InvestigationSan JoseHousehold items affected by SM installationUnder InvestigationSan JoseHousehold items affected by SM installationUnder InvestigationBakersfieldHousehold items affected by SM installationOtherDanvilleMeter/ModuleMeter/Module clearance issuesBakersfieldHousehold items affected by SM installationOtherDanvilleMeter/ModuleMeter/Module clearance issuesBakersfieldWellington InstallerUnder InvestigationA HONDACustomer Denies AccessUnder InvestigationViermoreHousehold items affected by SM installationUnder InvestigationPleasantonMeter/ModuleUnder InvestigationSan JosePower InterruptionUnder InvestigationSan JosePower InterruptionUnder InvestigationSan JosePower InterruptionUnder InvestigationCORDELIAWellington InstallerUnder InvestigationSATONOtherUnder InvestigationAtomin ViewPower InterruptionUnder InvestigationAtomin View				Resolved
San JoseHousehold items affected by SM installationUnder InvestigationSan JoseHousehold items affected by SM installationUnder InvestigationBakersfieldHousehold items affected by SM installationOtherDanvilleMeter/ModuleMeter/Module clearance issuesSan JoseWellington InstallerUnder InvestigationA HONDACustomer Denies AccessUnder InvestigationVermoreHousehold items affected by SM installationUnder InvestigationPleasantonMeter/ModuleUnder InvestigationSan JosePower InterruptionUnder InvestigationSan JoseHousehold items affected by SM installationUnder InvestigationScarDILAWellington InstallerUnder InvestigationScarDILAWellington InstallerUnder InvestigationScarDINOtherUnder InvestigationAdvintin ViewPower InterruptionUnder InvestigationPleasantonMeter/ModuleUnder InvestigationRATONOtherUnder InvestigationAdvinduleUnder InvestigationAdvinduleUnder InvestigationPower InterruptionUnder InvestigationRAYMONDWellington InstallerVellasantonHeter/ModuleAdvinduleUnder Investigation </td <td></td> <td></td> <td></td> <td>Open</td>				Open
Ban JoseHousehold items affected by SM installationUnder InvestigationBakersfieldHousehold items affected by SM installationOtherImage: Constraint of the second		*		Open
BakersfieldHousehold items affected by SM installationOtherIDanvilleMeter/ModuleMeter/Module clearance issuesIEl SobranteWellington InstallerUnder InvestigationIA HONDACustomer Denies AccessUnder InvestigationIVermoreHousehold items affected by SM installationUnder InvestigationIPleasantonMeter/ModuleUnder InvestigationIVarian JosePower InterruptionUnder InvestigationIVarian JosePower InterruptionUnder InvestigationIVarian JosePower InterruptionUnder InvestigationIVarian JosePower InterruptionUnder InvestigationIVarian JoseHousehold items affected by SM installationUnder InvestigationICORDELIAWellington InstallerUnder InvestigationIVormoreHousehold items affected by SM installationUnder InvestigationIVermoreHousehold items affected by S				Open
DanvilleMeter/ModuleMeter/Module clearance issuesEl SobranteWellington InstallerUnder InvestigationA HONDACustomer Denies AccessUnder InvestigationivermoreHousehold items affected by SM installationUnder InvestigationPleasantonMeter/ModuleUnder InvestigationBan JosePower InterruptionUnder InvestigationCacavilleMeter/ModuleUnder InvestigationVacavilleMeter/ModuleUnder InvestigationCordDELIAWellington InstallerUnder InvestigationCordDELIAWellington InstallerUnder InvestigationMountain ViewPower InterruptionUnder InvestigationPleasantonMeter/ModuleUnder InvestigationCordDELIAWellington InstallerUnder InvestigationCordDELIAWellington InstallerUnder InvestigationAdvintain ViewPower InterruptionUnder InvestigationPleasantonMeter/ModuleUnder InvestigationAtyMONDWellington InstallerUnder InvestigationCasa RamonPower InterruptionUnder InvestigationCasa RamonPower InterruptionUnder InvestigationStan RamonPower Interrup				Resolved
I SobranteWellington InstallerUnder InvestigationA HONDACustomer Denies AccessUnder InvestigationivermoreHousehold items affected by SM installationUnder InvestigationPleasantonMeter/ModuleUnder InvestigationSan JosePower InterruptionUnder InvestigationSan JosePower InterruptionUnder InvestigationSan JosePower InterruptionUnder InvestigationSan JosePower InterruptionUnder InvestigationSan JoseHousehold items affected by SM installationUnder InvestigationSan JoseHousehold items affected by SM installationUnder InvestigationCORDELIAWellington InstallerUnder InvestigationBRATONOtherUnder InvestigationAountain ViewPower InterruptionUnder InvestigationPleasantonMeter/ModuleUnder InvestigationRAYMONDWellington InstallerUnder InvestigationPleasantonMeter/ModuleUnder InvestigationRAYMONDWellington InstallerUnder InvestigationSan RamonPower InterruptionUnder InvestigationSan RamonPower InterruptionUnder InvestigationSuisun CityMeter/ModuleUnder InvestigationMountain ViewOtherUnder Investigation		-		Resolved
A HONDACustomer Denies AccessUnder InvestigationivermoreHousehold items affected by SM installationUnder InvestigationPleasantonMeter/ModuleUnder Investigationian JosePower InterruptionUnder Investigationian JoseHousehold items affected by SM installationUnder Investigationian JoseHousehold items affected by SM installationUnder InvestigationicondectorUnder InvestigationinstallericondectorUnder InvestigationinstallationivermoreHousehold items affected by SM installationUnder InvestigationivermoreHousehold items affected by SM installationUnder InvestigationRAYMONDWellington InstallerUnder InvestigationiresnoHousehold items affected by SM installationUnder InvestigationiresnoHousehold items affected by SM installationUnder InvestigationiresnoHousehold items affected by SM installationUnder Investigationisan RamonPower InterruptionUnder Investigation<				Open
IvermoreHousehold items affected by SM installationUnder InvestigationPleasantonMeter/ModuleUnder InvestigationSan JosePower InterruptionUnder InvestigationSan JosePower InterruptionUnder Investigation(acavilleMeter/ModuleUnder InvestigationSan JoseHousehold items affected by SM installationUnder Investigation(acavilleMeter/ModuleUnder InvestigationSan JoseHousehold items affected by SM installationUnder InvestigationCORDELIAWellington InstallerUnder InvestigationCORDELIAWellington InstallerUnder InvestigationCornorHousehold items affected by SM installationUnder InvestigationMountain ViewPower InterruptionUnder InvestigationPleasantonMeter/ModuleUnder InvestigationRAYMONDWellington InstallerUnder InvestigationRAYMONDWellington InstallerUnder InvestigationRamonPower InterruptionUnder InvestigationBan RamonPower InterruptionUnder InvestigationSoan RamonPower InterruptionUnder InvestigationSuisun CityMeter/ModuleUnder InvestigationAuntain ViewOtherUnder Investigation				Open
PleasantonMeter/ModuleUnder InvestigationGan JosePower InterruptionUnder InvestigationGan JosePower InterruptionUnder Investigation/acavilleMeter/ModuleUnder Investigation/acavilleMeter/ModuleUnder InvestigationSan JoseHousehold items affected by SM installationUnder InvestigationCORDELIAWellington InstallerUnder InvestigationCORDELIAWellington InstallerUnder InvestigationSRATONOtherUnder InvestigationNountain ViewPower InterruptionUnder InvestigationPleasantonMeter/ModuleUnder InvestigationRAYMONDWellington InstallerUnder InvestigationRAYMONDWellington InstallerUnder InvestigationRAYMONDWellington InstallerUnder InvestigationBan RamonPower InterruptionUnder Investigation <td></td> <td></td> <td></td> <td>Open</td>				Open
an JosePower InterruptionUnder Investigationaan JosePower InterruptionUnder Investigation/acavilleMeter/ModuleUnder Investigation/acavilleMeter/ModuleUnder Investigationaan JoseHousehold items affected by SM installationUnder InvestigationCORDELIAWellington InstallerUnder InvestigationBRATONOtherUnder InvestigationivermoreHousehold items affected by SM installationUnder InvestigationMountain ViewPower InterruptionUnder InvestigationPleasantonMeter/ModuleUnder InvestigationRAYMONDWellington InstallerUnder InvestigationBrancPower InterruptionUnder InvestigationBrancPower InterruptionUnder InvestigationBrancMeter/ModuleUnder InvestigationBrancPower InterruptionUnder InvestigationBrancPower Inter		-		Open
San JosePower InterruptionUnder Investigation/acavilleMeter/ModuleUnder InvestigationSan JoseHousehold items affected by SM installationUnder InvestigationCORDELIAWellington InstallerUnder InvestigationSRATONOtherUnder InvestigationSRATONOtherUnder InvestigationAountain ViewPower InterruptionUnder InvestigationPleasantonMeter/ModuleUnder InvestigationRAYMONDWellington InstallerUnder InvestigationSan RamonPower InterruptionUnder InvestigationSan RamonPower InterruptionUnder InvestigationSuisun CityMeter/ModuleUnder InvestigationAountain ViewOtherUnder Investigation				Open
VacavilleMeter/ModuleUnder InvestigationSan JoseHousehold items affected by SM installationUnder InvestigationCORDELIAWellington InstallerUnder InvestigationSRATONOtherUnder InvestigationSRATONOtherUnder InvestigationAountain ViewPower InterruptionUnder InvestigationPleasantonMeter/ModuleUnder InvestigationRAYMONDWellington InstallerUnder InvestigationFresnoHousehold items affected by SM installationUnder InvestigationSan RamonPower InterruptionUnder InvestigationSuisun CityMeter/ModuleUnder InvestigationMountain ViewOtherUnder Investigation				Open
San JoseHousehold items affected by SM installationUnder InvestigationCORDELIAWellington InstallerUnder InvestigationSRATONOtherUnder InvestigationSearceHousehold items affected by SM installationUnder InvestigationMountain ViewPower InterruptionUnder InvestigationPleasantonMeter/ModuleUnder InvestigationRAYMONDWellington InstallerUnder InvestigationFresnoHousehold items affected by SM installationUnder InvestigationSan RamonPower InterruptionUnder InvestigationSuisun CityMeter/ModuleUnder InvestigationMountain ViewOtherUnder Investigation				Open
CORDELIA       Wellington Installer       Under Investigation         GRATON       Other       Under Investigation         Granton       Household items affected by SM installation       Under Investigation         Mountain View       Power Interruption       Under Investigation         Pleasanton       Meter/Module       Under Investigation         RAYMOND       Wellington Installer       Under Investigation         Fresno       Household items affected by SM installation       Under Investigation         Gan Ramon       Power Interruption       Under Investigation         Suisun City       Meter/Module       Under Investigation         Aountain View       Other       Under Investigation				Open
GRATONOtherUnder InvestigationivermoreHousehold items affected by SM installationUnder InvestigationMountain ViewPower InterruptionUnder InvestigationPleasantonMeter/ModuleUnder InvestigationRAYMONDWellington InstallerUnder InvestigationFresnoHousehold items affected by SM installationUnder InvestigationBan RamonPower InterruptionUnder InvestigationBuisun CityMeter/ModuleUnder InvestigationMountain ViewOtherUnder Investigation		-		Open
Ivermore         Household items affected by SM installation         Under Investigation           Mountain View         Power Interruption         Under Investigation           Pleasanton         Meter/Module         Under Investigation           RAYMOND         Wellington Installer         Under Investigation           Fresno         Household items affected by SM installation         Under Investigation           Ban Ramon         Power Interruption         Under Investigation           Suisun City         Meter/Module         Under Investigation           Mountain View         Other         Under Investigation				Open
Mountain View         Power Interruption         Under Investigation           Pleasanton         Meter/Module         Under Investigation           RAYMOND         Wellington Installer         Under Investigation           resno         Household items affected by SM installation         Under Investigation           San Ramon         Power Interruption         Under Investigation           Buisun City         Meter/Module         Under Investigation           Mountain View         Other         Under Investigation	• • • • • • • • • • • • • • • • • • • •			Open
Pleasanton         Meter/Module         Under Investigation           RAYMOND         Wellington Installer         Under Investigation           Fresno         Household items affected by SM installation         Under Investigation           San Ramon         Power Interruption         Under Investigation           Suisun City         Meter/Module         Under Investigation           Mountain View         Other         Under Investigation				Open
RAYMOND         Wellington Installer         Under Investigation           Gresno         Household items affected by SM installation         Under Investigation           San Ramon         Power Interruption         Under Investigation           Suisun City         Meter/Module         Under Investigation           Mountain View         Other         Under Investigation		•		Open
iresno       Household items affected by SM installation       Under Investigation         San Ramon       Power Interruption       Under Investigation         Susun City       Meter/Module       Under Investigation         Mountain View       Other       Under Investigation			-	Open
San Ramon     Power Interruption     Under Investigation       Suisun City     Meter/Module     Under Investigation       Mountain View     Other     Under Investigation				Open
Buisun City         Meter/Module         Under Investigation           Mountain View         Other         Under Investigation				
Aountain View Other Under Investigation				Open
				Open
				Open
				Open
San Ramon         Meter/Module         Under Investigation           Sonoma         Customer Denies Access         Under Investigation				Open Open

Page 33 of 34

с с о

Unde M Unde Unde Unde O М Unde Unde

144	2/9/10
145	2/9/10
146	2/10/10
147	2/10/10
148	2/10/10
149	2/10/10
150	2/10/10
151	2/10/10
152	2/10/10
153	2/10/10
154	2/10/10
155	2/10/10
156	2/10/10
157	2/11/10
158	2/11/10
159	2/11/10
160	2/11/10
161	2/11/10
161	2/11/10
162	2/12/10
165	2/12/10
165	2/12/10
166	2/12/10
167	2/13/10
168	2/14/10
169	2/14/10
170	2/16/10
171	2/16/10
172	2/16/10
173	2/16/10
174	2/16/10
175	2/16/10
176	2/17/10
177	2/17/10
178	2/17/10
179	2/17/10
180	2/17/10
181	2/17/10
182	2/17/10
183	2/17/10
184	2/17/10
185	2/17/10
186	2/17/10
187	2/17/10
188	2/17/10
189	2/17/10
109	2/18/10
	2/18/10
191	
192	2/18/10
193	2/18/10
194	2/18/10

Cupertino	Wellington Installer	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Berkeley	Customer Denies Access	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
Carmel	Network Equipment Installation	Under Investigation	Open
Cupertino	Meter/Module	Under Investigation	Open
Cupertino	Power Interruption	Under Investigation	Open
Cupertino	Scheduling Problems	Under Investigation	Open
NORTH FOLK	Wellington Installer	Under Investigation	Open
Rancho Cordova	Meter/Module	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
San Ramon	Wellington Installer	Under Investigation	Open
/acaville	Household items affected by SM installation	Under Investigation	Open
lealdsburg	Customer Denies Access	Under Investigation	Open
-			
livermore	Household items affected by SM installation	Under Investigation	Open
lapa Suppusido	Meter/Module	Under Investigation	Open
Sunnyvale	Power Interruption	Under Investigation	Open
/allejo	Wellington Installer	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
San Jose	Power Interruption	Under Investigation	Open
San Ramon	Household items affected by SM installation	Under Investigation	Open
San Ramon	Household items affected by SM installation	Under Investigation	Open
San Ramon	Wellington Installer	Under Investigation	Open
Berkeley	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Meter/Module	Under Investigation	Open
Valnut Creek	Household items affected by SM installation	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
Cupertino	Wellington Installer	Under Investigation	Open
RIPON	Meter/Module	Under Investigation	Open
Santa Clara	Meter/Module	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
orestville	Customer Denies Access	Under Investigation	Open
/ladera	Wellington Installer	Under Investigation	Open
lewark	Household items affected by SM installation	Under Investigation	Open
San Jose	Wellington Installer	Under Investigation	Open
Sunnyvale	Meter/Module	Under Investigation	Open
/allejo	Household items affected by SM installation	Under Investigation	Open
/allejo	Wellington Installer	Under Investigation	Open
/allejo	Wellington Installer	Under Investigation	Open
Valnut Creek	Customer Denies Access	Under Investigation	Open
Berkeley	Meter/Module	Meter/Module clearance issues	Resolved
an Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
anta Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Sunnyvale	Household items affected by SM installation	Damaged Other Household Appliances	Resolved
/adera	Wellington Installer	Under Investigation	Open
	Wellington Installer	Under Investigation	Open
Variposa			
	Scheduling Problems Customer Denies Access	Under Investigation Under Investigation	Open Open

Page 34 of 34

Unde Unde

Unde M C C D

Unde Unde Unde Unde Unde

2/18/10
2/19/10
2/19/10
2/19/10
2/19/10

Los Banos	Other	Other	Resolved
American Canyon	Wellington Installer	Under Investigation	Open
Mountain View	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open

Page 35 of 34

O Unde Unde Unde

Status
Open
Resolved
Open
Open Resolved
Resolved
Open
Open
Open

Page 36 of 34

42         12/23/09           43         12/23/09           44         12/23/09           45         12/29/09           46         12/29/09           47         12/29/09           48         12/30/09           49         12/31/09           50         12/31/09           51         1/4/10           52         1/4/10           53         1/5/10           54         1/5/10           55         1/7/10           56         1/8/10           57         1/11/10           58         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           67         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10		
44         12/23/09           45         12/29/09           46         12/29/09           47         12/29/09           48         12/30/09           49         12/31/09           50         12/31/09           51         1/4/10           52         1/4/10           53         1/5/10           54         1/5/10           55         1/7/10           56         1/8/10           57         1/11/10           58         1/11/10           59         1/11/10           60         1/12/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10     <	42	12/23/09
45         12/29/09           46         12/29/09           47         12/29/09           48         12/30/09           49         12/31/09           50         12/31/09           51         1/4/10           52         1/4/10           53         1/5/10           54         1/5/10           55         1/7/10           56         1/8/10           57         1/11/10           58         1/11/10           58         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           71         1/22/10 </td <td>43</td> <td>12/23/09</td>	43	12/23/09
46         12/29/09           47         12/29/09           48         12/31/09           50         12/31/09           50         12/31/09           51         1/4/10           52         1/4/10           53         1/5/10           54         1/5/10           55         1/7/10           56         1/8/10           57         1/11/10           58         1/11/10           59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10      79         1/22/10      8	44	
47         12/29/09           48         12/31/09           50         12/31/09           50         12/31/09           51         1/4/10           52         1/4/10           53         1/5/10           54         1/5/10           55         1/7/10           56         1/8/10           57         1/11/10           58         1/11/10           59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           79         1/22/10           80         1/22/10 <td>45</td> <td></td>	45	
48         12/30/09           49         12/31/09           50         12/31/09           51         1/4/10           52         1/4/10           53         1/5/10           54         1/5/10           55         1/7/10           56         1/8/10           57         1/11/10           58         1/11/10           59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           77         1/25/10	46	
48         12/30/09           49         12/31/09           50         12/31/09           51         1/4/10           52         1/4/10           53         1/5/10           54         1/5/10           55         1/7/10           56         1/8/10           57         1/11/10           58         1/11/10           59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           77         1/25/10	47	
49         12/31/09           50         12/31/09           51         1/4/10           52         1/4/10           53         1/5/10           54         1/5/10           55         1/7/10           56         1/8/10           57         1/11/10           58         1/11/10           59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           80         1/22/10           81         1/23/10		
50         12/31/09           51         1/4/10           52         1/4/10           53         1/5/10           54         1/5/10           55         1/7/10           56         1/8/10           57         1/11/10           58         1/11/10           59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           80         1/22/10           81         1/23/10           82         1/25/10	49	
51         1/4/10           52         1/4/10           53         1/5/10           54         1/5/10           55         1/7/10           56         1/8/10           57         1/11/10           58         1/11/10           59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           79         1/22/10           80         1/22/10           81         1/23/10           82         1/26/10		
52         1/4/10           53         1/5/10           54         1/5/10           55         1/7/10           56         1/8/10           57         1/11/10           58         1/11/10           59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10		
53         1/5/10           54         1/5/10           55         1/7/10           56         1/8/10           57         1/1/10           58         1/1/10           59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           79         1/22/10           80         1/22/10           81         1/23/10           82         1/26/10           84         1/26/10           85         1/26/10 </td <td></td> <td></td>		
54         1/5/10           55         1/7/10           56         1/8/10           57         1/11/10           58         1/11/10           59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
55         1/7/10           56         1/8/10           57         1/1/10           58         1/11/10           59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/20/10           79         1/22/10           80         1/22/10           81         1/23/10           82         1/26/10           83         1/26/10           84         1/26/10           85         1/26/10		
56         1/8/10           57         1/11/10           58         1/11/10           59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/20/10           79         1/22/10           80         1/22/10           81         1/23/10           82         1/26/10           83         1/26/10           84         1/26/10           85         1/26/10		
57         1/11/10           58         1/11/10           59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           80         1/22/10           80         1/22/10           81         1/23/10           82         1/26/10           83         1/26/10           84         1/26/10           85         1/26/10		
58         1/11/10           59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
59         1/11/10           60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
60         1/11/10           61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
61         1/12/10           62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
62         1/12/10           63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           80         1/22/10           80         1/22/10           81         1/23/10           82         1/26/10           83         1/26/10           84         1/26/10		
63         1/12/10           64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           80         1/22/10           80         1/22/10           81         1/23/10           82         1/26/10           83         1/26/10           84         1/26/10           85         1/26/10		
64         1/12/10           65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
65         1/13/10           66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
66         1/14/10           67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
67         1/14/10           68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           79         1/22/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
68         1/14/10           69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
69         1/15/10           70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/22/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
70         1/15/10           71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           79         1/22/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
71         1/15/10           72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           79         1/22/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
72         1/15/10           73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           79         1/22/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
73         1/16/10           74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           79         1/22/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
74         1/19/10           75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           79         1/22/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
75         1/19/10           76         1/19/10           77         1/20/10           78         1/20/10           79         1/22/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10	73	1/16/10
76         1/19/10           77         1/20/10           78         1/20/10           79         1/22/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10	74	1/19/10
77         1/20/10           78         1/20/10           79         1/22/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10	75	
78         1/20/10           79         1/22/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10	76	1/19/10
79         1/22/10           80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10		
80         1/22/10           81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10	78	1/20/10
81         1/23/10           82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10	79	1/22/10
82         1/25/10           83         1/26/10           84         1/26/10           85         1/26/10	80	
82         1/26/10           84         1/26/10           85         1/26/10	81	
84         1/26/10           85         1/26/10	82	1/25/10
85 1/26/10	83	1/26/10
	84	1/26/10
86 1/26/10	85	1/26/10
1/20/10	86	1/26/10
87 1/26/10	87	1/26/10
88 1/26/10		
89 1/26/10		
90 1/26/10		
91 1/26/10		
92 1/26/10		

Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Walnut Creek	SmartMeter Customer Communication	Under Investigation	Open
El Granada	Power Interruption	Under Investigation	Open
ivermore	Meter/Module	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
os Banos	Network Equipment Installation	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
Aountain View	Household items affected by SM installation	Under Investigation	Open
/lenlo Park	Customer Denies Access	Under Investigation	Open
lerced	Customer Denies Access	Under Investigation	Open
UBURN	Power Interruption	Under Investigation	Open
Sebastopol	Other	Customer does not want a SmartMeter	Resolved
.os Altos	Other	Other	Resolved
ivermore	Household items affected by SM installation	Under Investigation	Open
Burlingame	Household items affected by SM installation	Under Investigation	Open
airfield	Meter/Module	Under Investigation	Open
ivermore.	Household items affected by SM installation	Under Investigation	Open
/acaville	Meter/Module	Under Investigation	Open
ivermore	Power Interruption	Under Investigation	Open
/loraga	Household items affected by SM installation	Under Investigation	Open
Sunnyvale	Household items affected by SM installation	Under Investigation	Open
Berkeley	Customer Denies Access	Customer does not want a SmartMeter	Resolved
ODI	Meter/Module	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Cupertino	Household items affected by SM installation	Under Investigation	Open
Dublin	Household items affected by SM installation	Under Investigation	Open
Corcoran	Wellington Installer	Under Investigation	Open
Dublin	Household items affected by SM installation	Under Investigation	Open
lapa	Scheduling Problems	Under Investigation	Open
San Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
San Jose	Household items affected by SM installation	Under Investigation	Open
/artinez	Other	Under Investigation	Open
vptos	Other	Other	Resolved
San Ramon	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Cupertino	Household items affected by SM installation	Under Investigation	Open
Cupertino	Power Interruption	Under Investigation	Open
remont	Household items affected by SM installation	Under Investigation	Open
Sebastopol	Customer Denies Access	Under Investigation	Open
censington	Household items affected by SM installation	Under Investigation	Open
Pinole	SmartMeter Customer Communication	General inquiry on communication	Resolved
merican Canyon	Customer Denies Access	Under Investigation	Open
ivermore	Customer Denies Access	Under Investigation	Open
/adera	Wellington Installer	Under Investigation	Open
IONTARA	Meter/Module	Under Investigation	Open
leasanton	Wellington Installer	Under Investigation	Open
San Jose	Household items affected by SM installation	Under Investigation	•
	Meter/Module		Open Open
	wieter/woodule	Under Investigation	Open
	Mollington Installor	Under Investigation	Onon
San Jose Stockton Sunnyvale	Wellington Installer Household items affected by SM installation	Under Investigation Under Investigation	Open Open

Page 37 of 34

93	1/26/10
94	1/26/10
95	1/26/10
96	1/27/10
97	1/27/10
98	1/27/10
99	1/28/10
100	1/28/10
101	1/28/10
102	1/28/10
103	1/28/10
104	1/28/10
105	1/28/10
106	1/28/10
100	1/29/10
107	1/29/10
109	1/29/10
110	1/29/10
111	1/29/10
112	1/29/10
113	1/29/10
114	1/29/10
115	1/29/10
116	1/29/10
117	1/29/10
118	1/31/10
119	1/31/10
120	1/31/10
121	1/31/10
122	1/31/10
123	2/1/10
124	2/1/10
125	2/1/10
126	2/1/10
127	2/1/10
128	2/1/10
129	2/1/10
130	2/2/10
131	2/3/10
132	2/3/10
133	2/3/10
134	2/3/10
135	2/3/10
136	2/3/10
137	2/4/10
138	2/4/10
139	2/4/10
140	2/5/10
141	2/5/10
142	2/5/10
142	2/3/10
143	2/0/10

ivermore	Customer Denies Access	Customer does not want a SmartMeter	Resolved
lerced	Customer Denies Access	Customer does not want a SmartMeter	Resolved
/allejo	Wellington Installer	Other	Resolved
lillsborough	Customer Denies Access	Under Investigation	Open
leasanton	Wellington Installer	Under Investigation	Open
Redwood City	Meter/Module	Under Investigation	Open
merican Canyon	Wellington Installer	Under Investigation	Open
I Sobrante	Wellington Installer	Under Investigation	Open
/loraga	Wellington Installer	Under Investigation	Open
leasanton	Household items affected by SM installation	Under Investigation	Open
an Francisco	Power Interruption	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	Open
an Jose	Wellington Installer	Under Investigation	Open
unnyvale	Power Interruption	Under Investigation	Open
upertino	Household items affected by SM installation	Under Investigation	Open
ladera	Wellington Installer	Under Investigation	Open
Pinole	Wellington Installer	Under Investigation	Open
Richmond	Wellington Installer	Under Investigation	Open
tio Vista	Household items affected by SM installation	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	Open
an Jose	Meter/Module	Under Investigation	Open
tockton	Wellington Installer	Under Investigation	Open
unnyvale	Household items affected by SM installation	Under Investigation	Open
unnyvale	Wellington Installer	Under Investigation	Open
ensington	Meter/Module	Meter/Module clearance issues	Resolved
an Jose	Household items affected by SM installation	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	Open
akersfield	Household items affected by SM installation	Other	Resolved
anville	Meter/Module	Meter/Module clearance issues	Resolved
I Sobrante	Wellington Installer	Under Investigation	Open
A HONDA	Customer Denies Access	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
leasanton	Meter/Module	Under Investigation	Open
an Jose	Power Interruption	Under Investigation	Open
an Jose	Power Interruption	Under Investigation	Open
acaville	Meter/Module	Under Investigation	Open
an Jose	Household items affected by SM installation	Under Investigation	Open
ORDELIA	Wellington Installer	Under Investigation	Open
RATON	Other	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
Iountain View	Power Interruption	Under Investigation	Open
leasanton	Meter/Module	Under Investigation	Open
AYMOND	Wellington Installer	Under Investigation	Open
resno	Household items affected by SM installation	Under Investigation	Open
an Ramon	Power Interruption	Under Investigation	Open
Suisun City	Meter/Module	Under Investigation	Open
Iountain View	Other	Under Investigation	Open
	Meter/Module	Under Investigation	Open
leasanton			
Pleasanton San Ramon	Meter/Module	Under Investigation	Open

Page 38 of 34

144	2/9/10
145	2/9/10
146	2/10/10
147	2/10/10
148	2/10/10
149	2/10/10
150	2/10/10
151	2/10/10
152	2/10/10
153	2/10/10
154	2/10/10
155	2/10/10
156	2/10/10
150	2/11/10
157	2/11/10
150	
159	2/11/10 2/11/10
161	2/11/10
162	2/12/10 2/12/10
163	
164	2/12/10
165	2/12/10
166	2/12/10
167	2/13/10
168	2/14/10
169	2/14/10
170	2/16/10
171	2/16/10
172	2/16/10
173	2/16/10
174	2/16/10
175	2/16/10
176	2/17/10
177	2/17/10
178	2/17/10
179	2/17/10
180	2/17/10
181	2/17/10
182	2/17/10
183	2/17/10
184	2/17/10
185	2/17/10
186	2/17/10
187	2/17/10
188	2/17/10
189	2/17/10
190	2/18/10
191	2/18/10
192	2/18/10
193	2/18/10
193	2/18/10
	2110/10

Cupertino	Wellington Installer	Under Investigation	Open
Santa Rosa	Customer Denies Access	Under Investigation	Open
Berkeley	Customer Denies Access	Under Investigation	Open
Berkeley	Wellington Installer	Under Investigation	Open
Carmel	Network Equipment Installation	Under Investigation	Open
Cupertino	Meter/Module	Under Investigation	Open
Cupertino	Power Interruption	Under Investigation	Open
Cupertino	Scheduling Problems	Under Investigation	Open
IORTH FOLK	Wellington Installer	Under Investigation	Open
ancho Cordova	Meter/Module	Under Investigation	Open
an Jose	Wellington Installer	Under Investigation	Open
an Ramon	Wellington Installer	Under Investigation	Open
acaville	Household items affected by SM installation	Under Investigation	Open
lealdsburg	Customer Denies Access	Under Investigation	Open
ivermore	Household items affected by SM installation	Under Investigation	Open
lapa	Meter/Module	Under Investigation	Open
unnyvale	Power Interruption	Under Investigation	Open
allejo	Wellington Installer	Under Investigation	Open
erkeley	Wellington Installer	Under Investigation	Open
an Jose	Power Interruption	Under Investigation	Open
an Ramon	Household items affected by SM installation	Under Investigation	Open
an Ramon	Household items affected by SM installation		•
an Ramon	Wellington Installer	Under Investigation	Open
erkeley	Household items affected by SM installation	Under Investigation	Open
		Under Investigation	Open
unnyvale Valnut Creek	Meter/Module	Under Investigation	Open
	Household items affected by SM installation	Under Investigation	Open
erkeley	Wellington Installer	Under Investigation	Open
upertino	Wellington Installer		Open
	Meter/Module		Open
anta Clara	Meter/Module	Under Investigation	Open
anta Rosa	Customer Denies Access	Under Investigation	Open
unnyvale	Household items affected by SM installation	Under Investigation	Open
upertino	Household items affected by SM installation	Under Investigation	Open
orestville	Customer Denies Access	Under Investigation	Open
1adera	Wellington Installer	Under Investigation	Open
lewark	Household items affected by SM installation	Under Investigation	Open
an Jose	Wellington Installer	Under Investigation	Open
unnyvale	Meter/Module	Under Investigation	Open
allejo	Household items affected by SM installation	Under Investigation	Open
allejo	Wellington Installer	Under Investigation	Open
allejo	Wellington Installer	Under Investigation	Open
Valnut Creek	Customer Denies Access	Under Investigation	Open
erkeley	Meter/Module	Meter/Module clearance issues	Resolved
an Jose	Customer Denies Access	Customer does not want a SmartMeter	Resolved
anta Rosa	Customer Denies Access	Customer does not want a SmartMeter	Resolved
Sunnyvale	Household items affected by SM installation	Damaged Other Household Appliances	Resolved
ladera	Wellington Installer	Under Investigation	Open
1ariposa	Wellington Installer	Under Investigation	Open
anger	Scheduling Problems	Under Investigation	Open
anta Rosa	Customer Denies Access	Under Investigation	Open
Somerset	Wellington Installer	Under Investigation	Open

Page 39 of 34

195	2/18/10
196	2/19/10
197	2/19/10
198	2/19/10
199	2/19/10

Los Banos	Other	Other	Resolved
American Canyon	Wellington Installer	Under Investigation	Open
Mountain View	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Household items affected by SM installation	Under Investigation	Open
Pleasanton	Meter/Module	Under Investigation	Open

Page 41 of 34

Page 42 of 34

Sunnyvale Household items affected by SM installation Under Investigation Open

Page 43 of 34

I

Berkeley Household items affected by SM installation Motion/Sensor Appliance Malfunctioning Resolved

Page 44 of 34

Resolved

Page 45 of 34

I

Page 46 of 34

San Francisco Wellington Installer

Safety Concern

Resolved

Page 47 of 34

Page 48 of 34

OCCIDENTAL Customer Denies Access Und

Under Investigation

Open

Page 49 of 34

Page 50 of 34

Open

Open

Page 51 of 34

Under Investigation

Open

Page 52 of 34

L

San Jose	Household items affected by SM installation	Under Investigation	Open

Page 53 of 34

I

San Ramon	Meter/Module	Under Investigation	Open

Page 54 of 34

Santa Rosa Customer Denies Access

Under Investigation

Open

Page 55 of 34

215 2/22	/10
----------	-----

L

inole

Page 56 of 34

216	2/22/10
-----	---------

I

Sunnyvale	Power Interruption	Under Investigation	Open
-----------	--------------------	---------------------	------

I Sobrante

#### inole

I Sobrante

i

217	2/22/10

Vacaville	Meter/Module	Under Investigation	Open
v aoa vino		ondor invooligation	

#### orestville

I

### ariposa

I

218 2/22/10

а

_				
	√allejo	Network Equipment Installation	Under Investigation	Open

219	2/23/10

ALTA	Meter/Module	Under Investigation	Open

Page 60 of 34

SB\_GT&S\_0783879

L

Clayton	Household items affected by SM installation	Under Investigation	Open

Page 61 of 34

SB\_GT&S\_0783880

Page 62 of 34

Open

Page 63 of 34

Page 64 of 34

224	2/23/10
-----	---------

Page 65 of 34

ustomer does not want a SmartMeter ther

ustomer does not want a SmartMeter

ustomer does not want a SmartMeter

ther ustomer does not want a SmartMeter

Page 66 of 34

Open

eter/Module clearance issues

ther eter/Module clearance issues

u

SB\_GT&S\_0783886

227 2/24/10

I

Livermore	Other	Under Investigation	Open

eter/Module clearance issues ustomer does not want a SmartMeter ustomer does not want a SmartMeter amaged Other Household Appliances

е

thez28 2/24/10

а

L

Madera Wellington Installer Under Investigation

Open

229 2/24/10

t

I

esolved esolved

esolved

esolved

esolved

esolved

esolved

Page 71 of 34

SB\_GT&S\_0783890

Open

eszodyved	2/24/10
esolved	
esolved	

Mana	Wellington Installer	Under Investigation	Open
Vapa		Under investigation	Open

esolved

esolved esolved

е

232 2/24/10

I

Pollock Pines Wellington Installer Under Investigation Open

esolved esolved esolved esolved

е

escologed 2/24/10

е

This report contains confidential customer information and is being submitted under California Public Utilities Code Section 583.

Pacific Gas and Electric Company
SmartMeterTM Complaint Report
High-Bill Complaint Report For Customers With SmartMeterTM Devices*

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key				
	Resolved Since the Last Report			
	New Since the Last Report			
	No SmartMeterTM Device Installed			

	Complaint					
No.	Date	Customer Name	Account	Service City	Status	Explanation of Complaint Resolution
1	2/17/10	{Redacted}	{Redacted}	FOSTER CITY	Open	Under Investigation
2	3/11/10			AMERICAN CANYON	Open	Under Investigation
3	3/18/10			BAKERSFIELD	Open	Under Investigation
4	3/29/10			ALAMO	Open	Under Investigation
5	4/7/10			BAKERSFIELD	Open	Under Investigation
6	4/8/10	_		SAN PABLO	Open	Under Investigation
7	4/13/10			BAKERSFIELD	Open	Under Investigation
8	4/16/10			STOCKTON	Resolved	Bill is Accurate. SmartMeter installed 3/16/09. Reviewed usage and bills. Provided 12-month pay plan. Walked through online billing sign-up so son can help mother manage bills and view usage. Advised of CARE program. Offered meter test; customer was satisfied and declined the meter test.
9	4/19/10			BAKERSFIELD	Open	Under Investigation
10	4/22/10			FREMONT	Open	Under Investigation
11	4/23/10			VALLEY SPRINGS	Open	Under Investigation
12	4/26/10	-		GRANITE BAY	Open	Under Investigation
13	4/27/10			OAKHURST	Resolved	Bill is Accurate. SmartMeter installed 1/7/10. Customer questioned usage increase after SmartMeter installation. Reviewed usage and bills. Customer declined offer to test the meter. Acknowledged use of electric heaters instead of propane. Also, his mother with medical condition is living with him now. Medical Baseline Application received, customer was satisfied.
14	4/28/10			BAKERSFIELD	Resolved	Meter Communication Issue. SmartMeter installed 4/7/09. Meter stopped communicating reads after 12/6/09. Bill was estimated for one month, and then delayed 1/6/10 - 4/8/10. Meter was tested and passed. However, since the meter was not communicating reads, a new SmartMeter was installed on 5/4/10. Customer was unhappy with poor service, missed appointments. A customer satisfaction adjustment was given for \$300. Customer was satisfied.
15	4/29/10	1		FORESTHILL	Open	Under Investigation
16	4/30/10	1		DALY CITY	Open	Under Investigation
17	5/1/10			MORAGA	Open	Under Investigation
18	5/3/10			GRANITE BAY	Open	Under Investigation

\_\_\_\_\_

This report contains confidential customer information and is being submitted under California Public Utilities Code Section 583.

Pacific Gas and Electric Company	Color Key
SmartMeterTM Complaint Report	Resolved Since the Last Report
High-Bill Complaint Report For Customers With SmartMeterTM Devices*	New Since the Last Report

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key	
Resolved Since the Last Report	
New Since the Last Report	
No SmartMeterTM Device Installed	

No.	Complaint Date	Customer Name	Account	Service City	Status	Explanation of Complaint Resolution
19	5/3/10			MENLO PARK		Meter Switched with Different Premise. Customer started service on 6/2/09; SmartMeter was also installed 6/2/09. Customer complained of high bills. During meter test on 5/3/10, found meters were switched with another apartment. Corrections were completed the same day (5/3): Meter information was corrected for both apartments and customer's account was credited under Rule 17.1 for period 6/2/09 through 4/16/10 (current bill date). Customer has credit balance of -\$1,690.06. Although Rule 17.1 allows a three-month backbilling for the other apartment, PG&E waived the additional charges for the other customer who had been underbilled.
20	5/5/10			ATHERTON	Open	Under Investigation
21	5/7/10			CLOVIS	Open	Under Investigation
22	5/7/10			ALTA	Open	Under Investigation

\* This Report tracks high-bill complaints from customers who state that their high bill is related in some way to the installation of a SmartMeterTM device.

16 Open Complaints on Last Report

- 3 Open Complaints Resolved Since the Last Report
- 6 New Complaints Since the Last Report
- 1 New Complaints Resolved Since the Last Report
- 5 New Complaints Open

Page 2 of 2

This report contains confidential customer information and is being submitted under California Public Utilities Code Section 583.

Pacific Gas and Electric Company
SmartMeterTM Complaint Report
High-Bill Complaint Report For Customers With SmartMeterTM Devices*

May 13, 2010 -- For the Period May 1, 2010 through May 7, 2010

Color Key					
	Resolved Since the Last Report				
	New Since the Last Report				
	No SmartMeterTM Device Installed				

	Complaint					
No.	Date	Customer Name	Account	Service City	Status	Explanation of Complaint Resolution
1	2/17/10	{Redacted}	{Redacted}	FOSTER CITY	Open	Under Investigation
2	3/11/10	4		AMERICAN CANYON	Open	Under Investigation
3	3/18/10	_		BAKERSFIELD	Open	Under Investigation
4	3/29/10	_		ALAMO	Open	Under Investigation
5	4/7/10	_		BAKERSFIELD	Open	Under Investigation
6	4/8/10	_		SAN PABLO	Open	Under Investigation
7	4/13/10			BAKERSFIELD	Open	Under Investigation
8	4/16/10			STOCKTON	Resolved	Bill is Accurate. SmartMeter installed 3/16/09. Reviewed usage and bills. Provided 12-month pay plan. Walked through online billing sign-up so son can help mother manage bills and view usage. Advised of CARE program. Offered meter test; customer was satisfied and declined the meter test.
9	4/19/10			BAKERSFIELD	Open	Under Investigation
10	4/22/10			FREMONT	Open	Under Investigation
11	4/23/10			VALLEY SPRINGS	Open	Under Investigation
12	4/26/10			GRANITE BAY	Open	Under Investigation
13	4/27/10			OAKHURST	Resolved	Bill is Accurate. SmartMeter installed 1/7/10. Customer questioned usage increase after SmartMeter installation. Reviewed usage and bills. Customer declined offer to test the meter. Acknowledged use of electric heaters instead of propane. Also, his mother with medical condition is living with him now. Medical Baseline Application received, customer was satisfied.
14	4/28/10			BAKERSFIELD	Resolved	Meter Communication Issue. SmartMeter installed 4/7/09. Meter stopped communicating reads after 12/6/09. Bill was estimated for one month, and then delayed 1/6/10 - 4/8/10. Meter was tested and passed. However, since the meter was not communicating reads, a new SmartMeter was installed on 5/4/10. Customer was unhappy with poor service, missed appointments. A customer satisfaction adjustment was given for \$300. Customer was satisfied.
15	4/29/10	1		FORESTHILL	Open	Under Investigation
16	4/30/10	1		DALY CITY	Open	Under Investigation
17	5/1/10			MORAGA	, Open	Under Investigation
18	5/3/10			GRANITE BAY	Open	Under Investigation

Page 1 of 2

19 5/3/10	MENLO PARK	Resolved Meter Switched with Different Premise. Customer started service on 6/2/09; SmartMeter was also installed 6/2/09. Customer complained of high bills. During meter test on 5/3/10, found meters were switched with another apartment. Corrections were completed the same day (5/3): Meter information was corrected for both apartments and customer's account was credited under Rule 17.1 for period 6/2/09 through 4/16/10 (current bill date). Customer has credit balance of -\$1,690.06. Although Rule 17.1 allows a three-month backbiiiing for the other apartment, PG&E waived the additional charges for the other customer who had been underbiiied.	19
20 5/5/10	ATHERTON	Open Under Investigation	20
21 5/7/10	CLOVIS	Open Under Investigation	21
22 5/7/10	ALTA	Open Under Investigation	22

\* This Report tracks high-bill complaints from customers who state that their high bill is related in some way to the installation of a SmartMeterTM device.

- 16 Open Complaints on Last Report
- 3 Open Complaints Resolved Since the Last Report
- 6 New Complaints Since the Last Report
- 1 New Complaints Resolved Since the Last Report
- 5 New Complaints Open

Page 2 of 2

Color Key					
	Resolved Since the Last Report				
	New Since the Last Report				
	No SmartMeterTM Device Installed				

Complaint			0 - i - 0'h		
Date 2/17/10	Customer Name {Redacted}	Account Redacted	Service City FOSTER CITY	Status Open	Explanation of Complaint Resolution Under Investigation
3/11/10		Inclucted	AMERICAN CANYON	Open	Under Investigation
3/18/10	-		BAKERSFIELD	Open	Under Investigation
3/29/10	-		ALAMO	Open	Under Investigation
4/7/10	-		BAKERSFIELD	Open	Under Investigation
4/8/10	-		SAN PABLO	Open	Under Investigation
4/13/10	-		BAKERSFIELD	Open	Under Investigation
4/16/10	-		STOCKTON	· ·	Bill is Accurate. SmartMeter installed 3/16/09. Reviewed
4/10/10			STOCKTON		usage and bills. Provided 12-month pay plan. Walked through online billing sign-up so son can help mother manage bills and view usage. Advised of CARE program. Offered meter test; customer was satisfied and declined the meter test.
4/19/10			BAKERSFIELD	Open	Under Investigation
4/22/10	-		FREMONT	Open	Under Investigation
4/23/10	_		VALLEY SPRINGS	Open	Under Investigation
4/26/10			GRANITE BAY	Open	Under Investigation
4/27/10			DAKHURST	Resolved	Bill is Accurate. SmartMeter installed 1/7/10. Customer questioned usage increase after SmartMeter installation. Reviewed usage and bills. Customer declined offer to test the meter. Acknowledged use of electric heaters instead of propane. Also, his mother with medical condition is living with him now. Medical Baseline Application received, customer was satisfied.
4/28/10			BAKERSFIELD	Resolved	Meter Communication Issue. SmartMeter installed 4/7/09. Meter stopped communicating reads after 12/6/09. Bill was estimated for one month, and then delayed 1/6/10 - 4/8/10. Meter was tested and passed. However, since the meter was not communicating reads, a new SmartMeter was installed on 5/4/10. Customer was unhappy with poor service, missed appointments. A customer satisfaction adjustment was given for \$300. Customer was satisfied.
4/29/10	1		FORESTHILL	Open	Under Investigation
4/30/10	1		DALY CITY	Open	Under Investigation
5/1/10			MORAGA	Open	Under Investigation
5/3/10			GRANITE BAY	Open	Under Investigation

Page 3 of 2

19	5/3/10	MENLO PARK	Resolved Meter Switched with Different Premise. Customer started service on 6/2/09; SmartMeter was also installed 6/2/09. Customer complained of high bills. During meter test on 5/3/10, found meters were switched with another apartment. Corrections were completed the same day (5/3): Meter information was corrected for both apartments and customer's account was credited under Rule 17.1 for period 6/2/09 through 4/16/10 (current bill date). Customer has credit balance of -\$1,690.06. Although Rule 17.1 allows a three-month backbiiiing for the other apartment, PG&E waived the additional charges for the other customer who had been underbiiied.	5/3/10
20	5/5/10	ATHERTON	Open Under Investigation	5/5/10
21	5/7/10	CLOVIS	Open Under Investigation	5/7/10
22	5/7/10	ALTA	Open Under Investigation	5/7/10
	This Report tracks high-bill complaints from customers	s who state that their high	h bill is related in some way to the installation of a SmartMeterTM device.	his Report

/10 This Report

**Open Complaints on Last Report** 16

- 3 Open Complaints Resolved Since the Last Report
- 6 New Complaints Since the Last Report
- New Complaints Resolved Since the Last Report 1
- 5 New Complaints Open

Color Key				
Resolved Since the Last Report				
New Since the Last Report				
No SmartMeterTM Device Installed				

Customer Name	Account	Service City	Status	Explanation of Complaint Resolution
{Redacted}	Redacted}	FOSTER CITY	Open	Under Investigation
(	(neddeted)	AMERICAN CANYON	Open	Under Investigation
		BAKERSFIELD	Open	Under Investigation
		ALAMO	Open	Under Investigation
		BAKERSFIELD	Open	Under Investigation
		SAN PABLO	Open	Under Investigation
		BAKERSFIELD	Open	Under Investigation
		STOCKTON	Resolved	Bill is Accurate. SmartMeter installed 3/16/09. Reviewed usage and bills. Provided 12-month pay plan. Walked through online billing sign-up so son can help mother manage bills and view usage. Advised of CARE program. Offered meter test; customer was satisfied and declined the meter test.
		BAKERSFIELD	Open	Under Investigation
		FREMONT	Open	Under Investigation
		VALLEY SPRINGS	Open	Under Investigation
		GRANITE BAY	Open	Under Investigation
		DAKHURST	Resolved	Bill is Accurate. SmartMeter installed 1/7/10. Customer questioned usage increase after SmartMeter installation. Reviewed usage and bills. Customer declined offer to test the meter. Acknowledged use of electric heaters instead of propane. Also, his mother with medical condition is living with him now. Medical Baseline Application received, customer was satisfied.
		BAKERSFIELD	Resolved	Meter Communication Issue. SmartMeter installed 4/7/09. Meter stopped communicating reads after 12/6/09. Bill was estimated for one month, and then delayed 1/6/10 - 4/8/10. Meter was tested and passed. However, since the meter was not communicating reads, a new SmartMeter was installed on 5/4/10. Customer was unhappy with poor service, missed appointments. A customer satisfaction adjustment was given for \$300. Customer was satisfied.
		FORESTHILL	Open	Under Investigation
		DALY CITY	Open	Under Investigation
		MORAGA	Open	Under Investigation
		GRANITE BAY	Open	Under Investigation

Page 5 of 2

19	5/3/10	MENLO PARK Resolu	<ul> <li>Meter Switched with Different Premise. Customer started service on 6/2/09; SmartMeter was also installed 6/2/09. Customer complained of high bills. During meter test on 5/3/10, found meters were switched with another apartment. Corrections were completed the same day (5/3): Meter information was corrected for both apartments and customer's account was credited under Rule 17.1 for period 6/2/09 through 4/16/10 (current bill date). Customer has credit balance of -\$1,690.06. Although Rule 17.1 allows a three-month backbiiiing for the other apartment, PG&amp;E waived the additional charges for the other customer who had been underbiiied.</li> </ul>
20	5/5/10	ATHERTON Ope	Under Investigation
21	5/7/10	CLOVIS Ope	Under Investigation
22	5/7/10	ALTA Ope	Under Investigation
4	*	This Report tracks high-bill complaints from customers who state that the	ir high bill is related in some way to the installation of a SmartMeterTM device.

- **Open Complaints on Last Report** 16
- 3 Open Complaints Resolved Since the Last Report
- 6 New Complaints Since the Last Report
- New Complaints Resolved Since the Last Report 1
- 5 New Complaints Open

Page 6 of 2

Color Key				
	Resolved Since the Last Report			
	New Since the Last Report			
	No SmartMeterTM Device Installed			

Account	Convine City	Status	Explanation of Complaint Resolution
Redacted}	Service City FOSTER CITY	Open	Under Investigation
(neddeted)	AMERICAN CANYON	Open	Under Investigation
	BAKERSFIELD	Open	Under Investigation
	ALAMO	Open	Under Investigation
	BAKERSFIELD	Open	Under Investigation
	SAN PABLO	Open	Under Investigation
	BAKERSFIELD	Open	Under Investigation
	STOCKTON		Bill is Accurate. SmartMeter installed 3/16/09. Reviewed usage and bills. Provided 12-month pay plan. Walked through online billing sign-up so son can help mother manage bills and view usage. Advised of CARE program. Offered meter test; customer was satisfied and declined the meter test.
	BAKERSFIELD	Open	Under Investigation
	FREMONT	Open	Under Investigation
	VALLEY SPRINGS	Open	Under Investigation
	GRANITE BAY	Open	Under Investigation
	OAKHURST	Resolved	Bill is Accurate. SmartMeter installed 1/7/10. Customer questioned usage increase after SmartMeter installation. Reviewed usage and bills. Customer declined offer to test the meter. Acknowledged use of electric heaters instead of propane. Also, his mother with medical condition is living with him now. Medical Baseline Application received, customer was satisfied.
	BAKERSFIELD	Resolved	Meter Communication Issue. SmartMeter installed 4/7/09. Meter stopped communicating reads after 12/6/09. Bill was estimated for one month, and then delayed 1/6/10 - 4/8/10. Meter was tested and passed. However, since the meter was not communicating reads, a new SmartMeter was installed on 5/4/10. Customer was unhappy with poor service, missed appointments. A customer satisfaction adjustment was given for \$300. Customer was satisfied.
	FORESTHILL	Open	Under Investigation
	DALY CITY	Open	Under Investigation
	MORAGA	Open	Under Investigation
	GRANITE BAY	Open	Under Investigation

Page 7 of 2

19	5/3/10	MENLO PARK	Resolvec	Meter Switched with Different Premise. Customer started service on 6/2/09; SmartMeter was also installed 6/2/09. Customer complained of high bills. During meter test on 5/3/10, found meters were switched with another apartment. Corrections were completed the same day (5/3): Meter information was corrected for both apartments and customer's account was credited under Rule 17.1 for period 6/2/09 through 4/16/10 (current bill date). Customer has credit balance of -\$1,690.06. Although Rule 17.1 allows a three-month backbiiiing for the other apartment, PG&E waived the additional charges for the other customer who had been underbiiied.
20	5/5/10	ATHERTON	Open	Under Investigation
21	5/7/10	CLOVIS	Open	Under Investigation
22	5/7/10	ALTA	Open	Under Investigation

This Report tracks high-bill complaints from customers who state that their high bill is related in some way to the installation of a SmartMeterTM device.

- 16 Open Complaints on Last Report
- 3 Open Complaints Resolved Since the Last Report
- 6 New Complaints Since the Last Report
- 1 New Complaints Resolved Since the Last Report
- 5 New Complaints Open

Page 8 of 2

Color Key					
Resolved Since the Last Report					
New Since the Last Report					
No SmartMeterTM Device Installed					

Service City	Status	Explanation of Complaint Resolution
FOSTER CITY		Under Investigation
AMERICAN CANYON	Open	Under Investigation
BAKERSFIELD	•	Under Investigation
ALAMO	Open	Under Investigation
BAKERSFIELD		Under Investigation
SAN PABLO	Open	Under Investigation
BAKERSFIELD		Under Investigation
STOCKTON		Bill is Accurate. SmartMeter installed 3/16/09. Reviewed usage and bills. Provided 12-month pay plan. Walked through online billing sign-up so son can help mother manage bills and view usage. Advised of CARE program. Offered meter test; customer was satisfied and declined the meter test.
BAKERSFIELD	•	Under Investigation
FREMONT		Under Investigation
VALLEY SPRINGS		Under Investigation
GRANITE BAY		Under Investigation
OAKHURST		Bill is Accurate. SmartMeter installed 1/7/10. Customer questioned usage increase after SmartMeter installation. Reviewed usage and bills. Customer declined offer to test the meter. Acknowledged use of electric heaters instead of propane. Also, his mother with medical condition is living with him now. Medical Baseline Application received, customer was satisfied.
BAKERSFIELD		Meter Communication Issue. SmartMeter installed 4/7/09. Meter stopped communicating reads after 12/6/09. Bill was estimated for one month, and then delayed 1/6/10 - 4/8/10. Meter was tested and passed. However, since the meter was not communicating reads, a new SmartMeter was installed on 5/4/10. Customer was unhappy with poor service, missed appointments. A customer satisfaction adjustment was given for \$300. Customer was satisfied.
FORESTHILL		Under Investigation
DALY CITY		Under Investigation
MORAGA	•	Under Investigation
GRANITE BAY	Open	Under Investigation

Page 9 of 2

19	5/3/10	MENLO PARK	Resolved Meter Switched with Different Premise. Customer started service on 6/2/09; SmartMeter was also installed 6/2/09. Customer complained of high bills. During meter test on 5/3/10, found meters were switched with another apartment. Corrections were completed the same day (5/3): Meter information was corrected for both apartments and customer's account was credited under Rule 17.1 for period 6/2/09 through 4/16/10 (current bill date). Customer has credit balance of -\$1,690.06. Although Rule 17.1 allows a three-month backbiiiing for the other apartment, PG&E waived the additional charges for the other customer who had been underbiiied.	MENLO PARK
20	5/5/10	ATHERTON	Open Under Investigation	ATHERTON
21	5/7/10	CLOVIS	Open Under Investigation	CLOVIS
22	5/7/10	ALTA	Open Under Investigation	ALTA
*	This Report tracks high-bill compl	aints from customers who state that	at their high bill is related in some way to the installation of a SmartMeterTM device.	

16 Open Complaints on Last Report

- 3 Open Complaints Resolved Since the Last Report
- 6 New Complaints Since the Last Report
- 1 New Complaints Resolved Since the Last Report
- 5 New Complaints Open

Page 10 of 2

	Color Key
	Resolved Since the Last Report
	New Since the Last Report
	No SmartMeterTM Device Installed
Status	Evaluation of Complaint Beachution
Open	Explanation of Complaint Resolution Under Investigation
Open	Under Investigation
Open	Under Investigation
Open	Under Investigation
Open	Under Investigation
Open	Under Investigation
Open	Under Investigation
Resolved	Bill is Accurate. SmartMeter installed 3/16/09. Reviewed usage and bills. Provided 12-month pay plan. Walked through online billing sign-up so son can help mother manage bills and view usage. Advised of CARE program Offered meter test; customer was satisfied and declined
	the meter test.
Open	Under Investigation
Resolved	Bill is Accurate. SmartMeter installed 1/7/10. Customer questioned usage increase after SmartMeter installation. Reviewed usage and bills. Customer declined offer to test the meter. Acknowledged use of electric heaters instead of propane. Also, his mother with medical condition is living with him now. Medical Baseline Application received, customer was satisfied.
Resolved	Meter Communication Issue. SmartMeter installed 4/7/09 Meter stopped communicating reads after 12/6/09. Bill was estimated for one month, and then delayed 1/6/10 - 4/8/10. Meter was tested and passed. However, since the meter was not communicating reads, a new SmartMeter was installed on 5/4/10. Customer was unhappy with poor service, missed appointments. A customer satisfaction adjustment was given for \$300. Customer was satisfied.
Open	Under Investigation
Open	Under Investigation
Open	Under Investigation

Page 11 of 2

19 5/3/10	MENLO PARK	Resolved Meter Switched with Different Premise. Customer started service on 6/2/09; SmartMeter was also installed 6/2/09. Customer complained of high bills. During meter test on 5/3/10, found meters were switched with another apartment. Corrections were completed the same day (5/3): Meter information was corrected for both apartments and customer's account was credited under Rule 17.1 for period 6/2/09 through 4/16/10 (current bill date). Customer has credit balance of -\$1,690.06. Although Rule 17.1 allows a three-month backbiiiing for the other apartment, PG&E waived the additional charges for the other customer who had been underbiiied.	Resolved
20 5/5/10	ATHERTON	Open Under Investigation	Open
21 5/7/10	CLOVIS	Open Under Investigation	Open
22 5/7/10	ALTA	Open Under Investigation	Open

16	Open Complaints on Last Report	16
3	Open Complaints Resolved Since the Last Report	3
6	New Complaints Since the Last Report	6
1	New Complaints Resolved Since the Last Report	1
5	New Complaints Open	5

Page 12 of 2

Color Key	
solved Since the Last Report	
w Since the Last Report	
SmartMeterTM Device Installed	
Explanation of Complaint Resolution	
der Investigation	
l is Accurate. SmartMeter installed 3/16/09. Re	
age and bills. Provided 12-month pay plan. Wa	
ough online billing sign-up so son can help mo	
nage bills and view usage. Advised of CARE p	
fered meter test; customer was satisfied and de meter test.	eciinea
der Investigation	
der Investigation	
dor Investigation	
der Investigation	
der Investigation	tomer
der Investigation I is Accurate. SmartMeter installed 1/7/10. Cust estioned usage increase after SmartMeter insta viewed usage and bills. Customer declined offe it the meter. Acknowledged use of electric heat tead of propane. Also, his mother with medica ndition is living with him now. Medical Baselin plication received, customer was satisfied.	allation. er to ers al e
der Investigation I is Accurate. SmartMeter installed 1/7/10. Cust estioned usage increase after SmartMeter insta viewed usage and bills. Customer declined offe it the meter. Acknowledged use of electric heat itead of propane. Also, his mother with medica ndition is living with him now. Medical Baseling	Allation. er to ers il e d 4/7/09 . Bill /6/10 - ince the tMeter /ith
der Investigation I is Accurate. SmartMeter installed 1/7/10. Cust estioned usage increase after SmartMeter instal viewed usage and bills. Customer declined offe to the meter. Acknowledged use of electric heat tead of propane. Also, his mother with medical ndition is living with him now. Medical Baseline plication received, customer was satisfied. ter Communication Issue. SmartMeter installed ter stopped communicating reads after 12/6/09 s estimated for one month, and then delayed 1/ /10. Meter was tested and passed. However, si ter was not communicating reads, a new Smart s installed on 5/4/10. Customer was unhappy w or service, missed appointments. A customer tisfaction adjustment was given for \$300. Custo	Allation. er to ers il e d 4/7/09 . Bill /6/10 - ince the tMeter /ith
der Investigation I is Accurate. SmartMeter installed 1/7/10. Cust estioned usage increase after SmartMeter instal viewed usage and bills. Customer declined offe it the meter. Acknowledged use of electric heat tead of propane. Also, his mother with medical ndition is living with him now. Medical Baseline plication received, customer was satisfied. Iter Communication Issue. SmartMeter installed ter stopped communicating reads after 12/6/09 s estimated for one month, and then delayed 1/ /10. Meter was tested and passed. However, si ter was not communicating reads, a new Smart s installed on 5/4/10. Customer was unhappy w or service, missed appointments. A customer tisfaction adjustment was given for \$300. Custo s satisfied.	Allation. er to ers il e d 4/7/09 . Bill /6/10 - ince the tMeter /ith
der Investigation I is Accurate. SmartMeter installed 1/7/10. Cust estioned usage increase after SmartMeter instal viewed usage and bills. Customer declined offe it the meter. Acknowledged use of electric heat tead of propane. Also, his mother with medical ndition is living with him now. Medical Baseline plication received, customer was satisfied. ter Communication Issue. SmartMeter installed ter stopped communicating reads after 12/6/09 s estimated for one month, and then delayed 1/ /10. Meter was tested and passed. However, si ter was not communicating reads, a new Smar s installed on 5/4/10. Customer was unhappy w or service, missed appointments. A customer tisfaction adjustment was given for \$300. Custo s satisfied. der Investigation	Allation. er to ers il e d 4/7/09 . Bill /6/10 - ince the tMeter /ith

Page 13 of 2

		(5/3): Meter information was corrected for both apartments and customer's account was credited under Rule 17.1 for period 6/2/09 through 4/16/10 (current bill date). Customer has credit balance of -\$1,690.06. Although Rule 17.1 allows a three-month backbiiiing for the other apartment, PG&E waived the additional charges for the other customer who had been underbiiied.	(5/3): Meter informatior apartments and custor Rule 17.1 for period 6/2 date). Customer has c Although Rule 17.1 allo the other apartment, Pu for the other customer
ATHERTON	Open	Under Investigation	Under Investigation
CLOVIS	Open	Under Investigation	Under Investigation
ALTA	Open	Under Investigation	Under Investigation
	CLOVIS ALTA	CLOVIS Open ALTA Open	Apartments and customer's account was credited under Rule 17.1 for period 6/2/09 through 4/16/10 (current bill date). Customer has credit balance of -\$1,690.06. Although Rule 17.1 allows a three-month backbiiiing for the other apartment, PG&E waived the additional charges for the other customer who had been underbilied.ATHERTONOpenCLOVISOpenUnder Investigation

- **Open Complaints on Last Report** 16
- 3 Open Complaints Resolved Since the Last Report
- 6 New Complaints Since the Last Report 1
  - New Complaints Resolved Since the Last Report
- 5 New Complaints Open

**Open Complaints on Last** 

**Open Complaints Re** New Complaints Sin New Complaints Re New Complaints Op

Page 15 of 2

solved Since the Last Report ce the Last Report solved Since the Last Report en

Page 16 of 2