

Facility: N/A; Folder: Colma Folder; Assigned To: Redacted

PGECLM 00002 USAN 07/23/10 08:40:12 0214102 NORMAL NOTICE

Message Number: 0214102 Received by Redacted at 08:21 on 07/23/10 by KRS

Work Begins: 07/27/10 at 08:30 Notice: 020 hrs Priority: 2
Night Work: N Weekend Work: N

Expires: 08/20/10 at 17:00 Update By: 08/18/10 at 16:59

Caller: Redacted
Company:
Address:
City:
Business Tel:
Email Address:

Nature of Work: HAND DIG TO INV SINK OVER SWR MAIN
Done for: SAME Explosives: N
Foreman: Redacted
Field Tel: Cell Tel: Redacted
Area Premarked: Y Premark Method: WHITE PAINT
Permit Type: NO
Vac / Pwr Equip Use In The Approx Location Of Member Facilities Requested: N
Excavation Enters Into Street Or Sidewalk Area: Y

Location:
Street Address: Redacted
Cross Street:

WRK IN ST IN FRT/O ADDR

Place: SAN BRUNO County: SAN MATEO State: CA
Long/Lat: Redacted

Sent to:
CTYDAL = CITY DALY CITY CTYSBR = CITY SAN BRUNO
COMSC2 = COMCAST-SAN CARLOS2 COMSC3 = COMCAST-SAN CARLOS3
NCOWTR = NORTH COAST CO WTR DIST PBTPAL = PACIFIC BELL PALO ALTO
PGECLM = PGE DISTR COLMA

Gas Tiffs:
\\SanCarlos01\SclTIF\Gas\Distribution\07-E14.tif

Electric Tiffs:
\\SanCarlos01\CmaTif\Elec\Distribution\E0324.tif
\\SanCarlos01\CmaTif\Elec\Distribution\F0304.tif

Audit History:

- 7/23/2010 8:42:18 AM:** Received
DETAILS: Ticket received for registration code PGECLM
- 7/23/2010 8:42:18 AM:** Put in Folder
DETAILS: Put in Redacted Folder by auto process
NOTE: Auto Processed per Responsibility Area
- 7/23/2010 8:42:18 AM:** Assigned
DETAILS: Assigned to Redacted - by auto process
NOTE: Assigned on folder placement
- 7/23/2010 2:40:12 PM:** Responded

DETAILS: .FACILITY MARKED: added by [Redact], located by [Redacted] Locate Time: 7/23/2010 1:26:06 PM
 User: PGE\J1Pj
 Area Premarked? Yes
 Facility Type - GT: No
 Facility Type - GD: Yes
 Facility Type - ET: No
 Facility Type - ED: No
 Facility Type - FIBER: No
 Time Arrived: 07/23/2010 01:15:06 PM; Weather: dry; Surface: asphalt
 Gas Footage: 0; Electric Footage: 0
 Line Number: ; MP:
 Critical Facility? No; Standby? No
 Method used: Conductive
 Conductive Type: ETS
 Any other Means? No; Method:

NOTE: Marked gas main.; Marked gas service.; Painted.; Elec exists overhead.

7/23/2010 2:40:12 PM: Positive Response to Excavator Queued

DETAILS: Positive Response to Excavator queued for delivery

7/23/2010 2:42:21 PM: Positive Response to Excavator Delivered

DETAILS: Positive Response to Excavator successfully sent to [Redacted]

Redacted

From: Redacted
Sent: Tuesday, October 19, 2010 1:33 PM
To: Redacted
Subject: [URG/ACT] Request for M&L tag

Importance: High

Hi Redac

Here is the information I received for the M&L Tag Request:

July 23, 2010: Underground Service Alert (USA) Ticket for Redacted at the City of San Bruno for Redacted Redacted for work over sewer main. Redacted from the City of San Bruno called USA prior to digging at Redacted and USA created a request to mark PG&E services on 7/23/2010 at 8:40 AM. PG&E completed the mark and locate tag at 7/23/2010 at 2:42 PM

They would like to receive this information this afternoon, so please keep me updated on the status. If we run into a lot of hurdles, I can keep them updated.

Thank you and please call me if you need additional information,
Redacted

Executive Assistant
Gas Maintenance & Construction

Redacted