

Historical Replacements and Hydro Test for Line 300 A

Original, replaced or re-tested sections of Line 300A between MP 261 to 291 in the Bakersfield Area.

Mile Point 1	Mile Point 2	Type	OD	Wall	Test Press.	Test Year	Test Dur.	Test Med.
261	268.6	Orig.	34	0.375	N/A	N/A	N/A	N/A
268.6	269.6	Re-test	34	0.375	1050	1971	Unk	Water
269.6	270.7	Orig.	34	0.375	N/A	N/A	N/A	N/A
270.7	270.8	Replac e	34	0.505	1634	2005	8 hrs	Water
270.8	272.0	Orig	34	0.375	N/A	N/A	N/A	N/A
272.0	275.0	Replac e	34	0.505	1633	2009	8 hrs	Water
275.0	275.6	Replac e	34	0.505	1660	2006	8 hrs	Water
275.6	276.5	Replac e	34	0.505	1707	2005	8 hrs	Water
276.5	278.0	Replac e	34	0.505	1721	2004	8 hrs	Water
278.0	278.0	Replac e	34	0.576	1140	1993	4 hrs	Water
278.0	280.0	Replac e	34	0.505	1624	2007	8 hrs	Water
280.0	291.0	Orig.	34	0.344	N/A	N/A	N/A	N/A