

Historical Replacements and Hydro Test for Line 300B

Original, replaced or re-tested sections of Line 300B between MP 263 to 293 in the Bakersfield Area.

Mile Point 1	Mile Point 2	Type	OD	Wall	Test Press.	Test Year	Test Dur.	Test Med.
263	272	Orig.	34	0.344	N/A	N/A	N/A	N/A
272.4	273.3	Replac e	34	0.505	1670	2005	8 hrs	Water
273.3	273.4	Replac e	34	0.438	1625	1996	8 hrs	Water
273.4	274.1	Replac e	36	0.576	1672	2005	8 hrs	Water
274.1	275.3	Replac e	34	0.505	1617	1989	8 hrs	Water
275.3	275.9	Replac e	34	0.5620	1918	1989	8 hrs	Water
275.9	277.5	Replac e	34	0.500	1251	2002	8 hrs	Water
277.5	278.3	Replac e	34	0.4380	1590	1990	8 hrs	Water
278.3	280.4	Replac e	34	0.505	1698	2003	8 hrs	Water
280.4	280.5	Orig.	34	0.344	N/A	N/A	N/A	N/A
280.5	280.6	Replac e	34	0.493	1621	1990	Unk	Water
280.6	283.1	Orig.	34	0.344	N/A	N/A	N/A	N/A
283.1	283.8	Replac e	34	0.505	1702	2005	8 hrs	Water
283.8	284.6	Orig.	34	0.344	N/A	N/A	N/A	N/A
284.6	290.2	Retest	34	0.344	950	1982	8 hrs	Water
290.2	293.0	Orig	34	0.344	N/A	N/A	N/A	N/A