



APPLIED TECHNOLOGY SERVICES



Nondestructive Examination Unit

3400 Crow Canyon Road, San Ramon, CA 94583

NONDESTRUCTIVE EXAMINATION DATA

Location and Unit No:	Redacted	Examination Date:	11/02/2010	Job ID#	07592 001
	Redacted	Examiner(s):	Redacted		
Client:	Gas T&D				
Client Contact:	Redacted				

COMPONENT EXAMINED: Gas Line 101 MP 19.99 34" diameter with a 24" reducer, a 6' long section of uncoated and sandblasted pipe was tested

INSPECTION METHOD: Magnetic Particle (ATS-MT-200 procedure) Wet Fluorescent, Continuous technique. AC Yoke – with a leg spacing of 5" - Magnaglo 20B. All exposed and sandblasted parts of the pipeline were tested with the MT-AC technique for SCC type indications in the axial orientation of the pipeline.

EXAMINATION RESULTS: No Reportable Indications were found in the testing of this pipe segment for SCC.

