

NEM Interconnection Status Report: 3rd Quarter 2011

NEM applicants whose power systems have not been interconnected 30 working days after the receipt of a complete application by PG&E.

Report Date: 10/12/11
Update 12/14/2011

Project ID	Reason for Non-Interconnection	Date Interconnection is Expected to Be Completed
ENOS - 8302	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action
ENOS - 45487	Site is not ready. Customer is relocating meter.	Depends on customer action
ENOS - 59175	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action
ENOS - 59178	Transformer upgrade required	Transformer upgrade pending
ENOS - 60429	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action
ENOS - 61327	Transformer upgrade initially required but change in Rule 21 now allows interconnection for this site without Transformer upgrade	Update: Permission to operate letter sent 10/14/2011
ENOS - 68569	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action
ENOS - 69381	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action
ENOS - 70881	Site is not ready.	Depends on customer action
ENOS - 71066	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action
ENOS - 72558	Customer has not given assurance of 24 hr access to disconnect	Update: Permission to operate letter sent 10/19/2011
ENOS - 72934	Change-of-party during application process	Pending Resolution

ENOS - 73405	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Update: Permission to operate letter sent 11/18/2011
ENOS - 74471	Site is not ready.	Update: Permission to operate letter sent 11/7/2011
ENOS - 74533	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Update: Permission to operate letter sent 10/21/2011
ENOS - 74812	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action
ENOS - 75291	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action