

Account ID: [Redacted]
Hm Ph: [Redacted]
Bus Ph: [Redacted]
Cont Ph: [Redacted]
Name: [Redacted]
Address: [Redacted]
City: SAN JOSE

Prem Tyne COM/IND
Bus Activty 611110
Home Area [Redacted]
Sub Area [Redacted]
Check Dinit
SI
IS
Gas Sd Id 0324825005
Elec Sd Id
MtrDd Route M/P02

Completion Information

PM Information

Job Code: 4190 - C Unspecified Outside
Eld Act Type 4: [Redacted] Comp Code 4 4190 - C Lock Outside Full Lock In
Eld Act Type 3: Comp Code 3
Eld Act Type 2: Comp Code 2
Eld Act Type 1: Comp Code 1
EAC Ref: 4
MR:
CR:

PM Order
PM Operator
Order Dates/Misc
Date Worked: 10/7/10
App Start Time: 08:00
App End Time: 08:00
Call # : 10710
Mtr # : 1151000

New Hazards / Surveys / Misc

Check Dinit
Tot Amt Order
Cost Only Flag

Technical Information

Give job to Redacted

FMR Ord Detail:
BEHIND CAFETERIA

FMR Completion:
BEHIND CAFETERIA

Dispatch:

Comment:

assist t&r dept. found 27.1 percent nat gas at reg box in front of cafeteria by school garden, clocked

Remarks:

houeline found 6.5 cfh leak in houseline. t&r sealed mtr issued hazard notice advise superintendent have plumber make repairs on their regulator.

Notes: