

## NEM Interconnection Status Report: 1st Quarter 2013

NEM applicants whose power systems have not been interconnected 30 working days after the receipt of a complete application by PG&E.

Report Date: 4/11/13

Project ID	Reason for Non-Interconnection	Date Interconnection is Expected to Be Completed
ENOS - 8302	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action
ENOS - 31006	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	4/21/2013
ENOS - 59175	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action
ENOS - 59178	Site is not ready	Depends on customer action
ENOS - 68569	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action
ENOS - 78273	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action
ENOS - 95844	Site is not ready	Depends on customer action
ENOS - 96200	Site is not ready	Depends on customer action
ENOS - 98299	Site is not ready	Depends on customer action
ENOS - 98483	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	4/20/2013
ENOS - 98613	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action
ENOS - 98933	Site is not ready	4/21/2013
ENOS - 102513	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action
ENOS - 104144	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	Depends on customer action
ENOS - 108890	The customer's facility failed PG&E's inspection; it did not meet the requirements for interconnection	4/15/2013