



GAS Operations
 Weld Inspection – L-114 Brentwood, CA

WELD INSPECTION VERIFICATION CHECKLIST

Location L-114 [Redacted] in Brentwood, CA
 Welding Inspector Terry Hypes – Canus Inspection
 RT Crew [Redacted] - Western Industrial X-ray – RT Level II
 PG&E Level III [Redacted] ATS Sr. Technical Specialist

Re-inspection of W-738, W-760, W-770, W-771, W-781

No .	Previous Weld #	Present Weld #	Visual Insp Results	WIX RT Results	PG&E Lvl III Results	CPUC Inspector
1.	W-781	TI-970	Accept 10/11/13	Accept 10/11/13	Accept 10/11/13	
2.	W-781	TI-971	Accept 10/11/13	Accept 10/11/13	Accept 10/11/13	
3.	W-738	TI-972R	Accept 10/11/13	Accept 10/11/13	Accept 10/11/13	
4.	W-738	TI-973	Accept 10/11/13	Accept 10/11/13	Accept 10/11/13	
5.	W-760	TI-976	Accept 10/11/13	Accept 10/11/13	Accept 10/11/13	
6.	W-760	TI-977	Accept 10/11/13	Accept 10/11/13	Accept 10/11/13	
7.	W-770	TI-978	Accept 10/14/13	Accept 10/14/13	Accept 10/14/13	
8.	W-771	TI-979	Accept 10/14/13	Accept 10/14/13	Accept 10/14/13	

Inspection of Tie – In Welds

No .	Weld #	Visual Insp Results	WIX RT Results	PG&E Lvl III Results	CPUC Inspector
1.					
2.					
3.					
4.					
5.					
6.					
7.					
8.					
9.					
10.					