Redacted

Leak Survey and Field Inspections Stamp

Wall Map/Plat: 103-3 Previous Leak Survey Start Date: 3-9-07
Scheduled Month/Year: 3-12 Previous Leak Survey Complete Date: 3-19-07

Survey Frequency/Type: ☒ 5-Year Survey ☐ 3-Year Survey ☐ Annual Survey ☐ 6-Months Survey ☐ Special Survey ☐ Audit

Address/Location Description: Town/City:

Date Surveyed	Surveyor LAN ID	Sample Color Highlighter Used	Type and Manufacturer Of Instrument Used[2]	Wind Speed Start of Day (MPH)[3]	Wind Speed Middle of Day (MPH)[3]	Serial Number Of Leak Survey Instrument (last 4 digits)	Foot Survey ☑	Mobile Survey ☑	Atmospheric Corrosion Survey ☑	Field Inspections Survey ☑	Actual Hours Surveyed[4]	Ft of Main Surveyed	# of Services Surveyed
4-5-12	J5C8	[redacted]	HR	4	10	3002	☑	☐	☐	☑	5.5	3571	96
4-9-12	SAVA	—	H.O	0	0	4006	☐	☑	☑	☑	2	5353	Ø
4-16-12	J5C8	[redacted]	HR	0	3	3002	☑	☐	☐	☑	7	7,304	125
4-18-12	J5C8	[redacted]	HR	0	5	3002	☑	☐	☐	☑	7	1,352	44
4-19-12	J5C8	[redacted]	HR	0	0	3002	☑	☐	☐	☑	4	5264	49
5-7-12	J5C8	[redacted]	HI	2	5	3002	☑	☐	☐	☑	7	8,276	109
5-8-12	J5C8	[redacted]	HI	0	2	6009	☑	☐	☐	☑	4	1128	40
5-9-12	J5C8	[redacted]	IR	0	5	4010	☑	☐	☐	☑	4	2425	68
5-10-12	J5C8	[redacted]	IR	0	2	4010	☑	☐	☐	☑	5	2006	54
5-11-12	J5C8	[redacted]	IR	0	—	4010	☑	☐	☐	☑	2	620	23
5-22-12	J5C8	—	HI	0	0	3002	☑	☐	☑	☑	5	0	26
5-23-12	J5C8	—	HI	0	0	3002	☑	☐	☑	☑	3	0	11
							☐	☐	☐	☐		