Bcc:

Subject: Spaulding Hydro Electric Powerhouse Site Visit - PG&E Follow-Up

Good afternoon Mr. Cheng,

I understand you had a very productive and informative visit to the Spaulding Powerhouse and Tram Last week. In the absence of a formal data request, I wanted to reach out to ensure you have received the information that you need.

I understand from Redacted you received the following documents during your site visit:

- 1. Transcript of the OSHA notification
- 2. Diagram of tram showing approximate body position
- 3. Log from DRUM switching Center showing incident timeline
- 4. Workers Comp Report 5020 and 5021
- 5. Spaulding Powerhouse#1 Operators Log

Additionally, I understand you have asked for copies of two Spaulding Tram drawings and the latest Tram Inspection report.

Please find the attached:

Drawing #393-224: Spaulding Tram 393224 Attch 01

Drawing #393-220:	Spaulding_Tram_393220_Attch_02	
Annual Inspection Report:	Spaulding_Tram_Annual_080113_Attch_03	
If there is anything we missed please reach out to me directly, my contact information is located at the bottom of this email.		
Kind Regards,		
Redacted		
Energy Supply Regulatory Compliance and Support, Pacific Gas and Electric Company Mailing address: 245 Market Street, Mail Code N13X, Office 1376, San Francisco, CA, 94105 Redacted		