



This KOP is located within a residential neighborhood adjacent to undeveloped land in the western portion of the Landscape Unit 17 in Chino Hills. An existing 220-kV transmission tower and conductors are visible on a low skyline ridge approximately 800 feet to the southwest.

Overall Visual Sensitivity: high. For residents of Crooked Creek Drive in general and KOP-South-13 specifically, the ratings of high viewer exposure, high viewer concern, and moderate-to-high visual quality lead to a high overall visual sensitivity of the visual setting and viewing characteristics.

Figure A-48a
Existing Conditions
for KOP-South-13
**Intersection of Avenida Anita/
Avenida Compadres,**
Chino Hills (Alternative 2,
Segment 8)

Source: SCE, 2007.